

**Eavluation of High Crash Locations  
Dark Criteria Study  
Location 2**

**Improvement Recommendations Matrix - US 9, MP 5.8-7.19**

<b>Site</b>	<b>Recommended Improvement</b>	<b>Status</b>
US 9 @ SR 20 Intersection (MP 6.10)	1 Evaluate for simple or complex intersection lighting as per Section 4.3.2 of the DelDOT Lighting Design Guidelines. Utility pole located on the southeast corner of the intersection should be the first option explored during the roadway lighting design process. Installing utility company-owned cutoff cobrahead luminaires on this pole should be investigated.	9/19/2013 - Handed recommendation off to Traffic Design. Currently being prioritized in the Intersection Improvements Program 11/20/2018 - In design
	2 Replace the damaged street name blade located on the pole in the median of southern leg of the intersection.	9/19/2013 - Signing - Maximo 580019 Complete - 10/28/2013
	3 Restripe stop bars, arrows, islands, and lanes on all approaches except southbound approach at the intersection. Much of the existing striping is worn out at the intersection.	9/24/2013 - Incorporated into Pave & Rehab project - T201206308