

tion. It also still possesses individual details such as a boxed cornice with returns; two, interior end brick chimneys; a Gothic style window in the center cross gable; and small, fixed, two pane windows in the attic story. The late nineteenth century house appears to be eligible as a contributing element in the Three Bay, I-House, Multiple Property Submission. Three bay I-houses are significant remnants of the basic vernacular dwelling type found throughout Sussex County. The majority of the houses in this submission, including this one, were part of working agricultural complexes, and are also significant under the priority of Agriculture (Ames et. al. 1989:79, 83).

CRS S-5146
Previously Surveyed
Individually Eligible
Plate 53; Appendix A, Plat 10

This previously surveyed, late nineteenth century agricultural complex is located on the north side of Road 40. The house is a two story, L-plan I-house. It is three bays wide with a projecting, two story, bay window on the front facade facing Road 40. There is a barn and several storage and machinery sheds on the property. This house appears to be individually eligible as it is a rare building type within the project corridor. Less than five residences within the project area have the two story, bay window projecting from the front facade as this house has. It is not clear if the house was originally constructed this way, or if the projecting bay was added at a later date. It is a unique building type to the area and is therefore noteworthy. The property is significant under the priority theme of Agriculture 1880-1940 (Ames et. al. 1989; Herman et. al. 1989).

CRS S-5147
Previously Surveyed
Individually Eligible
Plate 54; Appendix A, Plat 10

This previously surveyed, late nineteenth/early twentieth century house is located on the south side of Road 40. The building is a combination of the I-house form and the Classical Box style. It appears that a hipped roofed, three bay wide and deep Classical Box was built onto an already existing I-house, creating a massive structure. A hipped roofed porch wraps around the first story of the north and east facades. A hipped roofed, dormer window is positioned in attic story of the north and west facades. This dwelling is one of only two, combination I-house/Classical Box structures in the project corridor. The house successfully blends two distinct building types, from both the nineteenth and twentieth centuries, into a single home. The house reflects the changing attitudes of its owners, and their desire to "modernize" their home from a traditional I-house to a more "up to date" home of the early twentieth century. The house is in excellent condition and appears to be individually eligible. It is significant for its architecture, under the temporal period 1880-1940: Suburbanization (Herman et. al. 1989).

CRS S-8422
Individually Eligible
Plate 55; Appendix A, Plat 10

This agricultural outbuilding sits on the south side of Road 40. The rectangular shaped structure is approximately eighty feet long by forty feet wide. It is clad in horizontal wood siding. Raised on concrete block piers, This building has a metal, gable roof. There are three, large, garage type doors on the north facade facing Road 40. A smaller, wood panel door is present at the eastern end of the building. There is also a pair of sliding wood doors on the west end of the structure.



PLATE 53: CRS S-5146
View of south facade of dwelling, looking north.
Note large cross bay with Victorian detailing at the eaves.



PLATE 54: CRS S-5147
View of north and east facades of house, looking southwest.
Note pyramidal roof line, intersecting cross section, and large, wraparound porch.

This structure, although it is not clearly associated with the farm complex across the road (S-5146), appears to be an outbuilding that was used for the storage and loading of produce. It most likely dates to the early twentieth century, and is the only such structure in the project corridor. Further research is needed to verify its function and to tie it directly to a surrounding farm. Based strictly on its unique form and rarity within the project area, the building appears to be eligible. The structure is significant under the priority theme of Agriculture 1880-1940 (Ames et. al. 1989).

CRS S-5148/5149

Previously Surveyed

Not Eligible

Plate 56; Appendix A, Plat 10

This late nineteenth century agricultural complex sits on the south side of Road 40. The main house is a two and one-half story, three bay wide, and two bay deep I-house with a gable roof. The front or north facade, facing Route 40, has a centrally placed door. A single, one over one, double hung window in a plain wooden frame is positioned on either side of this entry. A shed roofed porch supported by turned wooden posts with decorative brackets, extends across the facade. Three, symmetrically placed, one over one, double hung windows with plain wooden frames are present in the second story. The gable roof is sheathed in composition shingles.

The rear or south facade has a partially enclosed porch across the first story. This porch has a shed roof supported by turned wooden posts identical to those on the front facade porch. The center portion of the facade is enclosed. There are two, one over one, double hung windows at either end of the facade.

The east and west facades each have two windows on both the first and second stories. All of these windows are one over one and double hung. There are also two, small, fixed, three pane windows in the attic story of both the east and west facades. The east facade has a modern, exterior end, brick chimney. The west facade has an interior end, brick chimney. The house rests on a concrete foundation and is covered in aluminum siding.

Several other buildings are on the property including a two story, three bay wide and one bay deep structure with a gable roof. This structure appears to have been moved to the property recently. Currently jacked up on concrete piers, this building is clad in horizontal wood siding. The main entrance is on the west facade. The building seems to date to the early twentieth century.

A modern storage building, rectangular in plan with a gable roof and a concrete block foundation, is located directly south of the main house. A shed roofed addition that is open at both ends is attached to the west facade of this storage building. The building appears to have constructed within the last 45 years. Several chicken houses are also present on the property.

This complex does not appear to be eligible either individually or as a contributing part of the Three Bay, I-House, Multiple Property Submission. The house has been altered. Also, the outbuildings remaining on the property do not appear to be original to the site.




PLATE 55: CRS S-8422
View of north and west facades of structure, looking southeast.
Note frame construction and large, varied openings on all facades.




PLATE 56: CRS S-5148
View of south and west facades of house, looking northeast.
Note altered fenestration and enclosed porch section.

CRS S-5140/5141
Previously Surveyed
Not Eligible
Plate 57; Appendix A, Plat 13

This late nineteenth century house sits at the southwest corner of Roads 565 and 594. The two and one-half story dwelling is a heavily altered, T-plan I-house with a cross gable roof. The north or front facade, facing Road 594 is three bays wide with the entrance in the center bay. The modern doorway is flanked by a one over one, double hung window in the western bay, and a large, modern, picture window in the eastern bay. Both windows have green louvered shutters. A one story, shed roofed porch extends across the facade. Plain, wooden posts support this porch.

There are three, symmetrically placed, modern, one over one, double hung windows with louvered shutters in the second story. A pointed, Gothic window is situated in the peak of the center cross gable. The roof is sheathed in composition shingles. A single, one over one, double hung window is centrally placed in both the first and second stories of the east facade.

A one story, gable roofed addition has been added onto the west and south facades. This addition also has modern, one over one, double hung windows with louvered shutters. A modern, exterior, brick chimney has been built between the original west facade of the house and the one story addition.

A two story, gable roofed addition has been constructed at the rear of the house creating a T-plan structure. A hipped roofed porch wraps around this rear addition on the east and south facades. The entire house is clad in aluminum siding and rests on a concrete foundation. A modern, metal storage shed is present to the west of the house.

This building does not appear to be eligible, either individually or as part of the Three Bay, I-House, Multiple Property Submission. The house has been heavily altered with the addition of a modern wing on the west facade, the insertion of modern windows and doors, the construction of a new chimney on the west facade, and the application of aluminum siding. There are better examples of the three bay I-house throughout the project corridor.

CRS S-5139
Previously Surveyed
Not Eligible
Plate 58; Appendix A, Plat 13

This late nineteenth century, house is located on the west side of Road 565. The original dwelling is a two and one-half story, three bay wide, two bay deep, I-house with a gable roof. The front or east facade, facing Road 565, is three bays wide with a center entrance. A single, one over one, double hung window with louvered shutters is positioned on either side of the center entrance. A hipped roofed, screened in porch extends across the entire first story of the house. There are two, one over one, double hung windows with louvered shutters located at either end of the second story facade. The gable roof is sheathed in composition shingles.

The north and south facades are identical with two, one over one windows on the first story, and two, small openings in the attic story. These openings were undoubtedly fixed windows at one time, although they are currently used as ventilators for the attic. An exterior end, concrete block chimney is centrally placed in the south facade between the two first story windows.



PLATE 57: CRS S-5140
View of north facade of house, looking southeast.



PLATE 58: CRS S-5139
View of south and west facades of house, looking east.
Note heavy alterations to exterior.

A rear, one story, gable roofed addition has been constructed at the southwest corner of the house. This addition appears to be modern and is two bays wide and deep with an entrance on the south facade. The windows in this part of the house are all modern, one pane and fixed. A gable roofed portico supported by plain, wooden posts extends out over the side entrance. There is an exterior, concrete block chimney on the west facade of the addition. The entire house is clad in dark brown aluminum siding.

This house does not appear to be eligible. The fenestration and form have been substantially altered and detract from the overall integrity of the house. There are better examples of the three bay I-house throughout the project corridor.

CRS S-5109

Previously Surveyed

Eligible: Three Bay, I-House, Multiple Property Submission
Figure 5; Plate 59; Appendix A, Plat 16

This previously surveyed, mid-nineteenth century, agricultural complex is situated on the east side of Road 592, approximately one hundred yards from the road. The dwelling is a two and one-half story I-house. It is three bays wide and one bay deep with a rear, two story section. The entire structure is clad in wood shake shingles. There are several outbuildings in poor condition on the property. These outbuildings include a barn and several sheds.

This property appears to be a contributing element in the Three Bay, I-House, Multiple Property Submission. The house retains its basic original form, fenestration, setting, and still possesses several agricultural outbuildings. Three bay I-houses are significant remnants of the basic vernacular dwelling type found throughout Sussex County. The majority of the houses in this submission, including this one, were part of working agricultural complexes, and are also significant under the priority of Agriculture (Ames et. al. 1989:79, 83).

CRS S-5127

Previously Surveyed

Not Eligible

Plate 60; Appendix A, Plat 16

This previously surveyed, L-plan house sits on the north side of Road 579. The house is two and one-half stories, two bays wide and deep with a gable roof and rear, two story wing. The entrance is in the south or front facade. The windows are mostly one over one and double hung. The house is clad in yellow, composition shingle siding.

This house is not eligible due to several alterations. These alterations include changes in fenestration, the pouring of a concrete slab for a front porch, the erection of a concrete block chimney on the east facade, and the application of composition siding. According to a previous survey, this house was constructed circa 1920, and was moved in 1956 from its original location on Route 13 (Corkadel 1984).



PLATE 59: CRS S-5109
View of south and east facades of house, looking north.
Note three bay fenestration, shake siding, and original windows.



PLATE 60: CRS S-5127
View of south and east facades of house, looking northwest.
Note altered exterior.

CRS S-5128
Previously Surveyed
Individually Eligible
Plates 61a, 61b, 61c, 61d, 61e; Appendix A, Plat 16

This large, mid-nineteenth century, agricultural complex is located on the east side of Road 527. The two story, three bay wide, and two bay deep I-house faces the road. The entrance is centrally placed in the west facade. A single, two over two, double hung window is positioned on either side of the entrance. A hipped roofed, screened in porch extends across the middle of the facade. This porch encloses the entrance and flanking windows. There are three, symmetrically placed, two over two, double hung windows in the second story. The gable roof is sheathed in asphalt shingles and has a boxed cornice with returns.

The north and south facades are identical, with two windows, symmetrically placed in each story. They are all two over two and double hung. There is an interior, brick chimney centrally located on each facade.

A rear, two story, two bay wide and one bay deep addition with a gable roof has been built at the rear of the house, creating a T-plan structure. An enclosed, one story, shed roofed addition was added onto the south side of the rear wing. There is an entrance leading into this addition on the east facade. The windows in the additions are all one over one and double hung. The entire house is clad in wood, shake shingles.

There are a variety of agricultural outbuildings on this property. The majority of the buildings are constructed of vertical boards and have gable roofs. The outbuildings include several types of sheds, a chicken house with metal silos, a corncrib, outhouse, barn, and vehicle storage structures.

This complex is individually eligible as an outstanding example of a nineteenth century farmstead which still operates as a farm today. The house is in good condition and retains its basic form and fenestration. The property is one of the largest and most intact agricultural complexes in the study area, with a variety of outbuildings. It is significant under the priority theme of Agriculture, within the temporal period 1830-1880 (Ames et. al. 1989:79).

CRS S-5131
Previously Surveyed
Eligible: Four Bay, I-House, Multiple Property Submission
Figure 6; Plate 62; Appendix A, Plat 19

This mid-nineteenth century property, situated on both the north and south sides of Road 527, was previously surveyed. The dwelling is a two story, four bay wide, one bay deep I-house with a gable roof and a rear, one and one-half story addition. The rear wing appears to house the kitchen. The entrance is located in the second bay from the east. There appears to have been a second door in the third bay, which is currently boarded over. There is a frame granary and barn located directly across the road from the house.

This agricultural complex is eligible as a contributing part of the Four Bay, I-House, Multiple Property Submission. There are only a handful of rare four bay I-houses within the corridor; and this complex is one of two, which retains its basic form and fenestration, as well as several outbuildings. The complex is abandoned, and is in fair condition. Four bay I-houses are significant remnants of the nineteenth century built environment of Sussex County. Both of the properties in this submission, including this one, were part of working agricultural complexes, and are also significant under the priority theme of Agriculture (Ames et. al. 1989:79, 83).



PLATE 61a: CRS S-5128
View of west and south facades of house, looking east.
Note excellent condition of building, with intact fenestration.



PLATE 61b: CRS S-5128



PLATE 61c: CRS S-5128



PLATE 61d: CRS S-5128



PLATE 61e: CRS S-5128



PLATE 62: CRS S-5131

View of south and east facades of house, looking northwest.
Note four bay fenestration, original windows, and rear kitchen wing.

CRS S-3191
Previously Surveyed
More Work Needed
Plate 63; Appendix A, Plat 19

This previously surveyed, two story, four bay wide, two bay deep I-house sits on the south side of Road 527. The dwelling has a gable roof, additions on the north and east facades, and is covered in shake shingle siding. It is unclear in which facade the original entrance was located, as both the east and west facades have been altered substantially. The main doorway is currently located in the gable end or north facade, facing the road. There are two, frame sheds on the property.

This house is not eligible as a contributing part of the Four Bay, I-House, Multiple Property Submission due to alterations on the main facades. The first story of the west facade has two pairs of six over one, double hung windows inserted on either end of the facade. These windows appear to have been installed in the twentieth century. A one story, shed roofed addition has been constructed across the entire east facade of the building, obscuring the original fenestration. Despite these alterations, the house is in excellent condition. It has two, frame outbuildings and a large parcel of land. According to a previous survey, the building was moved in 1937 from across the road, and originally had a shed, chicken house and a summer kitchen (West 1983). Further research is recommended for this property before a final decision can be made as to its individual eligibility.

CRS S-8423
Not Eligible
Plate 64; Appendix A, Plat 19

This abandoned house is located on the north side of Road 527. The building is rectangular in plan. This one and one-half story I-house is three bays wide and two bays deep with a gable roof. The entrance is placed in the middle bay of the front or south facade, and is flanked by a single window. The door has been replaced with a modern, wood door and the windows are boarded over. There are three, small, two over two, double hung windows in the upper story of the front facade. The gable roof is sheathed in composition shingles.

The east and west facades have two windows in both the first and second stories. Most of these windows are boarded over, although a single, two over two window remains in the west facade. A chimney was centrally placed in the west facade, but has been removed.

The original fenestration of the north facade is unclear as it has been heavily altered and much of the original siding material is gone, leaving the interior of the building exposed. The house is covered in composition shingle siding and rests on concrete block piers. There is a metal, gable roofed garage on the property.

This mid-nineteenth century house is in extremely poor condition and does not appear to be eligible. Many of the original elements are missing and much of the cladding material is gone, greatly compromising the integrity of the structure. There are better examples of three bay I-houses throughout the corridor.



PLATE 63: CRS S-3191
View of north and west facades of house, looking southeast.
Note early windows on second story of west facade.



PLATE 64: CRS S-8423
View of east facade of house, looking northwest.

CRS S-8424
Not Eligible
Plate 65; Appendix A, Plat 19

This late nineteenth/early twentieth century, Colonial Revival I-house is located on the north side of Road 527. The original house is two and one-half stories, three bays wide, and two bays deep with a gable roof. The entrance is positioned in the middle bay of the front or south facade, and is flanked by a single, six over one, double hung window with louvered shutters. A gable roofed pediment projects out over the front door. There are two, symmetrically placed, six over one, double hung windows in the second story of this facade. The gable roof is sheathed in composition shingles.

There is a gable roofed, one story addition on both the east and west facades of the house. These additions have modern windows and are covered in white, composition shingle siding that matches the main block of the house. The second story of the main house is visible above the one story additions on both the east and west facades. These windows are also six over one and double hung. A modern, brick chimney has been erected along the east side of the structure. There are two, small, three pane and fixed windows in the attic story. A two story, two bay wide and deep, flat roofed addition has been constructed across the rear or north facade of the house. This addition has six over six, double hung windows. There are two, frame garages with gable roofs and one, frame shed with a gable roof on the property.

This house does not appear to be eligible either individually or as part of the Three Bay, I-House, Multiple Property Submission. The original I-house has been heavily altered creating a Colonial Revival style building with modern additions. There are many more intact, three bay I-houses throughout the corridor with greater integrity.

CRS S-8425
Not Eligible
Plate 66; Appendix A, Plat 19

This mid-nineteenth century, agricultural complex sits on the north side of Road 527, at the intersection with Road 522. The dwelling is a two and one-half story, five bay wide, two bay deep, I-house with a center cross gable and a rear two story addition. The front or south facade faces Road 527 and has a center entrance. This entrance is flanked by two, single, two over two, double hung windows. A screened in, hipped roofed porch covers the three middle bays on the first story. There are five, symmetrically placed, two over two, double hung windows in the second story. A roundheaded, one over one window is located in the center cross gable in the front facade.

There are two, two over two, double hung windows symmetrically placed in the second story of the east facade. There is a single, two over two, double hung window in each story of the west facade. The gable roof has a boxed cornice with returns and is sheathed in asphalt shingles. There are interior end brick chimneys, covered in cement, at both the east and west ends of the dwelling.

A two story, gable roofed addition was constructed at the northwest corner of the house creating an L-plan structure. This addition is two bays wide and deep with a shed roofed, screened in porch on the west facade. There is a third chimney located along the north facade of the rear wing. A modern, one story, gable roofed addition was added onto the north facade of the rear ell. This addition wraps around to the east facade. The windows in this addition are also one over one and double hung. The entire house is clad in white aluminum siding. There are a variety of frame outbuildings on the property including chicken houses, barns, and sheds.



PLATE 65: CRS S-8424
View of south and east facades of house, looking northwest.



PLATE 66: CRS S-8425
View of south and east facades of house, looking northwest.
Note five bay fenestration, original windows, chimneys, and cross gable.

This complex appears to be eligible as a contributing part of the Five Bay, I-House, Multiple Property Submission. The property is still agricultural in nature and retains its rural setting. The house maintains its form and fenestration, and is a good example of the five bay, I-house architectural type.

CRS S-8426
More Work Needed
Plate 67; Appendix A, Plat 19

This abandoned I-house is located on the north side of Road 527. Access to the house was difficult, as it is heavily overgrown with vegetation, making clear photographs impossible to take. The building is three bays wide and one bay deep with a gable roof and an interior end, brick chimney on the east facade. The entrance appears to have been in the center of the south facade. It was flanked by a single window on each side. These windows appear to have been two over two and double hung, although they are currently covered over with boards and metal awnings. There are three, symmetrically placed window openings in the second story of the south facade.

The first and second stories of the east facade have a single window in the southernmost bay. These also appear to have been two over two and double hung. There were two, small windows in the attic story which are now missing. A large portion of the north facade has been robbed of its material, and is standing open to the elements. A clear description of this facade is not possible due to the amount of deterioration. The remainder of the house is clad in composition shingle siding.

Further site evaluation is needed to determine if this building could be a contributing part of the proposed, Three Bay, I-House, Multiple Property Submission.

CRS S-8427
Not Eligible
Plate 68; Appendix A, Plat 19

This one story cabin is situated on the south side of Road 527. The building is rectangular in plan with a cross gable roof. A cutaway, glass enclosed porch is located in the north facade. There is an entrance to the house through the porch. A second doorway is placed in the west facade. The windows in the house are a combination of one over one, double hung and small, fixed, single pane openings. The house rests on a concrete block foundation and is clad in tan, composition shingle siding. An exterior, concrete block chimney is positioned on the west facade. This house appears to postdate 1945 and possesses little architectural significance, or known historical association, making it ineligible based on National Register criteria.

CRS S-8428
Not Eligible
Plate 69; Appendix A, Plat 19

This small cottage is situated on the south side of Road 527. The building is square in plan. It is two bays wide and deep with a shed roofed addition on the south facade. The entry is placed on the east facade. The windows are a combination of one over one, and six over six, double hung. The building is clad in composition shingle siding and has a gable roof. An exterior brick chimney is present on the east facade.

The construction date of this cabin is unknown, although it appears to have been built circa 1940. The house may have been an outbuilding or shed for the home on the adjacent property. The building does not appear to be eligible as it possesses little architectural or historical significance.



PLATE 67: CRS S-8426
View of south and east facades of house, looking northwest.
Heavy overgrowth surrounds the house, preventing detailed photography.



PLATE 68: CRS S-8427
View of north and east facades of house, looking southwest.



PLATE 69: CRS S-8428
View of north and east facades of house, looking southwest.



PLATE 70: CRS S-8429
View of north facade of house, looking south.

CRS S-8429
Not Eligible
Plate 70; Appendix A, Plat 19

This one and one-half story cabin is located on the south side of Road 527. The cabin is basically rectangular in plan with a shallow pitched, gable roof and various additions. The main entrance is placed in the north facade facing the road. All of the windows in the house are modern. The building rests on a concrete foundation and is clad in tan, vinyl siding. This house appears to postdate 1945. It possesses little architectural significance or known historical association, making it ineligible based on National Register criteria.

CRS S-3192
Previously Surveyed
Not Eligible
Plate 71; Appendix A, Plat 19

Located on the north side of Road 527, this late nineteenth century house was previously surveyed. The building is of I-house form. It is four bays wide and two bays deep with a gable roof and rear additions. An enclosed, hipped roofed porch extends across the first story of the front facade. The four windows in the second story of the house all appear to have been replaced. There are no historic outbuildings associated with the property.

This house does not appear to be eligible due to heavy alterations that have greatly compromised the integrity of the structure. There are several other four bay I-houses within the project corridor that retain their original fenestration and are better examples of the building style.

CRS S-8430
Not Eligible
Plate 72; Appendix A, Plat 19

This long, rectangular house is situated on the west side of Route 113. The building is one story, five bays wide and two bays deep with a gable roof. A one bay deep, gable roofed section projects from the center of the front facade. This addition is screened in and has a center entrance. Large, modern, picture windows flank the entry. Extending out over the windows are flat, metal awnings supported by iron columns.

Four, six over six, double hung windows and one door are placed in the rear or west facade. Two, symmetrically placed, six over six windows are located on the end facades. A modern, exterior, brick chimney is centered in the south facade. A second brick chimney is placed in the interior along the west facade. A gable roofed shed sits in the backyard. The house is clad in composition shingle siding. This house appears to date to circa 1930, and possesses little architectural merit or known historical significance, and is not eligible. In accordance with guidance from the BAHP, buildings of this period do not form a preservation priority within the project corridor (Personal Communication with Steve DelSordo May 1991).



PLATE 71: CRS S-3192
View of south and east facades of house, looking northwest.
Note heavy alterations to exterior fabric.




PLATE 72: CRS S-8430
View of north and east facades of house, looking southwest.
Note obtrusive picture window.

CRS S-8431
More Work Needed
Plate 73; Appendix A, Plat 19

This Colonial Revival cottage is located on the west side of Route 113. The one and one-half story house is rectangular in plan with a gable roof and additions on the side and rear. The entrance is centrally placed in the east facade. Flanking this entry are pairs of modern, one over one windows with awnings. Two, gable roofed dormers with wooden cornices and returns, are evenly spaced in the upper story of the facade. These windows also have awnings. A hipped roofed, glass enclosed porch has been built on the north facade of the house. An exterior, brick chimney is centrally placed along the facade. Two, small, lunette windows are positioned on either side of the chimney in the attic story. Two, one over one windows with awnings are symmetrically placed in the first story of the south facade. An identical window is located in the attic story.

A square plan, flat roofed porch has been added onto the west or rear facade. Pairs of modern, sliding windows wraparound the porch. A wooden balustrade follows the roof line. An exterior, brick chimney stack is also present along the west facade. The entire house is clad in aluminum siding and sits on a concrete foundation. A T-plan, gable roofed garage is located at the rear of the property. The garage appears to date to the same period as the house.

This house appears to date to the 1920s or 1930s era when the Colonial Revival style was at its most popular. Individual details such as the lunette windows in the attic story, gable roofed dormers with boxed cornices, and the balustrade around the rear porch, all indicate that the house was constructed during this time period. It is possible however, that the house actually dates to the late 1940s or 1950s, and has recently had the Colonial Revival touches added. Further research into the history of this house is necessary before a judgment as to eligibility can be made.

CRS S-8432
Not Eligible
Plate 74; Appendix A, Plat 19

This one story, rectangular plan cottage sits on the west side of Route 113. The house is three bays wide and two bays deep with a projecting, one bay wide, cross gable section on the front facade. The gable roof flares out slightly on the front facade creating a cutaway porch. Metal railings support the overhanging roof. There is an entrance in the front facade and in the rear. The windows are modern, six over six, double hung with louvered shutters. An interior, brick chimney is centered along the ridge of the roof. The house sits on a concrete foundation and is clad in yellow, aluminum siding. This house lacks architectural merit or known historical significance and appears to postdate 1945, making it ineligible based on National Register Criteria.

CRS S-8433
Not Eligible
Plate 75; Appendix A, Plat 19

This one and one-half story, gable roofed cottage is situated on the west side of Route 113. The house is three bays wide and deep with two, shed roofed additions on the rear facade. The entrance is centrally placed in the front or east facade. All of the windows in the house are modern with louvered shutters. An interior, concrete block chimney is located in the rear or west facade. The house sits on a concrete foundation and is clad in white, aluminum siding. A concrete block shed and garage are present on the property. This house lacks architectural merit or known historical significance and appears to postdate 1945, making it ineligible based on National Register criteria.



PLATE 73: CRS S-8431
View of north and east facades of house, looking southwest.



PLATE 74: CRS S-8432
View of main facade of dwelling, looking west.



PLATE 75: CRS S-8433
View of east and south facades of dwelling, looking west.



PLATE 76: CRS S-8434
View of south and east facades of house, looking northwest.
Note obtrusive addition on side facade.

CRS S-8434
Not Eligible
Plate 76; Appendix A, Plat 19

This one story, gable front structure sits on the west side of Route 113. The house is two bays wide and three bays deep with a shed roofed, screened in porch on the front facade. The entrance is located in the east or front facade. Two, separate, shed roofed additions have been constructed on the north facade. Each of these additions is one bay deep. All of the windows in the house are modern. A concrete block chimney is placed along the ridge of the roof in the western end of the building. The entire house is clad in aluminum siding and rests on a concrete foundation. A one and one-half story, gable roofed garage with flanking one story, shed roofed additions, is located just west of the house. A modern garage door opens on the east facade, facing the road.

This house appears to date to the late nineteenth or early twentieth century. In 1868, the Sharp Hill School was located at this spot (Beers 1868, Appendix B). The original three bay by three bay, gable roofed structure could possibly be a former schoolhouse, however later additions detract from the original form. Changes in the fenestration also compromise the original symmetry of the building. There is at least one other example of a nineteenth century schoolhouse in the project corridor which retains its basic form and fenestration, and is a better example of the architectural type (See CRS S-5218). This building is not eligible.

CRS S-8435
Not Eligible
Plate 77; Appendix A, Plat 19

This L-plan, one story, gable roofed cottage is located on the east side of Route 113. The main or west facade, facing the road, is five bays wide. Doors occupy the second and fourth bays. The majority of the windows in the house are modern, six over six, and double hung with louvered shutters. The house has a concrete foundation and is clad in yellow, composition shingle siding. Two, frame sheds are present on the property.

This house appears to date the 1930s or 1940s. It possesses little architectural significance or merit. In accordance with guidance from the BAHP, buildings from this time period do not form a preservation priority within the project corridor (Personal Communication with Steve DelSordo May 1991). The house is not eligible.

CRS S-8436
More Work Needed
Plates 78a and 78b; Appendix A, Plat 19

This early twentieth century house sits on the east side of Route 113, approximately fifty yards from the road. This recently renovated house is three bays wide and one bay deep with a flared, gable roof. It has a rear, one and one-half story addition. The front door is placed in the southernmost bay of the front or west facade. Modern, six over six, double hung windows with paneled shutters occupy the remaining two bays. The gable roof extends outward over the front porch. Square, wooden posts support the roof. A balustrade with square spindles encircles the porch. A shed roofed dormer with two, small, six over six windows is centrally placed in the upper story.

A single, six over six, double hung window is placed in the first story of the south facade. Two, small, four pane windows are situated in the attic story. In the north facade, a modern, sliding, glass door with paneled shutters has been inserted in the first story. These doors open onto a modern, wood deck. A single, one over one window is present in the attic story.



PLATE 77: CRS S-8435
View of south and west facades of house, looking northeast.



PLATE 78a: CRS S-8436
View of west and north facades of house, looking north.



PLATE 78b: CRS S-8436
View of outbuilding to rear of house, looking south.



PLATE 79: CRS S-8437
View of south facade of dwelling, looking north.

A one and one-half story, one bay wide and two bay deep, gable roofed addition has been added onto the rear or east facade of the house. A separate entrance into the addition is located in the south facade. The house rests on a concrete foundation and is clad in vinyl siding.

A three bay, shed roofed garage is present just south of the house. The double, wood doors open on the west facade. An abandoned, shed roofed structure is located at the rear of the property. This building is approximately twenty five feet wide and seventy five feet long. It has a variety of door and window openings. Currently, the frame structure is covered in composition shingle siding and is in fair condition.

The main house appears to date to the early twentieth century. Although the building is in excellent condition, and has recently been remodeled, it has been heavily altered. Changes to the structure include: the insertion of modern windows and doors including dormers, the application of modern siding and roofing material, and the addition of a front porch and a one and one-half story wing at the rear of the house. While the house itself does not appear to be eligible, the one story, shed roofed structure at the rear of the property warrants further research. It has been suggested that this building may possibly have been used as early twentieth century, migrant worker housing for a nearby farm. More information is needed about this structure before a judgment as to eligibility can be made.

CRS S-8437
More Work Needed
Plate 79; Appendix A, Plat 19

This dwelling complex sits on the north side of Road 244. The house is a one story, three bay wide and two bay deep cottage with a gable roof and two flanking additions. The main entrance is centrally placed on the south facade facing the road. A gable roofed, pediment supported by plain, wooden posts projects over the entrance. Pairs of three over one, double hung windows flank the doorway. One story, gable roofed additions have been constructed on the east and west facades of the house. A second entrance is located in the south facade of the western addition. An exterior, brick chimney is positioned between the main house and the addition on the east facade. A small, shed roofed addition has also been built in the center of the rear or north facade. A third doorway is present in this addition. The house sits on a concrete foundation and is clad in a combination of aluminum and composition shingle siding.

There are several frame outbuildings at the rear of the property, north of the house. These include a frame shed, one car garage, and a vehicle storage structure. This property appears to be eligible, but no determination can be made until the age of the house and the outbuildings is verified. Further research is necessary.

CRS S-3216
Previously Surveyed
Individually Eligible
Plate 80; Appendix A, Plat 19

This dwelling complex is located on the south side of Road 244, east of Route 113. The house, which was previously surveyed, appears to have been constructed in two stages. A small, one story, two bay wide and one bay deep section with a gable roof, is present at the east end of the building. This section seems to be the earliest portion of the house. A larger, four bay wide and two bay deep, two story I-house is built on the west side, adjacent to the smaller structure. This portion of the house has three, small, three over three windows in the second story and end, interior, brick chimneys.




PLATE 80: CRS S-3216
View of north facade of dwelling.
Note unusual construction, early windows on second story, and attached kitchen.



PLATE 81a: CRS S-3217
View of north and west facades of house, looking southeast.
Note five bay fenestration on main facade.



PLATE 81b: CRS S-3217

View of workshop/tenant house to rear of main house, looking southeast.
Note frame construction, original windows, standing seam metal roof.

This house appears to be individually eligible as an example of an early nineteenth century, Chesapeake Bay Vernacular structure that was enlarged in the mid-nineteenth century. The larger and more popular I-house form was added onto the smaller structure creating a two part house. These architectural changes undoubtedly reflect the needs of a growing family, and their desire for more space within the home. This evolution of building types is not as clear in the majority of homes throughout the study area as it is in this dwelling. The property is significant within the temporal period of 1770-1830, and the historic context of Architecture (Herman et. al. 1989; Ames et. al. 1989).

CRS S-3217

Previously Surveyed

Individually Eligible

Plates 81a and 81b; Appendix A, Plat 22

This previously surveyed agricultural complex is positioned on the south side of Road 244. The farmhouse is a two and one-half story, T-plan I-house with a cross gable in the front facade. It is five bays wide and two bays deep with a one story porch on the north facade and corbeled brick chimneys.

Outbuildings include a two story, frame structure that is three bays wide and one bay deep. It has a metal, gable roof and a raised brick foundation. The windows are six over six and double hung. Attached to this building is an open, one story, gable roofed structure apparently used for machinery storage. The function of the two story building is unclear, although it may have been used as a foreman's dwelling at one time. Currently, it appears to be used for storage. In addition to this building, there are chicken coops and a grain shed on the property.

This property appears to be an individually eligible complex. It is significant as an intact collection of nineteenth century agricultural related buildings under the priority historic context of Agriculture, 1830-1880 (Herman et. al. 1989). A site plan for this complex can be found in Appendix E.

CRS S-3218

Previously Surveyed

Eligible: Three Bay, I-House, Multiple Property Submission

Figure 5; Plate 82; Appendix A, Plat 22

Located on the north side of Road 244, this agricultural property was previously surveyed. The I-house is three bays wide, two bays deep, and two stories with a gable roof and a rear, two story wing. The entrance is centrally placed in the front facade. A combination of one over one, and two over two, double hung windows is present in the house. There are several frame outbuildings on the property including a barn and several sheds, as well as a trotting ring for horses to the north of the house.

This mid-nineteenth century, complex is eligible as a contributing part of the proposed, Three Bay, I-House, Multiple Property Submission. The house retains its basic form and fenestration, as well as several outbuildings that contribute to the overall integrity of the complex. The land remains rural in nature and is still used to raise horses. This house appears to be eligible as a contributing member of the proposed Three Bay, I-House, Multiple Property Submission. The building retains its basic form and fenestration and is in good condition. Later alterations to the house do not detract from its overall integrity. Three Bay I-houses are significant architectural remnants of the basic vernacular dwelling type found throughout Sussex County.



PLATE 82: CRS S-3218
View of south and east facades of house, looking northwest.
Note three bay fenestration, original windows, and rear kitchen wing.




PLATE 83: CRS S-8438
View of south facade of house, looking north. Note heavy alterations.

CRS S-8438
Not Eligible
Plate 83; Appendix A, Plat 22

This heavily altered, two story I-house is situated on the north side of Road 244. The house appears to be three bays wide and two bays deep, but substantial alterations make it difficult to determine the original fenestration. A one story, one bay deep, flat roofed, enclosed addition is attached across the entire front or south facade. A modern doorway is placed off center in this addition. A single, one over one, modern window is positioned on either side of this entry. This addition is covered in green, composition shingle siding. Two, small, one over one windows are visible in the second story of the house above the addition.

A second, one story, flat roofed addition clad in blue, aluminum siding is constructed across the west facade of the house. This addition has a band of modern, four pane, picture windows across the length of the facade. A single, one over one, double hung window is visible in the southernmost bay of the second story of the house. One story, shed roofed additions are also present on the north and east facades of the building. An interior, concrete block chimney is located on the east facade. There are several frame sheds on the property, all of which are in poor condition. An above ground swimming pool is situated just west of the house.

This late nineteenth century, I-house has been so heavily altered that its original form is totally obscured by modern additions. All of the windows and doors in the house have been replaced, the chimneys are modern, and a variety of cladding materials have been applied to the exterior. Numerous examples of the three bay I-house form in better condition and retaining integrity are present throughout the project corridor. This property is not eligible.

CRS S-3214
Previously Surveyed
Eligible: Three Bay, I-House, Multiple Property Submission
Figure 5; Plate 84; Appendix A, Plat 22

This previously surveyed, two story, L-plan I-house is located at the southeast corner of Roads 244 and 243. The house is three bays wide and two bays deep with a gable roof and a rear, two story wing. There is a wraparound, hipped roofed porch on the north and west facades. Two, frame sheds are positioned to the east of the house.

This late nineteenth century complex appears to be eligible as a contributing member of the proposed Three Bay, I-House, Multiple Property Submission. The house retains its basic form and fenestration, as well as two outbuildings. Later alterations to the house do not detract from its overall integrity. Three bay I-houses are significant architectural remnants of the basic vernacular dwelling type found throughout Sussex County. The building is also significant under temporal period 1830-1880, with the agricultural priority theme (Ames et. al. 1989:79).

CRS S-3215
Previously Surveyed
Not Eligible
Plate 85; Appendix A, Plat 22

This previously surveyed house sits on the east side of Road 243, north of the intersection with Road 244. The dwelling is a two story, three bay wide, one bay deep I-house. This gable roofed dwelling has a rear, one story, shed roofed addition. The entrance is centrally placed in the front or west facade. A one story, shed roofed, one bay deep addition extends across the entire east facade of the house. A frame shed with a corrugated metal roof is present at the rear of the property.



PLATE 84: CRS S-3214
View of west facade of house, looking east.
Note three bay fenestration, original porch and detailing.



PLATE 85: CRS S-3215
View of west and south facades of house, looking northeast.

This late nineteenth century, house does not appear to be eligible either individually or as part of the Three Bay, I-House, Multiple Property Submission. Although the house retains its basic form, the fenestration has been significantly altered and the rear addition detracts from the overall integrity of the house. Throughout the study corridor, there are better examples of the three bay I-house form possessing greater integrity.

CRS S-3213
Previously Surveyed
Not Eligible
Plate 86; Appendix A, Plat 22

This previously surveyed, rectangular plan I-house is situated on the north side of Road 244. The house is two stories, three bays wide and one bay deep with additions on the north, south and east facades. The house has no chimney and is covered in blue, composition shingles. There are no historic outbuildings associated with this property.

This late nineteenth century house does not appear to be eligible either individually or as part of the Three Bay, I-House, Multiple Property Submission. The basic form of the building has been altered by a large addition on the east facade and an enclosed entry porch on the front facade. The addition obscures the original east facade. There are better examples of the three bay I-house form throughout the study corridor that possess greater integrity.

CRS S-8439
Not Eligible
Plate 87; Appendix A, Plat 22

This heavily altered dwelling is located south of Road 244, approximately one hundred yards into the woods. It is not visible from the road. The original house is a three bay wide, one bay deep, gable roofed I-house that is obscured by a massive, one story, shed roofed addition. This addition wraps around the entire structure. Modern, one over one, double hung windows are interspersed around the addition. The visible windows in the original house have also been replaced with modern, one over one panes. The entrance to the house is now situated in the north facade of the addition. The entire building is covered in white, aluminum siding.

This late nineteenth century, house is so heavily altered that the original house is lost among the overpowering, wraparound addition. The entire first floor of the I-house is no longer visible. Also, the remaining upper story windows have been replaced with modern, one over one, sashes. Better examples of the three bay I-house form, possessing greater integrity, are present throughout the corridor.

CRS S-8440
Not Eligible
Plate 88; Appendix A, Plat 22

This house sits on the east side of Road 319, just north of the intersection with Road 245. It is two stories, three bays wide and two bays deep with a gable roof and a rear ell. The entrance is centrally placed in the front or west facade. A single, one over one, double hung window with louvered shutters is present on either side of this entry. A gable roofed pediment supported by plain, wooden posts and resting on a raised concrete stoop, projects over the front door. There are three, one over one, double hung windows with louvered shutters in the second story. The gable roof is sheathed in composition shingles and has a boxed cornice with returns.




PLATE 86: CRS S-3213
View of south and west facades of house, looking northeast.
Note enclosed entry on main facade.



PLATE 87: CRS S-8439
View of south and west facades of house, looking northeast.
Note obtrusive addition along all facades.



PLATE 88: CRS S-8440
View of north and west facades of house, looking east.




PLATE 89: CRS S-5151
View of south and east facades of house, looking northwest.
Note heavy alterations to exterior fabric.

The south facade has two windows in the first story and a single window in the western-most bay of the second story. All are one over one and double hung with louvered shutters. The north facade is identical, with the exception of the second story, which has two windows. An interior, end, brick chimney is positioned along this facade.

A two story, two bay wide and one bay deep, gable roofed addition projects from the rear or east facade creating an L-plan dwelling. This addition has an entrance with a gable roofed pediment on the north facade. The windows in this part of the house are all one over one and double hung with louvered shutters. The house sits on a raised, concrete block foundation and is covered in blue composition shingle siding. There are two, modern, gambrel roofed sheds on the property.

This late nineteenth century house does not appear to be eligible either individually or as a part of the Three Bay, I-House, Multiple Property Submission. Colonial Revival touches from the twentieth century, such as louvered shutters and pediments over the doorways detract from the original, simple lines of the I-house. In addition, the lack of historic outbuildings takes away from the historic association and feeling of the property. There are better examples of three bay I-houses with greater integrity throughout the corridor.

CRS S-5151
Previously Surveyed
Not Eligible
Plate 89; Appendix A, Plat 12

This late nineteenth century house is situated on the north side of Road 40. The two story, gable front dwelling is two bays wide and deep with a wraparound enclosed porch on the south and east facades. The west facade has two, two over two, double hung windows on both the first and second floors. A concrete block, exterior chimney placed sits in the center of the facade. Only the second story of the south and east facades is visible due to the enclosed porch on the ground level. There are two, two over two, double hung windows on each facade. The porch has a hipped roof and a continuous band of one over one windows. There is an entrance on both the south and east facades. A shed roofed, enclosed, one story addition is attached on the north facade as well. The entire house is covered in blue aluminum siding and the roof is sheathed in composition shingles.

This house does not appear to be eligible. There are better examples of this type of housing stock throughout the corridor. The application of blue aluminum siding; the replacement of all the windows; the erection of a modern, concrete block chimney and the large, wrap-around porch, all greatly detract from the overall integrity of the structure.

CRS S-5152
Previously Surveyed
Not Eligible
Plate 90; Appendix A, Plat 12

This previously surveyed, one and one-half story, T-plan cabin sits on the north side of Road 40. The house is three bays wide and four bays deep with a gable roof. It is clad in aluminum siding. The entrance is centrally placed in the south facade. A gable roofed, two car garage is located at the rear of the property. The building appears to date to the 1930s or 1940s, and possesses little architectural merit or significance. It does not appear to be eligible.



PLATE 90: CRS S-5152
View of south facade of house, looking north.



PLATE 91: CRS S-5153
View of gambrel roofed house, looking north.

CRS S-5153
Previously Surveyed
Not Eligible
Plate 91; Appendix A, Plat 12

This house was previously surveyed. It is located on the north side of Road 40. It is a two story, gambrel roofed cottage covered in vinyl siding. The gambrel end of the building faces Road 40. This structure appears to date to the early twentieth century and possesses little architectural or historical significance. The application of aluminum siding and the construction of two additions detract from the overall appearance of the house. The building does not appear to be eligible.

CRS S-5154
Previously Surveyed
Eligible: Three Bay, I-House, Multiple Property Submission
Figure 5; Plate 92; Appendix A, Plat 12

This previously surveyed, mid-nineteenth century agricultural complex is located on the south side of Road 40. The house is a two and one-half story I-house. It is three bays wide and two bays deep with a gable roof and a rear, two story addition. There are several frame sheds and a garage located on the property. The house appears to be eligible as part of the Three Bay, I-House, Multiple Property Submission. This property retains its basic form, fenestration, and integrity. It also maintains an agricultural function. Three bay I-houses are significant remnants of the basic vernacular dwelling type found throughout Sussex County. The majority of the houses in this submission, including this one, were part of working agricultural complexes, and are also significant under the priority of Agriculture (Ames et. al. 1989:79, 83).

CRS S-5156
Previously Surveyed
Not Eligible
Plate 93; Appendix A, Plat 12

This mid-nineteenth century agricultural complex was previously surveyed. This property sits on the north side of Road 40 to the of west of the intersection with Road 42. The main house is two stories, three bays wide, and two bays deep with a gable roof and rear additions. A fourth window has been inserted in the first story of the front facade, altering the original, symmetrical, three bay placement. This deviation away from the basic, three bay, I-house form along with the absence of a second interior end chimney and fixed, attic story windows; the insertion of modern windows; and the construction of a modern porch over the front door, detract from the overall appearance of the house. As a result, this property is not eligible as a contributing element in the Three Bay, I-House, Multiple Property Submission.

CRS S-5213
Previously Surveyed
Eligible: Three Bay, I-House, Multiple Property Submission
Figure 5; Plate 94; Appendix A, Plat 12

This previously surveyed farm complex is situated at the intersection of Roads 40 and 42. The dwelling is a two and one-half story I-house, three bays wide and two bays deep with a gable roof and rear, two story addition. There are many outbuildings on the property including several sheds, machinery storage structures, and chicken houses with silos.



PLATE 92: CRS S-5154

View of north and east facades of house, looking southwest.
Note original three bay fenestration, Victorian porch detailing, and narrow attic windows.



PLATE 93: CRS S-5156

View of south and east facades of house, looking northwest.
Note altered primary facade with modern entry porch.




PLATE 94: CRS S-5213
View of north and west facades of house, looking southeast.
Note original windows and three bay fenestration.



PLATE 95: CRS S-5220
View of south and east facades of house, looking northwest.

This property appears to be eligible as a contributing element in the Three Bay, I-House, Multiple Property Submission. The mid-nineteenth century house retains its original form, fenestration, and setting. The property also maintains its agricultural function. Three bay I-houses are significant remnants of the basic vernacular dwelling type found throughout Sussex County. The majority of the houses in this submission, including this one, were part of working agricultural complexes, and are also significant under the priority of Agriculture (Ames et. al. 1989:79, 83).

CRS S-5220
Previously Surveyed
Not Eligible
Plate 95; Appendix A, Plat 12

This two story, Colonial Revival cottage is situated at the northeast corner of the intersection of Roads 42 and 596. The house is three bays wide and two bays deep with a gambrel roof. It has a one story, modern, gable roofed addition on the east facade. A shed roofed, enclosed porch extends across the north facade of the building. A gambrel roofed dormer is present in the center of the facade in the second story. The front door is placed in the easternmost bay of the south facade. Two, single, one over one, double hung windows with louvered shutters occupy the two remaining bays. A gambrel roofed dormer, identical to the one on the north facade, is placed in the second story.

A one story, two bay wide and deep, modern addition with a gable roof has been constructed on the east side of the original house. The north facade contains an entrance into this section. The entire house is clad in white, aluminum siding. The original house rests on a molded, concrete block foundation. Several frame outbuildings on the property include two sheds, a corn crib, and a three bay garage.

A previous survey indicates that this house was built between 1915 and 1930 (M. Mannix 1984). It is unclear if the house was originally constructed in the Colonial Revival style, or if alterations were made at a later date, although the gambrel roof does not appear to be original to the house. Further alterations including an enclosed porch; modern picture windows and louvered shutters; and a large, modern addition detract from the overall appearance of the cottage. Due to a loss of integrity, the house is not eligible.

CRS S-5214
Previously Surveyed
More Work Needed
Plate 96; Appendix A, Plat 15

This mid-nineteenth century farm complex was previously surveyed. This property is located at the southwest corner of Road 40 and Road 638. The house was constructed in two stages with the present rear ell appearing to be the original structure. This portion of the house is three bays wide and two bays deep with a gable roof and two, interior end, corbeled, brick chimneys. A larger, four bay wide, and two bay deep section has been constructed on the north facade facing the intersection. The main entrance is situated in this facade. There are a variety of agricultural outbuildings on the grounds including a barn with a silo, several frame sheds, a carriage house, and a workshop.

It appears that the rear portion of this house may be a late eighteenth or early nineteenth century structure. Further research is necessary to explore the background of this property and the people who may have built the original structure. This complex may be individually eligible, although no final decision can be made at this time without further research.



PLATE 96: CRS S-5214
View of west and south facades of house, looking northwest.
Note three bay rear section with end chimneys.




PLATE 97: CRS S-5218
View of south and east facades of house, looking northwest.
Note original windows along south facade, and end brick chimney at west facade.

CRS S-5218
Previously Surveyed
Individually Eligible
Plate 97; Appendix A, Plat 15

This previously surveyed, one and one-half story, gable roofed cottage sits on the west side of Road 638. The building is four bays deep and three bays wide with a shed roofed, enclosed, front porch and a brick foundation. This structure appears on an 1868 map of the project area, and is labeled as a schoolhouse (Beers 1868, Appendix B). According to a previous survey, the schoolhouse was converted into a dwelling in 1935 when the local schools were consolidated (Mannix 1984). The building type is unique to the project area. Also, the structure is a good example of a rural nineteenth century schoolhouse that has been adapted for use as a private residence. This structure appears to be individually eligible. The building is significant architecturally, but also for its association with the historic context of Education and the temporal period of 1830-1880 (Herman et. al. 1989).

CRS S-5215
Previously Surveyed
Eligible: Three Bay, I-House, Multiple Property Submission
Figure 5; Plate 98; Appendix A, Plat 15

Located on the north side of Road 40, this previously surveyed, mid-nineteenth century I-house is two and one-half stories, three bays wide, and two bays deep. It has a rear, gable roofed, two story addition. Although the house is in fair condition, it does retain its original form, fenestration, and setting. There are a variety of frame outbuildings and chicken coops on the property. The house appears to be eligible as a contributing part of the Three Bay, I-House, Multiple Property Submission. Three bay I-houses are significant remnants of the basic vernacular dwelling type found throughout Sussex County. The majority of the houses in this submission, including this one, were part of working agricultural complexes, and are also significant under the priority of Agriculture (Ames et. al. 1989:79, 83).

CRS S-5216
Previously Surveyed
Individually Eligible
Plate 99; Appendix A, Plat 15

This previously surveyed, mid-nineteenth century, farmhouse is situated on the south side of Road 40. The dwelling is of I-house form, two stories, three bays wide, and two bays deep with a gable roof. The south facade has a one story, attached kitchen wing with an exterior brick chimney. This house, while it does not fit into the Three or Four Bay, I-House, Multiple Property Submission due to the insertion of a doorway on the front facade, does appear to be individually eligible. The house retains most of its original elements including: two over two, double hung windows with carved, wooden frames; a wooden box cornice with carved vergeboards; and the attached summer kitchen. In addition, there are two sheds of vertical board construction on the grounds. The complex is significant under the priority theme of Agriculture (Ames et. al. 1989:79,83).




PLATE 98: CRS S-5215
View of south and east facades of house, looking northwest.
Note original three bay fenestration, end chimneys, and kitchen wing.



PLATE 99: CRS S-5216
View of east facade of house, looking west. Note attached summer kitchen.

CRS S-5217
Previously Surveyed
Not Eligible
Plate 100; Appendix A, Plat 15

This two story, three bay wide, and two bay deep I-house is located on the south side of Road 40. The first story of the front or north facade, facing Road 40, has a one story, shed roofed, enclosed porch. The entrance is centrally placed and is flanked by a pair of one over one, double hung windows. There are three, symmetrically placed, one over one, double hung windows in the second story. The gable roof is sheathed in composition shingles. The east and west facades are identical with two windows in each story. These windows are all one over one and double hung. Both the east and west facades have interior end, corbeled, brick chimneys. A one story, two bay deep addition has been constructed across the entire south facade. The gable roof flares outward over the addition, creating a New England style "salt box" effect. The entire house is clad in tan, aluminum siding. There are no outbuildings associated with this property.

This late nineteenth century house does not appear to be eligible either individually or as part of the Three Bay, I-House, Multiple Property Submission. The basic form of the I-house has been compromised by the "salt box" type addition on the south facade and the enclosed, modern porch on the north facade. There are better examples of three bay I-houses within the project corridor.

CRS S-8441
More Work Needed
Plate 101; Appendix A, Plat 16

This long and narrow, one story structure is positioned on the north side of Road 40. The building is three bays wide and five bays deep with a concrete block foundation and gable roof sheathed in composition shingles. The entrance is centrally located in the north facade facing Road 40. On either side of this entry there is a single, four over four, double hung window. The five windows on the east and west facades are a combination of modern, one over one, double hung sash and Craftsman style, three over one windows. There is an interior, brick chimney located in the west facade toward the rear of the building.

A small, one story, one bay wide section with a gable roof has been added onto the north facade, providing a connection or walkway, to a modern, one car garage at the end of the building. The entire structure is clad in white aluminum siding. There are several outbuildings on the property including a two story, gable roofed barn constructed of vertical board and a detached garage or machinery storage shed.

The original function of this building is unclear. Its narrow, rectangular shape indicates that it was possibly a school, church, or community center. Suggestions have been made that the building may have served as a German prisoner of war barracks during World War II. Without further research, no determination as to eligibility can be made at this time.

CRS S-8442
CCC Camp
Individually Eligible
Plates 102a, 102b, 102c, 102d; Appendix A, Plat 16

This picnic area sits on the south side of Road 40 in the Redden State Forest, on the east bank of Gravelly Branch of the Nanticoke River. The facility is composed of three structures: a pavilion, a shelter, and a latrine. The pavilion, which is the largest structure, is rectangular in plan and constructed of peeled logs. The building is open on three sides. It has a large,



PLATE 100: CRS S-5217
View of north and east facades of house, looking southwest.
Note heavy alterations to exterior fabric.




PLATE 101: CRS S-8441
View of south and west facades of structure, looking northeast.
Note unusual construction and size.



PLATE 102a: CRS S-8442
View of log pavilion. Note wood bracing.



PLATE 102b: CRS S-8442
View of log shelter. Note wood bracing and benches.



PLATE 102c: CRS S-8442
View of public restroom. Note log construction and corner notching.



PLATE 102d: CRS S-8442
View of stone fireplace.