



1. EAST APPROACH



2. NORTH ELEVATION



3. GENERAL VIEW SPAN#1 LOOKING SOUTH



4. UPSTREAM LOOKING NORTH



5. DOWNSTREAM LOOKING SOUTH



6. SPAN#1 EXISTING PERFORATION @
NORTH END



7. SPAN#1 PERFORATION AND KINKING W/
LOSS OF FILL @ SOUTH END



8. MINOR EROSION BETWEEN PIPES 1&2 AT
SOUTH END