



General Elevation looking east.



North Approach, looking north



South Approach, southbound lanes, looking south



Pier 1, looking south.



Pier 2, looking north.



Abutment B, looking north.



Abutment A backwall, looking southeast. Note hairline cracks and previous concrete repair patch.



Pedestal 8, Pier 1, looking north. Note spalled and delaminated concrete with associated fine cracks and exposed reinforcement with moderate delaminations.



Pier 1 underside of cap between Columns 3 and 4, looking south. Note spalled and unsound concrete with exposed reinforcement with minor delaminations.



Pier 1, looking southeast. Note crashwall has spall with exposed rebar on north face adjacent to Column 3.



Pier 1 west fascia, looking south.



Expansion and Fixed Bearing 4 at Pier 1, looking south. Concrete debris is in contact with the expansion and fixed bearing.



Fixed Bearing 1 at Pier 1, Span 2. Note the anchor bolt is not engaged and the washer is completely corroded.



Beam 9 in Span 1 at Pier 1, looking west. Note paint failure, and moderate to severe rust near the bearing.



West fascia overhang in Span 1 at Pier 1, looking east. Note heavy vegetation in joint and spall with exposed reinforcement.



West fascia overhang in Span 3, looking north. Large corner spall with exposed reinforcement.



Approach slab and backwall at Abutment B, looking east.



South approach header on east side, looking east. Note spall with exposed reinforcement.