



1. WEST APPROACH



2. SOUTH ELEVATION



3. GENERAL VIEW LOOKING EAST




4. TIDAL VIEW LOOKING SOUTH




5. TIDAL VIEW LOOKING NORTH



6. NORTH TIMBER ABUTMENT CRUSHED AND ROTATING WESTWARD



7. ACTIVE CORROSION TYP. TO GIRDERS IN SPAN #3



8. ACTIVE CORROSION TYP. TO DIAPHRAGMS IN SPAN #3



9. EROSION/UNDERMINING OF SUBSTRUCTURE AT PIER#2



10. MISSING STRUT AT PIER #2




11. SPLIT STRUT AT PIER#2



12. GENERAL SETTLEMENT AND DETERIORATION
OF SUB STRUCTURE SPAN #2



13. DECAY/ROT IN SOUTHEAST COLUMN OF PIER #2



14. DECAY/ROT OF WOODEN STRUCTURE UNDER
PIER #1