

**Appendix B**

**PLATES**



Plate 1. General view of the project area looking southwest showing Bridge NC-68 after removal of the bridge deck. The turbine house is visible on the right side of the frame. Rockland Road is visible in the background (Photographer: Ian Burrow, April 2005) [HRI Neg # 04091/D4:1].



Plate 2. View of Bridge NC-68 during trackhoe removal of bridge abutment fill looking southwest. The turbine house is visible on the extreme right side of the frame (Photographer: George Cress, May 2005) [HRI Neg # 04091/D3:9].



Plate 3. View looking south showing trackhoe removal of bridge fill along the east side of the former bridge abutment. A small section of the Kirk Mill foundation is visible at the extreme lower left corner of the frame (Photographer: George Cress, May 2005) [HRI Neg # 04091/D5:8].



Plate 4. View looking southeast showing two brick piers or footings and the probable remains of a concrete walkway along the east side of the bridge abutment (Photographer: George D. Cress, May 2005) [HRI Neg #04091/D3:25].



Plate 5. View looking west showing turbine house after removal of bridge abutment fill (Photographer: George D. Cress, May 2005) [HRI Neg #04091/D5:22].