

TABLES

Table 1. Previously Surveyed Pre-1952 Architect

Name (if known)	Address	Survey #	Photo #	Description
	147 Route 15	K-1283	1	Two-story, two-bay, side-gable addition. This addition contains front stoop. Fenestration consists of windows. Sheathed in aluminum.
	Northwest side, Seenytown Road	K-1285		Rectangular, brick, two-story, sheathed in white stucco. Fenestration consists of sash windows. Center hall plan. Property includes an old granary and stable, milkhouse, chicken house, and
	2191 Seenytown Road	K-1286	2	Farmstead. Two-story, three-bay enclosed, hipped front wall and sheltered by gabled side of two-over-two, double hung, Interior end, corbeled brick chimney construction. House: early 20 th
	West side, Route 15	K-1289	3	Two-story, two-bay, wood-frame rear ell and cross gable. Porch around to the south wall. Fenestration consists of sash windows. Gabled dormer
	North side, Route 42, west of Moores Corner	K-1290	4	Two-story, gabled front and west front porch with turned wood post north addition. Fenestration consists of hung, sash windows. House is made of resemble bricks. Deteriorating c. 1880.
Hickory Hill	North side, Route 42, Seven Hickories	K-1292	5-6	House, set back from road is a with raised, shed-roofed front porch consists primarily of two-over-two also includes a garage, bank building
	Intersection of Route 42 and Seenytown Road	K-1293	7	Two-story, two-bay, wood-frame siding. Fenestrated with six-over-six windows. Boxed cornice, arch asphalt shingles. Property also includes milkhouse, and silo. Most or all
	7408 Pearsons Corner Road	K-1298	8	Three-bay, two-story, wood-frame story, gabled rear ell, and enclosed consists primarily of two-over-two in aluminum siding. Early 20 th
	1164 Brenford Road	K-1373	9	Two-story, hipped roof, wood-frame full-width, enclosed, hipped rear ell. Fenestration includes four sash windows. House is sheathed Property also includes several

rural Properties Located within the Study Area

	Integrity	Comments
wood-framed house with shed south porch. Front door sheltered by a wide, gabled stoop. Fenestration includes one-over-one, double hung, sash windows. Sheathed in asphalt siding. c. 1900.	Alterations and additions have compromised architectural integrity.	
Side-gabled roof, three-bay house with rear ell. Fenestration includes two-over-two, double hung, sash windows. Two interior end chimneys. Property also includes a corn crib, stable, pump house, and newer corncrib, machine shed, and stable.	Demolished.	
Side-gabled, wood-framed house with front porch. Present main entry located in north porch. Original fenestration consists primarily of one-over-one, double hung, sash windows. House sheathed in stucco. Includes two interior end chimneys. Several outbuildings, most of recent century.	Property retains architectural integrity.	
Side-gabled house with hipped main roof and gabled porch. Porch extends across the east façade and wraps around the side. Fenestration includes one-over-one, double hung, sash windows. Projects from the east roof slope. c. 1920.	Property retains architectural integrity.	
Side-gabled plan, wood-framed house. Shed-roofed porch. Rear ell with addition and shed-roofed stoop. Fenestration consists primarily of one-over-one, double hung, sash windows. House sheathed in asphalt siding printed to look like wood. Includes outbuildings located north of house. House. c. 1920.	Alterations and additions have compromised architectural integrity.	
Two-story, four bay, wood-framed dwelling with front porch and side shed stoop. Fenestration includes two-over-two, double hung, sash windows. Property includes a corn crib and machine shed.	Property retains architectural integrity.	
Side-gabled house with rear ell sheathed in asphalt siding. Fenestration includes six-over-six and two-over-two, double hung, sash windows. House is sheathed in gray asphalt siding. Includes a corn crib, stable, pump house, and machine shed. All are demolished. House: c. 1870.	Due to alterations, house presently lacks architectural integrity.	
Side-gabled house with central gabled stoop, two-story shed-roofed porch. Fenestration includes two-over-two, double hung, sash windows. Sheathed in asphalt siding. c. 1920.	House retains architectural integrity.	
Side-gabled, American four square residence with front porch, hipped front dormer, and rear porch. Fenestration includes one-over-four and six-over-six, double hung, sash windows. House sheathed in aluminum siding. Constructed c. 1920. Includes outbuildings including greenhouses.	Despite some exterior changes to the house, the property retains architectural integrity.	

Table 1. Continued.

Name (if known)	Address	Survey #	Photo #	Description
	Southwest corner of Lynnbury Woods Road and Salisbury Road	K-1375	10-11	Two-and-one-half story, three-side, flat-roofed enclosed porch of main block consists of six- Pedimented dormers on east roof. wood-framed tenant house and owner, house was constructed
	East side, Johnson Farm Lane	K-1376	12	Five-bay, symmetrical, two-and-a-half story plan house with gabled rear ell. Fenestration consists of mixture of hung, sash windows. Sheathed
	Off southwest side, Salisbury Road	K-1382		Property includes house, several barn, machine sheds, hay barn, outbuildings.
	Northwest side, Brenford Road	K-1385	13-14	Two-story, three-bay, wood-framed center front gable, two-story, gabled porch. Gabled addition off of side consists primarily of two-over-two arch window in front gable peak. Printed to resemble bricks. Porch including sheds and small barn.
	South side, Moorton Road	K-1386	15	Two-story, three-bay, wood-framed turned posts. Fenestration consists of windows. Two corbeled brick chimneys. Sheathed in cement-asbestos siding located across road.
	765 Moorton Road	K-1394	16	Active farmstead. House is a two-story building with central, steeply pitched porch protects central front door. consists of two-over-two, double hung
	South side, Lynnbury Woods Road	K-1400	17-18	Altered, two-story, side-gabled three-bay vestibule. Fenestration consists of windows. House is sheathed in siding. large wood-framed barn with masonry. House: early 20 th century.
	Southeast side, Parsons Corner Road	K-1401		Three-bay, two-story, wood-framed full-width, hipped roof porch. Sheathed with two-over-two, double hung alterations.
M. Bishop House	1609 Route 42	K-1609	19-20	Five-bay, two-story, wood-framed toward street. Bay window on second two-story, shed-roofed rear addition. Sheathed in cement-asbestos siding. hung, sash windows. c. 1840s
	South side, Goldinger Road	K-1613		Two-story, two-bay, wood-framed foundation and walls sheathed in siding. porch. Fenestration consists of hung, sash windows. Exterior chimney at gable end.

	Integrity	Comments
<p>bay house with elaborate door surround and ies. Two-story, gabled rear ell. Fenestration ver-six, double hung, sash windows. of slope. Pyramidal hipped roof, two-story, assorted other outbuildings. According to n the 1870s.</p>	<p>Property, as a well-preserved farmstead, possesses the integrity necessary for National Register-eligibility.</p>	
<p>l-one half story, wood-framed, center hall gabled dormers, and interior end chimneys. e of six-over-six and one-over-one, double in aluminum siding. Early 19th century.</p>	<p>Due to alterations, the house lacks architectural integrity.</p>	
<p>l small weatherboarded outbuildings, small barn, corn cribs, and two corrugated metal</p>		<p>Not viewed. Driveway posted with "No trespassing" signs.</p>
<p>med, side gabled house with steeply pitched abled rear ell and hipped, full-width front outh wall of main block. Fenestration two, double hung, sash windows. Pointed k. House is sheathed in asphalt siding perty also includes agricultural outbuildings s. House c. 1880.</p>	<p>Despite some alterations and additions, the property retains architectural integrity.</p>	
<p>med house with central hipped stoop with ists of two-over-two, double hung, sash chimneys rise from either end of roof ridge. ding. c. 1900. Concrete block outbuildings</p>	<p>Property retains architectural integrity.</p>	
<p>wood-framed, two-story with attic, three bay atched cross gable. Hipped, three-bay front r with sidelights and transom. Fenestration le hung, sash windows. c. 1880.</p>	<p>Farmstead retains architectural integrity.</p>	
<p>, wood-framed house with hipped roof, three sists of one-over-one, double hung, sash aluminum siding. Property also includes ilkhouse and several other outbuildings.</p>	<p>Integrity of house compromised because of additions and alterations.</p>	<p>Farm is owned by Amish family.</p>
<p>med house with interior end chimneys, and heathed in asphalt siding and fenestrated g, sash windows. c. 1880; early 20th century</p>	<p>Demolished.</p>	
<p>med, gabled roof house with gable end facing façade, central gabled front stoop. Large, ition. Side, shed-roofed, screened porch. ding, fenestrated with two-over-two, double [survey form].</p>	<p>House lacks architectural integrity.</p>	
<p>med, rectangular house with concrete block n asbestos siding. Wood-framed front one-over-one, double hung, sash windows.</p>	<p>Demolished.</p>	

Table 1. Continued.

Name (if known)	Address	Survey #	Photo #	Description
	7065-7073 Pearsons Corner Road	K-1624	21	Unusual cross-gable plan house. The gabled front block is tall, with returns. The cross gable door is placed in the cross gable. double hung, sash windows. S
Garrison Farm House	315 Goldinger Road	K-1627	22	Two-story, three bay, wood-frame. story bay window, and modern and six-over-six, double hung asbestos shingles. Late nineteenth
	Northwest side, Lynnbury Woods Road	K-1628		Two-story, three-bay, balloon roof and unpainted weatherboard. hung sash windows.
	5474 DuPont Highway (Route 13)	K-1771	23	One-and-one-half story, wood porch and gabled front and rear one, double hung, sash window block.
	North side, Goldinger Road	K-1772	24-25	One-and-one-half story, basic cross gable and front, shed-roof. Fenestration consists primarily. Porch fenestrated with 18-light. Complex includes a contemporary silos and several sheds. House
	531 Route 42	K-3147	26	Three bay, two-story, hipped wraparound porch, east side s one-over-one, double hung, s 1920.
	497 Route 42	K-3148	27	Gabled front, two-story, two-l porch and shed-roofed rear el double hung, sash windows. S
	477 Route 42	K-3149	28	Two-bay, two-and story, hipped in aluminum siding with hipped off-center on south and east w c. 1920.
	467 Route 42	K-3150	29	One-and-one-half story, wood front dormer and porch recess window topped by added shed-wood posts. Stone block found
	5203 DuPont Highway (Route 13)	K-3151	30	Two-story, wood-framed, gable asphalt. Fenestration consists with horizontal muntins. A garage and contains paired front door wall. Late 19 th century.
	Northeast side, DuPont Highway (Route 13)	K-3152	31	Three-bay, two-and-one-half s hipped roof, wraparound porch over-one, double hung, sash a and sheathed in vinyl siding. c

	Integrity	Comments
<p>with associated agricultural outbuildings. two stories in height with a boxed cornice has a high steeply pitched roof. The front elevation. Fenestration includes one-over-one, sheathed in aluminum siding. c. 1920.</p>	The house lacks integrity due to additions and alterations.	
<p>wood-framed house with recessed entry, side, two-story porch. Fenestration consists of one-over-one sash windows. House is sheathed in cement-block. early 20th century.</p>	Lacks integrity due to alterations.	
<p>wood-framed house with brick foundation, gabled roof. Fenestrated with six-over-six, double hung windows.</p>	Demolished.	
<p>wood-framed bungalow with shed, screened, front porch and dormers. Fenestration consists of one-over-one sash windows. Foundation constructed of cast stone.</p>	Retains architectural integrity.	Recently abandoned.
<p>Irregularly rectangular, side-gabled house with end porch, enclosed, partial-width front porch. Fenestration consists of six-over-six, double hung, sash windows. House is sheathed in vinyl siding. Includes a two-car garage, several barns with associated outbuildings. early 20th century.</p>	House lacks architectural integrity.	
<p>Shed-roof, American foursquare house with six bay front porch and bay window. Fenestrated primarily with double hung windows. Sheathed in vinyl siding. c. 1920.</p>	Despite recent alterations, the house retains architectural integrity.	
<p>Shed-roof, wood-framed house with hipped front porch. Fenestration consists of one-over-one, double hung windows. Sheathed in aluminum siding.</p>	Due to alterations, the house lacks architectural integrity.	
<p>Shed-roof American foursquare house sheathed in aluminum siding. Front dormer fitted with vent. Doors placed on porch. Porch columns are sheltered by corrugated metal hoods.</p>	Due to recent alterations, the house lacks architectural integrity.	
<p>Wood-framed bungalow with new gable roofed porch behind front eaves. West rectangular bay window. Second story bay. Porch has battered columns. 1919 date carved in basement beam.</p>	Due to recent alterations, the house lacks architectural integrity.	
<p>Shed-roof front and wing plan house sheathed in aluminum siding. Fenestration consists of two-over-two, double hung, sash windows. Front porch projects from the building façade. A shed-roofed addition adjoins the south side.</p>	Due to alterations, the house lacks architectural integrity.	
<p>Shed-roof, American foursquare with pyramidal roof and rear shed porch. Fenestrated with one-over-one sash windows and modern, single-light casement windows. c. 1915.</p>	The house appears to retain architectural integrity.	

Table 1. Continued.

Name (if known)	Address	Survey #	Photo #	Description
	4762 DuPont Highway (Route 13)	K-3153	32-33	Rectangular, two-story, three-bay front porch with three-over-one, double hung, sash windows. Sheathed in stucco. Late 19 th century. Shed-roofed, wood-framed porch.
William Williams House (Beers)	4876 DuPont Highway (Route 13)	K-3154	34	Rectangular, two-story, three-bay front porch with aluminum siding. Fenestration includes double hung windows. A full-width, hip-roofed rear ell. Gabled rear ell. Early 20 th century. Includes agricultural outbuildings.
Sweet Memories Antiques	Northeast side, DuPont Highway (Route 13)	K-3155	35-36	One-and-one-half story, gambrel-roofed front porch and hip-roofed rear ell. Three-over-six, double hung, sash windows. Sheathed in cement-asbestos siding.
	Southwest side, Messina Hill Road	K-3163	37	Three-bay, two-story, gabled front porch with cement siding. Flat-roofed porch. Gabled rear ell with corner porches. Walls sheathed in cement-asbestos siding. Windows. c. 1900.
	South side, Lynnbury Woods Road, east of Messina Hill Road	K-3164		Two-story, three bay, side-gabled front porch, gabled rear ell, and central, end-gabled rear ell. Includes one-over-one, double hung windows.
	3915 Route 42	K-3169	38	One-and-one-half story, five-bay front porch with gabled front and rear dormers. Flat-roofed front porch. Exterior walls with brick chimneys. Chimney projects from east side.
C. Brown House	Northeast, Kenton Road	K-3171		Three bay, two-story and attic. Sheathed in asbestos-cement siding. Double hung, sash windows. A portion of the facade.
Jonathan Moore House (Beers)	4977 Kenton Road	K-3172	39	Two-story, wood-framed house with front door surmounted by three-light transoms. Flat roof, brick foundation and square chimney. Fenestration of two-over-two, double hung windows. Sheathed in weatherboard and interior brick chimneys with c-gabled rear ell.
	4693 Kenton Road	K-3173	40	Two-bay, two-story, wood-framed front porch and two-story, gambrel-roofed addition off back wall of house. Fenestration of two-over-two and one-over-one windows. Aluminum siding. Early 20 th century.
	Southeast side, Route 42, opposite 4201	K-6312	41	Gabled front, wood-framed, one-and-one-half story. Flat roof front porch. Main entry includes one-over-one and two-over-two windows. Sheathed in wood shingles, central brick chimney. 1920s.

	Integrity	Comments
bay, wood-framed house with hipped roof, wrought iron posts. Fenestration consists of one-over-one, double hung, sash windows. Gabled rear ell and rear addition. Property also includes a gabled and shed-roofed produce shed.	Due to alterations, the house lacks architectural integrity.	
bay, wood-framed house sheathed in aluminum siding. Fenestration consists of one-over-one, double hung, sash windows. Front porch projects from the front elevation. Property also includes several outbuildings.	The property retains architectural integrity.	
shed-roofed, wood-framed house with shed-roofed porch. Fenestration includes six-over-six windows. Shed front and rear dormers. Siding c. 1925.	The house retains architectural integrity.	
shed-roofed, T-plan house sheathed in white asbestos siding. Front porch serves as front door hood. Two-story, front porch. Roof sheathed in composition shingles, asbestos siding. One-over-one, double hung, sash windows.	The integrity of the property has been compromised due to abandonment and deterioration.	Endangered. Abandoned. Housing development under construction in immediate vicinity.
shed-roofed, wood-framed house with two-story, front porch, gabled roof stoop. Fenestration includes one-over-one, double hung, sash windows.	Demolished.	
bay, wood-framed house bungalow with front porch and single story, wood-framed rear ell. Shed-roofed porch. Siding sheathed in aluminum siding. Tall brick chimney. Siding c. 1925.	The house retains architectural integrity.	
cross-gabled, wood-framed house is sheathed in aluminum siding and is fenestrated with two-over-two, double hung, sash windows. Gabled front porch projects from the center.	Demolished.	
house with symmetrical five-bay façade. Central front porch with transom. Three bay façade porch with flat roof, paneled columns. Fenestration consists of one-over-one, double hung, sash windows flanked by shutters. House is sheathed in asphalt shingles. Two dormer windows project from the roof. Two story front porch.	The property retains architectural integrity.	
shed-roofed, gabled roof house with shed-roofed porch and rear ell. Hipped porch off rear ell, and front porch. Fenestration consists of modern one-over-one, double hung, sash windows. Sheathed in aluminum siding.	The house lacks integrity due to additions and alterations.	
one-and-one-half story cottage with hipped roof and front porch. Fenestration includes one-over-one, double hung, sash windows. Sheathed in aluminum siding. Associated gabled front garage. c. 1925.	The house retains architectural integrity.	

Table 1. Continued.

Name (if known)	Address	Survey #	Photo #	Description
	3807 Route 42	K-6374	42-43	One-and-one-half story, wood-screened porch. Large gabled of one-over-one, double hung, c. 1920s.
	Southeast side, Route 42	K-6375	44	L-shaped, one-story, wood-frame foundation and sheathed in asphalt. Fenestration consists of one-over-one, double hung, c. 1930.
	3735 Route 42	K-6376	45	Two story, hipped roof, wood-wing. House is presently vacant. porch removed. Fenestration consists of one-over-one, double hung windows. Hipped front dormer. Fenestration consists of one-over-four, double hung, sash windows. c. 20 th century.
	4984 Kenton Road	K-6377	46	Main portion is two-story, two-bay porch with turned posts. Two-bay porch. Fenestration consists primarily of one-over-one, double hung, sash windows. Sheathed in asphalt. alterations.
	4526 Kenton Road	K-6380	47	Two-story, wood-framed, side-front gable, enclosed, hipped roof. Fenestration consists largely of one-over-one, double hung windows. Four-light lancet window in front porch. Late 19 th century, late 20 th century.
Cheswold	Route 42, Commerce Street, Salisbury Road and New Street	K-6709	48-55	Nineteenth and twentieth century wood-framed. Houses are typically two bays wide with side gables and side porches. Includes a Victorian house and bungalow, a vernacular church and a c. 190-

	Integrity	Comments
framed bungalow. Shed-roofed full-width front dormer. Fenestration consists primarily of sash windows. Sheathed in asphalt shingles.	The house retains architectural integrity.	
shed, gabled roof house set on a concrete slab. Asphalt siding printed to resemble bricks. One-over-one, double hung, sash windows. c.	Although deteriorating, the house retains architectural integrity.	
framed house with two story, gabled east front and may be undergoing renovation. Front fenestration consists of one-over-one, double hung, sash windows; originally fenestrated with paired four-over-four windows. Sheathed in asphalt shingles. Early 20th century.	The house lacks integrity due to alterations.	
day, gabled front block with wraparound porch, shed-roofed, side addition. Fenestration consists of two-over-two and two-over-six, double hung windows. Sheathed in vinyl siding. c. 1900; late 20th century.	The house lacks integrity due to additions and alterations.	
gabled house with steeply pitched center front porch, and shed-roofed rear ell. Fenestration consists of one-over-one, double hung, sash window. Sheathed in vinyl siding. Early 20th century alterations.	Lacks integrity due to alterations.	
typical railroad village. Most buildings are typically two-stories in height and two or three front porches. Lesser numbers of vernacular buildings. Village also includes a Victorian store, now a pizza parlor.	Although individual buildings have been altered by modern siding materials and other changes, the village as a whole retains architectural integrity.	

Table 1 Photographic Captions

- Photo 1. House, 147 Route 15 (K-1283). Northeast façade toward southwest.
- Photo 2. House, 2191 Seenytown Road (K-1286). Northwest façade toward southeast.
- Photo 3. House, northwest side, Brenford Road (K-1289). Southeast façade and southwest elevation toward northwest.
- Photo 4. House, north side of Route 42, west of Moores Corner (K-1290). East façade and south elevation toward northwest.
- Photo 5. Farmhouse, Hickory Hill (K-1292). Southwest façade toward northeast.
- Photo 6. Barn, Hickory Hill (K-1292). Southwest and southeast elevations toward northeast.
- Photo 7. House, intersection of Seenytown Road and Route 42 (K-1293). Northwest and southwest elevations toward southeast.
- Photo 8. House, 7408 Pearsons Corner Road (K-1298). Northwest façade and southwest elevation toward southeast.
- Photo 9. House, 1164 Brenford Road (K-1373). Northwest façade and southwest elevation toward northeast.
- Photo 10. House located on farm at southwest corner of Lynnbury Woods Road and Salisbury Road (K-1375). Northeast façade and southeast elevation toward west.
- Photo 11. Secondary house and outbuildings, farm, corner of Lynnbury Woods Road and Salisbury Road (K-1375). General view toward south.
- Photo 12. House, east side, Johnson Farm Lane (K-1376). Northwest façade and northeast elevation toward southeast.
- Photo 13. House, northwest side, Brenford Road (K-1385). Southeast façade and southwest elevation toward north.
- Photo 14. Outbuildings behind Brenford Road house (K-1385). General view toward northwest.
- Photo 15. House, south side, Moorton Road (K-1386). North façade and east elevation toward south.
- Photo 16. House, 765 Moorton Road (K-1394). South façade toward north.
- Photo 17. House, south side, Lynnbury Woods Road (K-1400). West and north elevations toward southeast.

- Photo 18. Barn, south side, Lynnbury Woods Road (K-1400). North and west elevations toward southeast.
- Photo 19. House, 691 Route 42 (K-1609). Southeast façade toward northwest.
- Photo 20. House, 691 Route 42 (K-1609). Southeast façade and northeast elevation toward northwest.
- Photo 21. House, 7065-7073 Pearsons Corner Road (K-1624). Southeast elevation toward northwest.
- Photo 22. House, 315 Goldinger Road (K-1627). Northeast façade and southeast elevation toward northwest.
- Photo 23. House, 5474 DuPont Highway (K-1771). Southwest façade and northwest elevation toward east.
- Photo 24. House, north side, Goldinger Road (K-1772). Southeast façade and southwest elevation toward north.
- Photo 25. Barns, northwest side, Goldinger Road (K-1772). General view toward northeast.
- Photo 26. House, 531 Route 42 (K-3147). Southeast façade and northeast elevation toward northwest.
- Photo 27. House, 497 Route 42 (K-3148). Southeast façade and northeast elevation toward northwest.
- Photo 28. House, 477 Route 42 (K-3149). Southeast façade and northeast elevation toward northwest.
- Photo 29. House, 467 Route 42 (K-3150). Southeast façade toward northwest.
- Photo 30. House, 5203 DuPont Highway (K-3151). Northeast façade toward southwest.
- Photo 31. House, northeast side of DuPont Highway (K-3152). Southwest façade and southeast elevation toward northeast.
- Photo 32. House, 4762 DuPont Highway (K-3153). Southwest façade and southeast elevation toward northeast.
- Photo 33. Produce stand, 4762 DuPont Highway (K-3153). Southwest and southeast elevations toward northeast.
- Photo 34. House, 4876 DuPont Highway (K-3154). Southwest façade and southeast elevation toward northeast.
- Photo 35. Sweet Memories Antiques, northeast side, DuPont Highway (K-3155). Southwest façade and southeast elevation toward northeast.

- Photo 36. Sweet Memories Antiques, east side, DuPont Highway (K-3155). Southwest façade and northwest elevation toward southeast.
- Photo 37. House, southwest side Messina Hill Road near Lynnbury Woods Road (K-3163). Northeast façade and northwest elevation toward southwest.
- Photo 38. House, 3915 Route 42 (K-3169). Southeast façade and southwest elevation toward north.
- Photo 39. House, 4977 Kenton Road (K-3172). Northeast façade and southeast elevation toward west.
- Photo 40. House, 4693 Kenton Road (K-3173). Northeast façade and southeast elevation toward northwest.
- Photo 41. House, southeast side of Route 42 (K-6312). Northwest façade and southwest elevation toward southeast.
- Photo 42. House, 3807 Route 42 (K-6374). Northeast and southeast elevations toward west.
- Photo 43. House, 3807 Route 42 (K-6374). Southeast and southwest elevations toward northeast.
- Photo 44. House, southeast side. Route 42 (K-6375). Northwest and southwest elevations toward southeast.
- Photo 45. House, 3735 Route 42 (K-6376). Southeast façade and northeast elevation toward northwest.
- Photo 46. House, 4984 Kenton Road (K-6377). Southeast façade and southwest elevation toward northeast.
- Photo 47. House, 4526 Kenton Road (K-6380). Southwest façade and northwest elevation toward southeast.
- Photo 48. Kings Pizza, west side of Commerce Street, Cheswold (K-6709). Northeast façade and southeast elevation toward northwest.
- Photo 49. View of northwest side of Route 42, west of the firehouse, Cheswold (K-6709). Toward west.
- Photo 50. View of southeast side of Route 42, east of the post office, Cheswold (K-6709). Toward southeast.
- Photo 51. View of southeast side of Route 42, Cheswold (K-6709). Toward southeast.
- Photo 52. View of southeast portion of Cheswold (K-6709) on Salisbury Road/Commerce Street. Toward northwest.

- Photo 53. New Street streetscape, Cheswold (K-6709). Toward southwest.
- Photo 54. General view of southeast side of New Street, Cheswold (K-6709), toward southwest.
- Photo 55. Cheswold United Methodist Church. Northwest side, Route 42. Southeast and northeast elevations toward northwest.



Photo 1. House, 147 Route 15 (K-1283). Northeast façade toward southwest.




Photo 2. House, 2191 Seentown Road (K-1286). Northwest façade toward southeast.



Photo 3. House, northwest side, Brenford Road (K-1289). Southeast façade and southwest elevation toward northwest.



Photo 4. House, north side of Route 42, west of Moores Corner (K-1290). East façade and south elevation toward northwest.




Photo 5. Farmhouse, Hickory Hill (K-1292). Southwest façade toward northeast.



Photo 6. Barn, Hickory Hill (K-1292). Southwest and southeast elevations toward northeast.



Photo 7. House, intersection of Seenytown Road and Route 42 (K-1293) Northwest and southwest elevations toward southeast.



Photo 8. House, 7408 Pearsons Corner Road (K-1298). Northwest façade and southwest elevation toward southeast.



Photo 9. House, 1164 Brenford Road (K-1373). Northwest façade and southwest elevation toward northeast.



Photo 10. House located on farm at southwest corner of Lynnbury Woods Road and Salisbury Road (K-1375). Northeast façade and southeast elevation toward west.



Photo 11. Secondary house and outbuildings, farm, corner of Lynnbury Woods Road and Salisbury Road (K-1375). General view toward south.




Photo 12. House, east side, Johnson Farm Lane (K-1376). Northwest façade and northeast elevation toward southeast.




Photo 13. House, northwest side, Erenford Road (K-1385). Southeast façade and southwest elevation toward north.



Photo 14. Outbuildings behind Brenford Road house (K-1385). General view toward northwest.



Photo 15. House, south side, Moor on Road (K-1386). North façade and east elevation toward south.



Photo 16. House, 765 Moorton Road (K-1394). South façade toward north.



Photo 17. House, south side, Lynnbury Woods Road (K-1400). West and north elevations toward southeast.



Photo 18. Barn, south side, Lynnbury Woods Road (K-1400). North and west elevations toward southeast.



Photo 19. House, 691 Route 42 (K-1609). Southeast façade toward northwest.



Photo 20. House, 691 Route 42 (K-1609). Southeast façade and northeast elevation toward northwest.




Photo 21. House, 7065-7073 Pearsons Corner Road (K-1624). Southeast elevation toward northwest.



Photo 22. House, 315 Goldinger Road (K-1627). Northeast façade and southeast elevation toward northwest.



Photo 23. House, 5474 DuPont Highway (K-1771). Southwest façade and northwest elevation toward east.




Photo 24. House, north side, Goldinger Road (K-1772). Southeast façade and southwest elevation toward north.




Photo 25. Barns, northwest side, Goldinger Road (K-1772). General view toward northeast.



Photo 26. House, 531 Route 42 (K-3147). Southeast façade and northeast elevation toward northwest.



Photo 27. House, 497 Route 42 (K-3148). Southeast façade and northeast elevation toward northwest.



Photo 28. House, 477 Route 42 (K-3149). Southeast façade and northeast elevation toward northwest.



Photo 29. House, 467 Route 42 (K-3150). Southeast façade toward northwest.



Photo 30. House, 5203 DuPont Highway (K-3151). Northeast façade toward southwest.




Photo 31. House, northeast side of DuPont Highway (K-3152). Southwest façade and southeast elevation toward northeast.



Photo 32. House, 4762 DuPont Highway (K-3153). Southwest façade and southeast elevation toward northeast.



Photo 33 Produce stand, 4762 Du Pont Highway (K-3153). Southwest and southeast elevations toward northeast.



Photo 34 House, 4876 DuPont Highway (K-3154). Southwest façade and southeast elevation toward northeast.



Photo 35 Sweet Memories Antiques, northeast side, DuPont Highway (K-3155). Southwest façade and southeast elevation toward northeast.



Photo 36. Sweet Memories Antiques, east side, DuPont Highway (K-3155). Southwest façade and northwest elevation toward southeast.



Photo 37 House, southwest side Messina Hill Road near Lynnbury Woods Road (K-3163).
Northeast façade and northwest elevation toward southwest.



Photo 38. House, 3915 Route 42 (K-3169). Southeast façade and southwest elevation toward north.



Photo 39. House, 4977 Kenton Road (K-3172). Northeast façade and southeast elevation toward west.



Photo 40. House, 4693 Kenton Road (K-3173). Northeast façade and southeast elevation toward northwest.



Photo 41. House, southeast side of Route 42 (K-6312). Northwest façade and southwest elevation toward southeast.



Photo 42. House, 3807 Route 42 (K-6374). Northeast and southeast elevations toward west.



Photo 43. House, 3807 Route 42 (K-6374). Southeast and southwest elevations toward northeast.




Photo 44. House, southeast side. Route 42 (K-6375). Northwest and southwest elevations toward southeast.




Photo 45. House, 3735 Route 42 (K-6376). Southeast façade and northeast elevation toward northwest.




Photo 46. House, 4984 Kenton Road (K-6377). Southeast façade and southwest elevation toward northeast.




Photo 47. House, 4526 Kenton Road (K-6380). Southwest façade and northwest elevation toward southeast.



Photo 48. Kings Pizza, west side of Commerce Street, Cheswold (K-6709). Northeast façade and southeast elevation toward northwest.



Photo 49. View of northwest side of Route 42, west of the firehouse, Cheswold (K-6709).
Toward west.



Photo 50. View of southeast side of Route 42, east of the post office, Cheswold (K-6709).
Toward southeast.



Photo 51. View of southeast side of Route 42, Cheswold (K-6709). Toward southeast.



Photo 52. View of southeast portion of Cheswold (K-6709) on Salisbury Road/Commerce Street. Toward northwest.



Photo 53. New Street streetscape, Cheswold (K-6709). Toward southwest.



Photo 54. General view of southeast side of New Street, Cheswold (K-6709), toward southwest.



Photo 55. Cheswold United Methodist Church. Northwest side, Route 42. Southeast and northeast elevations toward northwest.