



1. SOUTH APPROACH



2. WEST ELEVATION




3. GENERAL VIEW FACING EAST



4. UPSTREAM WEST



5. DOWNSTREAM EAST



6. WEARING SURFACE VIEW FACING NORTHWEST



7. BANK EROSION BEHIND SOUTHEAST CURB LINE



8. ADVANCED CORROSION ALONG WATERLINE TYPICAL, EASILY PERFORATED w/ PICK HAMMER