Evaluation of High Crash Locations Dark Criteria Study Location 4

Improvement Recommendations Matrix - US 9, MP 8.9-10.39

Updated: 12/20/2018

Site		Recommended Improvement	Status
		Trim tree branches covering the guide sign on the southbound Old Furnace Road approach at the intersection.	Request sent to South District Maintenance on 7/18/13 9/24/2013 - COMPLETE
US 9 @ Old Furnace Rd / Whaley's Corner Rd Intersection (MP 9.75)			
	2	Restripe a stop bar and lane markings on the southbound Furnace Road	9/20/2013 - Handed off to pavement markings - Maximo 581202
		approach at the intersection.	10/16/2013 - COMPLETE
	3	Patch the pavement breach on the edge of the eastbound US Route 9	Request sent to South District Maintenance on 7/18/13
		approach to the intersection.	