

**Evaluation of High Crash Locations
Dark Criteria Study
Location 6**

Improvement Recommendations Matrix - Old Baltimore Pike, MP 2.1-4.29

Site	Recommended Improvement	Status
Old Baltimore Pike @ College Dr Intersection (MP 2.45)	1 Repost leaning Yield sign on southbound approach.	Complete
	2 Photometric calculations are recommended to determine if the existing lighting meets DeIDOT's standard lighting levels.	9/20/2013 - Handed off to Traffic Design. Awaiting prioritization within Intersection Improvements Program
Old Baltimore Pike @ SR 72 Intersection (MP 3.3)	3 Evaluate for complex intersection lighting as per Section 4.3.2 of the DeIDOT Lighting Design Guidelines. At a minimum, additional luminaires on the northeast, northwest and southwest corners of the intersection would improve lighting levels. Also, the lighting levels may benefit from increasing the wattage of the existing 250 Watts to 400 Watts.	Included in scope of Contract T201200108