1. NORTH APPROACH CULDASAC LOOKING SOUTH

2. WEST ELEVATION LOOKING NORTHEAST

3. GENERAL VIEW OF SOUTH CELL LOOKING EAST



4. UPSTREAM LOOKING WEST

5. DOWNSTREAM LOOKING EAST

6. ASPHALT OVERLAY WEARING SURFACE LOOKING WEST

7. SPAN 1, UPHEAVED/ BENT PIPE AT WEST END

8. SPAN 1, EXISTING HOLE AT WEST END

9. SPAN 1, SEVERE CORROSION AND LOSS OF FILL AT WEST END

10. SPAN 1, DISTORTION OF EAST HALF LOOKING EAST

11. SPAN 1, EASILY PERFORATED W/ HAMMER & LARGE CORROSION FLAKES NEAR CENTER OF RD