

**Evaluation of High Crash Locations  
Dark Criteria Study  
Location 4**

**Improvement Recommendations Matrix - US 9, MP 8.9-10.39**

<b>Site</b>	<b>Recommended Improvement</b>	<b>Status</b>
US 9 @ Old Furnace Rd / Whaley's Corner Rd Intersection (MP 9.75)	1 Trim tree branches covering the guide sign on the southbound Old Furnace Road approach at the intersection.	<b>Request sent to South District Maintenance on 7/18/13</b>
	2 Restripe a stop bar and lane markings on the southbound Furnace Road approach at the intersection.	<b>9/20/2013 - Handed off to pavement markings - Maximo 581202</b>
	3 Patch the pavement breach on the edge of the eastbound US Route 9 approach to the intersection.	<b>Request sent to South District Maintenance on 7/18/13</b>