


**APPENDIX A**

**CRS FORMS**

**FOR PREVIOUSLY SURVEYED RESOURCES**

CULTURAL RESOURCE SURVEY  
STRUCTURAL DATA FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



Form CRS-1  
FOR OFFICE USE ONLY

CRS # N-5065  
Quad ST. GEORGES  
SPO map # 06-07-32  
Hundred NEW CASTLE  
DOCUMENT 20-06/78/08/14

(7)

1. ADDRESS OF STRUCTURE : Church St. Bear.

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

a) Overall shape L  
stories  
bays 3  
wings 1



b) Structural system

c) Foundation  
materials ROCK  
basement

d) Exterior walls SHINGLE  
materials  
color(s) WHITE


e) Roof composition shingles, GABLE  
shape; materials  
cornice BOXED  
dormers  
chimney location(s)

f) Windows  
spacing  
type 1/1, double 1's, 2/2, 2x3  
trim WOODEN 4 panel  
shutters

g) Door  
spacing front door - wood w/ 1 diamond shaped glass pane  
type WOODEN 4 panel back door.  
trim

h) Porches SHED ROOF FRONT PORCH w/ 4 round green + WHITE  
location(s) COLUMNS w/ brackets.  
materials WOODEN SHED ROOF back wing w/ composition  
supports SHINGLES over corrugated metal roof.  
trim

i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION: good  deteriorated

remarks: \_\_\_\_\_

4. INTEGRITY: a) original site  b) moved

c) if moved, when and from where \_\_\_\_\_

d) list major alterations and dates (if known) \_\_\_\_\_

5. DATE OF INITIAL CONSTRUCTION: (at least 100 years ago)

6. ARCHITECT/BUILDER: \_\_\_\_\_

7. RELATED OUTBUILDINGS:

a) barn  b) carriage house  c) garage  d) privy

e) shed  f) greenhouse  g) shop  h) gardens

i) icehouse  j) springhouse  k) other

describe: Red wood Barn w/ gable roof w/ corrugated metal roof + exposed rafters.

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

9. Primary References: (include location of reference).

Mrs Bolyard - resident + owner


10. Surveyor: John Evans Date of Form: 1/25/79

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY  
LOCUS IDENTIFICATION FORM

FORM CRS-3

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 736 - 5685



FOR OFFICE USE ONLY


CRS # N-5065  
Quad ST. GEO  
SPO map # 06-07-32  
Hundred NEWCASTLE  
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: Ag Cx
2. STREET LOCATION: Church St Rd. ~~114~~ 382
3. OWNER'S NAME: HAROLD A. Bolyard TEL. # 834-1954  
ADDRESS: BEAR, DE 19701
4. TYPE OF LOCUS: a) structure  b) district  c) archaeological site   
d) other
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)  
a) fallow field  b) cultivated field  c) woodland   
d) scattered buildings  e) densely built up  f) other
6. THREATS TO LOCUS: (check more than one if necessary)  
a) none known  b) zoning  c) roads  d) developers   
e) deterioration  f) other
7. REPRESENTATION ON OTHER SURVEYS:  
TITLE: \_\_\_\_\_ # \_\_\_\_\_  
TITLE: \_\_\_\_\_ # \_\_\_\_\_  
TITLE: \_\_\_\_\_ # \_\_\_\_\_
8. YOUR NAME: S. MARVEL TEL. # \_\_\_\_\_  
YOUR ADDRESS: 33 Newark Dr. Apt 7 Newark De  
ORGANIZATION (if any) NCC Planning Dept. DATE: 1-25-79

USE BLACK INK ONLY

SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

10. Comprehensive Planning:
- a. Time Period(s) 1880 - 1940
  - b. Cultural Concept LANDSCAPE

11. Evaluation:
- a. Settlement & Development
  - b. Cultural Historic & Ethnic Issues
  - c. Built Environment
  - d. Material Culture
  - e. not eligible

INSUFFICIENT DATA

PS J...  
6/88

CULTURAL RESOURCE SURVEY  
LOCUS IDENTIFICATION FORM

D. AWARE HISTORIC  
PRESERVATION OFFICE  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



Form CRS-3

FOR OFFICE USE ONLY

CRS no. N-498  
Quad \_\_\_\_\_  
SPO map no. 08-09-32  
Hundred NEW CASTLE

YOUR NAME: LIZA GOUVERNEUR TELE: 322-4103

YOUR ADDRESS: HALL OF RECORDS

ORGANIZATION (if any): BUREAU OF HISTORIC PRES. DATE: 6/6/77

\*\*\*\*\*

1. TYPE OF LOCUS: a. structure  c. archaeological site \_\_\_\_\_  
b. district \_\_\_\_\_ d. other \_\_\_\_\_

2. NAME OF LOCUS: RED LION UNITED METHODIST CHURCH

3. STREET LOCATION: RED LION DE. COUNTY RD 382 + RT. 301

4. OWNER'S NAME: \_\_\_\_\_ TELE: \_\_\_\_\_

ADDRESS: \_\_\_\_\_

5. THREATS TO LOCUS: (check more than one if necessary)  
a. none known  d. developers \_\_\_\_\_  
b. zoning \_\_\_\_\_ e. deterioration \_\_\_\_\_  
c. roads \_\_\_\_\_ f. other \_\_\_\_\_

6. SURROUNDINGS OF LOCUS: (check more than one if necessary)  
a. fallow field \_\_\_\_\_ d. scattered buildings \_\_\_\_\_  
b. cultivated field \_\_\_\_\_ e. densely built up   
c. woodland \_\_\_\_\_ f. other \_\_\_\_\_

7. REPRESENTATION ON OTHER SURVEYS:  
TITLE: \_\_\_\_\_ NO. \_\_\_\_\_  
TITLE: \_\_\_\_\_ NO. \_\_\_\_\_  
TITLE: \_\_\_\_\_ NO. \_\_\_\_\_

8. USE REVERSE FOR SKETCH MAP AND COMMENTS.  
*Please indicate position of locus in relation to  
geographical landmarks such as streams and roads.*

CULTURAL RESOURCE SURVEY  
STRUCTURAL DATA FORM

BUREAU OF ARCHAEOLOGY AND  
HISTORIC PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



Form CRS-1

FOR OFFICE USE ONLY

CRS no. N-498  
Quad  
SPO map no. 08-09-32  
Hundred New Castle

1. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a. dimensions  
stories three  
bays three - front - 4 on sides.  
wings back wing - new addition
- b. foundation  
basement
- c. structural system
- d. walls - exterior  
materials brick - stained glass windows 2nd + 3rd stories
- e. walls - interior  
color (original)  
panelling  
trim
- f. roof  
shape excellent - gable  
materials  
dormers
- g. openings  
windows  
doors
- h. porches

2. CONDITION: a. excellent X d. deteriorated \_\_\_\_  
b. fair \_\_\_\_ e. demolished \_\_\_\_  
c. good \_\_\_\_ f. site destroyed \_\_\_\_

3. INTEGRITY: a. original site X b. moved \_\_\_\_  
c. if moved, when and from where \_\_\_\_\_

d. list major alterations and dates (if known) \_\_\_\_\_  
see file

4. RELATED OUTBUILDINGS AND PROPERTY (mark "X" if existing, "0" if demolished)

- |                         |                             |
|-------------------------|-----------------------------|
| a. barn _____           | h. gardens _____            |
| b. carriage house _____ | f. landscape features _____ |
| c. garage _____         | _____                       |
| d. privy _____          | j. other _____              |
| e. shed _____           | _____                       |
| f. greenhouse _____     | _____                       |
| g. shop _____           | _____                       |

5. DATE OF INITIAL CONSTRUCTION: 1853

6. ARCHITECT: \_\_\_\_\_

7. BUILDER: \_\_\_\_\_

8. BRIEFLY DESCRIBE THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE INCLUDING SIGNIFICANT ASSOCIATIONS:

*Church*

9. PRIMARY REFERENCES:

10. ADDRESS OF STRUCTURE: County Road 382 + Rt. 301 ~~Glasgow~~ Red Lion

11. DATE OF FORM: 6/6/77 SURVEYOR: Jan Aiken

INVESTIGATION CARD  
HISTORIC PRESERVATION PROGRAM  
DIVISION OF HISTORICAL AND  
CULTURAL AFFAIRS

(LEBANON CHURCH)

GRID NUMBER:

N-498

SUBJECT: Red Lion United Methodist Church  
No. 105


ADDRESS: Red Lion, Delaware

OWNER:

TENANT:

INVESTIGATOR: A. Copley      DATE: 7/7/72

REMARKS: Church was founded in 1819. The  
present building was built in 1853.



## HISTORY OF RED LION UNITED METHODIST CHURCH

1800-1818 - Methodists from Delaware, Maryland, New Jersey, and Pennsylvania would gather once a year in the camp meeting woods at RED LION, Delaware. Great spiritual revivals were held here with hundreds of people and as many as seventy ministers taking part. THIS WAS THE BEGINNING OF METHODISM IN RED LION.

1819-1852 - The Methodists of the Red Lion area wanted their own church so that they could have services every Sunday. In 1819, the first Red Lion Methodist Church was built. It was a plain wooden structure, but served as the worship center for the people of this community for thirty-four years. THIS WAS METHODISM ESTABLISHED IN RED LION.

1853-1959 - The present church structure was built in 1853. Our forefathers built well for it is still strong and solid after one hundred and five years of service. This building was thoroughly repaired in 1886, it was damaged by fire in 1944, and was repaired in 1945.

1958 - A number of renovating projects were completed; including among these the installing of a complete new lighting system, repointing of all the brick work, and the building of a parking lot behind the church.

1959 - The people of Red Lion Church launched into a much needed building program which included a New Educational Unit providing 14 classrooms, four restrooms, and a 32 ft. addition to the old sanctuary at a cost of \$72,000.

1962 - Improved parking facilities by black topping a large section of the parking lot at a cost of \$5,000.

1964 - Began our Radio Ministry broadcasting live the Sunday Morning Worship Service for one hour over WNRK. We have been on the air now almost five years and we have an estimated listening audience each Sunday of over two thousand (2,000) people. God has richly blessed this outreach. The cost of each Sunday's broadcast is \$52.00.

1965 - Renovated downstairs room making a lovely Church office.

1966 - Purchased additional land for needed parking facilities and black topped it to give us a parking area to accommodate 150 more cars. Centrally air conditioned the Sanctuary and downstairs rooms. Opened and renovated the balcony to increase our seating capacity by 45 seats. Cost of this was \$18,500.

1967 - Purchased a new organ at a cost of \$8,000.

1968 - Renovated downstairs Sunday School area making three additional rooms plus a work room. Also, a very lovely Chapel for Prayer Meetings, Bible Study, and Youth Meetings, etc. was established. The cost was \$1,000.

1969 - Purchased house lot next to Community House (about 1 1/2 acres) for Sunday School expansion and parking expansion at a cost of \$12,000. Renovated the Sanctuary with new carpet and new pews at a cost of \$10,000. Purchased a new parsonage with two acres of ground. Cost \$37,000.

### 1819 - ONE HUNDRED FIFTY (150) YEARS OLD - 1969

Untold numbers brought into a saving knowledge of Jesus Christ.

Untold numbers have found a deeper meaning to their faith, a closer walk with God, and a personal living relationship with Jesus Christ our Lord.

To GOD Be The Glory Great Things HE Hath Done!

---

CULTURAL RESOURCE SURVEY  
LOCUS IDENTIFICATION FORM

DELAWARE HISTORIC  
PRESERVATION OFFICE  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



Form CRS-3

FOR OFFICE USE ONLY

CRS no. N-1237  
Quad \_\_\_\_\_  
SPO map no. 08-09-32  
Hundred NEW CASTLE

YOUR NAME: LIZA GOUVERNEUR TELE: 322-4103

YOUR ADDRESS: HALL OF RECORDS

ORGANIZATION (if any): BUREAU OF HIST. PRESERVATION DATE: 6/6/77

\*\*\*\*\*

1. TYPE OF LOCUS: a. structure  c. archaeological site \_\_\_  
b. district \_\_\_ d. other \_\_\_

2. NAME OF LOCUS: \_\_\_\_\_

3. STREET LOCATION: Box 160, City Rd 382 + Rt 301, Red Lion

4. OWNER'S NAME: \_\_\_\_\_ TELE: \_\_\_\_\_

ADDRESS: \_\_\_\_\_

5. THREATS TO LOCUS: (check more than one if necessary)

a. none known  d. developers \_\_\_  
b. zoning \_\_\_ e. deterioration \_\_\_  
c. roads \_\_\_ f. other \_\_\_

6. SURROUNDINGS OF LOCUS: (check more than one if necessary)

a. fallow field \_\_\_ d. scattered buildings   
b. cultivated field \_\_\_ e. densely built up \_\_\_  
c. woodland \_\_\_ f. other \_\_\_

7. REPRESENTATION ON OTHER SURVEYS:

TITLE: \_\_\_\_\_ NO. \_\_\_\_\_

TITLE: \_\_\_\_\_ NO. \_\_\_\_\_

TITLE: \_\_\_\_\_ NO. \_\_\_\_\_

8. USE REVERSE FOR SKETCH MAP AND COMMENTS.

*Please indicate position of locus in relation to  
geographical landmarks such as streams and roads.*

CULTURAL RESOURCE SURVEY  
STRUCTURAL DATA FORM

BUREAU OF ARCHAEOLOGY AND  
HISTORIC PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



Form CRS-1

FOR OFFICE USE ONLY

CRS no. N-1237  
Quad \_\_\_\_\_  
SPO map no. 02.09.32  
Hundred NEW CASTLE

1. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE: (no photo in file)

- a. dimensions  
stories 2 1/2  
bays 3 - one door - 2 windows  
wings none
- b. foundation  
basement brick
- c. structural system frame
- d. walls - exterior  
materials clabored sheathing nice bargeboard detail on  
storm center gable.
- e. walls - interior  
color (original) \_\_\_\_\_  
panelling \_\_\_\_\_  
trim \_\_\_\_\_
- f. roof gable roof with center gable.  
shape \_\_\_\_\_  
materials asphalt  
dormers \_\_\_\_\_
- g. openings  
windows side bay windows - 1st floor  
doors \_\_\_\_\_
- h. porches 3, 1 front - 2 back

2. CONDITION: a. excellent X d. deteriorated \_\_\_\_\_  
b. fair \_\_\_\_\_ e. demolished \_\_\_\_\_  
c. good \_\_\_\_\_ f. site destroyed \_\_\_\_\_

3. INTEGRITY: a. original site \_\_\_\_\_ b. moved \_\_\_\_\_  
c. if moved, when and from where \_\_\_\_\_  
\_\_\_\_\_
- d. list major alterations and dates (if known) \_\_\_\_\_  
\_\_\_\_\_

4. RELATED OUTBUILDINGS AND PROPERTY (mark "X" if existing, "0" if demolished)

- |                         |                             |
|-------------------------|-----------------------------|
| a. barn <u>X</u>        | h. gardens _____            |
| b. carriage house _____ | i. landscape features _____ |
| c. garage _____         | _____                       |
| d. privy _____          | j. other _____              |
| e. shed <u>X</u>        | _____                       |
| f. greenhouse _____     | _____                       |
| g. shop _____           | _____                       |

5. DATE OF INITIAL CONSTRUCTION: \_\_\_\_\_

6. ARCHITECT: \_\_\_\_\_

7. BUILDER: \_\_\_\_\_

8. BRIEFLY DESCRIBE THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE INCLUDING SIGNIFICANT ASSOCIATIONS:

9. PRIMARY REFERENCES:

10. ADDRESS OF STRUCTURE: Box 160 Red Lion Bo County Rd 302 + Rt. 301 ~~Bladen~~

11. DATE OF FORM: 6/6/77 SURVEYOR: J. Allan