

DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-10112  
SPO Map 20-21-10  
Hundred Lewes & Rehoboth  
Quad Fairmount  
Other 3-34-18-36

1. HISTORIC NAME/FUNCTION: Dwelling, southeast side of Route 24 (Box 363)
2. ADDRESS/LOCATION: Southeast side of Route 24 (Box 363) between Love Creek and Route 1
3. TOWN/NEAREST TOWN: Lewes vicinity?
4. MAIN TYPE OF RESOURCE:      building       structure       site       object   
   landscape       district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 24 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: \_\_\_\_\_


Organization: McCormick Taylor, Inc. Date: May 2004

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
  - 1600-1750± Contact Period (Native American)
  - 1630-1730± Exploration and Frontier Settlement
  - 1730-1770± Intensified and Durable Occupation
  - 1770-1830± Early Industrialization
  - 1830-1880± Industrialization and Early Urbanization
  - 1880-1940± Urbanization and Early Suburbanization
  - 1940-1960± Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                       |
| <input type="checkbox"/> Forestry              | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting      | <input type="checkbox"/> Architecture, Engineering and Decorative Arts          |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                             |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                 |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-10112

1. ADDRESS/LOCATION: Southeast side of Route 24 (Box 363) between Love Creek and Route 1

2. FUNCTION(S): historic Single-family residential current Single-family residential

3. YEAR BUILT: 1950 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE OR FLOOR PLAN: rectangular

5. INTEGRITY: original site  moved   
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular Stories: 1 1/2  
Additions: side wings (east wing is two-car garage) and rear porch
- b. Structural system (if known): light frame
- c. Foundation: materials: concrete  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible & any subsequent coverings): white aluminum siding
- e. Roof: shape: side gable  
materials: asphalt shingles  
cornice: simple enclosed  
dormers: n/a  
chimney: location(s): brick chimney with corbelled top in front slope of roof at east end; similar brick chimney roughly centered in rear slope of roof

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: N
  - 1) Bays 9
  - 2) Windows 8

fenestration irregular  
type 6/6 on east and west wings; paired 6/6 east and west of front porch; windows west of door beneath porch not visible  
trim simple surrounds  
shutters louvered, green

## Facade (cont'd)

- 3) Door(s) 1  
     location east end of recessed porch formed by cutout and roof overhang  
     type not visible  
     trim simple surround
- 4) Porch(es) open sheltered porch formed by cutout and roof overhang; simple turned column supports

## b. Side: Direction: E

- 1) Bays 2
- 2) Windows 1  
     fenestration irregular  
     type 4/4 sash  
     trim simple surround  
     shutters louvered; green; outer corners cut off by roofline
- 3) Door(s) 2  
     location evenly spaced on facade  
     type overhead garage doors with 4 lights  
     trim simple surrounds
- 4) Porch(es) rear screened porch addition with secondary entrance

## c. Side: Direction: W [not visible]

- 1) Bays
- 2) Windows  
     fenestration  
     type  
     trim  
     shutters
- 3) Door(s)  
     location  
     type  
     trim
- 4) Porch(es)


## d. Rear: Direction: S [not visible]

- 1) Bays
- 2) Windows  
     fenestration  
     type  
     trim  
     shutters
- 3) Door(s)  
     location  
     type  
     trim
- 4) Porch(es)

## 9. INTERIOR:

10. LANDSCAPING: Scattered bushes planted close to house around perimeter; deciduous trees in front and rear yards.

## 11. OTHER COMMENTS:



CULTURAL RESOURCE SURVEY  
MAP FORM


CRS # S-10112

1. ADDRESS/LOCATION: 20361 John J. Williams Highway, Lewes, DE (3-34-18-37.03)
2. NOT FOR PUBLICATION  reason: \_\_\_\_\_
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS# S-10112

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SURVEY UPDATE FORM

CRS # S-1003

1. HISTORIC NAME/FUNCTION: Dwelling, North side of Route 24 between Love Creek and Tanglewood Drive
2. ADDRESS/LOCATION: North side of Route 24 between Love Creek and Tanglewood Drive
3. CURRENT CONDITION:    excellent     good     fair     poor     demolished
4. INTEGRITY: The condition of both the residence and the outbuildings has deteriorated further. The barn is particularly deteriorated; portions of the roof have caved in and the entire structure is leaning. The pump house mentioned in the 1979 CRS form appears to be gone.
5. SETTING INTEGRITY: The setting has not changed significantly.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
0	CRS 2 Main Building Form	
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: \_\_\_\_\_

Organization: McCormick Taylor, Inc.                      Date: May 2004

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-1003

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)


- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II
  
- 1600-1750± Contact Period (Native American)
- 1630-1730± Exploration and Frontier Settlement
- 1730-1770± Intensified and Durable Occupation
- 1770-1830± Early Industrialization
- 1830-1880± Industrialization and Early Urbanization
- 1880-1940± Urbanization and Early Suburbanization
- 1940-1960± Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication                         |
| <input type="checkbox"/> Forestry               | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes   |
| <input type="checkbox"/> Trapping/Hunting       | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying       | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering      | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing          | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling  | <input type="checkbox"/> Community Organizations                                  |
| <input type="checkbox"/> Finance                | <input type="checkbox"/> Occupational Organizations                               |
| <input type="checkbox"/> Professional Services  | <input type="checkbox"/> Major Families, Individuals and Events                   |



CULTURAL RESOURCE SURVEY  
MAP FORM

CRS # S-1003

1. ADDRESS/LOCATION: 20248 John J. Williams Highway, Lewes, DE (3-34-18-4)


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS# S-1003

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9

CULTURAL RESOURCE SURVEY  
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



FORM CRS-2

FOR OFFICE USE ONLY


CRS = 5-1002  
Quad Four corners  
SPO map = 20-21-10  
Hundred 20-21-10  
DOCUMENT 20-06/78/04/7

*Parcel 4 - Tax Map 3-34-18*

1. NAME OF LOCUS: Parcel 4 - Tax Map 3-34-18
2. STREET LOCATION: NW side of Rt 24 - south of junction w/ Rt. 254
3. OWNER'S NAME: Emma J. Baughen TEL. # \_\_\_\_\_  
ADDRESS: RD 2, Box 238, Lewis, De 19158
4. TYPE OF LOCUS: a) structure  b) district \_\_\_\_\_ c) archaeological site \_\_\_\_\_  
d) other \_\_\_\_\_
5. SURROUNDINGS (OF LOCUS: (check more than one if necessary)  
a) fallow field \_\_\_\_\_ b) cultivated field  c) woodland   
d) scattered buildings  e) densely built up \_\_\_\_\_ f) other \_\_\_\_\_
6. THREATS TO LOCUS: (check more than one if necessary)  
a) none known  b) zoning \_\_\_\_\_ c) roads \_\_\_\_\_ d) developers \_\_\_\_\_  
e) deterioration \_\_\_\_\_ f) other \_\_\_\_\_
7. REPRESENTATION ON OTHER SURVEYS:  
TITLE: \_\_\_\_\_ # \_\_\_\_\_  
TITLE: \_\_\_\_\_ # \_\_\_\_\_  
TITLE: \_\_\_\_\_ # \_\_\_\_\_
8. YOUR NAME: Phyllis Hastings TEL. # \_\_\_\_\_  
YOUR ADDRESS: Sumner County Courthouse  
ORGANIZATION (if any) Assist. Preservation Planner DATE: 10/13/79

USE BLACK INK ONLY

Locate position of locus in relation to  
physical landmarks such as streets, etc.



SKETCH

USE BLACK INK ONLY

9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

CULTURAL RESOURCE SURVEY  
STRUCTURAL DATA FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-1314




FOR OFFICE USE ONLY

Form CR-1  
CRS # 5-1063  
Quad Eastonwood  
SPD map # 20-21-10  
Hundred Fairview  
DOCUMENT 20-06778/100113

1. ADDRESS OF STRUCTURE : NE side of Rt. 24 south of junction of Rt. 284

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape main house - rectangular  
stories two stories  
bays 3 bay facade  
wing Two story gable wing at rear w/ single  
story lean-to additions on each side +  
on gable end
- b) Structural system  
frame, single piece w/ central hall
- c) Foundation  
materials brick  
basement
- d) Exterior walls  
materials modern aluminum siding  
color(s) gold
- e) Roof covered w/ asphalt + shingles  
shape: materials gable + lean-to  
cornice simple, closed + fascia board eaves  
dormers none  
chimney location(s) brick chimney at center peak of main house +  
lean-to exterior gable end of rear wing
- f) Windows  
spacing regular  
type double hung casings w/ 2/2 vertical bits, 1/2 bits, modern  
casements or jalousie windows on facade + lean-to on north side  
trim simple, architectonic, turn  
shutters no shutters
- g) Door  
spacing facade door in central bay (with enclosed porch) + modern  
type paneled door on north side (upon lean-to addition), door  
trim on south side of lean-to addition (on south side of gable wing)  
modern paneled door w/ wing - etc (all have simple trim)
- h) Porches  
location(s) Lean-to addition on facade was probably a porch  
materials that was since brick masonry + enclosed, the  
support lean-to addition on north side of 2 story wing  
trim possibly was originally a porch that has been  
enclosed
- i) Interior details (if accessible)



USE BLACK INK ONLY

115

3. CONDITION: good  deteriorated \_\_\_\_\_

remarks: \_\_\_\_\_

4. INTEGRITY: a) original site \_\_\_\_\_ b) moved \_\_\_\_\_  
 c) if moved, when and from where \_\_\_\_\_  
 d) list major alterations and dates (if known) *near garage wing  
 October in 1912 - clean to additions afterwards*

5. DATE OF INITIAL CONSTRUCTION: \_\_\_\_\_

6. ARCHITECT/BUILDER: \_\_\_\_\_

7. RELATED OUTBUILDINGS:  
 a) barn \_\_\_\_\_ b) carriage house \_\_\_\_\_ c) garage  d) privy \_\_\_\_\_  
 e) shed  f) greenhouse \_\_\_\_\_ g) shop \_\_\_\_\_ h) gardens \_\_\_\_\_  
 i) icehouse \_\_\_\_\_ j) springhouse \_\_\_\_\_ k) other \_\_\_\_\_


describe: *garage - gable roof, near facade concrete block walls w/ vertical  
 granite end, sliding door w/ battens doors, 2 shed: gable roof, asphalt  
 shingled walls, heavy battens door, 3 pump house - wood shingled gable  
 roof, high stucco, find w/ rounded base walls, 4 office - gable roof, shingled  
 - lean to on south end - corrugated metal roof, vertical beams, asphalt  
 shingled walls 5 concrete - shed + metal walls roof - vertical slatted  
 vertical plank walls*

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY  
 ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:  
*wall w/ block pier foundation; 2 shed shed + metal lean to roof w/  
 vertical plank slatted 3 barn - gable roof w/ lean to on west side  
 - vertical plank walls*

9. Primary References: (include location of reference).

10. Surveyor: *Phyllis Hartman* Date of Form: *10/31/79*

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-10113  
SPO Map 20-21-10  
Hundred Lewes & Rehoboth  
Quad Fairmount  
Other 3-34-18-3

1. HISTORIC NAME/FUNCTION: Dwelling, 20248 Route 24, NW side of Route 24 south of Tanglewood Drive
2. ADDRESS/LOCATION: 20248 Route 24, NW side of Route 24 south of Tanglewood Drive
3. TOWN/NEAREST TOWN: Lewes vicinity?
4. MAIN TYPE OF RESOURCE:
 

building <input checked="" type="checkbox"/>	structure <input type="checkbox"/>	site <input type="checkbox"/>	object <input type="checkbox"/>
landscape <input type="checkbox"/>	district <input type="checkbox"/>		
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 24 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: \_\_\_\_\_

Organization: McCormick Taylor, Inc. Date: May 2004

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
  - 1600-1750± Contact Period (Native American)
  - 1630-1730± Exploration and Frontier Settlement
  - 1730-1770± Intensified and Durable Occupation
  - 1770-1830± Early Industrialization
  - 1830-1880± Industrialization and Early Urbanization
  - 1880-1940± Urbanization and Early Suburbanization
  - 1940-1960± Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                       |
| <input type="checkbox"/> Forestry              | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting      | <input type="checkbox"/> Architecture, Engineering and Decorative Arts          |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                             |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                 |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-10113

1. ADDRESS/LOCATION: 20248 Route 24, NW side of Route 24 south of Tanglewood Drive

2. FUNCTION(S): historic Single-family residential current Single-family residential

3. YEAR BUILT: 1945 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE OR FLOOR PLAN: Rectangular with additions

5. INTEGRITY: original site  moved   
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year  
a.  
b.

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular with additions Stories: 1 1/2  
Additions: two-car garage and guest house/in-law suite to southwest, connected by hyphens

b. Structural system (if known): light frame

c. Foundation: materials: concrete block  
basement: full  partial  not visible  no basement

d. Exterior walls (original if visible & any subsequent coverings): white aluminum siding

e. Roof: shape: side gable  
materials: asphalt shingles  
cornice: simple enclosed  
dormers: continuous shed dormer on front (east) and rear (west) roof slopes  
chimney: location(s): exterior, slightly west of center on side (north) facade

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: E  
1) Bays 3  
2) Windows 4  
fenestration irregular  
type 6/1 on first floor; smaller version in dormer  
trim simple wide trim with molded lintel  
shutters n/a

**Facade (cont'd)**

- 3) **Door(s)** 1  
     **location** centered on façade; accessed via short flight of brick steps with metal railing  
     **type** paneled with three rectangular diagonal lights at top; exterior storm door  
     **trim** simple surround
- 4) **Porch(es)** n/a; two-car garage connects to the side (south) façade and also faces east

**b. Side: Direction: S**

- 1) **Bays** 2
- 2) **Windows** 3  
     **fenestration** irregular  
     **type** 2 windows with 6/1 sash on first floor; one with 6/6 sash in gable end  
     **trim** simple molded surrounds  
     **shutters** n/a
- 3) **Door(s)** hyphen at west end of the façade connects to garage  
     **location**  
     **type**  
     **trim**
- 4) **Porch(es)** two-car garage with east-facing overhead doors and a pedestrian entry; adjacent guest house/in-law suite has entry at east end of south façade

**c. Side: Direction: N**

- 1) **Bays** 2
- 2) **Windows** 3  
     **fenestration** irregular  
     **type** 2 windows with 6/1 sash on first floor; one with 6/6 sash in gable end  
     **trim** simple molded surrounds  
     **shutters** n/a
- 3) **Door(s)** n/a  
     **location**  
     **type**  
     **trim**
- 4) **Porch(es)** n/a


**d. Rear: Direction: W [not visible]**

- 1) **Bays**
- 2) **Windows**  
     **fenestration**  
     **type**  
     **trim**  
     **shutters**
- 3) **Door(s)**  
     **location**  
     **type**  
     **trim**
- 4) **Porch(es)**

**9. INTERIOR:**

10. **LANDSCAPING:** Bushes planted close to house along front façade; scattered deciduous and evergreen trees in yard; open fields to the north.

**11. OTHER COMMENTS:**



CULTURAL RESOURCE SURVEY  
MAP FORM

CRS # S-10113

1. ADDRESS/LOCATION: 20248 John J. Williams Highway, Lewes, DE (3-34-18-3)


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map )

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SURVEY UPDATE FORM

CRS # S-1005

1. HISTORIC NAME/FUNCTION: Dwelling, west side of Route 24 north of Tanglewood Drive

2. ADDRESS/LOCATION: West side of Route 24 north of Tanglewood Drive

3. CURRENT CONDITION: excellent  good  fair  poor  demolished

4. INTEGRITY: The condition of the house and outbuildings has deteriorated slightly; four of the outbuildings mentioned in the 1979 CRS form appear to be gone.

5. SETTING INTEGRITY: The setting has not changed significantly.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
0	CRS 2 Main Building Form	
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: \_\_\_\_\_

Organization: McCormick Taylor, Inc. Date: May 2004

8. OTHER NOTES OR OBSERVATIONS:


CRS# S-1005

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
  - 1600-1750± Contact Period (Native American)
  - 1630-1730± Exploration and Frontier Settlement
  - 1730-1770± Intensified and Durable Occupation
  - 1770-1830± Early Industrialization
  - 1830-1880± Industrialization and Early Urbanization
  - 1880-1940± Urbanization and Early Suburbanization
  - 1940-1960± Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- |   |   |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication                       |
| <input type="checkbox"/> Forestry               | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting       | <input type="checkbox"/> Architecture, Engineering and Decorative Arts          |
| <input type="checkbox"/> Mining/Quarrying       | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering      | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing          | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling  | <input type="checkbox"/> Community Organizations                                |
| <input type="checkbox"/> Finance                | <input type="checkbox"/> Occupational Organizations                             |
| <input type="checkbox"/> Professional Services  | <input type="checkbox"/> Major Families, Individuals and Events                 |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAP FORM

CRS # S-1005

1. ADDRESS/LOCATION: Northwest Side of Route 24 between Love Creek and Tanglewood Drive (3-34-18-40.02)


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-1005

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9

CULTURAL RESOURCE SURVEY  
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



FORM CRS-1

FOR OFFICE USE ONLY

CRS # 1065  
Quad Fairmount  
SPD map = 20-21-20  
Hundred 20-06/78/047  
DOCUMENT

Parcel 2-744 Map 3-34-18 40-027

1. NAME OF LOCUS: Parcel 2 Tax Map 3-34-18
2. STREET LOCATION: west side of Rt. 24 south of junction w/ Rt. 284
3. OWNER'S NAME: \_\_\_\_\_ TEL. # \_\_\_\_\_  
ADDRESS: \_\_\_\_\_
4. TYPE OF LOCUS: a) structure  b) district \_\_\_\_\_ c) archaeological site \_\_\_\_\_  
d) other \_\_\_\_\_
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)  
a) fallow field \_\_\_\_\_ b) cultivated field  c) woodland   
d) scattered buildings  e) densely built up \_\_\_\_\_ f) other \_\_\_\_\_
6. THREATS TO LOCUS: (check more than one if necessary)  
a) none known  b) zoning \_\_\_\_\_ c) roads \_\_\_\_\_ d) developers \_\_\_\_\_  
e) deterioration \_\_\_\_\_ f) other \_\_\_\_\_
7. REPRESENTATION ON OTHER SURVEYS:  
TITLE: \_\_\_\_\_  
TITLE: \_\_\_\_\_  
TITLE: \_\_\_\_\_
8. YOUR NAME: Daphne Hastings TEL. # \_\_\_\_\_  
YOUR ADDRESS: Sussex County Courthouse  
ORGANIZATION (if any): Preservation Planner DATE: 10/1/99

USE BLACK INK ONLY

5/11/02

**B. SKETCH MAP**

Use the grid to sketch the location of the site. Indicate the location of the site on the grid. Use the grid to sketch the location of the site. Indicate the location of the site on the grid.

**9. CAPTION:**

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

**INDICATE NORTH ON SKETCH**

**USE BLACK INK ONLY**

CULTURAL RESOURCE SURVEY  
STRUCTURAL DATA FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314




Form CRS-1  
FOR OFFICE USE ONLY

CRS # 5-10025  
Quad Fairmount  
SPO map # 20-21-10 20-21-11  
Hundred 20-21-10-11  
DOCUMENT 20-06/78/05/14

1. ADDRESS OF STRUCTURE : west side of Rt. 24; south of junction w/ Rt. 284

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape main house - rectangular  
stories two stories  
bays two bay facade  
wings two story gable wing at rear w/  
single story lean-to addition on west
- b) Structural system lean-to addition on west  
frame on facade
- c) Foundation materials brick  
basement
- d) Exterior walls materials asbestos shingles  
color(s) gold
- e) Roof covered w/ composition shingles  
shape: materials gable + lean-to  
cornice simple exposed rafters and cornice  
dormers none  
chimney location(s) covered brick chimneys on interior gable end  
of main house + rear gable wing
- f) Windows spacing irregular  
type 4-lite square casements in gable ends, double hung casets  
trim of 2/2 + 1/4 lites, median windows on facade lean-to  
shutters simple architrave trim, no shutters
- g) Door spacing facade door in right bay - wooden paneled door w/  
type simple surround, two doors on south side of house &  
trim addition - one is wooden w/ panels & other is masonry  
- both have simple trim
- h) Porches location(s) Single story - lean-to addition on facade. Seems  
materials to be an enclosed porch  
supports  
trim
- i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION: good  \_\_\_\_\_ deteriorated \_\_\_\_\_

remarks: \_\_\_\_\_

4. INTEGRITY: a) original site \_\_\_\_\_ b) moved \_\_\_\_\_

c) if moved, when and from where \_\_\_\_\_

d) list major alterations and dates (if known) \_\_\_\_\_

5. DATE OF INITIAL CONSTRUCTION: \_\_\_\_\_

6. ARCHITECT/BUILDER: \_\_\_\_\_

7. RELATED OUTBUILDINGS:

a) barn  b) carriage house \_\_\_\_\_ c) garage \_\_\_\_\_ d) privy \_\_\_\_\_

e) shed  f) greenhouse \_\_\_\_\_ g) shop \_\_\_\_\_ h) gardens \_\_\_\_\_

i) icehouse \_\_\_\_\_ j) springhouse \_\_\_\_\_ k) other \_\_\_\_\_

describe: one shed has gable roof w/ vertical board walls, shed roof on 4  
has gable roof w/ lean-to on north side - high black foundation w/  
vertical board & batten walls, 2 large modern gable roof barns,  
2 large granaries - both have corrugated metal gable roofs w/ lean-to  
on each side - one has weathered board walls while the other has  
vertical board walls - two smaller corn-cob six sheds w/

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

gable roofs w/ lean-tos on each side, long rectangular  
sheds - beam to roof, chicken coop - 2 sheds w/ corrugated metal w/ vertical board walls w/ weathered battens

9. Primary References: (include location of reference).

10. Surveyor: Phyllis Hastings Date of Form: 10/14/02

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-10114  
SPO Map 20-21-11  
Hundred Lewes & Rehoboth  
Quad Fairmount  
Other 3-34-12-23

1. HISTORIC NAME/FUNCTION: Dwelling, NW side of Route 24 between Tanglewood Drive and Road 284
2. ADDRESS/LOCATION: 147 Route 24, NW side of Route 24 between Tanglewood Drive and Road 284
3. TOWN/NEAREST TOWN: Lewes vicinity?
4. MAIN TYPE OF RESOURCE: building  structure  site  object   
landscape  district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 24 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis  
Principal Investigator name: Francine Arnold  
Principal Investigator signature: \_\_\_\_\_  
Organization: McCormick Taylor, Inc. Date: May 2004

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-10114

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750± Contact Period (Native American)
- 1630-1730± Exploration and Frontier Settlement
- 1730-1770± Intensified and Durable Occupation
- 1770-1830± Early Industrialization
- 1830-1880± Industrialization and Early Urbanization
- 1880-1940± Urbanization and Early Suburbanization
- 1940-1960± Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                       |
| <input type="checkbox"/> Forestry              | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting      | <input type="checkbox"/> Architecture, Engineering and Decorative Arts          |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                             |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                 |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-10114

1. ADDRESS/LOCATION: 147 Route 24, NW side of Route 24 between Tanglewood Drive and Road 284
2. FUNCTION(S): historic Single-family residential current Single-family residential
3. YEAR BUILT: 1945 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_
4. STYLE OR FLOOR PLAN: rectangular

5. INTEGRITY: original site  moved   
 if moved, from where \_\_\_\_\_ other location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_  
 a. enclosed front porch \_\_\_\_\_  
 b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular Stories: 1  
 Additions: enclosed front porch
- b. Structural system (if known): concrete block
- c. Foundation: materials: concrete block  
 basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible & any subsequent coverings): yellow vinyl siding
- e. Roof: shape: low-pitched side gable with overhanging eaves  
 materials: asphalt shingles  
 cornice: simple enclosed  
 dormers: n/a  
 chimney: location(s): exterior concrete block chimney centered on side (south) facade

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: E  
 1) Bays 6  
 2) Windows 6  
 fenestration irregular  
 type 5 evenly spaced porch windows with three horizontal lights; paired 1/1 at south end  
 trim simple surrounds  
 shutters n/a


## Facade (cont'd)

- 3) Door(s) 1  
     location south façade of porch; accessed via short flight of steps with metal railing  
     type not visible  
     trim not visible
- 4) Porch(es) enclosed shed-roofed front porch addition now houses main entry
- b. Side: Direction: S [not visible]
- 1) Bays
- 2) Windows  
     fenestration  
     type  
     trim  
     shutters
- 3) Door(s)  
     location  
     type  
     trim
- 4) Porch(es)
- c. Side: Direction: N
- 1) Bays 2
- 2) Windows 3  
     fenestration irregular  
     type 2/2 double-hung sash with horizontal lights; single at east end, paired at west  
     trim simple surrounds  
     shutters n/a
- 3) Door(s) n/a  
     location  
     type  
     trim
- 4) Porch(es) n/a
- d. Rear: Direction: W
- 1) Bays 3
- 2) Windows 3  
     fenestration irregular  
     type 2/2 double-hung sash with horizontal lights; paired south of door and single  
     to the south  
     trim simple surrounds  
     shutters n/a
- 3) Door(s) 1  
     location north end of facade  
     type paneled with 3 horizontal lights at top; exterior storm door  
     trim simple surround
- 4) Porch(es) small shed-roofed porch extension with wood supports and railing and  
     concrete block stairs shelters entry

## 9. INTERIOR:

10. LANDSCAPING: Bushes and shrubs planted around perimeter of house; lot is wooded at rear and sides with mostly deciduous trees.

## 11. OTHER COMMENTS:



CULTURAL RESOURCE SURVEY  
MAP FORM


CRS # S-10114

1. ADDRESS/LOCATION: 147 Route 24, Lewes, DE (3-34-12-23)
2. NOT FOR PUBLICATION  reason: \_\_\_\_\_
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-10114

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-10115  
SPO Map 20-21-11  
Hundred Lewes & Rehoboth  
Quad Fairmount  
Other 3-34-12-24

1. HISTORIC NAME/FUNCTION: Dwelling, NW side of Route 24 between Tanglewood Drive and Road 284
2. ADDRESS/LOCATION: 145 Route 24, NW side of Route 24 between Tanglewood Drive and Road 284
3. TOWN/NEAREST TOWN: Lewes vicinity?
4. MAIN TYPE OF RESOURCE:      building       structure       site       object   
   landscape       district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 24 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
1	CRS 3 Secondary Building Form	Garage
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: \_\_\_\_\_

Organization: McCormick Taylor, Inc. Date: May 2004

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750± Contact Period (Native American)
- 1630-1730± Exploration and Frontier Settlement
- 1730-1770± Intensified and Durable Occupation
- 1770-1830± Early Industrialization
- 1830-1880± Industrialization and Early Urbanization
- 1880-1940± Urbanization and Early Suburbanization
- 1940-1960± Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                       |
| <input type="checkbox"/> Forestry              | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting      | <input type="checkbox"/> Architecture, Engineering and Decorative Arts          |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                             |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                 |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-10115

1. ADDRESS/LOCATION: 145 Route 24, NW side of Route 24 between Tanglewood Drive and Road 284
2. FUNCTION(S): historic Single-family residential current Single-family residential
3. YEAR BUILT: 1940 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_
4. STYLE OR FLOOR PLAN: Craftsman
5. INTEGRITY: original site  moved   
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. shed-roofed rear porch addition

b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular with cross gable Stories: 1 1/2  
Additions:
- b. Structural system (if known): light frame
- c. Foundation: materials:  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible & any subsequent coverings): gray asbestos shingles
- e. Roof: shape: cross gable with overhanging eaves  
materials: asphalt shingles  
cornice: board fascia  
dormers: n/a  
chimney: location(s): exterior concrete block chimney extending through eave, north of center on rear (west) facade

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: E

1) Bays 3+

2) Windows 9

fenestration irregular

type ribbon of windows with 3 horizontal lights on porch to either side of door; paired window with single lights north of door; paired windows with 1/1 sash in gable end

trim simple surrounds


shutters n/a

- Facade (cont'd)**
- 3) **Door(s)** 2  
     **location** centered on front porch; second door at south end  
     **type** not visible; exterior storm doors on both  
     **trim** simple surrounds
- 4) **Porch(es)** main door leads into hipped-roof front porch with continuous windows;  
 secondary door is located beneath roof overhang with wrought iron support and accessed  
 via short flight of masonry steps with metal railing
- b. **Side: Direction: S**
- 1) **Bays** 3
- 2) **Windows** 3+  
     **fenestration** irregular  
     **type** paired with single lights on west gable end; not visible east of secondary  
     door; small rectangular basement windows; rectangular louvered vent in gable end  
     **trim** simple surrounds  
     **shutters** n/a
- 3) **Door(s)** n/a  
     **location**  
     **type**  
     **trim**
- 4) **Porch(es)** n/a
- c. **Side: Direction: N**
- 1) **Bays** 3
- 2) **Windows** 4  
     **fenestration** irregular  
     **type** 1/1 sash; smaller version in gable end  
     **trim** simple surrounds  
     **shutters** n/a
- 3) **Door(s)** n/a  
     **location**  
     **type**  
     **trim**
- 4) **Porch(es)** n/a
- d. **Rear: Direction: W**
- 1) **Bays** 2+
- 2) **Windows** 4+  
     **fenestration** irregular  
     **type** 1/1 sash of varying sizes, irregularly located; single pane window in rear  
     porch addition  
     **trim** simple surrounds  
     **shutters** n/a
- 3) **Door(s)** 1  
     **location** south façade of addition  
     **type** paneled with four lights in upper half and exterior storm door  
     **trim** simple surround
- 4) **Porch(es)** shed-roofed enclosed rear porch entry

9. **INTERIOR:**

10. **LANDSCAPING:** Bushes planted close to house along front façade; lot is wooded with mostly deciduous trees.

11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-10115

1. ADDRESS/LOCATION: 145 Route 24, NW side of Route 24 between Tanglewood Drive and Road 284
2. FUNCTION(S): historic Storage current Garage
3. YEAR BUILT: 1940 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_
4. STYLE/FLOOR PLAN: rectangular
5. INTEGRITY: original site  moved   
if moved, from where original location's CRS # year

list major alterations and additions with years (if known)

year

a.  
b.

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:

- a. Structural system frame
- b. Number of stories 1
- c. Wall coverings vertical board
- d. Foundation not visible
- e. Roof  
structural system front gable with exposed rafter ends  
coverings asphalt shingles  
openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: E
- 1) bays: 1
- 2) windows: n/a
- 3) door(s): overhead garage door
- 4) other: light fixture in gable end

- b. Side: direction: S
  - 1) bays: n/a
  - 2) windows: n/a
  - 3) door(s): n/a
  - 4) other: n/a

- c. Side: direction: N
  - 1) bays: n/a
  - 2) windows: n/a
  - 3) door(s): n/a
  - 4) other: n/a

- d. Rear: direction: W
  - 1) bays: n/a
  - 2) windows: n/a
  - 3) door(s): n/a
  - 4) other: n/a


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY  
MAP FORM

CRS # S-10115

1. ADDRESS/LOCATION: 20028 John J. Williams Highway, Lewes, DE (3-34-12-24)


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-10115

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-10116  
SPO Map 20-21-11  
Hundred Lewes & Rehoboth  
Quad Fairmount  
Other 3-34-12-108

1. HISTORIC NAME/FUNCTION: Dwelling, 19429 Route 24
2. ADDRESS/LOCATION: 19429 Route 24, South Side of Route 24 west of Mulberry Knoll Road
3. TOWN/NEAREST TOWN: Lewes vicinity?
4. MAIN TYPE OF RESOURCE:      building       structure       site       object   
   landscape       district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 24 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
2	CRS 3 Secondary Building Form	Outhouse, storage building
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: \_\_\_\_\_


Organization: McCormick Taylor, Inc. Date: May 2004

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
  - 1600-1750± Contact Period (Native American)
  - 1630-1730± Exploration and Frontier Settlement
  - 1730-1770± Intensified and Durable Occupation
  - 1770-1830± Early Industrialization
  - 1830-1880± Industrialization and Early Urbanization
  - 1880-1940± Urbanization and Early Suburbanization
  - 1940-1960± Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                       |
| <input type="checkbox"/> Forestry              | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting      | <input type="checkbox"/> Architecture, Engineering and Decorative Arts          |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                             |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                 |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-10116

1. ADDRESS/LOCATION: 19429 Route 24, South side of Route 24 west of Mulberry Knoll Road
2. FUNCTION(S): historic single-family dwelling current single-family dwelling
3. YEAR BUILT: 1950 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_
4. STYLE OR FLOOR PLAN: front-facing T
5. INTEGRITY: original site  moved   
if moved, from where other location's CRS # year

list major alterations and additions with years (if known)

year

a.

b.

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: T-shape Stories: 1  
 Additions: Open carport on east facade
- b. Structural system (if known): Light frame
- c. Foundation: materials: Concrete block  
 basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible & any subsequent coverings): White aluminum siding
- e. Roof: shape: Gable  
 materials: Asphalt shingles  
 cornice: n/a  
 dormers: n/a  
 chimney: location(s): Exterior concrete block chimney on east facade

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: N
- 1) Bays 3
- 2) Windows  
 fenestration regular  
 type 1/1 sash  
 trim simple aluminum surrounds  
 shutters n/a

**Facade (cont'd)**

- 3) **Door(s)**  
     **location**      centered  
     **type**           paneled with single light at top; aluminum exterior door w/top half light  
     **trim**            simple surround
- 4) **Porch(es)**      n/a

**b. Side: Direction: E**

- 1) **Bays**            3
- 2) **Windows**  
     **fenestration**   regular  
     **type**            1/1 sash  
     **trim**            simple aluminum surround  
     **shutters**       n/a
- 3) **Door(s)**  
     **location**       north side of rear side-gable portion  
     **type**            paneled with four-light top; exterior aluminum door w/top half light  
     **trim**            simple surround; no stairs leading to door
- 4) **Porch(es)**      shed-roofed open metal carport

**c. Side: Direction:**

- 1) **Bays**            W
- 2) **Windows**        4  
     **fenestration**   regular  
     **type**            1/1 sash; small single light window in gable end  
     **trim**            simple aluminum surrounds  
     **shutters**        n/a
- 3) **Door(s)**        n/a  
     **location**  
     **type**  
     **trim**
- 4) **Porch(es)**      n/a


**d. Rear: Direction: S**

- 1) **Bays**            not visible
- 2) **Windows**  
     **fenestration**  
     **type**  
     **trim**  
     **shutters**
- 3) **Door(s)**  
     **location**  
     **type**  
     **trim**
- 4) **Porch(es)**

**9. INTERIOR:**

10. **LANDSCAPING:** No plantings, surrounded by open fields.

**11. OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-10116

1. ADDRESS/LOCATION: 19429 Route 24, south side of Route 24 west of Mulberry Knoll Road

2. FUNCTION(S): historic outhouse current undetermined

3. YEAR BUILT: 1950 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: square

5. INTEGRITY: original site  moved   
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:

- a. Structural system frame
- b. Number of stories 1
- c. Wall coverings vertical board siding
- d. Foundation not visible
- e. Roof
  - structural system gable
  - coverings asphalt shingles
  - openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: E
  - 1) bays: 1
  - 2) windows: n/a
  - 3) door(s): centered
  - 4) other: n/a

- b. Side: direction: S
- 1) bays: n/a
  - 2) windows: n/a
  - 3) door(s): n/a
  - 4) other: n/a

- c. Side: direction: N
- 1) bays: n/a
  - 2) windows: n/a
  - 3) door(s): n/a
  - 4) other: n/a

- d. Rear: direction: W
- 1) bays: n/a
  - 2) windows: n/a
  - 3) door(s): n/a
  - 4) other: n/a


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-10116

1. ADDRESS/LOCATION: 19429 Route 24, south side of Route 24 west of Mulberry Knoll Road

2. FUNCTION(S): historic storage current storage

3. YEAR BUILT: 1950 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site  moved

if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. \_\_\_\_\_

b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:

a. Structural system concrete block

b. Number of stories 1

c. Wall coverings n/a

d. Foundation concrete block

e. Roof

structural system gable  
coverings asphalt shingles  
openings n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: N

1) bays: 1

2) windows: n/a

3) door(s): one single-panel metal door, located west of center

4) other: n/a

- b. Side: direction: E
- 1) bays: not visible
  - 2) windows:
  - 3) door(s):
  - 4) other:

- c. Side: direction: S
- 1) bays: not visible
  - 2) windows:
  - 3) door(s):
  - 4) other:

- d. Rear: direction: W
- 1) bays: 2
  - 2) windows: evenly spaced, small rectangular single-light; no surrounds
  - 3) door(s): n/a
  - 4) other: n/a


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY  
MAP FORM


CRS # S-10116

1. ADDRESS/LOCATION: 19429 John J. Williams Highway, Lewes, DE (3-34-12-108)
2. NOT FOR PUBLICATION  reason: \_\_\_\_\_
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-10116

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-10117  
SPO Map 20-21-11  
Hundred Lewes & Rehoboth  
Quad Fairmount  
Other 3-34-12-109

1. HISTORIC NAME/FUNCTION: Dwelling, P.O. Box 234 Route 24
2. ADDRESS/LOCATION: South side of Route 24, west of Mulberry Knoll Road
3. TOWN/NEAREST TOWN: Lewes vicinity?
4. MAIN TYPE OF RESOURCE:
 

building <input checked="" type="checkbox"/>	structure <input type="checkbox"/>	site <input type="checkbox"/>	object <input type="checkbox"/>
landscape <input type="checkbox"/>	district <input type="checkbox"/>		
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 24 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
1	CRS 3 Secondary Building Form	Storage building
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: \_\_\_\_\_

Organization: McCormick Taylor, Inc. Date: May 2004

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750± Contact Period (Native American)
- 1630-1730± Exploration and Frontier Settlement
- 1730-1770± Intensified and Durable Occupation
- 1770-1830± Early Industrialization
- 1830-1880± Industrialization and Early Urbanization
- 1880-1940± Urbanization and Early Suburbanization
- 1940-1960± Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                       |
| <input type="checkbox"/> Forestry              | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting      | <input type="checkbox"/> Architecture, Engineering and Decorative Arts          |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                             |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                 |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-10117

1. ADDRESS/LOCATION: P.O. Box 234 Route 24; South Side Of Route 24 West Of Mulberry Knoll Road

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1950 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE OR FLOOR PLAN: rectangular

5. INTEGRITY: original site  moved

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. \_\_\_\_\_

b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1 1/2  
Additions: large one-story rear addition of similar style and materials; date unknown

b. Structural system (if known): light frame

c. Foundation: materials: concrete  
basement: full  partial  not visible  no basement

d. Exterior walls (original if visible & any subsequent coverings): white aluminum siding

e. Roof: shape: front gable  
materials: asphalt shingles  
cornice: N/A  
dormers: N/A  
chimney: location(s): poured concrete exterior chimney centered on north side; covered up to eave

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: W  
1) Bays 3  
2) Windows  
fenestration irregular  
type 1/1 sash  
trim simple aluminum surrounds  
shutters N/A


## Facade (cont'd)

- 3) Door(s)  
     location west of center  
     type paneled with six-light upper section; metal exterior door w/two large lights at top comprising approximately 3/4 of door and blind section at bottom  
     trim simple surround
- 4) Porch(es) N/A
- b. Side: Direction: S
- 1) Bays 3
- 2) Windows 3  
     fenestration regular  
     type 1/1 double-hung sash  
     trim simple surrounds  
     shutters N/A
- 3) Door(s) N/A  
     location  
     type  
     trim
- 4) Porch(es) N/A
- c. Side: Direction: N
- 1) Bays 3
- 2) Windows 3  
     fenestration regular  
     type 2 windows with 1/1 double-hung sash, 1 small single-light rectangular window  
     trim simple surrounds  
     shutters N/A
- 3) Door(s) N/A  
     location  
     type  
     trim
- 4) Porch(es) N/A
- d. Rear: Direction:
- 1) Bays not visible
- 2) Windows  
     fenestration  
     type  
     trim  
     shutters
- 3) Door(s)  
     location  
     type  
     trim
- 4) Porch(es)

## 9. INTERIOR:

10. LANDSCAPING: Scattered deciduous and evergreen trees; small bushes at front corners and by chimney

## 11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-10117

1. ADDRESS/LOCATION: P.O. Box 234 Route 24, south side of Route 24 west of Mulberry Knoll Road

2. FUNCTION(S): historic storage current storage

3. YEAR BUILT: 1990 CIRCA?:  ARCHITECT/BUILDER: N/A (prefabricated shed)

4. STYLE/FLOOR PLAN: Square

5. INTEGRITY: original site  moved   
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year  
a.  
b.

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:  
a. Structural system prefabricated shed  
b. Number of stories 1  
c. Wall coverings metal  
d. Foundation unknown  
e. Roof  
structural system gable  
coverings asphalt shingles  
Openings n/a

8. DESCRIPTION OF ELEVATIONS:  
a. Facade: direction: West  
1) bays: 1  
2) windows: n/a  
3) door(s): one single-leaf door centered on facade  
4) other: n/a

b. Side: direction: North

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: n/a

c. Side: direction: South

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: n/a

d. Rear: direction: East

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: n/a


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY  
MAP FORM

CRS # S-10117

1. ADDRESS/LOCATION: Southeast Side of Route 24 west of the intersection with Mulberry Knoll Road (3-34-12-109)


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-10117

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-10118  
SPO Map 20-21-11  
Hundred Lewes & Rehoboth  
Quad Fairmount  
Other 3-34-12-110

1. HISTORIC NAME/FUNCTION: Dwelling, 19387 Route 24
2. ADDRESS/LOCATION: 19387 Route 24, south side of Route 24 west of Mulberry Knoll Road
3. TOWN/NEAREST TOWN: Lewes vicinity?
4. MAIN TYPE OF RESOURCE: building  structure  site  object   
landscape  district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 24 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
1	CRS 3 Secondary Building Form	Prefabricated shed
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis  
Principal Investigator name: Francine Arnold  
Principal Investigator signature: \_\_\_\_\_  
Organization: McCormick Taylor, Inc. Date: May 2004

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750± Contact Period (Native American)
- 1630-1730± Exploration and Frontier Settlement
- 1730-1770± Intensified and Durable Occupation
- 1770-1830± Early Industrialization
- 1830-1880± Industrialization and Early Urbanization
- 1880-1940± Urbanization and Early Suburbanization
- 1940-1960± Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                       |
| <input type="checkbox"/> Forestry              | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting      | <input type="checkbox"/> Architecture, Engineering and Decorative Arts          |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                             |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                 |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-10118

1. ADDRESS/LOCATION: 19387 Route 24, south side of Route 24 west of Mulberry Knoll Road

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1950 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE OR FLOOR PLAN: square

5. INTEGRITY: original site  moved   
if moved, from where \_\_\_\_\_ other location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: square Stories: 1 1/2  
Additions: shed-roofed open porch on rear (south) facade
- b. Structural system (if known): light frame
- c. Foundation: materials: poured concrete  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible & any subsequent coverings): asbestos shingles
- e. Roof: shape: gable  
materials: asphalt shingles  
cornice: n/a  
dormers: continuous shed dormer on front (north) facade  
chimney: location(s): exterior concrete block centered on side (east) facade

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: N
  - 1) Bays 3
  - 2) Windows 4
  - fenestration regular
  - type 2 paired with 1/1 sash on first floor; 2 w/4 horizontal lights in dormer
  - trim simple wood surrounds
  - shutters n/a

## Facade (cont'd)

- 3) Door(s)  
     location centered on front (north) facade  
     type not visible  
     trim simple surround

- 4) Porch(es) door is sheltered by a gable-roofed portico with slender support columns and reached by a short flight of concrete steps

## b. Side: Direction: E

- 1) Bays 2  
 2) Windows 2  
     fenestration regular  
     type 1/1 sash  
     trim simple surrounds  
     shutters n/a

- 3) Door(s) n/a  
     location  
     type  
     trim

- 4) Porch(es) n/a

## c. Side: Direction: W

- 1) Bays 3  
 2) Windows 3  
     fenestration regular w/two windows on first floor and one centered in gable peak  
     type 1/1 sash  
     trim simple surrounds  
     shutters n/a

- 3) Door(s) n/a  
     location  
     type  
     trim

- 4) Porch(es) n/a

## d. Rear: Direction: S

- 1) Bays  
 2) Windows not visible  
     fenestration  
     type  
     trim  
     shutters

- 3) Door(s) not visible  
     location  
     type  
     trim

- 4) Porch(es) Full-width, shed-roofed open metal porch/carport addition

9. INTERIOR: not visible

10. LANDSCAPING: One tree directly adjacent to front door close to the house; lot is otherwise open with some scattered deciduous trees on adjacent lots

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-10118

1. ADDRESS/LOCATION: 19387 Route 24, south side of Route 24 west of Mulberry Knoll Road

2. FUNCTION(S): historic storage current storage

3. YEAR BUILT: 1980 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: Rectangular, gambrel-roof prefabricated shed

5. INTEGRITY: original site  moved

if moved, from where

original location's CRS # year

list major alterations and additions with years (if known)

year

a. \_\_\_\_\_

b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:

a. Structural system frame

b. Number of stories 1

c. Wall coverings wood sheathing

d. Foundation not visible

e. Roof  
structural system gambrel  
coverings asphalt shingles  
openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: W
  - 1) bays: 1
  - 2) windows: n/a
  - 3) door(s): not visible
  - 4) other: n/a

b. Side: direction: N

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: n/a

c. Side: direction: S

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: n/a

d. Rear: direction: E

- 1) bays: 1
- 2) windows: horizontal rectangular window in gable end
- 3) door(s): n/a
- 4) other: n/a


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY  
MAP FORM

CRS # S-10118

1. ADDRESS/LOCATION: 19387 John J. Williams Highway, Lewes, DE (3-34-12-110)


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH




4. SITE PLAN:

CRS # S-10118

INDICATE NORTH ON PLAN



USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SURVEY UPDATE FORM

CRS # S-1007

1. HISTORIC NAME/FUNCTION: Dwelling, SE corner of intersection of Route 24 and Mulberry Knoll Road (284)
2. ADDRESS/LOCATION: SE corner of intersection of Route 24 and Mulberry Knoll Road (284)
3. CURRENT CONDITION: excellent  good  fair  poor  demolished
4. INTEGRITY: Vinyl siding has been added; it also covers the brick chimney up to the roof line on the east façade.
5. SETTING INTEGRITY: The setting has not changed significantly.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
0	CRS 2 Main Building Form	
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: \_\_\_\_\_

Organization: McCormick Taylor, Inc. Date: May 2004

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-1007


9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
  
  - 1600-1750± Contact Period (Native American)
  - 1630-1730± Exploration and Frontier Settlement
  - 1730-1770± Intensified and Durable Occupation
  - 1770-1830± Early Industrialization
  - 1830-1880± Industrialization and Early Urbanization
  - 1880-1940± Urbanization and Early Suburbanization
  - 1940-1960± Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                       |
| <input type="checkbox"/> Forestry              | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting      | <input type="checkbox"/> Architecture, Engineering and Decorative Arts          |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                             |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                 |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY  
MAP FORM


CRS # S-1007

1. ADDRESS/LOCATION: 19634 Mulberry Knoll Road, Lewes, DE (3-34-12-112)
2. NOT FOR PUBLICATION  reason: \_\_\_\_\_
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH




4. SITE PLAN:

CRS # S-1007

INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-10119  
SPO Map 20-21-11  
Hundred Lewes & Rehoboth  
Quad Fairmount  
Other 3-34-12-37

- HISTORIC NAME/FUNCTION: Dwelling, NW corner of intersection of Route 24 and Mulberry Knoll Road
- ADDRESS/LOCATION: NW corner of intersection of Route 24 and Mulberry Knoll Road
- TOWN/NEAREST TOWN: Lewes vicinity?
- MAIN TYPE OF RESOURCE: building  structure  site  object   
landscape  district
- MAIN FUNCTION OF PROPERTY: dwelling
- PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 24 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
2	CRS 3 Secondary Building Form	Storage shed, office building
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: \_\_\_\_\_


Organization: McCormick Taylor, Inc. Date: May 2004

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
  - 1600-1750± Contact Period (Native American)
  - 1630-1730± Exploration and Frontier Settlement
  - 1730-1770± Intensified and Durable Occupation
  - 1770-1830± Early Industrialization
  - 1830-1880± Industrialization and Early Urbanization
  - 1880-1940± Urbanization and Early Suburbanization
  - 1940-1960± Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- |   |   |
|---|---|
| <input type="checkbox"/> Agriculture                      | <input type="checkbox"/> Transportation and Communication                       |
| <input type="checkbox"/> Forestry                         | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting                 | <input type="checkbox"/> Architecture, Engineering and Decorative Arts          |
| <input type="checkbox"/> Mining/Quarrying                 | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering                | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing                    | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling            | <input type="checkbox"/> Community Organizations                                |
| <input type="checkbox"/> Finance                          | <input type="checkbox"/> Occupational Organizations                             |
| <input checked="" type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                 |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-10119

1. ADDRESS/LOCATION: NW corner of intersection of Route 24 and Mulberry Knoll Road
2. FUNCTION(S): historic Single-family residential current Single-family residential
3. YEAR BUILT: 1910 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_
4. STYLE OR FLOOR PLAN: rectangular
5. INTEGRITY: original site  moved   
 if moved, from where \_\_\_\_\_ other location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known)

year

- a. \_\_\_\_\_  
 b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular Stories: 1 1/2  
 Additions: one-story addition to rear (west) façade; enclosed front porch
- b. Structural system (if known): light frame
- c. Foundation: materials: concrete block  
 basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible & any subsequent coverings): white aluminum siding
- e. Roof: shape: front gable  
 materials: asphalt shingles  
 cornice: n/a  
 dormers: n/a  
 chimney: location(s): exterior concrete block chimney centered on rear (west) facade

8. DESCRIPTION OF ELEVATIONS:


- a. Facade: Direction: E
- 1) Bays multiple
- 2) Windows multiple  
 fenestration regular  
 type paired aluminum windows flanking the porch and in the gable end; two windows on each façade of the porch  
 trim simple wood surrounds  
 shutters n/a

- Facade (cont'd)
- 3) Door(s) 1  
     location centered  
     type metal with blind bottom third and louvered glass upper  
     trim simple surround
- 4) Porch(es) enclosed hipped roof front entry porch centered on the façade, resting on concrete block piers at the exterior corners; door accessed via a short flight of wood steps with railings
- b. Side: Direction: N
- 1) Bays 3
- 2) Windows 3  
     fenestration irregular  
     type one larger window with 1/1 sash at east end; two windows w/4 horizontal lights at west end. Two-light horizontal windows visible at basement level.  
     trim simple wood surrounds  
     shutters n/a
- 3) Door(s) n/a  
     location  
     type  
     trim
- 4) Porch(es) n/a
- c. Side: Direction: S
- 1) Bays 3
- 2) Windows 3  
     fenestration regular  
     type 1/1 sash; two-light horizontal windows visible at basement level  
     trim simple wood surrounds  
     shutters n/a
- 3) Door(s) n/a  
     location  
     type  
     trim
- 4) Porch(es) n/a
- d. Rear: Direction: W
- 1) Bays 3
- 2) Windows 3  
     fenestration irregular  
     type paired windows with 1/1 sash in gable end; four-light horizontal windows on rear addition  
     trim simple wood surrounds  
     shutters n/a
- 3) Door(s) 1  
     location south end of rear addition  
     type nine-light upper portion; exterior metal door with large single light upper half  
     trim simple surround
- 4) Porch(es) n/a

## 9. INTERIOR:

10. LANDSCAPING: Bushes at the corners of the front porch and one along the north façade close to the house; scattered deciduous trees on the lot; bushes around the gambrel-roofed modern office building.

## 11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-10119

1. ADDRESS/LOCATION: NW corner of Route 24 and Mulberry Knoll Road

2. FUNCTION(S): historic office building current office building

3. YEAR BUILT: 1990 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site  moved

if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. \_\_\_\_\_

b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:

a. Structural system light frame

b. Number of stories 2

c. Wall coverings vinyl siding

d. Foundation not visible

e. Roof

structural system gambrel  
coverings asphalt shingles  
openings 4 skylights

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: E

1) bays: 3

2) windows: One window with 1/1 sash near south end; two skylights in lower roof slope.

3) door(s): Two doors on first floor, one at each end, with nine-light upper sections.

4) other: n/a

b. Side: direction: N

- 1) bays: 2
- 2) windows: Two windows with 1/1 sash on second story in gable end.
- 3) door(s): One door centered on first floor.
- 4) other: n/a

c. Side: direction: S

- 1) bays: not visible
- 2) windows: not visible
- 3) door(s): not visible
- 4) other: n/a

d. Rear: direction: W

- 1) bays: not visible
- 2) windows: not visible
- 3) door(s): not visible
- 4) other: n/a

9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-10119

1. ADDRESS/LOCATION: NW corner of intersection of Route 24 and Mulberry Knoll Road

2. FUNCTION(S): historic storage current storage

3. YEAR BUILT: 1985 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: rectangular prefabricated shed

5. INTEGRITY: original site  moved

if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. \_\_\_\_\_

b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:

a. Structural system light frame

b. Number of stories 1

c. Wall coverings vertical board siding

d. Foundation not visible

e. Roof

structural system gambrel with slightly overhanging eaves

coverings asphalt shingles

openings n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: N

1) bays: 1

2) windows: n/a

3) door(s): not visible

4) other: n/a

b. Side: direction: E

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: n/a

c. Side: direction: W

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: n/a

d. Rear: direction: S

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: n/a


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY  
MAP FORM


CRS # S-10119

1. ADDRESS/LOCATION: Northwest side of Route 24 at the intersection of Mulberry Knoll Road, Lewes, DE (3-34-12-37)
2. NOT FOR PUBLICATION  reason: \_\_\_\_\_
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map )

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-10120  
SPO Map 20-21-11  
Hundred Lewes & Rehoboth  
Quad Fairmount  
Other 3-34-12-36

1. HISTORIC NAME/FUNCTION: Dwelling, north side of Route 24 between Mulberry Knoll Road and Retz Lane
2. ADDRESS/LOCATION: North side of Route 24 between Mulberry Knoll Road and Retz Lane
3. TOWN/NEAREST TOWN: Lewes vicinity?
4. MAIN TYPE OF RESOURCE: building  structure  site  object   
landscape  district
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 24 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
1	CRS 3 Secondary Building Form	Storage shed
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis  
Principal Investigator name: Francine Arnold  
Principal Investigator signature: \_\_\_\_\_  
Organization: McCormick Taylor, Inc. Date: May 2004

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
  - 1600-1750± Contact Period (Native American)
  - 1630-1730± Exploration and Frontier Settlement
  - 1730-1770± Intensified and Durable Occupation
  - 1770-1830± Early Industrialization
  - 1830-1880± Industrialization and Early Urbanization
  - 1880-1940± Urbanization and Early Suburbanization
  - 1940-1960± Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                       |
| <input type="checkbox"/> Forestry              | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting      | <input type="checkbox"/> Architecture, Engineering and Decorative Arts          |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                             |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                 |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-10120

1. ADDRESS/LOCATION: North Side Of Route 24 Between Mulberry Knoll Road And Retz Lane

2. FUNCTION(S): historic single-family residential current single-family residential

3. YEAR BUILT: 1955 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE OR FLOOR PLAN: irregular

5. INTEGRITY: original site  moved   
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: irregular Stories: 1 1/2  
Additions:
- b. Structural system (if known): light frame
- c. Foundation: materials: concrete block  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible & any subsequent coverings): yellow vinyl siding
- e. Roof: shape: gable  
materials: asphalt shingles  
cornice: n/a  
dormers: n/a  
chimney: location(s): brick chimney centered in ridge of side-gabled front portion of the residence;  
second brick chimney located in ridge of front-gabled rear portion of the residence

8. DESCRIPTION OF ELEVATIONS:


- a. Facade: Direction: E
  - 1) Bays 3
  - 2) Windows 2
 fenestration regular  
type 1/1 vinyl sash  
trim simple vinyl surrounds  
shutters n/a

- Facade (cont'd)
- 3) Door(s) 1  
     location centered  
     type paneled bottom third with light above; exterior screen door  
     trim simple surround
- 4) Porch(es) Door is sheltered by a wide pedimented portico with slender corner support columns and accessed via a concrete block stoop with three steps.
- b. Side: Direction: N
- 1) Bays 6
- 2) Windows 5  
     fenestration regular  
     type 1/1 vinyl sash  
     trim simple vinyl surrounds  
     shutters n/a
- 3) Door(s) 1  
     location centered  
     type not visible  
     trim not visible
- 4) Porch(es) n/a
- c. Side: Direction: S
- 1) Bays 5+
- 2) Windows 5+  
     fenestration regular  
     type 1/1 sash; one window with 2/1 sash in gable end; windows with 4 horizontal lights at west end  
     trim simple surrounds  
     shutters n/a
- 3) Door(s) none visible  
     location  
     type  
     trim
- 4) Porch(es) n/a
- d. Rear: Direction: W
- 1) Bays 2
- 2) Windows paired  
     fenestration irregular  
     type paired window with 1/1 sash north of rear door  
     trim simple surround  
     shutters n/a
- 3) Door(s) 1  
     location south end of rear (west) facade  
     type paneled bottom, several lights on top; exterior metal and screen door  
     trim simple surround, small concrete stoop
- 4) Porch(es) n/a

## 9. INTERIOR:

10. LANDSCAPING: Small bushes and shrubs planted closely adjacent to the house on many facades but most noticeably at the front; scattered deciduous trees on the lot.

## 11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-10120

1. ADDRESS/LOCATION: North side of Route 24 between Mulberry Knoll Road and Retz Lane

2. FUNCTION(S): historic storage current storage

3. YEAR BUILT: 1980 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: square

5. INTEGRITY: original site  moved   
if moved, from where original location's CRS # year

list major alterations and additions with years (if known)

year

a.

b.

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:

a. Structural system prefabricated shed

b. Number of stories 1

c. Wall coverings vinyl

d. Foundation not visible

e. Roof  
structural system frame; gable  
coverings asphalt shingles  
openings n/a

8. DESCRIPTION OF ELEVATIONS:


a. Facade: direction: E

1) bays: 1

2) windows: n/a

3) door(s): one, centered

4) other: n/a



CULTURAL RESOURCE SURVEY  
MAP FORM


CRS # S-10120

1. ADDRESS/LOCATION: Northwest side of Route 24, west of the intersection with Mulberry Knoll Road, Lewes, DE (3-34-12-36)
2. NOT FOR PUBLICATION  reason: \_\_\_\_\_
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-10120

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-10121  
SPO Map 20-21-11  
Hundred Lewes & Rehoboth  
Quad Fairmount  
Other 3-34-12-35

1. HISTORIC NAME/FUNCTION: Dwelling, NE corner of intersection of Route 24 and Retz Lane
2. ADDRESS/LOCATION: North side of Route 24 between Retz Lane and Mulberry Knoll Road
3. TOWN/NEAREST TOWN: Lewes vicinity?
4. MAIN TYPE OF RESOURCE:      building       structure       site       object   
   landscape       district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 24 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
2	CRS 3 Secondary Building Form	Storage sheds
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: \_\_\_\_\_

Organization: McCormick Taylor, Inc. Date: May 2004

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750± Contact Period (Native American)
- 1630-1730± Exploration and Frontier Settlement
- 1730-1770± Intensified and Durable Occupation
- 1770-1830± Early Industrialization
- 1830-1880± Industrialization and Early Urbanization
- 1880-1940± Urbanization and Early Suburbanization
- 1940-1960± Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                       |
| <input type="checkbox"/> Forestry              | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting      | <input type="checkbox"/> Architecture, Engineering and Decorative Arts          |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                             |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                 |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-10121

1. ADDRESS/LOCATION: NE corner of intersection of Route 24 and Retz Lane
2. FUNCTION(S): historic Single-family dwelling current Single-family dwelling
3. YEAR BUILT: 1955 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_
4. STYLE OR FLOOR PLAN: Ranch
5. INTEGRITY: original site  moved   
 if moved, from where \_\_\_\_\_ other location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_

a. \_\_\_\_\_

b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular Stories: 1  
Additions:
- b. Structural system (if known): light frame
- c. Foundation: materials: concrete block  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible & any subsequent coverings): white vinyl siding
- e. Roof: shape: side gable w/overhanging eaves  
materials: asphalt shingles  
cornice: n/a  
dormers: n/a  
chimney: location(s): n/a

8. DESCRIPTION OF ELEVATIONS:


- a. Facade: Direction: E
- |            |   |
|------------|---|
| 1) Bays    | 5 |
| 2) Windows | 3 |
- fenestration irregular  
 type 2 windows w/4 horizontal lights south of door; tripartite picture window north of door  
 trim metal awnings  
 shutters red louvered

- Facade (cont'd)
- 3) Door(s) 2  
location main entry south of center; garage door at north end  
type paneled w/4 transom lights in door; overhead garage door with 4 lights  
trim full-length shutters flanking main door
- 4) Porch(es) n/a
- b. Side: Direction: S
- 1) Bays 2
- 2) Windows 2  
fenestration regular  
type four horizontal lights  
trim simple surrounds  
shutters red louvered
- 3) Door(s) n/a  
location  
type  
trim
- 4) Porch(es) n/a
- c. Side: Direction: N
- 1) Bays not visible
- 2) Windows  
fenestration  
type  
trim  
shutters
- 3) Door(s) n/a  
location  
type  
trim
- 4) Porch(es) n/a
- d. Rear: Direction: W
- 1) Bays 8
- 2) Windows 7  
fenestration regular  
type six with 1/1 sash on rear addition; one with four horizontal lights at south end  
trim simple surrounds  
shutters n/a
- 3) Door(s) 1  
location north end  
type one large (2/3) light, exterior screen door  
trim simple surround
- 4) Porch(es) n/a

## 9. INTERIOR:

10. LANDSCAPING: Scattered bushes, many planted directly adjacent to house on front and side facades; some deciduous and evergreen trees on perimeter of lot. Fenced dog run at rear of residence.

## 11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-10121

1. ADDRESS/LOCATION: NE corner of intersection of Route 24 and Retz Lane

2. FUNCTION(S): historic Storage current storage

3. YEAR BUILT: 1985 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: Rectangular prefabricated shed

5. INTEGRITY: original site  moved

if moved, from where

original location's CRS # year

list major alterations and additions with years (if known)

year

a.

b.

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:

a. Structural system wood frame

b. Number of stories 1

c. Wall coverings vertical board

d. Foundation resting on concrete block

e. Roof

structural system gambrel

coverings asphalt shingle

openings n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: E

1) bays: 1

2) windows: n/a

3) door(s): two barn-style centered on facade

4) other: n/a

- b. Side: direction: N
  - 1) bays: n/a
  - 2) windows: n/a
  - 3) door(s): n/a
  - 4) other: n/a

- c. Side: direction: S
  - 1) bays: n/a
  - 2) windows: n/a
  - 3) door(s): n/a
  - 4) other: n/a

- d. Rear: direction: W
  - 1) bays: n/a
  - 2) windows: n/a
  - 3) door(s): n/a
  - 4) other: n/a


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-10121

1. ADDRESS/LOCATION: NE corner of intersection of Route 24 and Retz Lane

2. FUNCTION(S): historic storage current storage

3. YEAR BUILT: 1985 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site  moved

if moved, from where

original location's CRS # year

list major alterations and additions with years (if known)

year

a. \_\_\_\_\_

b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:

a. Structural system metal

b. Number of stories 1

c. Wall coverings seamed metal

d. Foundation not visible

e. Roof

structural system metal, gable

coverings standing seam metal

openings n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: E

1) bays: 1

2) windows: n/a

3) door(s): centered double doors

4) other: n/a

**b. Side: direction: N**

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: n/a

**c. Side: direction: S**

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: n/a

**d. Rear: direction: W**

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: n/a


**9. INTERIOR (if accessible):**

**a) Floor plan**

**b) Partition/walls**

**c) Finishes**

**d) Furnishings/machinery**



CULTURAL RESOURCE SURVEY  
MAP FORM

CRS # S-10121

1. ADDRESS/LOCATION: 1 Retz Lane, Lewes, DE (3-34-12-35)


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map )

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-10122  
SPO Map 20-21-11  
Hundred Lewes & Rehoboth  
Quad Fairmount  
Other 3-34-12-81

1. HISTORIC NAME/FUNCTION: Dwelling, 19058 Route 24
2. ADDRESS/LOCATION: 19058 Route 24, northeast corner of intersection of Route 24 and Plantation Road
3. TOWN/NEAREST TOWN: Lewes vicinity?
4. MAIN TYPE OF RESOURCE:      building       structure       site       object   
   landscape       district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 24 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
1	CRS 3 Secondary Building Form	Garage
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: \_\_\_\_\_

Organization: McCormick Taylor, Inc. Date: May 2004

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750± Contact Period (Native American)
- 1630-1730± Exploration and Frontier Settlement
- 1730-1770± Intensified and Durable Occupation
- 1770-1830± Early Industrialization
- 1830-1880± Industrialization and Early Urbanization
- 1880-1940± Urbanization and Early Suburbanization
- 1940-1960± Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                       |
| <input type="checkbox"/> Forestry              | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting      | <input type="checkbox"/> Architecture, Engineering and Decorative Arts          |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                             |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                 |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-10122

1. ADDRESS/LOCATION: 19058 Route 24, NE corner of intersection of Route 24 and Plantation Road
2. FUNCTION(S): historic Single-family residential current Single-family residential
3. YEAR BUILT: 1955 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_
4. STYLE OR FLOOR PLAN: Ranch
5. INTEGRITY: original site  moved   
if moved, from where \_\_\_\_\_ other location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known)

year

a.

b.

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular Stories: 1  
Additions: shed-roofed rear porch
- b. Structural system (if known): light frame
- c. Foundation: materials: concrete block  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible & any subsequent coverings): white aluminum siding
- e. Roof: shape: side gable with overhanging eave  
materials: asphalt shingles  
cornice: n/a  
dormers: n/a  
chimney: location(s): stone chimney in rear slope of roof, slightly south of center

8. DESCRIPTION OF ELEVATIONS:


- a. Facade: Direction: E
- |    |         |   |
|----|---------|---|
| 1) | Bays    | 4 |
| 2) | Windows | 3 |
- fenestration irregular  
type tripartite picture window at south end; multi-light bay window south of door  
underneath porch; paired windows north of door  
trim simple surrounds, metal awnings  
shutters louvered

- Facade (cont'd)
- 3) Door(s) 1
    - location north of center, beneath porch
    - type paneled with exterior storm door
    - trim simple surround
  - 4) Porch(es) shed-roofed open porch with wrought iron corner supports sheltering entry and bay window; accessed via short flight of steps with metal railing
- b. Side: Direction: S
- 1) Bays 1
  - 2) Windows 1
    - fenestration regular
    - type 1/1 sash
    - trim simple surround; metal awning
    - shutters louvered
  - 3) Door(s) n/a
    - location
    - type
    - trim
  - 4) Porch(es) n/a
- c. Side: Direction: N
- 1) Bays not visible
  - 2) Windows
    - fenestration
    - type
    - trim
    - shutters
  - 3) Door(s) n/a
    - location
    - type
    - trim
  - 4) Porch(es) n/a
- d. Rear: Direction: W
- 1) Bays 3
  - 2) Windows 2
    - fenestration regular
    - type 1/1 sash
    - trim simple surrounds; metal awnings
    - shutters louvered
  - 3) Door(s) not visible
    - location
    - type
    - trim
  - 4) Porch(es) large shed-roofed screen porch on concrete slab, centered on facade

## 9. INTERIOR:

10. LANDSCAPING: Bushes planted closely adjacent to house and in yard; evergreen trees clustered at north and west perimeter; scattered deciduous trees at sides.

## 11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-10122

1. ADDRESS/LOCATION: 519 Plantation Road, NE corner of intersection of Route 24 and Plantation Road
2. FUNCTION(S): historic garage current garage
3. YEAR BUILT: 1955 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_
4. STYLE/FLOOR PLAN: square
5. INTEGRITY: original site  moved   
if moved, from where original location's CRS # year

list major alterations and additions with years (if known)

year

a.  
b.

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:

- a. Structural system light frame
- b. Number of stories 1
- c. Wall coverings white vinyl siding
- d. Foundation not visible
- e. Roof  
structural system front gable  
coverings asphalt shingles  
openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S  
1) bays: 2  
2) windows: n/a  
3) door(s): 2 overhead garage doors  
4) other: n/a

- b. Side: direction: E
  - 1) bays: 2
  - 2) windows: one at west end of the façade; details not visible
  - 3) door(s): one pedestrian entry at east end of the façade; simple surround
  - 4) other: n/a
  
- c. Side: direction: W
  - 1) bays: not visible
  - 2) windows: not visible
  - 3) door(s): not visible
  - 4) other: n/a
  
- d. Rear: direction: S
  - 1) bays: not visible
  - 2) windows: not visible
  - 3) door(s): not visible
  - 4) other: n/a


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY  
MAP FORM


CRS # S-10122

1. ADDRESS/LOCATION: Northwest side of Route 24, at the intersection of Plantation Road, Lewes, DE (3-34-12-81)
2. NOT FOR PUBLICATION  reason: \_\_\_\_\_
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN

