


APPENDIX A: Delaware CRS Forms



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-8145

1. HISTORIC NAME/FUNCTION: Dwelling, Box 121, South Side Of Route 54, East Of Sound Church Road (394A)

2. ADDRESS/LOCATION: South Side Of Route 54, East Of Sound Church Road (394A)

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: None

5. SETTING INTEGRITY: N/A

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
2	CRS 3 Secondary Building Form	Barn and chicken house
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Katie Diehl

Principal Investigator name: Francine Arnold

Principal Investigator signature: _____

Organization: Mc Cormick Taylor, Inc. Date: June 2004

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-8145

Based on field survey in June 2004, this resource (S-8145) was demolished.


9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750" Contact Period (Native American)
 - 1630-1730" Exploration and Frontier Settlement
 - 1730-1770" Intensified and Durable Occupation
 - 1770-1830" Early Industrialization
 - 1830-1880" Industrialization and Early Urbanization
 - 1880-1940" Urbanization and Early Suburbanization
 - 1940-1960" Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-8145
SPO Map 20-21-05
Hundred Baltimore
Quad Assawoman Bay
Other 5-33-19-17.02

1. HISTORIC NAME/FUNCTION: Dwelling, Box 121, south side of Route 54 east of Sound Church Road (394A)
2. ADDRESS/LOCATION: South side of Route 54 east of Sound Church Road (394A)
3. TOWN/NEAREST TOWN: Williamsville vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
 landscape district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 54 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
2	CRS 3 Secondary Building Form	Barn, chicken house
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: _____

Organization: McCormick Taylor, Inc. Date: January 2003 (Revised April 2004)

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-8145

The CRS number for this resource was previously assigned during the Beach Access Project survey conducted by KFS in 1989. The survey was never completed or submitted to the DE SHPO. However, the DE SHPO requested that the CRS number be used so as not to duplicate resources.

At the time of survey, this property was being prepared for demolition.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):


- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750" Contact Period (Native American)
 - 1630-1730" Exploration and Frontier Settlement
 - 1730-1770" Intensified and Durable Occupation
 - 1770-1830" Early Industrialization
 - 1830-1880" Industrialization and Early Urbanization
 - 1880-1940" Urbanization and Early Suburbanization
 - 1940-1960" Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-8145

1. ADDRESS/LOCATION: Box 121, south side of Route 54 east of Sound Church Road (394A)
2. FUNCTION(S): historic Single-family residential current Single-family residential
3. YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER: _____
4. STYLE OR FLOOR PLAN: Colonial Revival
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

- a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangular Stories: 1 1/2
Additions: rear porch
- b. Structural system (if known): light frame
- c. Foundation: materials: concrete
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings):
- e. Roof: shape: gable
materials: wood shingles
cornice: simple enclosed with returns
dormers: n/a
chimney: location(s): brick chimney in ridge at west end

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: N
- | | | |
|----|---------|---|
| 1) | Bays | 4 |
| 2) | Windows | 3 |
- fenestration irregular
type paired windows with 6/1 sash flanking door; smaller window with geometric pattern
muntins at west end
trim simple surrounds
shutters single piece of wood with three raised squares

Facade (cont'd)

- 3) **Door(s)** 1
 location centered
 type missing
 trim simple surround and sidelights
- 4) **Porch(es)** open gable-roofed portico with paired support columns and a brick stoop

b. Side: Direction: W

- 1) **Bays** 4
- 2) **Windows** 3
 fenestration irregular
 type windows on porch extension have 6/1 sash; smaller gable has round window in gable end; larger gable has window with 6/1 sash in gable end and paired windows w/6/1 sash and awning on first floor
 trim simple surrounds; awning over porch windows
 shutters as on main façade; present on windows of larger gable; some missing
- 3) **Door(s)** 1
 location centered on porch
 type glass louvered top; exterior storm door
 trim simple surround
- 4) **Porch(es)** enclosed sun porch at north end; windows of porch wrap around to west end of front (north) facade

c. Side: Direction: E

- 1) **Bays** 2
- 2) **Windows** 3
 fenestration regular
 type paired windows in gable end
 trim simple surrounds
 shutters as on other facades; some missing
- 3) **Door(s)** n/a
 location
 type
 trim
- 4) **Porch(es)** n/a


d. Rear: Direction: S

- 1) **Bays** 4
- 2) **Windows** 3
 fenestration regular
 type 6/1 double-hung sash; some missing; glass louvered windows on porch
 trim simple surrounds
 shutters n/a
- 3) **Door(s)** 1
 location centered on porch addition; accessed via short flight of wood steps
 type missing; exterior storm door
 trim simple surround
- 4) **Porch(es)** enclosed flat-roofed porch addition at west end

9. INTERIOR:

10. **LANDSCAPING:** Bushes closely adjacent to house on front and side facades; scattered shrubs in rear yard; wooded perimeter of lot.

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-8145

1. ADDRESS/LOCATION: Box 121, south side of Route 54 east of Sound Church Road

2. FUNCTION(S): historic barn current storage

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system frame
b. Number of stories 2
c. Wall coverings asbestos shingles
d. Foundation not visible
e. Roof
structural system gable with exposed rafter ends
coverings asphalt shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: N
1) bays: 3
2) windows: one centered hay loft opening above doors
3) door(s): two large openings on ground level; doors missing
4) other:

- b. Side: direction: W
 - 1) bays: 1
 - 2) windows: n/a
 - 3) door(s): one pedestrian opening at south end; door missing
 - 4) other:

- c. Side: direction: E
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:

- d. Rear: direction: S
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-8145

1. ADDRESS/LOCATION: Box 121, south side of Route 54 east of Sound Church Road (394A)

2. FUNCTION(S): historic Barn/storage current storage

3. YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: square

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system frame
b. Number of stories 1
c. Wall coverings wood clapboard
d. Foundation not visible
e. Roof
structural system hipped; exposed rafter ends
coverings wood shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: N
1) bays: 1
2) windows: n/a
3) door(s): large opening with paneled sliding barn-style door
4) other:

- b. Side: direction: E
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:

- c. Side: direction: W
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:

- d. Rear: direction: S
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-8145

1. ADDRESS/LOCATION: South Side of Rt. 54 at the intersection of Zion Church Rd (TP 5-33-19-17.02)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-8145

INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-8145 Date 1/16/03 Photo Roll # 1 Surveyor Jennifer M. Holl/Katie Diehl

Description (1) Lateral view of residence, facing southwest; (2) Lateral view of residence, facing east; (3) Lateral view of residence, facing northwest; (4) Lateral view of small barn and vehicular garage, facing southeast

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-8145 Date 1/16/03 Photo Roll # 1 Surveyor Jennifer M. Holl/Katie Diehl

Description (5) Lateral view of small barn and vehicular garage, facing northeast; (6) Lateral view of chicken house, facing northeast; (7) Lateral view of chicken house, facing north; (8) Lateral view of chicken house, facing southwest


Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10123
SPO Map 20-21-05
Hundred Baltimore
Quad Assawoman Bay
Other 5-33-19-18

1. HISTORIC NAME/FUNCTION: Dwelling, south side of Route 54 opposite Old Mill Bridge Road (381)
2. ADDRESS/LOCATION: South side of Route 54 opposite Old Mill Bridge Road (381)
3. TOWN/NEAREST TOWN: Williamsville vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
 landscape district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 54 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
2	CRS 3 Secondary Building Form	Garage, chicken house
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: _____

Organization: McCormick Taylor, Inc. Date: January 2003 (Revised April 2004)

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-10123

The CRS number for this resource was previously assigned during the Beach Access Project survey conducted by KFS in 1989. The survey was never completed or submitted to the DE SHPO. However, the DE SHPO requested that the CRS number be used so as not to duplicate resources.

At the time of survey, this property was being prepared for demolition.


10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750" Contact Period (Native American)
 - 1630-1730" Exploration and Frontier Settlement
 - 1730-1770" Intensified and Durable Occupation
 - 1770-1830" Early Industrialization
 - 1830-1880" Industrialization and Early Urbanization
 - 1880-1940" Urbanization and Early Suburbanization
 - 1940-1960" Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10123

1. ADDRESS/LOCATION: South side of Route 54 opposite Old Mill Bridge Road (381)

2. FUNCTION(S): historic Single-family residential current Single-family residential

3. YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: Ranch

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. shed-roofed rear screen porch

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1
Additions: shed-roofed screen porch at west end of rear (south) facade

b. Structural system (if known): light frame

c. Foundation: materials: concrete
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): blue aluminum siding

e. Roof: shape: gable with overhanging eave
materials: asphalt shingles
cornice: n/a
dormers: n/a
chimney: location(s): wide exterior brick chimney at north end of side (west) facade

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: N
1) Bays 4
2) Windows 3
fenestration irregular
type window with 1/1 sash at east end; paired windows, one with 8/1 one with 1/1 east of door; tripartite picture window west of door
trim simple surrounds; siding below windows painted to match extended shutters
shutters blue louvered; shutters extend below window sills

Facade (cont'd)

3) **Door(s)** 1
 location slightly west of center
 type solid with raised molding designs and small light at top center
 trim simple surround; sidelights on west side; brick steps and stoop

4) **Porch(es)** n/a

b. Side: Direction: W

1) **Bays** 1

2) **Windows** 1

fenestration regular

type 1/1 sash

trim simple surround; siding below painted to match extended shutters

shutters blue louvered; shutters extend below window sills

3) **Door(s)** n/a

location

type

trim

4) **Porch(es)**

c. Side: Direction: E

1) **Bays** not visible

2) **Windows**

fenestration

type

trim

shutters

3) **Door(s)**

location

type

trim

4) **Porch(es)**

d. Rear: Direction: S

1) **Bays** 1

2) **Windows** n/a

fenestration

type

trim

shutters

3) **Door(s)** n/a

location

type


trim

4) **Porch(es)** shed-roofed screen porch addition on west end extends approximately 2/3 the length of the façade; portions of screen missing

9. INTERIOR:

10. **LANDSCAPING:** Small bushes planted closely adjacent to house on front and side facades; wooded rear of lot, one tree in front yard.

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10123

1. ADDRESS/LOCATION: South side of Route 54 opposite Old Mill Bridge Road (381)

2. FUNCTION(S): historic garage current garage/storage

3. YEAR BUILT: 1960 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system frame
b. Number of stories 1
c. Wall coverings aluminum siding
d. Foundation concrete
e. Roof
structural system gable
coverings metal
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: W
1) bays: 1
2) windows: n/a
3) door(s): large opening (two-car accommodation); door missing
4) other: _____

- b. Side: direction: N
 - 1) bays: 1
 - 2) windows: one window with 1/1 sash centered on facade
 - 3) door(s): n/a
 - 4) other:

- c. Side: direction: S
 - 1) bays: 1
 - 2) windows: one window with 1/1 sash centered on facade
 - 3) door(s): n/a
 - 4) other:

- d. Rear: direction: E
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10123

1. ADDRESS/LOCATION: South side of Route 54 opposite Old Mill Bridge Road (381)

2. FUNCTION(S): historic chicken house current storage

3. YEAR BUILT: 1935 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system frame
- b. Number of stories 1
- c. Wall coverings wood clapboard
- d. Foundation resting on concrete block piers
- e. Roof
structural system shed roof with exposed rafters
coverings not visible
openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: N
 - 1) bays: 3
 - 2) windows: two open square windows east of door
 - 3) door(s): wood batten door at west end
 - 4) other: _____

- b. Side: direction: E
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:

- c. Side: direction: W
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:

- d. Rear: direction: S
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10123

1. ADDRESS/LOCATION: South Side of Rt. 54 at the intersection with Old Mill Bridge Road (TP S-33-19-18)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-10123

INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-10123 Date 1/16/03 Photo Roll # 1 Surveyor Jennifer M. Holl/Katie Diehl

Description (1) Lateral view of residence, facing southeast; (2) Lateral view of residence and garage, facing northeast; (3) Lateral view of chicken house, facing northeast

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10028
SPO Map 20-21-05
Hundred Baltimore
Quad Assawoman Bay
Other 5-33-12-75

1. HISTORIC NAME/FUNCTION: Dwelling, north side of Route 54 east of Old Mill Bridge Road (381)
2. ADDRESS/LOCATION: North side of Route 54 east of Old Mill Bridge Road (381)
3. TOWN/NEAREST TOWN: Williamsville vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
landscape district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 54 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
1	CRS 3 Secondary Building Form	Garage
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: _____


Organization: McCormick Taylor, Inc. Date: January 2003 (Revised April 2004)

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750" Contact Period (Native American)
 - 1630-1730" Exploration and Frontier Settlement
 - 1730-1770" Intensified and Durable Occupation
 - 1770-1830" Early Industrialization
 - 1830-1880" Industrialization and Early Urbanization
 - 1880-1940" Urbanization and Early Suburbanization
 - 1940-1960" Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10028

1. ADDRESS/LOCATION: North side of Route 54 east of Old Mill Bridge Road (381)

2. FUNCTION(S): historic Single-family residential current Single-family residential

3. YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1
Additions: gable-roofed one-room addition to east facade

b. Structural system (if known): light frame

c. Foundation: materials: concrete
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): white vinyl siding

e. Roof: shape: side gable
materials: asphalt shingles
cornice: simple closed
dormers: n/a
chimney: location(s): brick chimney slightly west of center in rear slope of roof

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: S
1) Bays 3
2) Windows 2
fenestration regular
type tripartite picture windows with single center light and double flanking lights
trim simple surrounds
shutters green louvered

Facade (cont'd)

- 3) Door(s) 1
 location centered; accessed via short flight of brick stairs and stoop w/metal railing
 type solid with exterior storm door
 trim simple surround

- 4) Porch(es) n/a

b. Side: Direction: E

- 1) Bays 3
 2) Windows 2
 fenestration irregular
 type paired windows w/4 horizontal lights south of door; single window with same details but only one shutter east of door
 trim simple surrounds

shutters green louvered; window north of door is missing south shutter (too close to door for it to fit)

- 3) Door(s) 1
 location north of center; accessed via concrete steps and stoop w/metal railing
 type paneled with incorporated fanlight and exterior storm door
 trim simple surround

- 4) Porch(es) n/a

c. Side: Direction: W

- 1) Bays not visible

- 2) Windows
 fenestration
 type
 trim
 shutters

- 3) Door(s)
 location
 type
 trim

- 4) Porch(es)

d. Rear: Direction: N

- 1) Bays 4

- 2) Windows 4
 fenestration irregular
 type four windows with 1/1 sash as on other facades; one smaller window with 1/1 sash
 trim simple surrounds
 shutters green louvered; easternmost is missing shutter on east side


- 3) Door(s) n/a
 location
 type
 trim

- 4) Porch(es) n/a

9. INTERIOR:

10. LANDSCAPING: Bushes planted in close proximity to house along length of front façade and scattered on other facades. One tree to the rear of the residence near the garage; another small tree along east façade of garage.

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10028

1. ADDRESS/LOCATION: North side of Route 54 east of Old Mill Bridge Road (381)

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: square

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system light frame
b. Number of stories 1
c. Wall coverings white vinyl siding
d. Foundation concrete
e. Roof
structural system side gable with overhanging eave
coverings asphalt shingles
openings ventilation chimney in rear (north) slope

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: S
1) bays: 2
2) windows: full-length glass sliding windows west of overhead door
3) door(s): overhead garage door at east end
4) other: _____

- b. Side: direction: E
 - 1) bays: 1
 - 2) windows: small rectangular louvered vent in gable end
 - 3) door(s): overhead garage door at north end
 - 4) other:

- c. Side: direction: W
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:

- d. Rear: direction: S
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10028

1. ADDRESS/LOCATION: North Side of Rt. 54, just east of Old Mill Bridge Road (TP 5-33-12-75)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-10028 Date 1/16/03 Photo Roll # 1 Surveyor Jennifer M. Holl/Katie Diehl

Description (1) Lateral view of residence, facing northeast; (2) Lateral view of shed, facing northwest; (3) Lateral view of modern shed and tent structure, facing north; (4) Elevation of rear façade of residence, facing south; (5) Lateral view of residence, facing northwest


Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10029
SPO Map 20-21-05
Hundred Baltimore
Quad Assawoman Bay
Other 5-33-12-77

1. HISTORIC NAME/FUNCTION: Dwelling, north side of Route 54 east of Old Mill Bridge Road (381)
2. ADDRESS/LOCATION: North side of Route 54 east of Old Mill Bridge Road (381)
3. TOWN/NEAREST TOWN: Williamsville vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
 landscape district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 54 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
2	CRS 3 Secondary Building Form	Outbuildings (former chicken house; storage shed)
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: _____


Organization: McCormick Taylor, Inc. Date: January 2003 (Revised April 2004)

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750" Contact Period (Native American)
 - 1630-1730" Exploration and Frontier Settlement
 - 1730-1770" Intensified and Durable Occupation
 - 1770-1830" Early Industrialization
 - 1830-1880" Industrialization and Early Urbanization
 - 1880-1940" Urbanization and Early Suburbanization
 - 1940-1960" Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10029

1. ADDRESS/LOCATION: North side of Route 54 east of Old Mill Bridge Road (381)
2. FUNCTION(S): historic Single-family residential current Single-family residential
3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____
4. STYLE OR FLOOR PLAN: Minimal Traditional
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known)

year

- a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: L-shaped Stories: 1 1/2
Additions: shed-roofed rear addition
- b. Structural system (if known): light frame
- c. Foundation: materials: rough-faced concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): light yellow aluminum siding
- e. Roof: shape: cross-gable with overhanging eaves
materials: asphalt shingles
cornice: simple enclosed
dormers: n/a
chimney: location(s): exterior concrete block chimney, painted white, at north end of east facade

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: S
- | | |
|------------|---|
| 1) Bays | 5 |
| 2) Windows | 3 |
- fenestration irregular
type hipped-roof porch has two windows with three horizontal lights and smaller window with 1/1 sash in gable end; shed-roofed porch has bay window with six vertical lights
trim simple surrounds
shutters n/a

Facade (cont'd)

- 3) Door(s) 2
location centered on hipped-roof porch and west of bay window on shed-roofed porch
type paneled w/3 diagonal lights at top and exterior storm doors
trim simple surrounds
- 4) Porch(es) At west end, projecting from cross-gable, is an enclosed hipped-roof porch with a central door accessed via a short double flight of concrete block steps with metal railing. At east end, the side gable extends out to form a shed-roofed porch with wrought iron supports sheltering an entry and a bay window.
- b. Side: Direction: W
- 1) Bays 4
- 2) Windows 4
fenestration irregular
type two windows with two vertical single lights on main portion; one window with three horizontal lights on hipped-roof front porch; small horizontal rectangular light on rear addition
trim simple surrounds
shutters n/a
- 3) Door(s) n/a
location
type
trim
- 4) Porch(es) n/a
- c. Side: Direction: E
- 1) Bays 2
- 2) Windows 2
fenestration irregular
type window with two vertical single lights on first floor; smaller window with 1/1 sash in gable end; small horizontal basement window
trim simple surrounds
shutters n/a
- 3) Door(s) n/a
location
type
trim
- 4) Porch(es) n/a
- d. Rear: Direction: N; not visible
- 1) Bays
- 2) Windows
fenestration
type
trim
shutters
- 3) Door(s)
location
type
trim
- 4) Porch(es)


9. INTERIOR:

10. LANDSCAPING: Various bushes and plantings around perimeter of house in close proximity; wooded rear lot and scattered trees and bushes in front and on sides.

11. OTHER COMMENTS:

USE BLACK INK ONLY

CRS-2



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10029

1. ADDRESS/LOCATION: North side of Route 54 east of Old Mill Bridge Road (381)

2. FUNCTION(S): historic chicken house current storage

3. YEAR BUILT: 1935 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: square

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system frame
b. Number of stories 1
c. Wall coverings board; red
d. Foundation not visible
e. Roof
structural system shed
coverings metal
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: E
1) bays: 3
2) windows: small rectangular window south of door; window with 1/1 sash north of door
3) door(s): battened Dutch door centered on facade
4) other: _____

- b. Side: direction: S
 - 1) bays: 1
 - 2) windows: n/a
 - 3) door(s): battened Dutch door at east end
 - 4) other:

- c. Side: direction: N; not visible
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: W
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10029

1. ADDRESS/LOCATION: North side of Route 54 east of Old Mill Bridge Road (381)

2. FUNCTION(S): historic Storage shed current Storage shed

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system frame
b. Number of stories 1
c. Wall coverings vertical board siding; red
d. Foundation not visible
e. Roof
structural system gambrel
coverings asphalt shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: S
1) bays: 1
2) windows: n/a
3) door(s): large double battened doors
4) other: _____

- b. Side: direction: E
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:

- c. Side: direction: W
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:

- d. Rear: direction: N
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10029

1. ADDRESS/LOCATION: North Side of Rt. 54, east of Old Mill Bridge Road (TP 5-33-12-77)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-10029

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-10029 Date 1/16/03 Photo Roll # 1 Surveyor Jennifer M. Holl/Katie Diehl

Description (1) Elevation of front façade of residence, facing northeast; (2) Lateral view of garage, facing northwest; (3) Lateral view of residence, facing west


Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-8146
SPO Map 20-21-05
Hundred Baltimore
Quad Assawoman Bay
Other 5-33-12-78

1. HISTORIC NAME/FUNCTION: Dwelling, north side of Route 54 east of Old Mill Bridge Road (381)
2. ADDRESS/LOCATION: North side of Route 54 east of Old Mill Bridge Road (381)
3. TOWN/NEAREST TOWN: Fenwick Island vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
 landscape district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 54 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
4	CRS 3 Secondary Building Form	Outbuildings (storage)
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: _____

Organization: McCormick Taylor, Inc. Date: January 2003 (Revised April 2004)

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-8146

The CRS number for this resource was previously assigned during the Beach Access Project survey conducted by KFS in 1989. The survey was never completed or submitted to the DE SHPO. However, the DE SHPO requested that the CRS number be used so as not to duplicate resources.

One of the associated outbuildings, a machine storage shed, appears to lie on an adjacent tax parcel but to be historically associated with this property; therefore, a secondary building form (CRS-3) has been included for this outbuilding.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750" Contact Period (Native American)
 - 1630-1730" Exploration and Frontier Settlement
 - 1730-1770" Intensified and Durable Occupation
 - 1770-1830" Early Industrialization
 - 1830-1880" Industrialization and Early Urbanization
 - 1880-1940" Urbanization and Early Suburbanization
 - 1940-1960" Suburbanization and Early Ex-urbanization


- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY

CRS-1



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-8146

1. ADDRESS/LOCATION: North side of Route 54 east of Old Mill Bridge Road (381)

2. FUNCTION(S): historic Single-family residential current Single-family residential

3. YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular Stories: 1 1/2
Additions: shed-roofed addition to rear (south) facade
- b. Structural system (if known): light frame
- c. Foundation: materials: rough-faced concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): light green asbestos shingles
- e. Roof: shape: side gable with overhanging eaves
materials: asphalt shingles
cornice: simple closed
dormers: n/a
chimney: location(s): brick chimney in rear (south) slope of roof west of center

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: S
 - 1) Bays 3
 - 2) Windows 2
 - fenestration regular
 - type paired windows with 6/1 double-hung sash to each side of the door
 - trim simple vinyl surrounds
 - shutters n/a

Facade (cont'd)

- 3) **Door(s)** 1
 location centered on facade
 type large double sliding glass door accessed via 3 concrete block steps
 trim simple surround
- 4) **Porch(es)** door is located in an enclosed front-gabled entry portico

b. Side: Direction: W

- 1) **Bays** 3
- 2) **Windows** 4
 fenestration irregular
 type two large flanking one small window with 6/1 sash on first floor; paired window with 6/1 centered in gable end
 trim simple vinyl surrounds
 shutters n/a
- 3) **Door(s)** n/a
 location
 type
 trim
- 4) **Porch(es)** n/a

c. Side: Direction: E; not visible

- 1) **Bays**
- 2) **Windows**
 fenestration
 type
 trim
 shutters
- 3) **Door(s)**
 location
 type
 trim
- 4) **Porch(es)**


d. Rear: Direction: N

- 1) **Bays** 4
- 2) **Windows** 2
 fenestration regular
 type two windows with 6/1 sash at west end
 trim simple vinyl surrounds
 shutters n/a
- 3) **Door(s)** 2
 location one now-unused door centered on façade; one at west end of shed-roofed addition
 type unused door has twelve blind lights; door in addition
 trim simple surrounds
- 4) **Porch(es)** addition to east end of façade has wood deck and ramp (covering concrete steps leading to door)

9. INTERIOR:

10. **LANDSCAPING:** Scattered bushes planted close to perimeter of house; rear edge of lot and surroundings have scattered deciduous trees.

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-8146

1. ADDRESS/LOCATION: North side of Route 54 east of Old Mill Bridge Road (381)

2. FUNCTION(S): historic storage current storage

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system concrete block
b. Number of stories 1
c. Wall coverings n/a
d. Foundation not visible
e. Roof
structural system gable with exposed rafters; frame
coverings asphalt shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: E
1) bays: 1
2) windows: n/a
3) door(s): vertical board door with simple surround centered on facade
4) other: wood clapboard in gable end

- b. Side: direction: S
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:

- c. Side: direction: N
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:

- d. Rear: direction: W
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-8146

1. ADDRESS/LOCATION: North side of Route 54 east of Old Mill Bridge Road (381)

2. FUNCTION(S): historic garage/storage current garage/storage

3. YEAR BUILT: 1945 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: square

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system frame

b. Number of stories 1

c. Wall coverings wood clapboard on rear façade; asphalt shingles in stone pattern on others

d. Foundation not visible

e. Roof
structural system gable with board fascia and exposed rafter ends
coverings asphalt shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S
1) bays: 1
2) windows: n/a
3) door(s): full-width horizontal sliding wood doors
4) other: _____

- b. Side: direction: E
 - 1) bays: 1
 - 2) windows: one window opening centered on façade; now blind
 - 3) door(s): n/a
 - 4) other:

- c. Side: direction: W
 - 1) bays: 1
 - 2) windows: one window opening centered on façade; now blind
 - 3) door(s): n/a
 - 4) other:

- d. Rear: direction: N
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-8146

1. ADDRESS/LOCATION: North side of Route 54 east of Old Mill Bridge Road (381)

2. FUNCTION(S): historic agricultural/storage current storage

3. YEAR BUILT: 1945 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: square

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system frame
- b. Number of stories 1
- c. Wall coverings wood clapboard
- d. Foundation resting on concrete block piers
- e. Roof
structural system gable with board fascia and exposed rafter ends
coverings asphalt shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S
 - 1) bays: 2
 - 2) windows: n/a
 - 3) door(s): 2 doors roughly centered on façade; eastern door is vertical board, western door has four lights in upper half
 - 4) other: _____

b. Side: direction: W

- 1) bays: 1
- 2) windows: one window with 6/6 double-hung sash centered on facade
- 3) door(s): n/a
- 4) other:

c. Side: direction: E; not visible

- 1) bays:
- 2) windows:
- 3) door(s):
- 4) other:

d. Rear: direction: N

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-8146

1. ADDRESS/LOCATION: North side of Route 54 east of Old Mill Bridge Road (381)

2. FUNCTION(S): historic machine storage current machine storage

3. YEAR BUILT: 1945 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system frame

b. Number of stories 1

c. Wall coverings wood clapboard and board

d. Foundation resting on concrete block piers

e. Roof
structural system truncated gable with board fascia and exposed rafter ends
coverings asphalt shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: S

1) bays: 2

2) windows: n/a

3) door(s): large two-bay open section at east end; pedestrian door with battened lower half and screened oval opening in upper half and simple surround at west end

4) other: _____

- b. Side: direction: E
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:

- c. Side: direction: W; not visible
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:

- d. Rear: direction: N
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:


9. INTERIOR (if accessible):

- a) Floor plan

- b) Partition/walls wood support columns, some braced, running front to back at intervals

- c) Finishes

- d) Furnishings/machinery



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-8146

1. ADDRESS/LOCATION: North Side of Rt. 54, east of Old Mill Bridge Road (TP 5-33-12-78)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-8146

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-8146 Date 1/16/03 Photo Roll # 2 Surveyor Jennifer M. Holl/Katie Diehl

Description (1) Elevation of front façade of residence, facing north; (2) Lateral view of residence, facing northeast; (3) Lateral view of residence, facing southeast; (4) Lateral view of storage shed, facing north

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-8146 Date 1/16/03 Photo Roll # 2 Surveyor Jennifer M. Holl/Katie Diehl

Description (5) Lateral view of machine shed, facing northwest; (6) Lateral view of equipment shed, facing west; (7) Lateral view of former chicken house, facing north

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-2084

1. HISTORIC NAME/FUNCTION: Dwelling

2. ADDRESS/LOCATION: South side of Route 54, between River Run and Salty Way Drive (TP 5-33-12-94)

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: The exterior of the dwelling is clad in white asbestos shingle; shed roof lean-to additions are seen to the rear ell; first story is enclosed with a second story wood roof deck.

5. SETTING INTEGRITY: Marvin's Market and gas station is now located to the east of this resource; open fields are seen north of this resource, across Route 54.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	
1	CRS 3 Secondary Building Form	Chicken House
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Jennifer M. Holl and Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: _____

Organization: McCormick Taylor, Inc. Date: September 2003 (Revised April 2004)

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-2084

The original CRS Form for this property could not be located at the Delaware SHPO Office.

Please see attached CRS Forms for further description.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750" Contact Period (Native American)
- 1630-1730" Exploration and Frontier Settlement
- 1730-1770" Intensified and Durable Occupation
- 1770-1830" Early Industrialization
- 1830-1880" Industrialization and Early Urbanization
- 1880-1940" Urbanization and Early Suburbanization
- 1940-1960" Suburbanization and Early Ex-urbanization


b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-2084

1. ADDRESS/LOCATION: South side of Rt 54, east of River Run

2. FUNCTION(S): historic Single family dwelling current Single family dwelling

3. YEAR BUILT: 1900 CIRCA: ARCHITECT/BUILDER: Unknown

4. STYLE OR FLOOR PLAN: L-shaped with additions

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: L-shaped with additions Stories: 2
Additions: shed-roof additions to rear ell; one-story enclosed front addition with roof deck

b. Structural system (if known): Light frame

c. Foundation: materials: concrete
basement: full partial not visible no basement

d. Exterior walls (original if visible & any subsequent coverings): White asbestos shingle siding

e. Roof: shape: gable with cross-gable and overhanging eaves
materials: asphalt shingles
cornice: board fascia
dormers: none
chimney: location(s): brick chimney in ridge at south end of cross-gable

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: North (not visible; obscured by plantings)
1) Bays 2
2) Windows
fenestration
type
trim
shutters

Facade (cont'd)

3) Door(s)
location
type
trim

4) Porch(es) enclosed

b. Side: Direction: East

1) Bays 4

2) Windows 4
fenestration Irregular
type 1/1 double-hung sash; one within first floor lean-to smaller than others
trim simple wood surrounds
shutters none

3) Door(s) none

location
type
trim

4) Porch(es) none

c. Side: Direction: West

1) Bays 2

2) Windows 4

fenestration Irregular
type two windows on each floor with 1/1 double-hung sash; one at south end
of first floor smaller than others
trim simple wood surrounds
shutters none

3) Door(s) none

location
type
trim

4) Porch(es) none

d. Rear: Direction: South

1) Bays 4

2) Windows 2

fenestration Regular
type two with 1/1 double-hung sash on first floor; second floor is blind
trim simple wood surrounds
shutters none

3) Door(s) 2


location centered on each lean-to shed-roof addition
type four-light upper portions and exterior storm doors
trim slightly decorated architraves

4) Porch(es) none

9. INTERIOR: n/a

10. LANDSCAPING: Large bushes obscuring front façade; scattered deciduous trees

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-2084

1. ADDRESS/LOCATION: South side of Route 54, east of River Run

2. FUNCTION(S): historic Chicken house current Garage

3. YEAR BUILT: 1950 CIRCA: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system frame
b. Number of stories 1
c. Wall coverings wood clapboard
d. Foundation not visible
e. Roof
structural system gable with board fascia
coverings standing seam metal
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: E
1) bays: 6
2) windows: one window with 6/6 sash and simple surround, very deteriorated and some panes missing, in enclosed section at north end
3) door(s): one vertical board door in enclosed section near south end
4) other: three large open bays between two enclosed section and one large bay with roof slightly raised at south end

- b. Side: direction: N
 - 1) bays: 2
 - 2) windows: n/a
 - 3) door(s): two tall vertical openings; east end has vertical board door, west end door is missing
 - 4) other: large metal oil tank on exterior wall between doors

- c. Side: direction: S
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:

- d. Rear: direction: W [not visible]
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-2084

1. ADDRESS/LOCATION: South Side of Rt. 54, between River Run & Salty Way (TP 5-33-12-94)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-2084 Date 1/16/03 Photo Roll # 2 Surveyor Jennifer M. Holl/Katie Diehl

Description (1) Lateral view of residence, facing southwest; (2) Lateral view of residence, facing northwest; (3) Lateral view of residence, facing northeast; (4) Elevation of side façade of residence, facing east

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-2084 Date 1/16/03 Photo Roll # 2 Surveyor Jennifer M. Holl/Katie Diehl

Description (5) Elevation of front façade of former chicken house, facing south; (2) Lateral view of former chicken house, facing southwest


Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-8147
SPO Map 20-21-05
Hundred Baltimore
Quad Assawoman Bay
Other 5-33-12-88

1. HISTORIC NAME/FUNCTION: Dwelling, north side of Route 54 b/t Old Mill Bridge Rd and Laws Point Dr
2. ADDRESS/LOCATION: North side of Route 54 between Old Mill Bridge Road (381) and Laws Point Drive
3. TOWN/NEAREST TOWN: Fenwick Island vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
landscape district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 54 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: _____

Organization: McCormick Taylor, Inc. Date: September 2003 (Revised April 2004)

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-8147

The CRS number for this resource was previously assigned during the Beach Access Project survey conducted by KFS in 1989. The survey was never completed or submitted to the DE SHPO. However, the DE SHPO requested that the CRS number be used so as not to duplicate resources.


10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750" Contact Period (Native American)
 - 1630-1730" Exploration and Frontier Settlement
 - 1730-1770" Intensified and Durable Occupation
 - 1770-1830" Early Industrialization
 - 1830-1880" Industrialization and Early Urbanization
 - 1880-1940" Urbanization and Early Suburbanization
 - 1940-1960" Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-8147

1. ADDRESS/LOCATION: North side of Route 54 between Old Mill Bridge Road (381) and Laws Point Drive
2. FUNCTION(S): historic Single-family residential current unoccupied
3. YEAR BUILT: 1935 CIRCA?: ARCHITECT/BUILDER: _____
4. STYLE OR FLOOR PLAN: Craftsman
5. INTEGRITY: original site moved
 if moved, from where _____ other location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____

- a. _____
 b. _____

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: square Stories: 1 1/2
 Additions: n/a
- b. Structural system (if known): light frame
- c. Foundation: materials: concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): asbestos shingle siding
- e. Roof: shape: side gable
 materials: asphalt shingles
 cornice: bracketed cornice on dormer
 dormers: shed dormer centered on front (south) facade
 chimney: location(s): n/a

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: S
- | | | |
|----|---------|---|
| 1) | Bays | 3 |
| 2) | Windows | 2 |
- fenestration irregular
 type paired windows with 1/1 sash on each side of door; ribbon of three windows with 1/1 sash in dormer
 trim simple wood surrounds
 shutters n/a

Facade (cont'd)

- 3) Door(s) 1
 location centered beneath overhanging eave and porch on front (south) facade
 type large central light with muntins forming two small lights at top and bottom and two long vertical lights
 trim simple surround

- 4) Porch(es) overhanging eave shelters porch with wood supports (currently under renovation)

b. Side: Direction: E

- 1) Bays 3

- 2) Windows 4
 fenestration regular
 type paired windows with 1/1 sash; three on first floor and one in gable end
 trim simple surround
 shutters n/a

- 3) Door(s) n/a
 location
 type
 trim

- 4) Porch(es) n/a

c. Side: Direction: W

- 1) Bays 3

- 2) Windows 5
 fenestration irregular
 type paired windows with 1/1 sash, two on first floor and one in gable end; smaller window with 1/1 sash at north end
 trim simple surrounds
 shutters n/a

- 3) Door(s) n/a
 location
 type
 trim

- 4) Porch(es) n/a

d. Rear: Direction: N

- 1) Bays 2

- 2) Windows 1
 fenestration irregular
 type 1/1 sash; one window at west end on first floor, paired windows in dormer
 trim simple surrounds
 shutters n/a


- 3) Door(s) 1
 location east of center
 type not visible
 trim simple surround

- 4) Porch(es) door is reached via a wood deck with short flight of stairs

9. INTERIOR:

10. LANDSCAPING: Wooded perimeter of lot

11. OTHER COMMENTS:



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-8147

1. ADDRESS/LOCATION: North Side of Rt. 54, west of Grays Lane (TP 5-33-12-88)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-8147

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-8147 Date 1/16/03 Photo Roll # 2 Surveyor Jennifer M. Holl/Katie Diehl

Description (1) Lateral view of residence, facing northeast; (2) Lateral view of residence, facing northwest; (3) Lateral view of residence, facing southeast


Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-8148
SPO Map 20-21-05
Hundred Baltimore
Quad Assawoman Bay
Other 5-33-12-92

1. HISTORIC NAME/FUNCTION: George Edward Gray House/Dwelling
2. ADDRESS/LOCATION: North side of Route 54 between Old Mill Bridge Road and Laws Point Drive
3. TOWN/NEAREST TOWN: Bayville vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
landscape district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 54 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
5	CRS 3 Secondary Building Form	Garage, feed house, guest cottage, 2 sheds
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: _____

Organization: McCormick Taylor Inc. Date: January 2003 (Revised June 2004)

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-8148

The CRS number for this resource was previously assigned during the Beach Access Project survey conducted by KFS in 1989. The survey was never completed or submitted to the DE SHPO. However, the DE SHPO requested that the CRS number be used so as not to duplicate resources.

This tax parcel was previously identified and assigned CRS #S-2086; however, during a field view on April 21, 2003 it was agreed that a new CRS number would be assigned (S-8148) as the dwelling associated with S-2086 had been razed.

Based on new information received in April 2004, it was determined that the former chicken feed house (tax parcel 5-33-12-92.03) was located on a different tax parcel than the main dwelling (tax parcel 5-33-12-92). While the two buildings are historically associated, they are now situated on different tax parcels.

Included within tax parcel 5-33-12-92 but located on the opposite (east) side of Gray's Lane is a one-story dwelling (or guest cottage) with two shed outbuildings. This dwelling does not appear on a 1948 United States Geological Survey map; but evidence suggests that it dates to c. 1946 based on an oral history interview conducted with owner Anna Lee Gray on June 2, 2004.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750" Contact Period (Native American)
- 1630-1730" Exploration and Frontier Settlement
- 1730-1770" Intensified and Durable Occupation
- 1770-1830" Early Industrialization
- 1830-1880" Industrialization and Early Urbanization
- 1880-1940" Urbanization and Early Suburbanization
- 1940-1960" Suburbanization and Early Ex-urbanization


b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input checked="" type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-8148

1. ADDRESS/LOCATION: North side of Route 54 between Old Mill Bridge Road and Laws Point Drive
2. FUNCTION(S): historic Single-family residential current Single-family residential
3. YEAR BUILT: 1942 CIRCA?: ARCHITECT/BUILDER: George Edward Gray
4. STYLE OR FLOOR PLAN: rectangular
5. INTEGRITY: original site moved
 if moved, from where _____ other location's CRS # _____ year _____

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. one-story addition on north façade with gable-roofed enclosed portion, screen porch & roof deck with balustrade	c. 1942
b. gable-roofed open porte-cochere on west facade	c. 1942

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangular Stories: 2.5
Additions: porch on east façade, open carport on west facade
- b. Structural system (if known): light frame
- c. Foundation: materials: brick
basement: full partial not visible no basement
- d. Exterior walls (original if visible & any subsequent coverings): white wood shingles
- e. Roof: shape: side gable
materials: green asphalt shingles
cornice: simple molded
dormers: n/a
chimney: location(s): exterior brick chimney with corbelled top centered on west façade; another in rear slope of roof at east end

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: South
- | | |
|------------|---|
| 1) Bays | 3 |
| 2) Windows | 5 |
- fenestration regular
type 8/8 double-hung sash; 2 on first story flanking door, 3 on second story
trim simple wood surrounds
shutters green, faux-louvered

Facade (cont'd)

- 3) **Door(s)** 1
 location centered on façade beneath portico
 type paneled; exterior door has 12 lights
 trim sidelights with simple decorative surround
- 4) **Porch(es)** entry is sheltered by gable-roofed portico with an arched pediment and paired columns at the outer corners resting on brick piers and short brick staircase
- b. **Side: Direction: East**
- 1) **Bays** 1
- 2) **Windows** 2
 fenestration regular
 type not visible; windows appear to be smaller than those on front façade and probably have 8/8 double-hung sash
 trim simple wood surrounds
 shutters green, louvered
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** screened porch with corner columns and decorative geometric woodwork and roof deck with wood balustrade at south end of facade
- c. **Side: Direction: West**
- 1) **Bays** 2
- 2) **Windows** 4
 fenestration regular
 type not visible; windows appear to be smaller than those on front façade and probably have 8/8 double-hung sash
 trim simple wood surrounds
 shutters green, louvered
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** open gable-roofed carport with paired columns resting on brick piers at exterior corners
- d. **Rear: Direction: North**
- 1) **Bays** 3
- 2) **Windows**
 fenestration regular
 type 6/6 double-hung wood sash windows; 8/8 single and paired double-hung wood sash windows
 trim simple wood surrounds
 shutters green, louvered; and no shutters
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** none

9. **INTERIOR:** Unknown; access denied.

10. **LANDSCAPING:** Ornamental bushes and trees planted close to house along front (south) and side (west) facades; scattered deciduous and evergreen trees on lot, mostly to sides. U-shaped gravel driveway in front of house, with access from Route 54 (seen on c. 1962 aerial photograph). Wood rail fence follows tax parcel boundary on west.

11. **OTHER COMMENTS:**

- b. Side: direction: East
- 1) bays: 3
 - 2) windows: 6/6 double-hung wood sash
 - 3) door(s): n/a
 - 4) other: n/a
- c. Side: direction: West
- 1) bays: 3
 - 2) windows: 6/6 double-hung wood sash
 - 3) door(s): n/a
 - 4) other: n/a
- d. Rear: direction: North [not visible]
- 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other: n/a


9. INTERIOR (if accessible):

a) Floor plan Access was gained in the front (southeastern) room only, so the overall shape of the interior could not be discerned.

b) Partition/walls The interior walls appeared to be finished in both dry wall and wood paneling, but access was only granted to the southeastern room only.

c) Finishes Painted dry wall and wood paneling in the southeastern room.

d) Furnishings/machinery No built-ins were noted; office furniture (such as chairs and desks) were noted in the southeastern room.



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-8148

1. ADDRESS/LOCATION: North side of Route 54 between Old Mill Bridge Road and Laws Point Drive

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 1942 CIRCA?: ARCHITECT/BUILDER: George Edward Gray

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system light frame
b. Number of stories 1 1/2
c. Wall coverings white wood shingles
d. Foundation not visible
e. Roof
structural system side gable
coverings green asphalt shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: East
1) bays: 2
2) windows: n/a
3) door(s): 2 wood vehicular garage doors
4) other: n/a

- b. Side: direction: South
 - 1) bays: 3
 - 2) windows: 6/6 double-hung wood sash, evenly spaced; 3 on first floor, 2 on second floor in gable end
 - 3) door(s): n/a
 - 4) other: n/a

- c. Side: direction: North [not visible]
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other: n/a

- d. Rear: direction: West [not visible]
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other: n/a


9. INTERIOR (if accessible): not accessible

a) Floor plan Unknown [not visible]

b) Partition/walls Unknown [not visible]

c) Finishes Unknown [not visible]

d) Furnishings/machinery Unknown [not visible]



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-8148

1. ADDRESS/LOCATION: East side of Gray's Lane near Lighthouse Road (Rt. 54)

2. FUNCTION(S): historic Dwelling/guest cottage current dwelling

3. YEAR BUILT: 1946 CIRCA?: ARCHITECT/BUILDER: George Edward Gray

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system light frame
b. Number of stories 1
c. Wall coverings vinyl siding
d. Foundation concrete block
e. Roof
structural system side gable
coverings asphalt shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: West
1) bays: 3
2) windows: two 1/1 vinyl windows with simple surrounds
3) door(s): one centered door with lights in upper half and storm door, sheltered by cantilevered gable-roofed portico
4) other: interior brick chimney centered in roof ridge

b. Side: direction: South

- 1) bays: 2
- 2) windows: two 1/1 vinyl windows with simple surrounds
- 3) door(s): n/a
- 4) other: n/a

c. Side: direction: North

- 1) bays: 2
- 2) windows: two 1/1 vinyl windows with simple surrounds
- 3) door(s): n/a
- 4) other: n/a

d. Rear: direction: East

- 1) bays: 3
- 2) windows: three 1/1 vinyl windows with simple surrounds, one slightly smaller than others
- 3) door(s): n/a
- 4) other: n/a


9. INTERIOR (if accessible): not accessible

a) Floor plan n/a

b) Partition/walls n/a

c) Finishes n/a

d) Furnishings/machinery n/a



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-8148

1. ADDRESS/LOCATION: East side of Gray's Lane near Lighthouse Road (Rt. 54)

2. FUNCTION(S): historic storage current storage

3. YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system frame
- b. Number of stories 1
- c. Wall coverings vinyl siding
- d. Foundation n/a
- e. Roof
structural system front gable
coverings asphalt shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: West
 - 1) bays: 1
 - 2) windows: n/a
 - 3) door(s): one centered single leaf door
 - 4) other: n/a

b. Side: direction: South

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: blind

c. Side: direction: North

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: blind

d. Rear: direction: East (not visible; likely blind)

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: blind


9. INTERIOR (if accessible): not accessible

a) Floor plan n/a

b) Partition/walls n/a

c) Finishes n/a

d) Furnishings/machinery n/a



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-8148

1. ADDRESS/LOCATION: East side of Gray's Lane near Lighthouse Road (Rt. 54)

2. FUNCTION(S): historic storage current storage

3. YEAR BUILT: 1965 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system frame
b. Number of stories 1
c. Wall coverings horizontal flushboard
d. Foundation concrete
e. Roof
structural system gambrel
coverings asphalt shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: West
1) bays: 1
2) windows: n/a
3) door(s): centered double barn-style doors, one with louvers in upper half
4) other: n/a

b. Side: direction: South

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: blind

c. Side: direction: North

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: blind

d. Rear: direction: East (not visible; likely blind)

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: blind


9. INTERIOR (if accessible): not accessible

a) Floor plan n/a

b) Partition/walls n/a

c) Finishes n/a

d) Furnishings/machinery n/a



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-8148

1. ADDRESS/LOCATION: North Side of Rt. 54, at the intersection of Gray's Lane (TP 5-33-12-92, 5-33-12-92.03)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



||||| National Registry Boundary

INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-8148 Date 1/16/03 Photo Roll # 3 Surveyor Jennifer M. Holl/Katie Diehl

Description (1) Elevation of front façade of residence, facing north; (2) Lateral view of residence and former feed warehouse, facing northeast; (3) Lateral view of residence, facing northwest; (4) Lateral view of residence, facing northeast

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-8148 Date 1/16/03 Photo Roll # 3 Surveyor Jennifer M. Holl/Katie Diehl

Description (5) Lateral view of former feed warehouse, facing northwest; (6) Lateral view of former feed warehouse, facing northeast; (7) Lateral view of car wash on property, facing northwest

Negative location (if other than SHPO) _____

Attach contact print(s):



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-8148 Date 04/27/04 Photo Roll # 5 Surveyor Jennifer M. Holl/Katie Diehl

Description (8) Lateral view of guest cottage and outbuildings, facing north; (9) Lateral view of outbuildings, facing northeast; (10) Lateral view of guest cottage and outbuildings, facing east; (11) Lateral view of guest cottage, facing southeast

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-8148 Date 4/27/04 Photo Roll # 5 Surveyor Jennifer M. Holl/Katie Diehl

Description (12) View of residence and garage, facing southwest; (13) View of residence, garage and former fed warehouse, facing southwest; (14) Lateral view of guest cottage, facing northeast

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-8148 Date 6/4/04 Photo Roll # 6 Surveyor Jennifer M. Holl/Katie Diehl

Description (15) View of front façade of feed house, facing north; (17) Lateral view of feed house, facing northeast; (18) Lateral view of feed house, facing southeast; (19) Lateral view of feed house, facing southwest

Negative location (if other than SHPO) _____

Attach contact print(s):




doc # 20-06-01-05-12

CRS-13

B.H. District

FORM CRS-3

CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM



DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314

FOR OFFICE USE ONLY

CRS # S-2086
Quad Assawoman Bay
SPO map # 20-21-05
Hundred Baltimore
DOCUMENT 20-06/78/0477


1. NAME OF LOCUS: Parcel 92 - Tax Map S-33-12
2. STREET LOCATION: West side of dirt road, 2 1/4 mile North of Rt. 29
3. OWNER'S NAME: George Edward Gray TEL. # _____
ADDRESS: Rt. 1, Box 132, Selbyville, DE 19975
4. TYPE OF LOCUS: a) structure b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field c) woodland _____
d) scattered buildings e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Sarah Bryan, Emily Bittingham TEL. # 856-7701 ext. 361
YOUR ADDRESS: Old Sussex County Court House, Georgetown, DE 19947
ORGANIZATION (if any) Historical Surveyors DATE: 7/25/80

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.

North




9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

USE BLACK INK ONLY

INDICATE NORTH ON SKETCH



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-2085

1. HISTORIC NAME/FUNCTION: Dwelling, south side of Route 54, between Salty Way Drive and Teaberry Circle

2. ADDRESS/LOCATION: South side of Route 54, between Salty Way and Teaberry Circle

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: No significant alterations appear to have been made to the historic fabric of the property since the 1980 survey form.

5. SETTING INTEGRITY: The setting has been altered by the construction of modern commercial buildings to the southeast of the resource on the same tax parcel.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
2	CRS 3 Secondary Building Form	Modern commercial buildings
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: _____

Organization: McCormick Taylor, Inc. Date: September 2003 (Revised April 2004)

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-2085

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II


 - 1600-1750" Contact Period (Native American)
 - 1630-1730" Exploration and Frontier Settlement
 - 1730-1770" Intensified and Durable Occupation
 - 1770-1830" Early Industrialization
 - 1830-1880" Industrialization and Early Urbanization
 - 1880-1940" Urbanization and Early Suburbanization
 - 1940-1960" Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-2085

1. ADDRESS/LOCATION: South side of Route 54, between Salty Way and Teaberry Circle

2. FUNCTION(S): historic Single-family residential current Single-family residential

3. YEAR BUILT: 1910 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular Stories: 2
Additions:
- b. Structural system (if known): light frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible & any subsequent coverings): aluminum siding
- e. Roof: shape: side gable
materials: asphalt shingles
cornice:
dormers: n/a
chimney: location(s): central

8. DESCRIPTION OF ELEVATIONS:
a. Facade: Direction: S
1) Bays 3
2) Windows
fenestration regular
type 1/1 vinyl replacement
trim
shutters blue, paneled

Facade (cont'd)

- 3) **Door(s)**
 location west end
 type not visible
 trim not visible
- 4) **Porch(es)** one-story screened-in wood porch on west end of rear facade

b. Side: Direction: E

- 1) **Bays** 2
- 2) **Windows**
 fenestration regular
 type 1/1 vinyl replacement
 trim
 shutters blue, paneled
- 3) **Door(s)** n/a
 location
 type
 trim
- 4) **Porch(es)**

c. Side: Direction: W


- 1) **Bays** 2
- 2) **Windows**
 fenestration regular
 type 1/1 vinyl replacement
 trim
 shutters blue, paneled
- 3) **Door(s)** n/a
 location
 type
 trim
- 4) **Porch(es)**

d. Rear: Direction: N

- 1) **Bays** 3
- 2) **Windows**
 fenestration regular
 type 1/1 vinyl replacement
 trim
 shutters blue, paneled
- 3) **Door(s)**
 location central
 type wood paneled
 trim
- 4) **Porch(es)** gable roof portico

9. **INTERIOR:**10. **LANDSCAPING:**11. **OTHER COMMENTS:**

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-2085

1. ADDRESS/LOCATION: South side of Route 54, between Salty Way and Teaberry Circle

2. FUNCTION(S): historic N/A current commercial

3. YEAR BUILT: 1980 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system frame
b. Number of stories 2
c. Wall coverings vertical vinyl siding
d. Foundation not visible
e. Roof
structural system flat
coverings not visible
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: N
1) bays: 3
2) windows: 1/1 vinyl windows with snap in muntins
3) door(s): double leaf wood paneled
4) other: full length one story porch with shed roof and simple posts

- b. Side: direction: E
 - 1) bays: 2
 - 2) windows: 1/1 vinyl windows with snap in muntins
 - 3) door(s): n/a
 - 4) other:

- c. Side: direction: S; not visible
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: W; not visible
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-2085

1. ADDRESS/LOCATION: South Side of Rt. 54, between Salty Way & Teaberry Circle (TP 5-33-12-97)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-2085 Date 1/16/03 Photo Roll # 3 Surveyor Jennifer M. Holl/Katie Diehl

Description (1) Lateral view of residence and shed, facing southeast; (2) Lateral view of residence, facing southwest; (3) Lateral view of modern commercial buildings, facing south; (4) Lateral view of residence, facing west

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13

BEGIN

HSE,	PARCEL	96-		
------	--------	-----	--	--

T.MAP 5-33-12

Use black ink and completely fill each box. Entries above the ruled line will appear on fiche labels.

CRS

S-	2085.		
----	-------	--	--



STATE OF DELAWARE

DIVISION OF
HISTORICAL & CULTURAL AFFAIRS

HALL OF RECORDS • DEWEE • 1985

FICHE TITLE FRAME

Date ordered:

Camera:

Date filmed:

Operator's Signature:

The images on this microfiche are unaltered photocopies of the material contained in the survey files, Bureau of Archaeology and Historic Preservation-

Inventory

B.H. District 7

CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM



FORM CRS-3

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314

FOR OFFICE USE ONLY


CRS # S-2085
Quad Assawoman Bay
SPO map # 20-21-05
Hundred Baltimore
DOCUMENT 20-06/78/04/77

1. NAME OF LOCUS: Assel 9/6 Tax Map 5-33-12
2. STREET LOCATION: South side of Rt. 54, 3/4 mile west of 586
3. OWNER'S NAME: Barbara Tomker TEL. # _____
ADDRESS: Rt. 1, Box 133, Selbyville, DE 19975
4. TYPE OF LOCUS: a) structure b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field _____ c) woodland
d) scattered buildings _____ e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Sarah Bryan, Emily Brittingham TEL. # 556-7701 PA 260
YOUR ADDRESS: Old Sussex County Court House, Georgetown, DE
ORGANIZATION (if any): Historical Surveyors DATE: 7/21/94

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

CULTURAL RESOURCE SURVEY
STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314




Form CRS-1
FOR OFFICE USE ONLY

CRS # S-2085
Quad Crossman Bay
SPO map # 20-21-05
Hundred Baltimore
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : Parcel 96 Tax Map S-33-12

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape Rectangular
stories 2 stories
bays 3 bays
wings one story gable addition on right side
- b) Structural system bracket, single-pile
- c) Foundation materials concrete block
basement
- d) Exterior walls materials aluminum siding
color(s) green
- e) Roof shape; materials gable roof w/ asbestos shingles
cornice aluminum trim cornice
dormers none
chimney location(s) brick colored left exterior end chimney
- f) Windows spacing symmetrical
type 6/6 lites, single hung
trim none chipable
shutters none 4 lites window on gable end
chipable
6 lites window in addition
- g) Door spacing center line plan
type hills, 6 lites, 2 vertical panels
trim none
- h) Porches location(s) gable roof stoop
materials
supports square column w/ trilobe like design
trim no cornice
- i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION: good deteriorated

remarks: _____

4. INTEGRITY: a) original site b) moved

c) if moved, when and from where _____

d) list major alterations and dates (if known) _____

5. DATE OF INITIAL CONSTRUCTION: _____

6. ARCHITECT/BUILDER: _____

7. RELATED OUTBUILDINGS:

a) barn b) carriage house c) garage d) privy

e) shed f) greenhouse g) shop h) gardens

i) icehouse j) springhouse k) other

describe: *Shed, gable roof shed.*


8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

9. Primary References: (include location of reference).

field survey

10. Surveyor: *Sarah Ryan, Emily Brittingham* Date of Form: *7/28/80*

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-8150
SPO Map 20-21-05
Hundred Baltimore
Quad Assawoman Bay
Other 5-33-12-93

1. HISTORIC NAME/FUNCTION: Dwelling, north side of Route 54 east of Gray's Lane
2. ADDRESS/LOCATION: North side of Route 54 east of Gray's Lane
3. TOWN/NEAREST TOWN: Fenwick Island vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
landscape district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 54 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
1	CRS 3 Secondary Building Form	Shed
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: _____

Organization: McCormick Taylor, Inc. Date: September 2003 (Revised April 2004)

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-8150

The CRS number for this resource was previously assigned during the Beach Access Project survey conducted by KFS in 1989. The survey was never completed or submitted to the DE SHPO. However, the DE SHPO requested that the CRS number be used so as not to duplicate resources.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):


- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750" Contact Period (Native American)
 - 1630-1730" Exploration and Frontier Settlement
 - 1730-1770" Intensified and Durable Occupation
 - 1770-1830" Early Industrialization
 - 1830-1880" Industrialization and Early Urbanization
 - 1880-1940" Urbanization and Early Suburbanization
 - 1940-1960" Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-8150

1. ADDRESS/LOCATION: North side of Route 54 east of Gray's Lane

2. FUNCTION(S): historic Single-family residential current Single-family residential

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. enclosed front porch

b. enclosed rear porch

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1 1/2
Additions: enclosed front and rear porches

b. Structural system (if known): light frame

c. Foundation: materials: rough-faced concrete block and concrete block
basement: full partial not visible no basement

d. Exterior walls (original if visible & any subsequent coverings): white aluminum siding

e. Roof: shape: front gable with overhanging eaves (hipped roof and shed roofed additions)
materials: asphalt shingles
cornice: simple enclosed, board fascia
dormers: n/a
chimney: location(s): n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: S
1) Bays 3
2) Windows 2
fenestration irregular
type 2 windows with 1/1 sash on first floor; 1 smaller with 1/1 sash in gable end
trim simple surrounds
shutters black, louvered on first floor

Facade (cont'd)

3) Door(s) 1
 location centered on façade; accessed via short flight of concrete steps w/metal railing
 type paneled with two small square lights at top; exterior storm door
 trim simple surround

4) Porch(es) n/a

b. Side: Direction: E

1) Bays 6

2) Windows 6

fenestration irregular

type 2 evenly spaced windows with 3/1 sash on main portion; 4 windows with 3 horizontal lights on east façade of rear porch addition

trim simple surrounds

shutters black, louvered on main portion

3) Door(s) n/a

location

type

trim

4) Porch(es) shed-roofed enclosed porch extends out from rear (northeast) corner of house

c. Side: Direction: W

1) Bays 3

2) Windows 3

fenestration irregular

type oriel-style window with three vertical panes at south end; 2 small rectangular windows with 1/1 sash to the north

trim simple surrounds

shutters n/a

3) Door(s) n/a

location

type

trim

4) Porch(es) n/a

d. Rear: Direction: N [not visible]

1) Bays

2) Windows

fenestration

type

trim

shutters

3) Door(s)

location

type


trim

4) Porch(es)

9. INTERIOR:

10. LANDSCAPING: Small bushes and shrubs planted closely adjacent to house along front (south) and side (east) facades; lot is lightly wooded with mostly deciduous trees.

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-8150

1. ADDRESS/LOCATION: North side of Route 54 east of Gray's Lane

2. FUNCTION(S): historic Storage current Storage

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system light frame
- b. Number of stories 1
- c. Wall coverings aluminum siding on front façade and wood shingles on secondary facades
- d. Foundation not visible; appears to rest on piers
- e. Roof
 - structural system front gable
 - coverings green asphalt shingles
 - openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S
 - 1) bays: 1
 - 2) windows: n/a
 - 3) door(s): paneled door with six lights at the top, located on the east end
 - 4) other: _____

b. Side: direction: W

- 1) bays: 1
- 2) windows: one window with 1/1 double-hung sash and simple surround centered on facade
- 3) door(s): n/a
- 4) other:

c. Side: direction: E [not visible]

- 1) bays:
- 2) windows:
- 3) door(s):
- 4) other:

d. Rear: direction: N [not visible]

- 1) bays:
- 2) windows:
- 3) door(s):
- 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-8150

1. ADDRESS/LOCATION: North Side of Rt. 54, just east of Gray's Lane (TP 5-33-12-93)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-8150

INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-8150 Date 1/16/03 Photo Roll # 3 Surveyor Jennifer M. Holl/Katie Diehl

Description (1) Lateral view of residence, facing northeast; (2) Lateral view of residence, facing northwest; (3) Lateral view of shed, facing northeast


Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-8149
SPO Map 20-21-05
Hundred Baltimore
Quad Assawoman Bay
Other 5-33-19-589

1. HISTORIC NAME/FUNCTION: Dwelling, 1 Teaberry Circle
2. ADDRESS/LOCATION: 1 Teaberry Circle, south side of Route 54 between Salty Way and Laws Point Dr.
3. TOWN/NEAREST TOWN: Fenwick Island vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
landscape district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 54 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: _____

Organization: McCormick Taylor, Inc. Date: September 2003 (Revised April 2004)

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-8149

The CRS number for this resource was previously assigned during the Beach Access Project survey conducted by KFS in 1989. The survey was never completed or submitted to the DE SHPO. However, the DE SHPO requested that the CRS number be used so as not to duplicate resources.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):


- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750" Contact Period (Native American)
 - 1630-1730" Exploration and Frontier Settlement
 - 1730-1770" Intensified and Durable Occupation
 - 1770-1830" Early Industrialization
 - 1830-1880" Industrialization and Early Urbanization
 - 1880-1940" Urbanization and Early Suburbanization
 - 1940-1960" Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-8149

1. ADDRESS/LOCATION: 1 Teaberry Circle, south side of Route 54 b/t Salty Way and Laws Point Drive

2. FUNCTION(S): historic Single-family residential current Single-family residential

3. YEAR BUILT: 1945 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular Stories: 1 1/2
Additions: n/a
- b. Structural system (if known): light frame; brick veneer
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible & any subsequent coverings): brick veneer on front; blue vertical weatherboard on secondary facades
- e. Roof: shape: side gable with overhanging eaves
materials: asphalt shingles
cornice: simple enclosed with board fascia and box returns
dormers: 3 gable dormers on front, 1 continuous shed dormer on rear
chimney: location(s): exterior brick chimney, wide at base, east of center on side (north) facade

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: E
 - 1) Bays 3
 - 2) Windows 5
 - fenestration irregular
 - type 1 window with 1/1 sash south of door; paired windows with 1/1 sash north of door; smaller windows with 1/1 sash in each dormer
 - trim simple surrounds and plain stone lintels on first floor
 - shutters black, louvered on first floor windows; none on dormer windows

Facade (cont'd)

- 3) Door(s) 1
 location centered on facade
 type paneled bottom with diamond-pattern muntins on top
 trim simple surround, plain stone lintel
- 4) Porch(es) door is reached via short flight of wood steps with railing and small deck porch

b. Side: Direction: N

- 1) Bays 1
- 2) Windows 2
 fenestration irregular
 type 1/1 sash on first floor, paired with 1/1 sash in gable end
 trim simple surrounds
 shutters black, louvered
- 3) Door(s) n/a
 location
 type
 trim
- 4) Porch(es) n/a

c. Side: Direction: S [not visible]

- 1) Bays
- 2) Windows
 fenestration
 type
 trim
 shutters
- 3) Door(s)
 location
 type
 trim
- 4) Porch(es)


d. Rear: Direction: W

- 1) Bays 4
- 2) Windows 6
 fenestration irregular
 type not clearly visible; one large and one small window on first floor, three large and one small on second floor
 trim simple surrounds
 shutters n/a
- 3) Door(s) 2
 location north and south ends
 type paired multi-light doors at north end; single door at south end
 trim simple surrounds
- 4) Porch(es) low, open rear deck/patio with simple wood rail

9. INTERIOR:

10. LANDSCAPING: Lot is wooded; bushes and shrubs planted around perimeter of house and rear deck.

11. OTHER COMMENTS: To the southwest is a small outbuilding with a low-pitched gable roof and board and batten siding.



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-8149

1. ADDRESS/LOCATION: South Side of Rt. 54, at the intersection of Teaberry Circle (TP 5-33-19-589)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY


CRS # S-8149 Date 1/16/03 Photo Roll # 3 Surveyor Jennifer M. Holl/Katie Diehl

Description (1) Lateral view of residence, facing south; (2) Lateral view of residence, facing west; (3) Lateral view of residence, facing southwest

Negative location (if other than SHPO) _____

Attach contact print(s):





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-2087
SPO Map 20-21-05
Hundred Baltimore
Quad Assawoman Bay
Other 5-33-19-22

1. HISTORIC NAME/FUNCTION: Dwelling, south side of Route 54 b/t Salty Way and Keenwick Road
2. ADDRESS/LOCATION: 142A Route 54, south side of Route 54 between Salty Way and Keenwick Road
3. TOWN/NEAREST TOWN: Fenwick Island vicinity?
4. MAIN TYPE OF RESOURCE:

building <input checked="" type="checkbox"/>	structure <input type="checkbox"/>	site <input type="checkbox"/>	object <input type="checkbox"/>
landscape <input type="checkbox"/>	district <input type="checkbox"/>		
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 54 Improvements Project

7. ADDITIONAL FORMS USED:

#: Form:	List property types:
1	CRS 2 Main Building Form
0	CRS 3 Secondary Building Form
0	CRS 4 Archaeological Site Form
0	CRS 5 Structure (Building-Like) Form
0	CRS 6 Structure (Land Feature) Form
0	CRS 7 Object Form
0	CRS 8 Landscape Elements Form
1	CRS 9 Map Form N/A
0	CRS 14 Potential District Form

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: _____

Organization: McCormick Taylor, Inc. Date: September 2003 (Revised April 2004)

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-2087

No previous survey form was found at the DE SHPO.


10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750" Contact Period (Native American)
 - 1630-1730" Exploration and Frontier Settlement
 - 1730-1770" Intensified and Durable Occupation
 - 1770-1830" Early Industrialization
 - 1830-1880" Industrialization and Early Urbanization
 - 1880-1940" Urbanization and Early Suburbanization
 - 1940-1960" Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-2087

1. ADDRESS/LOCATION: 142A Route 54, south side of Route 54 between Salty Way and Keenwick Road

2. FUNCTION(S): historic Single-family residential current Single-family residential

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. two-car garage on side (west) facade

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1
Additions: two-car garage on side (west) facade

b. Structural system (if known): light frame

c. Foundation: materials: concrete block
basement: full partial not visible no basement

d. Exterior walls (original if visible & any subsequent coverings): white asbestos shingles

e. Roof: shape: side gable
materials: asphalt shingles
cornice: simple enclosed with box returns
dormers: n/a
chimney: location(s): n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: N
1) Bays 4
2) Windows 3
fenestration irregular
type windows with 4 horizontal lights at east and west ends; identical paired windows immediately west of door
trim simple surrounds
shutters louvered, green


Facade (cont'd)

- 3) Door(s) 1
 location slightly east of center
 type diagonal lights on main door; exterior storm door
 trim simple molded surround
- 4) Porch(es) door is accessed via short flight of brick steps and stoop with wood railing
- b. Side: Direction: E
- 1) Bays 2
- 2) Windows 2
 fenestration regular
 type double-hung sash with 4 horizontal lights; rectangular basement windows
 visible and louvered vent in gable peak
 trim simple surrounds
 shutters n/a
- 3) Door(s) n/a
 location
 type
 trim
- 4) Porch(es) n/a
- c. Side: Direction: W
- 1) Bays 1
- 2) Windows 1
 fenestration regular
 type double-hung sash with 4 horizontal lights
 trim simple surround
 shutters n/a
- 3) Door(s) n/a
 location
 type
 trim
- 4) Porch(es) two-car garage with side-gable roof, overhead metal door, and similar
 construction details connects to house at south end of facade
- d. Rear: Direction: S [not visible]
- 1) Bays
- 2) Windows
 fenestration
 type
 trim
 shutters
- 3) Door(s)
 location
 type
 trim
- 4) Porch(es)

9. INTERIOR:

10. LANDSCAPING: Small bushes planted close to house on front façade; circular sand driveway; wooded lot with mostly deciduous trees.

11. OTHER COMMENTS:



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-2087

1. ADDRESS/LOCATION: South Side of Rt. 54, east of Teaberry Circle (TP 5-33-19-22)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



-----	TAX PARCEL BOUNDARY
□	BUILDING LESS THAN 50 YEARS OLD
▨	BUILDING MORE THAN 50 YEARS OLD
☁	TREE LINE



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-2087 Date 1/16/03 Photo Roll # 3 Surveyor Jennifer M. Holl/Katie Diehl

Description (1) Lateral view of residence, facing southeast; (2) Lateral view of residence, facing southwest


Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-8134
SPO Map 20-21-05
Hundred Baltimore
Quad Assawoman Bay
Other 5-33-19-24.01

- HISTORIC NAME/FUNCTION: Dwelling, south side of Route 54 b/t Salty Way and Keenwick Road
- ADDRESS/LOCATION: Box 144 Route 54, south side of Route 54 between Salty Way and Keenwick Road
- TOWN/NEAREST TOWN: Fenwick Island vicinity?
- MAIN TYPE OF RESOURCE: building structure site object
landscape district
- MAIN FUNCTION OF PROPERTY: Dwelling
- PROJECT TITLE/ REASON FOR SURVEY (if applicable): Route 54 Improvements Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
1	CRS 3 Secondary Building Form	Garage
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: _____

Organization: McCormick Taylor, Inc. Date: September 2003 (Revised April 2004)

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-8134

The CRS number for this resource was previously assigned during the Beach Access Project survey conducted by KFS in 1989. The survey was never completed or submitted to the DE SHPO. However, the DE SHPO requested that the CRS number be used so as not to duplicate resources.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750" Contact Period (Native American)
 - 1630-1730" Exploration and Frontier Settlement
 - 1730-1770" Intensified and Durable Occupation
 - 1770-1830" Early Industrialization
 - 1830-1880" Industrialization and Early Urbanization
 - 1880-1940" Urbanization and Early Suburbanization
 - 1940-1960" Suburbanization and Early Ex-urbanization


- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY

CRS-1



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-8134

1. ADDRESS/LOCATION: Box 144 Route 54, south side of Route 54 between Salty Way and Keenwick Road

2. FUNCTION(S): historic Single-family residential current Single-family residential

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: Colonial Revival

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. additions to angle formed at southwest corner of the house

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1 1/2
Additions: slat-roofed additions, one with roof deck and balustrade, at southwest corner

b. Structural system (if known): light frame

c. Foundation: materials: concrete block
basement: full partial not visible no basement

d. Exterior walls (original if visible & any subsequent coverings): white vinyl siding

e. Roof: shape: side gable
materials: standing seam metal
cornice: simple enclosed
dormers: n/a
chimney: location(s): brick chimney in rear slope of roof west of center

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: N
1) Bays 6
2) Windows 5
fenestration regular
type 6/6 double-hung sash
trim simple surrounds
shutters n/a


Facade (cont'd)

- 3) Door(s) 1
 location centered on facade
 type paneled with exterior storm door
 trim simple surround and sidelights extending halfway down
- 4) Porch(es) door is sheltered by a gable-roofed portico with simple paired columns resting on a concrete block stoop with brick steps
- b. Side: Direction: E
- 1) Bays 3
- 2) Windows 5
 fenestration irregular
 type 6/6 double-hung sash; paired windows in gable end
 trim simple surrounds
 shutters n/a
- 3) Door(s) n/a
 location
 type
 trim
- 4) Porch(es) n/a
- c. Side: Direction: W
- 1) Bays 4
- 2) Windows 3+ (part of façade obscured by large bush)
 fenestration regular
 type ribbon of three windows with 6/6 double-hung sash centered on small gable end
 trim simple surrounds
 shutters n/a
- 3) Door(s) 1
 location centered on flat-roofed addition at south end
 type not visible; exterior storm door
 trim simple surround
- 4) Porch(es) door is accessed via short flight of brick stairs with metal railings
- d. Rear: Direction: S [not visible]
- 1) Bays
- 2) Windows
 fenestration
 type
 trim
 shutters
- 3) Door(s)
 location
 type
 trim
- 4) Porch(es)

9. INTERIOR:

10. LANDSCAPING: Bushes planted close to house around perimeter; surrounding lot is open cultivated fields.

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-8134

1. ADDRESS/LOCATION: South side of Route 54 between Salty Way Drive and Keenwick Road

2. FUNCTION(S): historic barn current garage

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system frame
b. Number of stories 1
c. Wall coverings wood clapboard
d. Foundation concrete block
e. Roof
structural system frame
coverings standing seam metal
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: N
1) bays: 1
2) windows: n/a
3) door(s): double horizontally sliding wood barn doors
4) other:

- b. Side: direction: E
 - 1) bays: 1
 - 2) windows: one window with 6/6 double-hung sash
 - 3) door(s): n/a
 - 4) other:

- c. Side: direction: W [not visible]
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: S [not visible]
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-8134

1. ADDRESS/LOCATION: South Side of Rt. 54, between Teaberry Circle and Keenwick Road (TP 5-33-19-24.01)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-8134 Date 1/16/03 Photo Roll # 3 Surveyor Jennifer M. Holl/Katie Diehl

Description (1) Lateral view of residence, facing southeast; (2) Lateral view of garage, facing southwest; (3) Lateral view of residence, facing southwest; (4) Elevation of front façade of residence, facing south; (5) Elevation of front façade of residence and garage, facing south

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-2097

1. HISTORIC NAME/FUNCTION: Dwelling, south side of Route 54 2/10 mile NW of 58C

2. ADDRESS/LOCATION: Box 149 Route 54, south side of Route 54 2/10 mile NW of 58C

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: No significant alterations appear to have been made to the historic fabric of the property since the 1980 survey form.

5. SETTING INTEGRITY: The setting has not altered significantly, apart from the destruction of several chicken houses associated with the Adkins properties on the opposite side of Route 54.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
2	CRS 3 Secondary Building Form	Garage, storage buildings
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Jennifer Holl/Katie Diehl/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: _____

Organization: McCormick Taylor, Inc. Date: September 2003
(Revised April 2004)

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-2097

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):


- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750" Contact Period (Native American)
 - 1630-1730" Exploration and Frontier Settlement
 - 1730-1770" Intensified and Durable Occupation
 - 1770-1830" Early Industrialization
 - 1830-1880" Industrialization and Early Urbanization
 - 1880-1940" Urbanization and Early Suburbanization
 - 1940-1960" Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-2097

1. ADDRESS/LOCATION: Box 149 Route 54, south side of Route 54 2/10 mile NW of 58C
2. FUNCTION(S): historic Single-family residential current Single-family residential
3. YEAR BUILT: 1935 CIRCA?: ARCHITECT/BUILDER: _____
4. STYLE OR FLOOR PLAN: Dutch Colonial Revival
5. INTEGRITY: original site moved
 if moved, from where _____ other location's CRS # _____ year _____

list major alterations and additions with years (if known) year

- a. rear ell
- b. shed-roofed addition at southeast corner

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: irregular Stories: 2
Additions: rear ell and shed-roofed addition to southeast corner
- b. Structural system (if known): light frame
- c. Foundation: materials: brick
basement: full partial not visible no basement
- d. Exterior walls (original if visible & any subsequent coverings): white vinyl siding
- e. Roof: shape: side gambrel
materials: wood shingles
cornice: simple molded
dormers: continuous shed dormer on front (north) and rear (south) facades; dormer on south façade is interrupted by ell addition
chimney: location(s): brick exterior chimney extending through ridge of roof centered on west façade; brick chimney in roof ridge at east end

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: N
- | | |
|------------|---|
| 1) Bays | 5 |
| 2) Windows | 7 |
- fenestration irregular
 type multi-light bay windows in each side wing; windows with 8/8 sash flanking door; 6/6 sash windows in dormer
 trim simple surrounds
 shutters louvered, green


Facade (cont'd)

- 3) Door(s) 1
location centered on facade
type paneled with two lights at top and exterior storm door
trim simple molded surround
- 4) Porch(es) Door is sheltered by gable-roofed arched portico supported by columns, resting on brick stoop and steps with flanking lion statues.
- b. Side: Direction: W
- 1) Bays 2
- 2) Windows 3+
fenestration irregular
type paired windows with 6/6 sash on side addition; wider windows with 6/6 sash in gable end on second story; ell not visible
trim simple surrounds
shutters louvered, green
- 3) Door(s) n/a
location
type
trim
- 4) Porch(es) n/a
- c. Side: Direction: E
- 1) Bays 3
- 2) Windows 5+
fenestration irregular
type paired windows with 6/6 sash on side addition; 6/6 sash in gable end; oriel window at north end of shed-roofed rear porch addition; 1/1 sash at south end of shed-roofed rear porch; wide with 6/6 sash on second story of rear ell
trim simple surrounds
shutters louvered, green on all windows except rear porch; only one shutter on oriel
- 3) Door(s) 1
location slightly south of center on rear porch
type two large lights in upper portion
trim simple surround
- 4) Porch(es) shed-roofed addition has enclosed porch windows and door at south end; door is accessed via short flight of concrete steps with metal railing
- d. Rear: Direction: S
- 1) Bays 2+
- 2) Windows 4+
fenestration irregular
type 1/1 sash on first floor; wide 6/6 sash on second floor; not all windows visible
trim simple surrounds
shutters louvered, green on second floor
- 3) Door(s) 1
location west end of rear ell
type two large lights in upper portion
trim simple surround
- 4) Porch(es) n/a

9. INTERIOR:

10. LANDSCAPING: Bushes and trees planted in close proximity to house around entire perimeter and some around outbuildings; sides and rear of lot lightly wooded with mostly deciduous trees.

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-2097

1. ADDRESS/LOCATION: Box 149 Route 54, south side of Route 54 2/10 mile NW of 58C

2. FUNCTION(S): historic Garage current Garage

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: square

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system frame
- b. Number of stories 1
- c. Wall coverings white wood clapboard siding
- d. Foundation not visible; concrete slab floor
- e. Roof
structural system hipped gable with board fascia and box returns
coverings wood shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: N
 - 1) bays: 1
 - 2) windows: n/a
 - 3) door(s): large (two-car) opening; door not visible
 - 4) other: eagle ornament centered in gable end

- b. Side: direction: E
 - 1) bays: 1
 - 2) windows: one window with 6/6 double-hung sash, simple surround, and green louvered shutters centered on facade
 - 3) door(s): n/a
 - 4) other:

- c. Side: direction: W
 - 1) bays: 1
 - 2) windows: one window with 6/6 double-hung sash, simple surround, and green louvered shutters centered on facade
 - 3) door(s): n/a
 - 4) other:

- d. Rear: direction: S
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan open

b) Partition/walls

c) Finishes no interior wall finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-2097

1. ADDRESS/LOCATION: Box 149 Route 54, south side of Route 54 2/10 mile NW of 58C

2. FUNCTION(S): historic storage current storage

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Two adjoining rectangular sheds

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system two rectangular frame structures with front-gable roofs, approximately two feet apart and joined at the interior roofline
b. Number of stories 1
c. Wall coverings white wood clapboard siding
d. Foundation not visible
e. Roof
structural system front gable; two roofs join
coverings wood shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: N
1) bays: 2
2) windows: n/a
3) door(s): one solid door with simple surround centered on each portion
4) other: _____

- b. Side: direction: E
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:

- c. Side: direction: W
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:

- d. Rear: direction: W
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-2097

1. ADDRESS/LOCATION: South Side of Rt. 54, at intersection with Bayville Road (TP 5-33-19-27)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-2097

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-2097 Date 1/16/03 Photo Roll # 4 Surveyor Jennifer M. Holl/Katie Diehl

Description (1) Elevation of front façade of residence, facing south; (2) Lateral view of residence and outbuildings, facing southwest; (3) Lateral view of outbuildings, facing southwest; (4) Lateral view of residence, facing northwest; (5) Lateral view of residence, facing southeast

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13

BH District 7

CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM



FORM CRS-2

FOR OFFICE USE ONLY

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314

CRS # 5-2097
Quad Assawoman Bay
SPO map 20-21-05
Hundred Baltimore
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: Parcel 27 Tax Map 5-33-19
2. STREET LOCATION: South side of Rt. 54, 3/4 mile NW of 58C
3. OWNER'S NAME: Donald & Tsabelle Campbell TEL. # _____
ADDRESS: Box 149 - Selbyville, Del. 19975
4. TYPE OF LOCUS: a) structure b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field c) woodland
d) scattered buildings e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Sarah Bryan, Emily Cuttighorn TEL. # 856 7701 ext 31
YOUR ADDRESS: Old Sussex County Court House, Georgetown DE 19127
ORGANIZATION (if any) Historical Surveys, Inc. DATE: 7/31/80


USE BLACK INK ONLY

3. SKETCH MAP

Please indicate position of house in relation to geographical landmarks such as streams and roads.

North

INDICATE NORTH ON SKETCH




USE BLACK INK ONLY

9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-2089/2099/2100

1. HISTORIC NAME/FUNCTION: Adkins Farm/Agricultural Complex

2. ADDRESS/LOCATION: North side of Route 54, at the intersection of Bayville Road

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: No significant alterations appear to have been made to the historic fabric of the property since the 1980 survey form.

5. SETTING INTEGRITY: The setting has not altered significantly, apart from the destruction of several chicken houses on the Adkins Farm.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
3	CRS 2 Main Building Form	Dwellings
8	CRS 3 Secondary Building Form	Garages, storage buildings, corn cribs, sheds, chicken house
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Jennifer Horner/Katie Post/Lara Otis

Principal Investigator name: Francine Arnold

Principal Investigator signature: _____

Organization: McCormick Taylor, Inc. Date: September 2003 (Revised June 2004)

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-2089/2099/2100

The Adkins Farm/ Agricultural Complex was previously surveyed as three separate resources.(S-2089/2099/2100). During the current survey (September 2003) the properties were evaluated as an agricultural complex and combined.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750" Contact Period (Native American)
- 1630-1730" Exploration and Frontier Settlement
- 1730-1770" Intensified and Durable Occupation
- 1770-1830" Early Industrialization
- 1830-1880" Industrialization and Early Urbanization
- 1880-1940" Urbanization and Early Suburbanization
- 1940-1960" Suburbanization and Early Ex-urbanization


b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-2089

1. ADDRESS/LOCATION: East side of Bayville Road, north of Route 54

2. FUNCTION(S): historic Single-family residential current vacant

3. YEAR BUILT: 1880 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE OR FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. one-story rear ell addition

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 2.5
Additions: on rear (south) façade, a one-story, one bay by one bay lean-to addition

b. Structural system (if known): light frame

c. Foundation: materials: brick
basement: full partial not visible no basement

d. Exterior walls (original if visible & any subsequent coverings): wood shingles

e. Roof: shape: gable
materials: asphalt shingles
cornice: cornice returns
dormers: n/a
chimney: location(s): brick chimney east end of the gable peak

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: North
1) Bays 3
2) Windows
fenestration regular
type 1/1 double-hung replacement windows
trim simple surrounds
shutters n/a

Facade (cont'd)

- 3) Door(s)
 location centered, first floor
 type wood panel
 trim plain, wood
- 4) Porch(es) n/a

b. Side: Direction: West

- 1) Bays 2
- 2) Windows
 fenestration regular
 type 1/1
 trim simple surrounds
 shutters n/a
- 3) Door(s) n/a
 location n/a
 type n/a
 trim n/a
- 4) Porch(es) n/a

c. Side: Direction: East; not visible

- 1) Bays 2
- 2) Windows
 fenestration regular
 type not visible
 trim not visible
 shutters not visible
- 3) Door(s) not visible
 location not visible
 type not visible
 trim not visible
- 4) Porch(es) n/a

d. Rear: Direction: South


- 1) Bays 3
- 2) Windows
 fenestration regular
 type 1/1 double-hung replacement windows
 trim plain, wood
 shutters n/a
- 3) Door(s) none
 location n/a
 type n/a
 trim n/a
- 4) Porch(es) none

9. INTERIOR: Unknown

10. LANDSCAPING: Open agricultural fields to north, abandoned chicken houses to south along Route 54, Bayville Road (County Road 58B) located to the west of the dwelling

11. OTHER COMMENTS:

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-2099

1. ADDRESS/LOCATION: North side of Route 54, west of the intersection of Keenwick Road

2. FUNCTION(S): historic Single-family residential current Single-family residential

3. YEAR BUILT: 1939 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE OR FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular Stories: 2.5
Additions:
- b. Structural system (if known): light frame
- c. Foundation: materials: brick
basement: full partial not visible no basement
- d. Exterior walls (original if visible & any subsequent coverings): wood shakes painted white
- e. Roof: shape: gable
materials: green asphalt shingles
cornice: small return
dormers: n/a
chimney: location(s): brick chimney; center rear slope

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: South
 - 1) Bays 3
 - 2) Windows
 - fenestration regular
 - type narrow 6/6 wood tripartite on 1st floor; 6/6 wood sash on the 2nd floor
 - trim simple surrounds
 - shutters green, wood

Facade (cont'd)

- 3) Door(s)
 location center
 type wood paneled
 trim pilasters; 4-light transom; pediment
- 4) Porch(es) brick entry stairs

b. Side: Direction: East

- 1) Bays 2
- 2) Windows
 fenestration irregular
 type 6/6 wood sash
 trim simple surrounds
 shutters green, wood
- 3) Door(s)
 location southern end
 type 12-light; wood
 trim simple surround
- 4) Porch(es) shed roof entry porch with simple posts


c. Side: Direction: West

- 1) Bays 2
- 2) Windows
 fenestration irregular
 type 6/6 wood sash
 trim simple surrounds
 shutters green, wood
- 3) Door(s) n/a
 location
 type
 trim
- 4) Porch(es) n/a

d. Rear: Direction: North

- 1) Bays 3
- 2) Windows
 fenestration irregular
 type 6/6 wood sash
 trim simple surrounds
 shutters n/a
- 3) Door(s) 1
 location centered on first story
 type not visible
 trim not visible
- 4) Porch(es) enclosed rear porch addition

9. **INTERIOR:** The first floor consists of a utility room, kitchen, dining room, half bath and living room with a fireplace. The second floor consists of three bedrooms and a full bath; most of the walls and ceilings in the dwelling are plaster, and the floors are carpet over pine.
10. **LANDSCAPING:** Various large and small bushes, including holly, planted close to house around perimeter; lot also includes open fields.
11. **OTHER COMMENTS:** The information concerning the interior was taken verbatim from will of Wilfred J. Adkins (Sussex County Will Book 265, Page 44), dated September 22, 1995.



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-2099

1. ADDRESS/LOCATION: 300 Route 54, north side of Route 54, 0.1 mile northwest of County Road 58C

2. FUNCTION(S): historic corn crib current storage

3. YEAR BUILT: 1900 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system light frame
- b. Number of stories 1
- c. Wall coverings white wood clapboard
- d. Foundation slab
- e. Roof
structural system front gable with exposed rafter ends and board fascia
coverings green wood shakes
openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: South
 - 1) bays: 1
 - 2) windows: n/a
 - 3) door(s): vertical board door with simple surround centered on facade
 - 4) other: n/a

- b. Side: direction: East
 - 1) bays: 1
 - 2) windows: one window with 4/4 double-hung sash and simple surround centered on facade
 - 3) door(s): n/a
 - 4) other: n/a

- c. Side: direction: West [not visible]
 - 1) bays: 1
 - 2) windows: not visible
 - 3) door(s): n/a
 - 4) other: n/a

- d. Rear: direction: North [not visible]
 - 1) bays: 1
 - 2) windows: not visible
 - 3) door(s): not visible
 - 4) other: n/a


9. INTERIOR (if accessible): not accessible

a) Floor plan Unknown

b) Partition/walls Unknown

c) Finishes Unknown

d) Furnishings/machinery Unknown



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-2099

1. ADDRESS/LOCATION: 300 Route 54, north side of Route 54, 1/10 mile NW of 58C

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 1945 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: square

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system light frame
b. Number of stories 1.5
c. Wall coverings white wood clapboard siding
d. Foundation concrete slab
e. Roof
structural system front gable
coverings asphalt shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: South
1) bays: one large (two-car) opening almost entire width of facade
2) windows: n/a
3) door(s): n/a
4) other: n/a

b. Side: direction: East [not visible]

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: n/a

c. Side: direction: West [not visible]

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: n/a

d. Rear: direction: North [not visible]

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: n/a


9. INTERIOR (if accessible):

a) Floor plan open

b) Partition/walls none

c) Finishes garage appears to be unfinished with bare wood studs

d) Furnishings/machinery none



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-2100

1. ADDRESS/LOCATION: NW corner of the intersection of Route 54 and Bayville Road (County Road 58B)
2. FUNCTION(S): historic Single-family residential current Single-family residential
3. YEAR BUILT: 1912 CIRCA?: ARCHITECT/BUILDER: Unknown
4. STYLE OR FLOOR PLAN: rectangular
5. INTEGRITY: original site moved
 if moved, from where _____ other location's CRS # _____ year _____

list major alterations and additions with years (if known)

year

a. shed-roofed addition to rear (north) facade

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular Stories: 1.5
 Additions: one-story shed-roofed addition to rear (north) facade
- b. Structural system (if known): light frame
- c. Foundation: materials: rough-faced concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible & any subsequent coverings): aluminum siding; fish-scale shingles under front porch and on bays
- e. Roof: shape: hipped
 materials: asphalt shingles
 cornice: simple enclosed
 dormers: hipped-roof dormers in each roof slope
 chimney: location(s): brick chimney near ridge on side (west) slope of roof

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: South
- 1) Bays 3
- 2) Windows 2
- fenestration irregular
 type large multi-light bay window west of door (replacement); small rectangular wood sash window with six vertical lights east of door (original)
 trim simple surrounds
 shutters no shutters on windows; door has louvered flanking shutters

Facade (cont'd)

- 3) Door(s) 1
 location slightly east of center
 type not visible
 trim simple surround
- 4) Porch(es) full-width, hipped-roof front porch with bracketed columns, wood railing and stairs

b. Side: Direction: West

- 1) Bays 3
- 2) Windows 6
 fenestration irregular
 type large multi-light bay window centered on first floor; paired windows with 12 lights each to the south, window to the north obscured by bush; 3 ribbon windows with 4 vertical lights over one in dormer
 trim simple surrounds
 shutters faux-louvered vinyl shutters present on both stories
- 3) Door(s) none
 location n/a
 type n/a
 trim n/a
- 4) Porch(es) n/a

c. Side: Direction: East

- 1) Bays 4
- 2) Windows 5
 fenestration irregular
 type large bay window at south end; small rectangular window with 5 vertical lights near center; paired windows at north end and on rear addition; single window in dormer
 trim simple surrounds
 shutters faux-louvered vinyl; on all windows except small rectangular w/vertical lights
- 3) Door(s) none
 location n/a
 type n/a
 trim n/a
- 4) Porch(es) n/a


d. Rear: Direction: North

- 1) Bays 3
- 2) Windows 5
 fenestration irregular
 type 2 windows with 1/1 sash flanking door; 3 wood sash Craftsman-style windows with 4 vertical lights over one in dormers
 trim simple surrounds
 shutters louvered
- 3) Door(s) 1
 location centered on first story; accessed via short flight of steps w/metal railing
 type paneled with patterned glass in upper half
 trim simple surround
- 4) Porch(es) enclosed rear porch addition

9. INTERIOR: Unknown

10. LANDSCAPING: Various large and small bushes, including holly, planted close to house around perimeter; lot also includes open fields and wooded stand to the west.

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-2100

1. ADDRESS/LOCATION: NW corner of the intersection of Route 54 and Bayville Road (County Road 58B)

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 1980 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: square

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system light frame
- b. Number of stories 1
- c. Wall coverings white vinyl siding
- d. Foundation concrete block
- e. Roof
structural system front gable
coverings asphalt shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: West
 - 1) bays: 2
 - 2) windows: none
 - 3) door(s): wide vinyl overhead garage door
 - 4) other: n/a

b. Side: direction: North

- 1) bays: 2
- 2) windows: none
- 3) door(s): one door with paneled bottom and six lights above at west end of facade
- 4) other: n/a

c. Side: direction: South

- 1) bays: 2
- 2) windows: none
- 3) door(s): none
- 4) other: n/a

d. Rear: direction: East

- 1) bays: 2
- 2) windows: one window with double-hung sash and louvered shutters centered on facade
- 3) door(s): none
- 4) other: n/a


9. INTERIOR (if accessible): not accessible

a) Floor plan Unknown

b) Partition/walls Unknown

c) Finishes Unknown

d) Furnishings/machinery Unknown



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-2100

1. ADDRESS/LOCATION: NW corner of the intersection of Route 54 and Bayville Road (County Road 58B)

2. FUNCTION(S): historic corn crib current storage

3. YEAR BUILT: 1900 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system light frame
b. Number of stories 1
c. Wall coverings white wood clapboard
d. Foundation not visible
e. Roof
structural system front gable
coverings asphalt shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: South
1) bays: 1
2) windows: n/a
3) door(s): centered on facade
4) other: n/a

b. Side: direction: East

- 1) bays: 1
- 2) windows: one window with 4/4 double-hung wood sash and louvered shutters centered on facade
- 3) door(s): n/a
- 4) other: n/a

c. Side: direction: West

- 1) bays: 1
- 2) windows: none
- 3) door(s): none
- 4) other: n/a

d. Rear: direction: North

- 1) bays: 1
- 2) windows: none
- 3) door(s): none
- 4) other: none


9. INTERIOR (if accessible): not accessible

a) Floor plan Unknown

b) Partition/walls Unknown

c) Finishes Unknown

d) Furnishings/machinery Unknown



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-2100

1. ADDRESS/LOCATION: NW corner of the intersection of Route 54 and Bayville Road (County Road 58B)

2. FUNCTION(S): historic corn crib current storage

3. YEAR BUILT: 1900 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system light frame
b. Number of stories 1
c. Wall coverings wood clapboard
d. Foundation Not visible
e. Roof
structural system side gable
coverings asphalt shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: West
1) bays: 1
2) windows: none
3) door(s): battened door slightly west of center
4) other: n/a

b. Side: direction: South

- 1) bays: 1
- 2) windows: none
- 3) door(s): none
- 4) other: n/a

c. Side: direction: North

- 1) bays: 1
- 2) windows: none
- 3) door(s): none
- 4) other: n/a

d. Rear: direction: East [not visible]

- 1) bays: 1
- 2) windows: not visible
- 3) door(s): not visible
- 4) other: n/a


9. INTERIOR (if accessible): not accessible

a) Floor plan Unknown

b) Partition/walls Unknown

c) Finishes Unknown

d) Furnishings/machinery Unknown



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-2100

1. ADDRESS/LOCATION: NW corner of the intersection of Route 54 and Bayville Road (County Road 58B)

2. FUNCTION(S): historic storage current storage

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system light frame
b. Number of stories 1
c. Wall coverings vinyl
d. Foundation not visible
e. Roof
structural system front gable
coverings asphalt shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: S
1) bays: 1
2) windows: n/a
3) door(s): single door at west end of facade
4) other: _____

- b. Side: direction: E
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other: n/a

- c. Side: direction: W [not visible]
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: N
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-2100

1. ADDRESS/LOCATION: NW corner of the intersection of Route 54 and Bayville Road (County Road 58B)

2. FUNCTION(S): historic Machine storage current Machine storage

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system concrete block with wood roof
- b. Number of stories 1
- c. Wall coverings concrete block
- d. Foundation slab
- e. Roof
structural system side gable with exposed rafter ends; raised at north end
coverings asphalt shingles
openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: East
 - 1) bays: 5 large openings formed by slender support columns
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other: n/a

- b. Side: direction: South
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other: horizontal weatherboard in gable end

- c. Side: direction: North
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other: eastern slope of roof is raised

- d. Rear: direction: West
 - 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other: n/a


9. INTERIOR (if accessible):

a) Floor plan Open

b) Partition/walls No partitions between bays

c) Finishes Unfinished with exposed walls

d) Furnishings/machinery Farm equipment stored inside shed



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-2100

1. ADDRESS/LOCATION: NW corner of the intersection of Route 54 and Bayville Road (County Road 58B)

2. FUNCTION(S): historic Chicken house current Vacant

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

- a.
- b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system light frame
- b. Number of stories 1
- c. Wall coverings corrugated metal sheathing and concrete block
- d. Foundation not visible
- e. Roof
structural system shed roof
coverings metal
openings none

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: South
 - 1) bays: 2
 - 2) windows: none
 - 3) door(s): wood door east side of front facade
 - 4) other: 2 story metal chicken feed tower

- b. Side: direction: East
 - 1) bays: multiple
 - 2) windows: n/a

 - 3) door(s): n/a

 - 4) other: n/a

- c. Side: direction: West
 - 1) bays: multiple
 - 2) windows: n/a

 - 3) door(s): n/a

 - 4) other: n/a

- d. Rear: direction: North
 - 1) bays: 2
 - 2) windows: n/a

 - 3) door(s): n/a

 - 4) other: n/a


9. INTERIOR (if accessible): not accessible

a) Floor plan Likely open; this chicken house appears as though it could have housed up to 5,000 broilers at one time

b) Partition/walls Unknown

c) Finishes Likely unfinished walls

d) Furnishings/machinery Unknown



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-2089/S-2099/S-2100

1. ADDRESS/LOCATION: North Side of Rt. 54, at the intersection with Bayville Road (TP 5-33-19-25, 5-33-20-02, 5-33-20-03)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH




||||| National Registry Boundary

4. SITE PLAN:

CRS # S-2089/S-2099/S-2100

INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-2089 Date 1/16/03 Photo Roll # 4 Surveyor Jennifer M. Holl/Katie Diehl

Description (1) Lateral view of I-House, facing northeast; (2) Lateral view of I-House, facing north

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-2099 Date 1/16/03 Photo Roll # 4 Surveyor Jennifer M. Holl/Katie Diehl

Description (1) Elevation of front façade of Colonial Revival House, facing north; (2) Lateral view of Colonial Revival House and outbuildings, facing northeast; (3) Lateral view of Colonial Revival House, facing southeast; (4) Lateral view of outbuildings, facing northwest

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-2099 Date 1/16/03 Photo Roll # 4 Surveyor Jennifer M. Holl/Katie Diehl

Description (5) Lateral view of Colonial Revival House, facing southwest; (6) Lateral view of Colonial Revival House, facing northwest

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-2100 Date 1/16/03 Photo Roll # 4 Surveyor Jennifer M. Holl/Katie Diehl

Description (1) Lateral view of bungalow, facing northwest; (2) Lateral view of bungalow, facing northwest; (3) Lateral view of bungalow, facing northeast; (4) Lateral view of equipment shed, facing northwest

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-2100 Date 1/16/03 Photo Roll # 4 Surveyor Jennifer M. Holl/Katie Diehl

Description (5) View of outbuildings, facing northwest; (6) Lateral view of bungalow, facing west; (7) Lateral view of equipment shed, facing north; (8) Lateral view of garage, facing east

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-2100 Date 1/16/03 Photo Roll # 4 Surveyor Jennifer M. Holl/Katie Diehl

Description (9) Elevation of side façade of bungalow, facing west; (10) View of chicken house, facing east; (11) Lateral view of chicken house, facing north

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13

B. H. District 7

CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM



DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314

FORM CRS-2

FOR OFFICE USE ONLY

CRS # S-2089
Quad A
SPO map # 0-21-05
Hundred 1
DOCUMENT 0-06/78/0477


1. NAME OF LOCUS: Parcel 5 - Tax Map S-33-13
2. STREET LOCATION: SE side of Rd 58 B, 1/4 mile NE of Rt 57
3. OWNER'S NAME: Althea Pepper Murrell TEL. # _____
ADDRESS: Rt. 1, Box 144, Selbyville, DE 19975
4. TYPE OF LOCUS: a) structure b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field c) woodland
d) scattered buildings e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known b) zoning _____ c) roads _____ d) developer _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Sarah Buser, Emily Billingham TEL. # 851-1701 ext 36
YOUR ADDRESS: Old Sussex County Court House, Georgetown, DE, 1994
ORGANIZATION (if any) Historical Surveyors DATE: 7/31/80

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.

↑ North



INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

CULTURAL RESOURCE SURVEY
STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314



FOR OFFICE USE ONLY


Form CRS-1

CRS # 5-2109
Quad Assawoman Bay
SPO map # 20-21-05
Hundred Baltimore
DOCUMENT 20-0677 3/08/14

1. ADDRESS OF STRUCTURE : Parcel 5 Tax Map 5-33-13

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape T shape
stories 2 stories
bays 3 bays
wings 1-story gable roof wing on rear
1-story shed roof addition on left of
- b) Structural system brick
frame; single pile
- c) Foundation
materials brick
basement
- d) Exterior walls
materials
color(s) hand hewn wooden shingles
brown
- e) Roof
shape; materials gable roof; asbestos shingles
cornice molded box cornice with partial return;
dormers none
chimney location(s) simple brick chimney on left exterior
end of main house; simple brick chimney on interior
- f) Windows end of wing.
spacing regular
type 1/6 lites; single hung - 2 lite eyebrow windows
trim molded trim; slip sill in gable ends
shutters none
- g) Door
spacing center hall plan
type white; 2 panels
trim plain trim - gable roof hood over door has
wooden shingles, molded box cornice & 3 square wooden
- h) Porches supports
location(s)
materials
supports None
trim
- i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION: good _____ fair deteriorated _____

marks: _____

4. INTEGRITY: a) original site b) moved _____

c) if moved, when and from where _____

d) list major alterations and dates (if known) _____

5. DATE OF INITIAL CONSTRUCTION: _____

6. ARCHITECT/BUILDER: _____

7. RELATED OUTBUILDINGS:

a) barn _____ b) carriage house _____ c) garage _____ d) privy _____

e) shed _____ f) greenhouse _____ g) shop _____ h) gardens _____

i) icehouse _____ j) springhouse _____ k) other concrete

describe: concrete low gable roof with wooden
shingles, & wooden exterior

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

9. Primary References: (include location of reference).

field survey

10. Surveyor: Sarah Bryan, Emily Birmingham Date of Form: 7/30/80

USE BLACK INK ONLY

B.H. District 1

CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314



FORM CR-3

FOR OFFICE USE ONLY

CRS # S-2099
Quad Assawomeet Bay
SPD map # 20-21-01
Hundred Baltimore
DOCUMENT 20-06/78/01/1

1. NAME OF LOCUS: Parcel 3 Tax Map 5-33-20
2. STREET LOCATION: North side of Rt. 54, 1/2 mile NW of 58C
3. OWNER'S NAME: Wilfred J. Adkins TEL. # _____
ADDRESS: Rt. 54, Selbyville, Del. 19975
4. TYPE OF LOCUS: a) structure b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field c) woodland _____
d) scattered buildings e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Senate Report, Emily Brittingham TEL. # 856 221-0150
YOUR ADDRESS: Old Sussex County Court House, Georgetown, DE 19341
ORGANIZATION (if any) Historical Surveys DATE: 7/30/00

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY
STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314




Form CRS-1
FOR OFFICE USE ONLY

CRS # S-2099
Quad As. Ansonia Bay
SPO map # 20-21-05
Hundred Ca. 10000
DOCUMENT 20-1678/09/14

1. ADDRESS OF STRUCTURE : _____
2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape central block
stories 2 stories
bays 3 bays
wings 1 story gable wing on left
b) Structural system
frame, single pile
c) Foundation
materials brick
basement




- d) Exterior walls
materials hand sawn wooden shingles
color(s) white
e) Roof
shape: gable roof; materials asbestos shingles
cornice molded box cornice with partial returns
dormers none
chimney location(s) simple brick exterior chimney
f) Windows
spacing regular
type 6/8 lites; single hung
trim molded trim
shutters greek flush shutters
g) Door
spacing center hall plan
type white; 6 panels
trim white plaster on each side, triangular pediment over door, 4 lite transom, molded trim
h) Porches
location(s) right side - end roof
materials brick floor - foundation
supports white square wooden supports
trim molded box cornice
i) Interior details (if accessible)

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads. 



INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

3. CONDITION: good _____ deteriorated _____

remarks: _____

4. INTEGRITY: a) original site _____ b) moved _____

c) if moved, when and from where _____

d) list major alterations and dates (if known) _____

5. DATE OF INITIAL CONSTRUCTION: _____

6. ARCHITECT/BUILDER: _____

7. RELATED OUTBUILDINGS:

a) barn _____ b) carriage house _____ c) garage _____ d) privy _____

e) shed _____ f) greenhouse _____ g) shop _____ h) gardens _____

i) icehouse _____ j) springhouse _____ k) other chicken house _____

describe: garage has gable roof & white aluminum siding

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

9. Primary References: (include location of reference).

field survey

10. Surveyor: Sarah Bryan, Emily Brinkman Date of Form: 7/30/80

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM



DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314

FORM CP5-2

FOR OFFICE USE ONLY

CRS # 5-2100
Quad Darwinville Bay
SPO map # 20-31-05
Hundred Baltimore
DOCUMENT 20-06/78/14/7

1. NAME OF LOCUS: Parcel 3 - Tax Map 5-33-201
2. STREET LOCATION: North side of Rt. 54, 1/2 mile NW of S&C
3. OWNER'S NAME: Wilfred J. Adkins TEL. # _____
ADDRESS: Rt. 54, Selbyville, Del. 19975
4. TYPE OF LOCUS: a) structure b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field c) woodland _____
d) scattered buildings e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Sarah Bryan, Emily Butteringham TEL. # 856 7701 ext 361
YOUR ADDRESS: Old Sussex County Court House, Georgetown, DE. 19742
ORGANIZATION (if any) Historical Surveyors DATE: 7/21/10

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY
STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314




Form CRS-1
FOR OFFICE USE ONLY

CRS # 5-100
Quad Asa Woodson Ave
SPQ map # 20-21-05
Hundred Washington
DOCUMENT 20-06 178/08/14

1. ADDRESS OF STRUCTURE : Parcel 3 - Tax Map 5-33-20
2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape rectangular
stories 2 stories
bays 5 bays
wings none
- b) Structural system frame, single pile
- c) Foundation materials concrete block
basement
- d) Exterior walls materials hand laid wooden shingles
color(s) brown
- e) Roof shape: materials gable roof; wooden shingles
cornice plain box cornice
dormers none
chimney location(s) brick covered interior end chimney on left & right sides
- f) Windows spacing regular
type 1/2 lites, single hung white casings on 2nd floor
trim plain trim, ship sill
shutters none
- g) Door spacing 2 doors in center of buildings
type typewriter, 4 lites, 3 panels
trim plain
- h) Porches location(s) None
materials
supports
trim
- i) Interior details (if accessible)




USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.

↑ North



INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

3. CONDITION: good _____ fair x _____ deteriorated _____

remarks: _____

4. INTEGRITY: a) original site b) moved _____

c) if moved, when and from where _____

d) list major alterations and dates (if known) _____

5. DATE OF INITIAL CONSTRUCTION: _____

6. ARCHITECT/BUILDER: _____

7. RELATED OUTBUILDINGS:

a) barn _____ b) carriage house _____ c) garage _____ d) privy _____

e) shed _____ f) greenhouse _____ g) shop _____ h) gardens _____

i) icehouse _____ j) springhouse _____ k) other chicken houses

describe: Chicken houses are in good condition

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

9. Primary References: (include location of reference).

field survey

10. Surveyor: Smith, Bupin, Emily Britton Date of Form: 7/31/80

USE BLACK INK ONLY