



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10140
SPO Map 08-09-10
Hundred Seaford
Quad Seaford East
Other 3-31 3.00 26.00

1. HISTORIC NAME/FUNCTION: Dwelling, 9010 Elks Road
2. ADDRESS/LOCATION: 9010 Elks Road (S side)
3. TOWN/NEAREST TOWN: Seaford vicinity?
4. MAIN TYPE OF RESOURCE:

building <input checked="" type="checkbox"/>	structure <input type="checkbox"/>	site <input type="checkbox"/>	object <input type="checkbox"/>
landscape <input type="checkbox"/>	district <input type="checkbox"/>		
5. MAIN FUNCTION OF PROPERTY: Residential
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
Route 13/13a/Road 46 Intersection Improvement

7. ADDITIONAL FORMS USED:

#: Form:	List property types:
1 CRS 2 Main Building Form	
1 CRS 3 Secondary Building Form	
CRS 4 Archaeological Site Form	
CRS 5 Structure (Building-Like) Form	
CRS 6 Structure (Land Feature) Form	
CRS 7 Object Form	
CRS 8 Landscape Elements Form	
CRS 9 Map Form	N/A
CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Gerald M. Kuncio

Principal Investigator name: Gerald M. Kuncio

Principal Investigator signature: *Gerald M. Kuncio*

Organization: Skelly And Loy, Inc. Date: August 11, 2004

9. OTHER NOTES OR OBSERVATIONS:

CRS# 10140

Built within the Lakeshore Residential Development, platted in 1939.

Historic maps and highway plans date the building to ca. 1940.

Building is not threatened by physical harm from the Route 13/13A/Road 46 Intersection Improvements project.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750± Contact Period (Native American)
 - 1630-1730± Exploration and Frontier Settlement
 - 1730-1770± Intensified and Durable Occupation
 - 1770-1830± Early Industrialization
 - 1830-1880± Industrialization and Early Urbanization
 - 1880-1940± Urbanization and Early Suburbanization
 - 1940-1960± Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10140

1. ADDRESS/LOCATION: 9010 Elks Road

2. FUNCTION(S): historic Residential current Residential

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE OR FLOOR PLAN: Rectangular

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: Rectangular Stories: 1
Additions: None

b. Structural system (if known): Frame

c. Foundation: materials: Concrete block
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): Shake

e. Roof: shape: Hipped
materials: Asphalt
cornice: Box
dormers: None
chimney: location(s): 2 - Near center of the roof, just east of the peak (brick); front of house, east side of the facade.

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: N
1) Bays 3
2) Windows 4
fenestration Irregular
type Narrow 2/2 wood sash and 1/1 sash (within porch)
trim Narrow wood frames
shutters None

Facade (cont'd)

- 3) **Door(s)** 1
 location Centered
 type Wood and screen porch door with sidelights
 trim Sidelights and narrow transom
- 4) **Porch(es)** 2 bay enclosed (wood and screen) under roof eaves.

b. Side: Direction: E

- 1) **Bays** 4
- 2) **Windows** 3
 fenestration Regular
 type 2/2 wood sash
 trim Narrow wood frames
 shutters None
- 3) **Door(s)** 1
 location Rear, partial width enclosed porch
 type Paneled, late 20th century replacment with 1 fixed light
 trim Sidelight on north end
- 4) **Porch(es)** 1 frame, wood, and glass partial width porth at the rear of the elevation.

c. Side: Direction: W

- 1) **Bays** 3
- 2) **Windows** 4
 fenestration Regular
 type 2/2 wood sash
 trim Narrow wood frames
 shutters None
- 3) **Door(s)** None
 location N/A
 type N/A
 trim N/A
- 4) **Porch(es)** N/A

d. Rear: Direction: S

- 1) **Bays** 3
- 2) **Windows** Not visible
 fenestration Not visible
 type Not visible
 trim Not visible
 shutters Not visible
- 3) **Door(s)** Not visible
 location Not visible
 type Not visible
 trim Not visible
- 4) **Porch(es)** 1 partial width at rear and east side of the house.

9. **INTERIOR:** Not Accessed

10. **LANDSCAPING:** Flat front yard with driveway on the east side of the house edged by shrubbery; also scattered trees.

11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10140

1. ADDRESS/LOCATION: 9010 Elks Road (S side)

2. FUNCTION(S): historic Outbuilding/Storage current Outbuilding/Storage

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: Rectangular

5. INTEGRITY: original site moved

if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

- a.
- b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system Frame
- b. Number of stories 1
- c. Wall coverings Barn siding
- d. Foundation Not visible
- e. Roof
structural system Gable end with exposed rafters
coverings Rolled
openings None

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: N
 - 1) bays: 1
 - 2) windows: None
 - 3) door(s): 1, frame with barn siding
 - 4) other: N/A

- b. Side: direction: E
 - 1) bays: 1
 - 2) windows: None
 - 3) door(s): None
 - 4) other: N/A

- c. Side: direction: W
 - 1) bays: 1
 - 2) windows: None
 - 3) door(s): None
 - 4) other: N/A

- d. Rear: direction: S
 - 1) bays: 1
 - 2) windows: Not visible
 - 3) door(s): Not visible
 - 4) other: Not visible

9. INTERIOR (if accessible):

a) Floor plan Not Accessed

b) Partition/walls Not Accessed

c) Finishes Not Accessed

d) Furnishings/machinery Not Accessed



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10140

1. ADDRESS/LOCATION: 9010 Elks Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



USE BLACK INK ONLY

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # S-10140 Date 7/1/2004 Photo Roll # C-4568 Surveyor Gerald Kuncio

Description 10 - Façade and east side, facing SW; 11- Façade and west side, facing SE; 12 - Outbuilding, facade and east side, facing SW

Negative location (if other than SHPO) _____

Attach contact print(s):



10



11



12

Doc # 20-06-01-05-12

CRS-13