

**CRS No. N14394**

Address: 4233 Summit Bridge Road

Date of Construction/Major Alteration: ca. 1960

Time Period: 1960-2000±, Deurbanization and Sprawl

Geographic Zone: Upper Peninsula

Historic Period Theme(s): Architecture, Engineering, and Decorative Arts (Residential Architecture)

Name: Tush House

Tax Parcel: 1300700015

### *Description*

The dwelling at 4233 Summit Bridge Road is a one-story brick Ranch house with a linear form and overhanging eave. The house has original two-over-two windows with vinyl shutters, a recessed pane-and-panel entry with sidelights, and an interior brick chimney. The property also features two small wood sheds (one is modern), located to the north and east of the dwelling respectively. The property is surrounded by agricultural fields. An asphalt driveway runs east from Summit Bridge Road providing access to the dwelling. The property features a manicured lawn with mature trees and shrubs.

### *Historical Narrative*


The dwelling at 4233 Summit Bridge Road was likely built between 1958 and 1962 by Grover C. Tush and his wife, Mary P. (New Castle County Deed Book T61:7). The dwelling appears on the New Castle County aerials of the U.S. 301 project area and is depicted on the 1953 USGS map of the area as a magenta colored dwelling, indicating that the dwelling was constructed after 1953. The Tushs purchased the 0.88 acre lot "...with no improvements thereon erected..." from Claude W. and Helen D. Austin for one dollar in March 1958. The dwelling appears on a 1962 aerial photograph of the area. The parcel remained in the Tush family until March 2001, when Janet T. Neville acquired the property from Grover C. Tush, Jr. (New Castle County Deed Instrument 20010402 0022232).

### *National Register Evaluation*


The property at 4233 Summit Bridge Road was evaluated as a Residential Resource as identified in the *U.S. 301 Historic Context and Reconnaissance Survey Report* (A.D. Marble & Company 2005). Ranch dwellings are common mid-twentieth-century building types in the U.S. 301 APE. Therefore, these resources are generally not considered eligible unless they are part of eligible collections. As noted in the context, dwellings dating to the mid-twentieth century would not be considered eligible for listing in the National Register unless they retain an exceptionally high degree of integrity and a significant associated documentary record (construction plans, building contracts, etc.) that could provide new insight into residential construction and development during this period (A.D. Marble & Company 2005). The property was not constructed as part of a residential development and does not have the potential to yield information on residential construction or development, and therefore is not eligible for listing in the National Register under Criterion A. Based on the background research conducted for this project, the property does not appear to be associated with an individual who played a role in the historic development of the U.S. 301 project area; therefore, the property is not eligible for listing under Criterion B. The dwelling is an example of a common mid-twentieth-century form; therefore, the property is not eligible for listing under Criterion C. The property does not appear to possess the potential to yield information on building practices or methods of construction; therefore, the property does

not appear to be eligible for listing under Criterion D. Due to lack of significance, the Tush House is not eligible for listing in the National Register.

CRS No. N14394



N14394. Photograph 1: Tush House, view of south and west elevations, looking east.



N14394. Photograph 2: Tush House, shed, west elevation, looking northeast. This shed is located northeast of the dwelling.

DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901



CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS#: N14394.  
SPO Map: 06-07-30  
Hundred: Saint Georges  
Quad: Saint Georges  
Other: 1300700015

1. HISTORIC NAME/FUNCTION Tush House
2. ADDRESS/LOCATION: 4233 Summit Bridge Rd
3. TOWN/NEAREST TOWN: Middletown vicinity?
4. MAIN TYPE OF RESOURCE:      building     structure     site     object   
   landscape     district
5. MAIN FUNCTION OF PROPERTY:  
Single Dwelling      Storage
6. PROJECT TITLE/REASON FOR SURVEY (if applicable):  
U.S. 301 Project Development

7. ADDITIONAL FORMS USED:

#:	Form:	List Property Types:
1	CRS02	Dwelling
1	CRS03	Shed
1	CRS09	N/A

8. SURVEYOR INFORMATION:

Surveyor Name: Lauren Archibald / Architectural Historian

Principal Investigator Name: Barbara Copp / Sr. Architectural Historian

Principal Investigator Signature: Barbara M. Copp

Organization: A.D. Marble & Company Date: 9/26/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS#

N14394.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II
- 1600-1750 Contact Period (Native American)
- 1630-1730 Exploration and Frontier Settlement
- 1730-1770 Intensified and Durable Occupation
- 1770-1830 Early Industrialization
- 1830-1880 Industrialization and Early Urbanization
- 1880-1940 Urbanization and Early Suburbanization
- 1940-1960 Suburbanization and Early Ex-urbanization
- 1960-2000 Deurbanization and Sprawl

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                         |
| <input type="checkbox"/> Forestry              | <input type="checkbox"/> Settlement Patterns and Demographic Changes              |
| <input type="checkbox"/> Trapping/Hunting      | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                  |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                               |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                   |
| <input type="checkbox"/> Other                 | <input type="checkbox"/> Unknown  |



CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # N14394.01

1. ADDRESS/LOCATION: 4233 Summit Bridge Rd.
2. FUNCTION(S): historic Single Family Dwelling current Single Family Dwelling
3. YEAR BUILT: 1960 CIRCA?:  ARCHITECT/BUILDER: Unknown
4. STYLE OR FLOOR PLAN: Ranch
5. INTEGRITY: original site  moved 

<u>if moved, from where</u>	<u>other location's CRS #</u>	<u>year</u>
N/A	N/A	N/A
N/A	N/A	N/A
<u>list major alterations and additions with years (if known)</u>		<u>year</u>
a. N/A		N/A
b. N/A		N/A
6. CURRENT CONDITION: excellent  good  fair  poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
  - a. Overall shape: Rectangular Stories: One (1)  
Additions: N/A
  - b. Structural system (if known): Masonry (brick)
  - c. Foundation: materials: Brick  
basement: full  partial  not visible  no basement
  - d. Exterior walls (original if visible& any subsequent coverings): Brick, common bond
  - e. Roof: shape: Low-pitched gable with ridge parallel to Summit Bridge Road  
materials: Asphalt shingles  
cornice: Plain, boxed, vinyl  
dormers: N/A  
chimney: location(s): An interior brick chimney is located on the northern end of the roof ridge.
8. DESCRIPTION OF ELEVATIONS:
  - a. Facade: Direction: W
    - 1) Bays Seven (7)
    - 2) Windows Six (6)  
fenestration Irregular  
type (2) sets of 1/1 DHS paired; (3) single 1/1 DHS; (1) 3/1 picture window  
trim Brick sills; plain, flat, aluminum surround  
shutters 1/1 panel, vinyl

**Facade (cont'd)**

- 3) **Door(s)** One (1)  
     **location** Off-center  
     **type** Single, flush with sidelights  
     **trim** Plain, flat, aluminum surround
- 4) **Porch(es)** Recessed entrance
- b. **Side: Direction: S**
- 1) **Bays** Three (3)
- 2) **Windows** Three (3)  
     **fenestration** Irregular  
     **type** (3) 1/1 DHS; two different sizes  
     **trim** Plain, flat, aluminum surround  
     **shutters** 1/1 panel, vinyl
- 3) **Door(s)** N/A  
     **location** N/A  
     **type** N/A  
     **trim** N/A
- 4) **Porch(es)** N/A
- c. **Side: Direction: N**
- 1) **Bays** Three (3)
- 2) **Windows** Two (2)  
     **fenestration** Irregular  
     **type** (1) Chicago-style picture window; (1) 1/1 DHS  
     **trim** Brick sills; plain, flat, aluminum surround  
     **shutters** 1/1 panel, vinyl
- 3) **Door(s)** One (1)  
     **location** Located towards western end  
     **type** Single-leaf, flush  
     **trim** N/A
- 4) **Porch(es)** N/A
- d. **Rear: Direction: E**
- 1) **Bays** Seven (7)
- 2) **Windows** Six (6)  
     **fenestration** Irregular  
     **type** (5) 1/1 DHS; (1) set of paired, 1/1 DHS  
     **trim** Brick sills; plain, flat, aluminum surround  
     **shutters** 1/1 panel, vinyl
- 3) **Door(s)** One (1)  
     **location** Off-center  
     **type** Sliding glass patio door  
     **trim** Plain, flat, aluminum surround
- 4) **Porch(es)** Open poured concrete slab for patio

9. **INTERIOR:** Not accessible.

10. **LANDSCAPING:** Mature maple trees are located throughout the property. Small foundation plantings/shrubs surround the dwelling.

11. **OTHER COMMENTS:** N/A



CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # N14394.02

1. ADDRESS/LOCATION: 4233 Summit Bridge Rd.

2. FUNCTION(S): historic Shed current Shed

3. YEAR BUILT: 1955 CIRCA?:  ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: Open, rectangular

5. INTEGRITY: original site  moved

if moved, from where

N/A

original location's CRS #

N/A

year

N/A

N/A

N/A

N/A

list major alterations and additions with years (if known)

a. N/A

year

N/A

b. N/A

N/A

6. CURRENT CONDITION: excellent good X fair poor

7. DESCRIPTION:

a. Structural system Frame

b. Number of stories One (1)

c. Wall coverings Vertical aluminum siding, beaded, red

d. Foundation None; The shed sits atop a poured concrete slab.

e. Roof

structural system High-pitched gable with ridge perpendicular to Summit Bridge Road

coverings Standing seam metal

openings N/A

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: W

1) bays: Two (2)

2) windows: (1) 12-light, fixed sash

3) door(s): (1) single-leaf, pedestrian door

4) other: Flower box is located underneath window.

- b. Side: direction: S
  - 1) bays: Two (2)
  - 2) windows: 0
  - 3) door(s): (2) single-leaf, wooden, Dutch doors
  - 4) other: N/A

- c. Side: direction: N
  - 1) bays: One (1)
  - 2) windows: (1) 6-light, fixed
  - 3) door(s): 0
  - 4) other: N/A

- d. Rear: direction: E
  - 1) bays: Not accessible
  - 2) windows: Not accessible
  - 3) door(s): Not accessible
  - 4) other: Not accessible

9. INTERIOR (if accessible):

a) Floor plan            Not accessible.

b) Partition/walls        Not accessible.

c) Finishes            Not accessible.

d) Furnishings/machinery    Not accessible.



**CULTURAL RESOURCE SURVEY  
MAP FORM**

**DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901**

**CRS#: N14394.**


**1. ADDRESS/LOCATION: 4233 Summit Bridge Rd**

**2. NOT FOR PUBLICATION:**


**3. LOCATION MAP:**

**Indicate position of resource in relation to geographical landmarks such as streams and crossroads.**

**(attach section of USGS quad map with location marked or draw location map)**



4. SITE PLAN:



**CRS No. N14395**

Name: Westrod House

Address: 4872 Summit Bridge Road

Tax Parcel: 1301200010

Date of Construction/Major Alteration: ca. 1960; ca. 1970

Time Period: 1960-2000, Deurbanization and Sprawl

Geographic Zone: Upper Peninsula

Historic Period Theme(s): Architecture, Engineering, and Decorative Arts (Residential Architecture)

### *Description*

The dwelling at 4872 Summit Bridge Road is located at the end of a long gravel driveway. The irregularly shaped lot features a secondary modern dwelling located to the east of the primary dwelling. The dwelling at 4872 Summit Bridge Road is a gable front dwelling with a side gable addition (ca. 1970). The dwelling exhibits characteristics of the Ranch form, including a long, linear plan and overhanging eaves. The dwelling is clad in vertical wood paneling and features modern windows and doors. The complex roofline is sheathed with asphalt shingles and is pierced with an interior stone chimney. A small wood frame shed (ca. 1930) is located to the west of the dwelling. The property features a manicured lawn with mature trees and shrubs.

### *Historical Narrative*


The dwelling at 4872 Summit Bridge Road was built in 1960, according to the New Castle County parcel detail website. The long, linear structure (east/west orientation) appears on a 1962 aerial photograph of the area. It also is depicted on the photo-revised version of the 1953 topographic map in magenta, indicating that it was built after 1953. In June 1960, Stephen F. Westrod and his wife, Alice V., purchased a 6.85-acre lot from Joseph A. Vesztróczi and his wife, Mary T., for five dollars (New Castle County Deed Book D66:527). The Westrod's built a house on their lot soon after. Stephen F. Westrod died in December 1991 and the parcel passed by will to his wife (New Castle County Register of Wills WR101380). The property is currently co-owned by Alice V. Westrod and Stephanie A. Westrod (New Castle County Deed Book 2592 283).

### *National Register Evaluation*

The property at 4872 Summit Bridge Road was evaluated as a Residential Resource as identified in the *U.S. 301 Historic Context and Reconnaissance Survey Report* (A.D. Marble & Company 2005). Ranch dwellings are common mid-twentieth-century building types in the U.S. 301 APE. Therefore, these resources are generally not considered eligible unless they are part of eligible collections. As noted in the context, dwellings dating to the mid-twentieth century would not be considered eligible for listing in the National Register unless they retain an exceptionally high degree of integrity and a significant associated documentary record (construction plans, building contracts, etc.) that could provide new insight into residential construction and development during this period (A.D. Marble & Company 2005). The property was not constructed as part of a residential development and does not have the potential to yield information on residential construction or development; therefore, it is not eligible for listing in the National Register under Criterion A. Based on the background research conducted for this project, the property does not appear to be associated with an individual who played a role in the historic development of the U.S. 301 project area; therefore, the property is not eligible for listing under Criterion B. With its side gable addition, the dwelling is an example of a common mid-twentieth-century form;

therefore, the property is not eligible for listing under Criterion C. The property does not appear to possess the potential to yield information on building practices or methods of construction; therefore, the property does not appear to be eligible for listing under Criterion D. Due to lack of significance, the Tush House is not eligible for listing in the National Register.

CRS No. N14395




N14395. Photograph 1: Westrod House, view of east elevations looking west. Note the *circa*-1970 side gable addition extending from the south elevation.


CRS No. N14395



N14395. Photograph 2: Westrod House, view of south elevation, looking north.



N14395. Photograph 3: Shed at Tush House, south and east elevation, looking west. This shed is located west of the dwelling.



**U.S. 301 Project Development**  
**1962 Aerial**  
Westrod House - CRS No. N14395



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901



CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS#: N14395.  
SPO Map: 06-07-29  
Hundred: Saint Georges  
Quad: Middletown  
Other: 1301200010

1. HISTORIC NAME/FUNCTION Westrod House
2. ADDRESS/LOCATION: 4872 Summit Bridge Rd
3. TOWN/NEAREST TOWN: Middletown vicinity?
4. MAIN TYPE OF RESOURCE:      building  structure  site  object   
   landscape  district
5. MAIN FUNCTION OF PROPERTY:  
Single Dwelling      Storage
6. PROJECT TITLE/REASON FOR SURVEY (if applicable):  
U.S. 301 Project Development
7. ADDITIONAL FORMS USED:

#:	Form:	List Property Types:
1	CRS02	Dwelling
1	CRS03	Shed
1	CRS09	N/A

8. SURVEYOR INFORMATION:

Surveyor Name: Lauren Archibald / Architectural Historian  
Principal Investigator Name: Barbara Copp / Sr. Architectural Historian  
Principal Investigator Signature: *Barbara M Copp*  
Organization: A.D. Marble & Company Date: 9/26/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS#

N14395.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II
- 1600-1750 Contact Period (Native American)
- 1630-1730 Exploration and Frontier Settlement
- 1730-1770 Intensified and Durable Occupation
- 1770-1830 Early Industrialization
- 1830-1880 Industrialization and Early Urbanization
- 1880-1940 Urbanization and Early Suburbanization
- 1940-1960 Suburbanization and Early Ex-urbanization
- 1960-2000 Deurbanization and Sprawl

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                         |
| <input type="checkbox"/> Forestry              | <input type="checkbox"/> Settlement Patterns and Demographic Changes              |
| <input type="checkbox"/> Trapping/Hunting      | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                  |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                               |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                   |
| <input type="checkbox"/> Other                 | <input type="checkbox"/> Unknown  |



CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # N14395.01

1. ADDRESS/LOCATION: 4872 Summit Bridge Rd.
2. FUNCTION(S): historic Single Family Dwelling current Single Family Dwelling
3. YEAR BUILT: 1960 CIRCA?:  ARCHITECT/BUILDER: Unknown
4. STYLE OR FLOOR PLAN: Open, rectangular

5. INTEGRITY: original site  moved

if moved, from where

N/A

other location's CRS #

N/A

year

N/A

N/A

N/A

N/A

list major alterations and additions with years (if known)

a. N/A

year

N/A

b. N/A

N/A

6. CURRENT CONDITION: excellent good  fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: **Rectangular with rear ell** Stories: **One (1)**  
Additions: **N/A**

b. Structural system (if known): **Frame**

c. Foundation: Materials: **The dwelling appears to rest on a poured concrete slab.**  
basement: **full partial not visible X no basement**

d. Exterior walls (original if visible & any subsequent coverings): **Vertical wood siding/plywood, painted red**

e. Roof: shape: **Low-pitched gable with ridge perpendicular to Summit Bridge Road**  
materials: **Asphalt shingles**  
cornice: **Plain, boxed, wooden**  
dormers: **N/A**

chimney: location(s): **An interior brick chimney is located on the W wing and an interior stone chimney is located on the S wing.**

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: **E**

1) Bays **Three (3)**

2) Windows **Two (2)**

fenestration **Regular**

type **(2) one-light, fixed sash, assymmetrical**

trim **N/A**

shutters **N/A**

**Facade (cont'd)**

- 3) **Door(s)** One (1)  
     **location** Center bay  
     **type** (1) set of double-leaf, aluminum doors with 1/1 light aluminum storm doors  
     **trim** N/A
- 4) **Porch(es)** A concrete slab serves as a patio off the front entrance.
- b. **Side: Direction: N**
- 1) **Bays** Two (2)
- 2) **Windows** Two (2)  
     **fenestration** Irregular  
     **type** (2) 2-light, fixed; different sizes  
     **trim** N/A  
     **shutters** N/A
- 3) **Door(s)** 0  
     **location** N/A  
     **type** N/A  
     **trim** N/A
- 4) **Porch(es)** N/A
- c. **Side: Direction: S**
- 1) **Bays** Three (3)
- 2) **Windows** Three (3)  
     **fenestration** Irregular  
     **type** (3) one-light, fixed sash; different sizes  
     **trim** N/A  
     **shutters** N/A
- 3) **Door(s)** 0  
     **location** N/A  
     **type** N/A  
     **trim** N/A
- 4) **Porch(es)** N/A
- d. **Rear: Direction: W**
- 1) **Bays** Three (3)
- 2) **Windows** Three (3)  
     **fenestration** Irregular  
     **type** (1) set of paired one-light, fixed sash; (2) one-light, fixed sash  
     **trim** N/A  
     **shutters** N/A
- 3) **Door(s)** 0  
     **location** N/A  
     **type** N/A  
     **trim** N/A
- 4) **Porch(es)** N/A

9. **INTERIOR:** Not accessible

10. **LANDSCAPING:** Mature trees surround the property.

11. **OTHER COMMENTS:** N/A



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # N14395.02

1. ADDRESS/LOCATION: 4872 Summit Bridge Rd.

2. FUNCTION(S): historic Workshop current Shed

3. YEAR BUILT: 1950 CIRCA?:  ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: Open, regular

5. INTEGRITY: original site  moved

If moved, from where

N/A

original location's CRS #

N/A

year

N/A

N/A

N/A

N/A

list major alterations and additions with years (if known)

a. N/A

year

N/A

b. N/A

N/A

6. CURRENT CONDITION: excellent good  fair poor

7. DESCRIPTION:

a. Structural system Frame

b. Number of stories One (1)

c. Wall coverings Wooden clapboard, painted red

d. Foundation None

e. Roof

structural system High-pitched gable with shed extension off of southern end

coverings Tar paper

openings N/A

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: E

1) bays: Two (2)

2) windows: (1) paired, six-light, fixed, wooden with wooden sill

3) door(s): (1) single-leaf, 6 light/2 panel, wooden

4) other: N/A

**b. Side: direction: N**

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

**c. Side: direction: S**

- 1) bays: One (1)
- 2) windows: (1) 24-light, fixed, wooden
- 3) door(s): 0
- 4) other: N/A

**d. Rear: direction: W**

- 1) bays: One (1)
- 2) windows: 0
- 3) door(s): (1) single-leaf, wooden, pedestrian opening
- 4) other: N/A

**9. INTERIOR (if accessible):**

**a) Floor plan            Not accessible**

**b) Partition/walls        Not accessible**

**c) Finishes            Not accessible**

**d) Furnishings/machinery    Not accessible**



**CULTURAL RESOURCE SURVEY  
MAP FORM**

**DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901**

CRS#: N14395


1. ADDRESS/LOCATION: 4872 Summit Bridge Rd

2. NOT FOR PUBLICATION:


3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)



4. SITE PLAN:



**CRS No. N14396**

Address: 421 Boyds Corner Road

Date of Construction/Major Alteration: ca. 1958

Time Period: 1940-1960±, Suburbanization and Early Ex-urbanization

Geographic Zone: Upper Peninsula

Historic Period Theme(s): Mining/Quarrying

Name: Standard Bitrulithic Company

Tax Parcel: 1300700035

### *Description*

The building located at 421 Boyds Corner Road was once part of the Standard Bitrulithic Company, a West Virginia based corporation that once owned acreage within the immediate area along the Delaware Railroad. This gable front industrial building appears to be the only structure remaining from this company property. The frame dwelling is clad in standing seam metal and features wood paneling over the multiple window bays. The building rests on a concrete block foundation and its gable front roofline is sheathed in standing seam metal. The building is accessed primarily by a large modern overhead garage door located on the south elevation. This modern door is protected by a pair of standing seam metal sliding doors that are located on the exterior of the building. A shed roof addition is located on the west elevation. The parcel is located off of Boyds Corner Road and features a manicured lawn. A gravel driveway provides access to the building.

### *Historical Narrative*


The industrial warehouse structure at 421 Boyds Corner Road was built sometime between 1955 and 1962. The structure appears on the photo-revised version of the 1953 topographic map, indicating that it was built after 1953. The warehouse is clearly visible on a 1962 aerial photograph of the area. Between February 1955 and February 1957, the Standard Bitrulithic Company, a corporation of West Virginia, purchased several contiguous parcels at the area northeast of intersection of Boyds Corner Road and the Delaware Railroad (New Castle County Deed Books Z55:351, W56:300, Y56:536, R59:11). The parcel at 421 Boyds Corner Road has served in an industrial role since the late 1950s/early 1960s. Ownership of the parcel has changed numerous times since that period. It appears that the property once owned by Standard Bitrulithic was subdivided over time. An adjacent parcel to the north and west, which appears to have once been owned by the Standard Bitrulithic Company, is now owned by Tilcon Minerals, Inc (New Castle County Deed Book U118:151). Currently, the parcel at 421 Boyds Corner Road is owned by Marine Fuel Oil Services LLC, which acquired the property in June 2001 (New Castle County Deed Instrument 20010613 0046484).

### *National Register Evaluation*

The property at 421 Boyds Corner Road was evaluated as an Industrial Resource as identified in the *U.S. 301 Historic Context and Reconnaissance Survey Report* (A.D. Marble & Company 2005). Although the property retains location adjacent to a major transportation corridor (the Delaware Railroad), it lacks associated buildings and features that relate to its historic industrial use. The property does not retain elements reflecting the historic function of the property and it does not possess a strong association with the industrial development of the area; therefore, the property is not eligible under Criterion A. Based on background research, the property is not associated with persons who established significant industries, inventions, or innovations in industrial activities or were of other historical importance; therefore, the property is not eligible

under Criterion B. The property is a modest and non-descript example of a mid-twentieth-century industrial building that has been altered and lacks integrity of materials. It does not exhibit ornamentation of a specific architectural style, nor does it reflect the nature of its historic function; therefore, the property is not eligible under Criterion C. The property does not appear to be likely to yield important information about industrial practices; therefore, the property is not eligible under Criterion D.

**CRS No. N14396**



**N14396. Photograph 1: Standard Bitrulithic Company, view of south and west elevations, looking east.**

DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901



CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS#: N14396.  
SPO Map: 06-07-30  
Hundred: Saint Georges  
Quad: Saint Georges  
Other: 1300700035

1. HISTORIC NAME/FUNCTION: Standard Bitrulithic Company
2. ADDRESS/LOCATION: 421 Boyds Corner Rd
3. TOWN/NEAREST TOWN: Middletown vicinity?
4. MAIN TYPE OF RESOURCE:      building  structure  site  object   
   landscape  district
5. MAIN FUNCTION OF PROPERTY:  
Extractive Facility
6. PROJECT TITLE/REASON FOR SURVEY (if applicable):  
U.S. 301 Project Development

7. ADDITIONAL FORMS USED:

#:	Form:	List Property Types:
1	CRS01	Warehouse
1	CRS09	N/A

8. SURVEYOR INFORMATION:

Surveyor Name: Lauren Archibald / Architectural Historian

Principal Investigator Name: Barbara Copp / Sr. Architectural Historian

Principal Investigator Signature: *Barbara M. Copp*

Organization: A.D. Marble & Company Date: 9/26/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750 Contact Period (Native American)
- 1630-1730 Exploration and Frontier Settlement
- 1730-1770 Intensified and Durable Occupation
- 1770-1830 Early Industrialization
- 1830-1880 Industrialization and Early Urbanization
- 1880-1940 Urbanization and Early Suburbanization
- 1940-1960 Suburbanization and Early Ex-urbanization
- 1960-2000 Deurbanization and Sprawl

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |  |  |
|--|--|
| <input type="checkbox"/> Agriculture                 | <input type="checkbox"/> Transportation and Communication              |
| <input type="checkbox"/> Forestry                    | <input type="checkbox"/> Settlement Patterns and Demographic Changes   |
| <input type="checkbox"/> Trapping/Hunting            | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input checked="" type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government                                    |
| <input type="checkbox"/> Fishing/Oystering           | <input type="checkbox"/> Religion                                      |
| <input type="checkbox"/> Manufacturing               | <input type="checkbox"/> Education                                     |
| <input type="checkbox"/> Retailing/Wholesaling       | <input type="checkbox"/> Community Organizations                       |
| <input type="checkbox"/> Finance                     | <input type="checkbox"/> Occupational Organizations                    |
| <input type="checkbox"/> Professional Services       | <input type="checkbox"/> Major Families, Individuals and Events        |
| <input type="checkbox"/> Other                       | <input type="checkbox"/> Unknown                                       |



CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # N14396

1. ADDRESS/LOCATION: 421 Boyds Corner Rd.

2. FUNCTION(S): historic Warehouse current Warehouse

3. YEAR BUILT: 1958 CIRCA?:  ARCHITECT/BUILDER: Unknown

4. STYLE OR FLOOR PLAN: Open, Rectangular

5. INTEGRITY: original site  moved

<u>if moved, from where</u>	<u>other location's CRS #</u>	<u>year</u>
N/A	N/A	N/A
N/A	N/A	N/A

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. N/A	N/A
b. N/A	N/A

6. CURRENT CONDITION: excellent good  fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: Rectangular Stories: One (1)  
Additions: N/A

b. Structural system (if known): Frame

c. Foundation: Materials: The building rests on a poured concrete slab.  
basement: full partial not visible no basement

d. Exterior walls (original if visible & any subsequent coverings): Corrugated aluminum siding

e. Roof: shape: Low-pitched gable  
materials: Corrugated metal  
cornice: N/A  
dormers: N/A  
chimney: location(s): N/A

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: S

1) Bays	One (1)
2) Windows	0
fenestration	N/A
type	N/A
trim	N/A
shutters	N/A

**Facade (cont'd)**

- |    |                  |                          |
|----|------------------|--------------------------|
| 3) | <b>Door(s)</b>   | <b>One (1)</b>           |
|    | <b>location</b>  | <b>Center</b>            |
|    | <b>type</b>      | <b>Metal garage door</b> |
|    | <b>trim</b>      | <b>N/A</b>               |
| 4) | <b>Porch(es)</b> | <b>N/A</b>               |
- b. **Side: Direction: E**
- |    |                     |                       |
|----|---------------------|-----------------------|
| 1) | <b>Bays</b>         | <b>Not accessible</b> |
| 2) | <b>Windows</b>      | <b>Not accessible</b> |
|    | <b>fenestration</b> | <b>Not accessible</b> |
|    | <b>type</b>         | <b>Not accessible</b> |
|    | <b>trim</b>         | <b>Not accessible</b> |
|    | <b>shutters</b>     | <b>Not accessible</b> |
| 3) | <b>Door(s)</b>      | <b>Not accessible</b> |
|    | <b>location</b>     | <b>Not accessible</b> |
|    | <b>type</b>         | <b>Not accessible</b> |
|    | <b>trim</b>         | <b>Not accessible</b> |
| 4) | <b>Porch(es)</b>    | <b>Not accessible</b> |
- c. **Side: Direction: W**
- |    |                     |  |
|----|---------------------|--|
| 1) | <b>Bays</b>         | <b>Nine (9)</b>  |
| 2) | <b>Windows</b>      | <b>Eight (8)</b>   |
|    | <b>fenestration</b> | <b>Irregular</b>   |
|    | <b>type</b>         | <b>Square-shaped; openings now covered over with painted plywood</b> |
|    | <b>trim</b>         | <b>N/A</b>   |
|    | <b>shutters</b>     | <b>N/A</b>   |
| 3) | <b>Door(s)</b>      | <b>One (1)</b>   |
|    | <b>location</b>     | <b>Southern end</b>  |
|    | <b>type</b>         | <b>Single-leaf, metal, solid</b>                                     |
|    | <b>trim</b>         | <b>N/A</b>   |
| 4) | <b>Porch(es)</b>    | <b>N/A</b>   |
- d. **Rear: Direction: N**
- |    |                     |                       |
|----|---------------------|-----------------------|
| 1) | <b>Bays</b>         | <b>Not accessible</b> |
| 2) | <b>Windows</b>      | <b>Not accessible</b> |
|    | <b>fenestration</b> | <b>Not accessible</b> |
|    | <b>type</b>         | <b>Not accessible</b> |
|    | <b>trim</b>         | <b>Not accessible</b> |
|    | <b>shutters</b>     | <b>Not accessible</b> |
| 3) | <b>Door(s)</b>      | <b>Not accessible</b> |
|    | <b>location</b>     | <b>Not accessible</b> |
|    | <b>type</b>         | <b>Not accessible</b> |
|    | <b>trim</b>         | <b>Not accessible</b> |
| 4) | <b>Porch(es)</b>    | <b>Not accessible</b> |

9. **INTERIOR: Warehouse with one-story, three-bay, concrete block section on NW for office**

10. **LANDSCAPING: Surrounded by asphalt parking lot, grassed area to S and W**

11. **OTHER COMMENTS: N/A**



CULTURAL RESOURCE SURVEY  
MAP FORM

DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CRS#: N14396


1. ADDRESS/LOCATION: 421 Boyds Corner Rd

2. NOT FOR PUBLICATION:


3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)



4. SITE PLAN:



**CRS No. N14397**

**Name: Nicholas L. and Mildred Swyka House**

**Address: 1147 Bethel Church Road**

**Tax Parcel: 1100570003**

**Date of Construction/Major Alterations: ca. 1952; ca. 1985**

**Time Period: 1940-1960± Suburbanization and Early Ex-urbanization**

**Geographic Zone: Upper Peninsula**

**Historic Period Theme(s): Architecture, Engineering, and Decorative Arts (Residential Architecture)**

### *Description*

The Nicholas L. and Mildred Swyka House is located on the west side of Bethel Church Road. The irregularly shaped 7.47-acre property consists of a 1952 Minimal Traditional house and a *circa*-1952 garage. The property also features four modern workshops/sheds situated to the northwest of the dwelling. Distinctive characteristics of the Minimal Traditional dwelling include its side gable form with a gabled dormer on the façade (south elevation) and its shallow eaves. The house also features a full-width, shed-roof dormer on the rear (north) elevation. A one-story, *circa*-1985 addition extends the full width of the rear (north) elevation. The 1952 block of the house is clad in brick laid in a bond of continuous running stretches, while the rear, *circa*-1985 addition is clad in vertical board siding. The dwelling is primarily lit by one-over-one light, double-hung sash, aluminum windows but also features three-over-one light, double-hung sash, wood windows on the west elevation.

The one-story garage, which sits to the west of the dwelling, features a one-bay, *circa*-1952, brick, front gable block with a one-bay, *circa*-1985, shed-roof addition attached to the west elevation. The addition is clad in vertical board siding. A paved asphalt driveway is located to the west of the dwelling and leads to the south elevation of the garage. The property features a manicured lawn, mature trees, and flower beds. A split-rail fence delineates the property's boundaries.

### *Historical Narrative*

This 7.47-acre property was once part of a 183.63-acre farm known as "Biggs Corner Farm," owned by Sewell C. Biggs. In August 1946, Sewell C. Biggs conveyed a four-acre parcel along the north side of Bethel Church Road to Nicholas L. Swyka and his wife, Mildred P., for \$1,000 (New Castle County Deed Book O46:581). The deed indicates that the piece of property contained "...a frame dwelling house" (*ibid.*). By 1952, the Swykas had torn down the existing frame dwelling and replaced it with the one-and-one-half story brick dwelling and garage, both of which were designed by Mr. Swyka and remain on the property today (Nicholas L. Swyka, personal communication, June 29, 2006).

More recently, the Swykas added land to their existing 4-acre parcel. In September 1995, the Swykas added "Lot no. 227" from the neighboring "Villages at Fairview Farm" (New Castle County Deed Book 1996:347). A year later, Nicholas and Mildred Swyka purchased yet another parcel from the neighboring development (New Castle County Deed Book 2179:114), bringing the parcel to its present-day size of 7.47 acres. Nicholas and Mildred Swyka continue to retain their 7.47 acres of land in 2006.

### *National Register Evaluation*


The property located at 1147 Bethel Church Road was evaluated as a Residential Resource as identified in the *U.S. 301 Historic Context and Reconnaissance Survey Report* (A.D. Marble & Company 2005). Minimal Traditional dwellings are common mid-twentieth-century building types in the U.S. 301 APE. Therefore, these resources are generally not considered eligible unless they are part of eligible collections. As noted in the context, dwellings dating to the mid-twentieth century would not be considered eligible for listing in the National Register unless they retain an exceptionally high degree of integrity and a significant associated documentary record (construction plans, building contracts, etc.) (A.D. Marble & Company 2005). Although subdivided from farmland in 1946, the property was not constructed as part of a residential development and has no significant documentary record that could provide more information on mid-twentieth-century subdivision practices and therefore is not eligible for listing in the National Register under Criterion A. Based on the background research conducted for this project, the property does not appear to be associated with an individual who played a role in the historic development of the U.S. 301 project area; therefore, the property is not eligible for listing under Criterion B. The dwelling's integrity is compromised the large addition which extends the width of the rear elevation and the replacement of some windows. Further, with its side gable roof with gabled front dormer and shallow eaves, the house is an example of a common mid-twentieth-century form; thus, the property is not eligible for listing under Criterion C. The property does not appear to possess the potential to yield information on building practices or methods of construction; therefore the property does not appear to be eligible for listing under Criterion D.

CRS No. N14397



N14397. Photograph 1: Dwelling, south and east elevations, view looking northwest.

CRS No. N14397



N14397. Photograph 2: Addition and shed roof dormer, east elevation, view looking west.

CRS No. N14397



N14397. Photograph 3: Garage, south and west elevations, view looking northeast.

DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901



CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS#: N14397.  
SPO Map: 04-05-30  
Hundred: Pencader  
Quad: Elkton  
Other: 1100570003

1. HISTORIC NAME/FUNCTION: Nicholas L. and Mildred Swyka House

2. ADDRESS/LOCATION: 1147 Bethel Church Road

3. TOWN/NEAREST TOWN: Middletown vicinity?

4. MAIN TYPE OF RESOURCE:      building     structure     site     object   
   landscape     district

5. MAIN FUNCTION OF PROPERTY:  
Single Dwelling      Secondary Structure

6. PROJECT TITLE/REASON FOR SURVEY (if applicable):  
U.S. 301 Project Development

7. ADDITIONAL FORMS USED:

#:	Form:	List Property Types:
1	CRS02	Dwelling
1	CRS03	Garage
1	CRS09	N/A

8. SURVEYOR INFORMATION:

Surveyor Name: Emma K. Young / Architectural Historian  
Principal Investigator Name: Barbara Copp / Sr. Architectural Historian

Principal Investigator Signature: Barbara M. Copp

Organization: A.D. Marble & Company Date: 6/29/2006

9. OTHER NOTES OR OBSERVATIONS:

CRS#

N14397.

Dwelling and garage were designed and built by current owners.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750 Contact Period (Native American)
- 1630-1730 Exploration and Frontier Settlement
- 1730-1770 Intensified and Durable Occupation
- 1770-1830 Early Industrialization
- 1830-1880 Industrialization and Early Urbanization
- 1880-1940 Urbanization and Early Suburbanization
- 1940-1960 Suburbanization and Early Ex-urbanization
- 1960-2000 Deurbanization and Sprawl

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                         |
| <input type="checkbox"/> Forestry              | <input type="checkbox"/> Settlement Patterns and Demographic Changes              |
| <input type="checkbox"/> Trapping/Hunting      | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                  |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                               |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                   |
| <input type="checkbox"/> Other                 | <input type="checkbox"/> Unknown  |



CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # N14397

1. ADDRESS/LOCATION: 1147 Bethel Church Road

2. FUNCTION(S): historic Dwelling current Dwelling

3. YEAR BUILT: 1952 CIRCA?:  ARCHITECT/BUILDER: Designed by Nicholas Swyka

4. STYLE OR FLOOR PLAN: Minimal Traditional

5. INTEGRITY: original site  moved

<u>if moved, from where</u>	<u>other location's CRS #</u>	<u>year</u>
N/A	N/A	N/A
N/A	N/A	N/A

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. Rear addition	1987
b. N/A	N/A

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: Side gable with dormers Stories: 1.5  
Additions: Gabled

b. Structural system (if known): Wood frame

c. Foundation: materials: Brick  
basement: full  partial  not visible  no basement

d. Exterior walls (original if visible& any subsequent coverings): Brick; vertical wood on the addition

e. Roof: shape: Side gable  
materials: Asphalt shingles  
cornice: N/A  
dormers: Gabled dormers on main block; shed roof dormers on rear addition  
chimney: location(s): Brick, interior, on rear addition

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: S
  - 1) Bays 3
  - 2) Windows
    - fenestration Regular
    - type (2) tripartite, 1/1 DHS, aluminum; (1) set of paired, 1/1 DHS aluminum
    - trim Vinyl with brick sills
    - shutters N/A

**Facade (cont'd)**

- 3) **Door(s)** 1  
     **location** Center  
     **type** Wood pane and panel with one-light, aluminum screen door  
     **trim** Brick
- 4) **Porch(es)** N/A

**b. Side: Direction: E**

- 1) **Bays** 4
- 2) **Windows**  
     **fenestration** Regular  
     **type** (3) 1/1 DHS; (1) set of paired, 1/1 DHS,  
     **trim** Vinyl with brick sills  
     **shutters** N/A
- 3) **Door(s)** 0  
     **location** N/A  
     **type** N/A  
     **trim** N/A
- 4) **Porch(es)** Enclosed rear addition contains paired, 1-light, aluminum windows

**c. Side: Direction: W**

- 1) **Bays** 5
- 2) **Windows** 0  
     **fenestration** Irregular  
     **type** (1) Chicago-style picture window; (3) sets of paired, 3/1 DHS wood  
     **trim** Wood with brick sills  
     **shutters** N/A
- 3) **Door(s)** 1  
     **location** Center of main block  
     **type** Wood panel and pane with aluminum storm door  
     **trim** Wood
- 4) **Porch(es)** Three brick steps lead to a brick landing protected by a front-gabled entry porch.

**d. Rear: Direction: N**

- 1) **Bays** 3
- 2) **Windows** 0  
     **fenestration** N/A  
     **type** N/A  
     **trim** N/A  
     **shutters** N/A
- 3) **Door(s)** 0  
     **location** N/A  
     **type** N/A  
     **trim** N/A
- 4) **Porch(es)** Modern rear addition conceals details of elevation; addition contains paired one-light, casement windows and modern sliding-glass doors

9. **INTERIOR:** Not accessible

10. **LANDSCAPING:** Mature trees, bushes, flower beds; modern buildings; split-rail fence delineates property boundaries.

11. **OTHER COMMENTS:** The dwelling was designed by Nicholas Swyka, the current owner.



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # N14397

1. ADDRESS/LOCATION: 1147 Bethel Church Road

2. FUNCTION(S): historic Garage current Garage

3. YEAR BUILT: 1952 CIRCA?:  ARCHITECT/BUILDER: Designed by Nicholas Swyka

4. STYLE/FLOOR PLAN: Open, Regular

5. INTEGRITY: original site  moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
N/A	N/A	N/A
N/A	N/A	N/A
<u>list major alterations and additions with years (if known)</u>		<u>year</u>
a. One-bay garage added to west elevation		1987
b. N/A		N/A

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:

- a. Structural system Frame
- b. Number of stories 1
- c. Wall coverings Brick; wood siding on addition
- d. Foundation Poured concrete foundation on addition
- e. Roof
  - structural system Front gable with shed roof (addition)
  - coverings Asphalt shingles
  - openings Decorative vent on ridge of main block

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S
  - 1) bays: 2
  - 2) windows: 0
  - 3) door(s): (2) overhead aluminum garage doors
  - 4) other: Louvered vent in gable of main block

**b. Side: direction: E**

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

**c. Side: direction: W**

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

**d. Rear: direction: S**

- 1) bays: (1)
- 2) windows: (1) set of paired, 9-light, aluminum
- 3) door(s): 0
- 4) other: Dog pen attached to south elevation

**9. INTERIOR (if accessible):**

**a) Floor plan            Not accessible**

**b) Partition/walls        Not accessible**

**c) Finishes            Not accessible**

**d) Furnishings/machinery    Not accessible**



**CULTURAL RESOURCE SURVEY  
MAP FORM**

**DELAWARE STATE HISTORIC PRESERVATION OFFICE  
16 THE GREEN, DOVER, DE 19901**

CRS#:

N14397.


**1. ADDRESS/LOCATION:** 1147 Bethel Church Road

**2. NOT FOR PUBLICATION:**

**3. LOCATION MAP:**

**Indicate position of resource in relation to geographical landmarks such as streams and crossroads.**

**(attach section of USGS quad map with location marked or draw location map)**



4. SITE PLAN:

