

Appendix B: Delaware Cultural Resource Survey Forms

Survey forms are attached for the following resources:

- Dwelling, S side of Road 353, West of intersection with SR 17 (S-10037)
- Clinton Robinson House (S-10030)
- John R. Townsend House (S-2455)
- T. N. Steel, Jr. House (S-10031)
- Harold Marvel House (S-2454)
- Clifton Toomey House (S-2453)
- Dwelling, W side of Road 352, South of Bernice Road (S-10032)
- J. Hall House (S-2356)
- Orville Quillen House (S-10033)
- A. Clark House (S-2342)
- E. Chandler House (S-2355)
- Dwelling, S side of Road 368, West of Road 362 (S-10034)
- Dwelling, NW side of Road 362 at Road 368 (S-10035)
- Dwelling, E side of Road 361 at Road 368 (S-10036)

Six of the resources have existing survey forms: John R. Townsend House (S-2455), Harold Marvel House (S-2454), Clifton Toomey House (S-2453), J. Hall House (S-2356), A. Clark House (S-2342), and E. Chandler House (S-2355). Survey Update Forms have been provided for these resources as well as current appropriate forms if earlier forms were not adequate.



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10037
SPO Map 20-21-07
Hundred Baltimore
Quad Frankford
Other 1-34-11-231

1. HISTORIC NAME/FUNCTION: Dwelling, S side of Road 353, W of intersection with SR 17
2. ADDRESS/LOCATION: S side of Road 353, W of intersection with SR 17
3. TOWN/NEAREST TOWN: Millville vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
 landscape district
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
DE Route 26 Alternate (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	single-family dwelling
1	CRS 3 Secondary Building Form	garage
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

8. SURVEYOR INFORMATION:

Surveyor name: Martin Abbot & Rebecca Hunt

Principal Investigator name: Martin Abbot

Principal Investigator signature: _____

Organization: URS Corporation, King Of Prussia, PA Date: 5/1/2003

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-10037

Shown on 1928 USGS map.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S- 10037

1. ADDRESS/LOCATION: S side of Road 353, W of intersection with SR 17

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1870 CIRCA?: ARCHITECT/BUILDER: Not Known

4. STYLE OR FLOOR PLAN: Massed-Plan Side-Gable with modern additions

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>other location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	

list major alterations and additions with years (if known) year

a. multiple late 20th century additions

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 2
Additions: one-story north frame addition, frame addition on second floor, two-story frame south addition

b. Structural system (if known): balloon frame

c. Foundation: materials: concrete block
basement: full partial not visible no basement

d. Exterior walls (original if visible & any subsequent coverings): vinyl siding

e. Roof: shape: gable
materials: asphalt shingles
cornice: box
dormers: N/A
chimney: location(s): exterior frame chimney on south addition

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: N

1) Bays 1

2) Windows

fenestration 2 paired windows with half round window above on first floor, 1 window with half round window above on second floor

type 1/1 vinyl and fixed half-round sash

trim plain vinyl

shutters N/A

Facade (cont'd)

- 3) **Door(s)** N/A
 location N/A
 type N/A
 trim N/A
 4) **Porch(es)** N/A

b. Side: Direction: E

- 1) **Bays** 6
 2) **Windows**
 fenestration 1 on first level of rear addition, original is regular with 2 per level, 1 on first floor of front addition
 type 1/1, vinyl, double-hung sash
 trim plain vinyl
 shutters N/A
 3) **Door(s)**
 location 1 on rear addition, 1 on front addition
 type glass panel over raised panel and solid with small glass panel
 trim plain vinyl
 4) **Porch(es)** double-height wood deck on rear addition, small wood deck on front addition


c. Side: Direction: W

- 1) **Bays** 4
 2) **Windows**
 fenestration none on front addition, original is regular with 2 per floor, 1 on first level of rear addition and paired on second level of rear addition
 type 1/1 double-hung vinyl replacement sash on original section and fixed vinyl sash on second floor of rear addition
 trim plain vinyl
 shutters N/A
 3) **Door(s)** N/A
 location N/A
 type N/A
 trim N/A
 4) **Porch(es)** N/A

d. Rear: Direction: Not visible

- 1) **Bays** N/A
 2) **Windows**
 fenestration N/A
 type N/A
 trim N/A
 shutters N/A
 3) **Door(s)** N/A
 location N/A
 type N/A
 trim N/A
 4) **Porch(es)** N/A

9. **INTERIOR:** N/A10. **LANDSCAPING:** no planting beds, large grass field to west11. **OTHER COMMENTS:** middle 1 1/2 story section is original house



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S- 10037

1. ADDRESS/LOCATION: S side of Road 353, W of intersection with SR 17

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 1960 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

if moved, from where	original location's CRS #	year
N/A	N/A	0

list major alterations and additions with years (if known)	year
a. N/A	0
b.	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood frame

b. Number of stories 1

c. Wall coverings vinyl siding

d. Foundation N/A

e. Roof
structural system gable
coverings standing seam metal
openings N/A

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: N
 - 1) bays: 1
 - 2) windows: N/A
 - 3) door(s): 1 opening, door type not visible
 - 4) other: N/A

- b. Side: direction: E
 - 1) bays: 1
 - 2) windows: none
 - 3) door(s): none
 - 4) other: N/A

- c. Side: direction: W
 - 1) bays: 1
 - 2) windows: none
 - 3) door(s): none
 - 4) other: N/A

- d. Rear: direction: N/A
 - 1) bays: N/A
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A

9. INTERIOR (if accessible):

- a) Floor plan N/A

- b) Partition/walls N/A

- c) Finishes N/A

- d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10037

1. ADDRESS/LOCATION: S Side Of Road 353, W Of Intersection With Sr 17


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



Representative Photographs: Dwelling, S side of Road 353, West of Intersection with
SR 17 (S-)



1. View southwest of front and side facades.



2. View southeast of front and side facades.



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10030
SPO Map 20-21-07
Hundred Baltimore
Quad Frankford
Other 1-34-11-234

1. HISTORIC NAME/FUNCTION: Clinton Robinson House
2. ADDRESS/LOCATION: SE Corner of Road 353 and SR 17
3. TOWN/NEAREST TOWN: Millville vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
 landscape district
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
DE Route 26 Alternate (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	single-family dwelling
0	CRS 3 Secondary Building Form	N/A
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

8. SURVEYOR INFORMATION:

Surveyor name: Martin Abbot And Rebecca Hunt

Principal Investigator name: Martin Abbot

Principal Investigator signature: _____

Organization: URS Corporation, King Of Prussia, Pa Date: 5/1/2003

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-10030

Not on 1928 USGS map, On 1951 USGS map.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750∨ Contact Period (Native American)
 - 1630-1730∨ Exploration and Frontier Settlement
 - 1730-1770∨ Intensified and Durable Occupation
 - 1770-1830∨ Early Industrialization
 - 1830-1880∨ Industrialization and Early Urbanization
 - 1880-1940∨ Urbanization and Early Suburbanization
 - 1940-1960∨ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10030

1. ADDRESS/LOCATION: SE Corner of Road 353 and SR 17

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1945 CIRCA?: ARCHITECT/BUILDER: Not Known

4. STYLE OR FLOOR PLAN: Bungalow

5. INTEGRITY: original site moved

if moved, from where
N/A

other location's CRS #
N/A

year
0

list major alterations and additions with years (if known)

a. small addition under construction on rear elevation, to cover utilities

year
2003

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1 1/2
Additions: small frame addition under construction on rear elevation, to cover utilities

b. Structural system (if known): balloon frame

c. Foundation: materials: concrete block
basement: full partial not visible no basement

d. Exterior walls (original if visible & any subsequent coverings): asbestos siding

e. Roof: shape: gable
materials: asphalt shingles
cornice: exposed rafter ends
dormers: N/A
chimney: location(s): central, interior, brick

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: NW

1) Bays 2

2) Windows

fenestration 2 groups of paired windows flanking enclosed porch

type 6/1 original wood

trim plain wood

shutters wood louvered

Facade (cont'd)

- 3) **Door(s)**
 location 1 centered
 type screen door with main door not visible
 trim plain wood
- 4) **Porch(es)** enclosed porch centered on front with flanking 1/1 windows, front gable roof and 2 stacked windows with 3 lights on each side

b. Side: Direction: SW

- 1) **Bays** 2
- 2) **Windows**
 fenestration 2 on first floor, 1 centered on second floor
 type 6/1 original wood sash
 trim plain wood
 shutters wood louvered, on all windows
- 3) **Door(s)** none
 location N/A
 type N/A
 trim N/A
- 4) **Porch(es)** N/A

c. Side: Direction: NE

- 1) **Bays** 3
- 2) **Windows**
 fenestration 2 on first floor, 1 centered on second floor
 type single-light horizontal and 6/1 original wood sash on first floor, 6/1 original wood sash on second floor
 trim plain wood
 shutters wood louvered on 6/1 windows and door
- 3) **Door(s)**
 location 1 centered
 type upper glass panels visible
 trim not visible
- 4) **Porch(es)** central porch with masonry steps and stoop, cast-iron rails and columns and metal canopy

d. Rear: Direction: SE

- 1) **Bays** 3
- 2) **Windows**
 fenestration 3
 type 6/1 original wood sash at W end, others are 2 single-light horizontal wood sash
 trim plain wood
 shutters wood louvered on 6/1
- 3) **Door(s)** none
 location N/A
 type N/A
 trim N/A
- 4) **Porch(es)** N/A

9. **INTERIOR:** N/A

10. **LANDSCAPING:** plantings on front elevation, property fronted on front 2 sides by roads and back 2 sides by agricultural field

11. **OTHER COMMENTS:**



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-10030

1. ADDRESS/LOCATION: SE Corner Of Road 353 And SR 17
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



Representative Photographs: Clinton Robinson House (S-10030)



1. View east of front and side facades.



2. View south of front and side facades.



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-2455

1. HISTORIC NAME/FUNCTION: John R. Townsend House
2. ADDRESS/LOCATION: E side of SR 17, N of intersection with Road 353
3. CURRENT CONDITION: excellent good fair poor demolished
4. INTEGRITY: Existing materials and features suggest that the house has remained similar to its appearance on the previous (1981) survey form.
5. SETTING INTEGRITY: former agricultural fields now subdivided so agricultural buildings are no longer part of this property.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	single-family dwelling
1	CRS 3 Secondary Building Form	garage
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

7. SURVEYOR INFORMATION:

Surveyor name: Martin Abbot And Rebecca Hunt

Principal Investigator name: Martin Abbot

Principal Investigator signature: _____

Organization: URS, King Of Prussia, PA Date: 5/1/2003

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-2455

Majority of earlier form not legible.

Named John R. Townsend House on 1981 survey form.

Not on 1868 Beers' Atlas, on 1928 USGS.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-2455

1. ADDRESS/LOCATION: E Side of SR 17, N of intersection with Road 353

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1875 CIRCA?: ARCHITECT/BUILDER: Not Known

4. STYLE OR FLOOR PLAN: I-House

5. INTEGRITY: original site moved

if moved, from where	other location's CRS #	year
N/A	N/A	0

list major alterations and additions with years (if known) year

- | | |
|---------------------------------------------------------------------------------------------------------------------|---|
| a. 2 1/2 story rear addition, appears to have been built in late 19 th or early 20 th century | 0 |
| b. 1-story side and rear addition, appears to have been built in mid-20 th century | 0 |

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: T-shape, later additions make L-shape Stories: 2 1/2
Additions: 2 1/2 story addition off back of original block, 1 story additions on south and back of 2 1/2 story addition

b. Structural system (if known): balloon frame

c. Foundation: materials: parged original, concrete block additions
basement: full partial not visible no basement

d. Exterior walls (original if visible & any subsequent coverings): vinyl siding

e. Roof: shape: gable
materials: asphalt shingles
cornice: box
dormers: none
chimney: location(s): concrete block interior chimney on east end addition

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: W

1) Bays 3

2) Windows

fenestration regular with 2 on first floor and 3 on second

type 1/1 double-hung original wood

trim vinyl

shutters none

Facade (cont'd)

- 3) **Door(s)**
 location central
 type not visible
 trim not visible
- 4) **Porch(es)** screened porch centered on front elevation, vinyl siding

b. Side: Direction: N

- 1) **Bays** 5
- 2) **Windows**
 fenestration regular with 1 on each floor of the front section, 2 on each floor of the middle section, and 1 on each rear addition.
 type 1/1 double-hung original wood, except rear addition has fixed sash
 trim vinyl
 shutters N/A
- 3) **Door(s)** N/A
 location N/A
 type N/A
 trim N/A
- 4) **Porch(es)** N/A

c. Side: Direction: S

- 1) **Bays** 1 on original front section, remainder of building not accessible
- 2) **Windows**
 fenestration regular on front section with 1 per floor
 type 1/1 double-hung original wood on first and second floors
 trim vinyl
 shutters N/A
- 3) **Door(s)** not visible
 location N/A
 type N/A
 trim N/A
- 4) **Porch(es)** N/A

d. Rear: Direction: E

- 1) **Bays** 3
- 2) **Windows**
 fenestration only on middle, one-story addition
 type paired, 1/1 double-hung
 trim vinyl
 shutters N/A
- 3) **Door(s)**
 location 1 centered on rear addition
 type jalousie
 trim vinyl
- 4) **Porch(es)** N/A

9. **INTERIOR:** N/A10. **LANDSCAPING:** grass field to S, horse pasture to N11. **OTHER COMMENTS:** N/A



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-2455

1. ADDRESS/LOCATION: E Side of SR 17, N of intersection with Road 353
2. FUNCTION(S): historic garage current garage
3. YEAR BUILT: 1925 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE/FLOOR PLAN: square
5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	<u>0</u>

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
<u>a. N/A</u>	<u>0</u>
<u>b.</u>	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood framing
- b. Number of stories 1
- c. Wall coverings weather board
- d. Foundation N/A
- e. Roof
structural system pyramidal with exposed rafter ends
coverings asphalt shingles
openings none

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: W
- 1) bays: 1
- 2) windows: none
- 3) door(s): 2 siding wood doors
- 4) other: N/A

- b. Side: direction: N
 - 1) bays: 1
 - 2) windows: none
 - 3) door(s): none
 - 4) other: N/A

- c. Side: direction: S
 - 1) bays: 1
 - 2) windows: none
 - 3) door(s): none
 - 4) other: N/A

- d. Rear: direction: E
 - 1) bays: 1
 - 2) windows: none
 - 3) door(s): none
 - 4) other: N/A

9. INTERIOR (if accessible):

- a) Floor plan N/A
- b) Partition/walls N/A
- c) Finishes N/A
- d) Furnishings/machinery N/A




CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-2455


1. ADDRESS/LOCATION: E Side Of Sr 17, N Of Intersection With Road 353
2. NOT FOR PUBLICATION. reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.
(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



Representative Photographs: John R. Townsend House (S-2455)



1. View northeast of front façade.



2. View southeast of front and side facades.



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10031
SPO Map 20-21-07
Hundred Baltimore
Quad Frankford
Other 1-34-12-382

1. HISTORIC NAME/FUNCTION: T.N. Steel, Jr. House
2. ADDRESS/LOCATION: E side of Substation Rd, S of Road 353
3. TOWN/NEAREST TOWN: Millville vicinity?
4. MAIN TYPE OF RESOURCE: building landscape structure district site object
5. MAIN FUNCTION OF PROPERTY: farm
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
DE Route 26 Alternate (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	single-family dwelling
3	CRS 3 Secondary Building Form	barn, garage, hen house
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

8. SURVEYOR INFORMATION:

Surveyor name: Martin Abbot And Rebecca Hunt

Principal Investigator name: Martin Abbot

Principal Investigator signature: _____

Organization: URS Corporation, King Of Prussia, PA Date: 5/1/2003

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-10031


It would appear that the house is shown on the 1868 Beers' Atlas as T.W. Steel, Jr. house.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|-------------------------------------------------|-----------------------------------------------------------------------------------|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S- 10031

1. ADDRESS/LOCATION: E side Of Substation Rd, S of Road 353

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1860 CIRCA?: ARCHITECT/BUILDER: Not Known

4. STYLE OR FLOOR PLAN: Hall-Parlor Plan

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>other location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	<u>0</u>

list major alterations and additions with years (if known) year

a. 1-story rear addition, early 20th century 0

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular original, addition makes L-shape Stories: 2
Additions: 1-story rear, frame addition

b. Structural system (if known): balloon frame

c. Foundation: materials:
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings):
Asbestos shingles over clapboards

e. Roof: shape: gable
materials: asphalt shingles
cornice: box
dormers: none
chimney: location(s): brick external chimney on east side of original, parged masonry internal chimney on south end of addition

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: N

1) Bays 1

2) Windows

fenestration 1 window on second floor, first floor not known because covered by enclosed porch
type not known – covered by board
trim simple wood molding
shutters none

Facade (cont'd)

- 3) **Door(s)** Not visible
location N/A
type N/A
trim N/A

- 4) **Porch(es)** front enclosed porch with asbestos siding, full-width, paired 1/1 double-hung wood windows flanking centered door, hip roof with asphalt shingles, boards cover foundation.

b. Side: Direction: E

- 1) **Bays** 4

2) **Windows**

fenestration none on first floor of original section, 2 symmetrical windows flanking chimney on second floor of original section, none on addition

type 1/1 double-hung wood sash

trim simple wood molding

shutters none

- 3) **Door(s)** 2

location rear addition

type N/A covered by screen doors

trim simple wood trim

- 4) **Porch(es)** full-width porch on rear addition, posts are unfinished tree limbs, roof added to extend from roof of addition, roof covered with asphalt shingles

c. Side: Direction: W

- 1) **Bays** 3

2) **Windows**

fenestration paired windows centered on first floor of original section, single window centered on second floor of original section, paired windows on north end of addition, single window on south end of addition.

type 1/1 double-hung wood sash

trim simple wood molding

shutters none

- 3) **Door(s)** none

location N/A

type N/A

trim N/A

- 4) **Porch(es)** N/A

d. Rear: Direction: S

- 1) **Bays** 3

2) **Windows**

fenestration 1 on rear of original section under porch, 2 symmetrical windows on addition

type 1/1 double-hung wood sash

trim simple wood molding

shutters none

- 3) **Door(s)** none

location N/A

type N/A

trim N/A

- 4) **Porch(es)** porch on east elevation partially covers rear elevation of original section

9. **INTERIOR:** N/A

10. **LANDSCAPING:** no planting beds adjacent to house, agricultural fields surround building cluster

11. **OTHER COMMENTS:**



CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10031

1. ADDRESS/LOCATION: E side of Substation Rd, S of Road 353

2. FUNCTION(S): historic barn current barn

3. YEAR BUILT: 1900 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE/FLOOR PLAN: rectangular, central enclosed area with flanking covered storage areas

5. INTEGRITY: original site moved

if moved, from where	original location's CRS #	year
N/A	N/A	0

list major alterations and additions with years (if known)	year
a. N/A	0
b.	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system woo frame
- b. Number of stories 1 1/2
- c. Wall coverings vertical board siding
- d. Foundation N/A
- e. Roof
 - structural system gable
 - coverings standing seam metal
 - openings N/A

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S
 - 1) bays: 1
 - 2) windows: none
 - 3) door(s): central vertical board door on first floor and at loft
 - 4) other: symmetrical open storage areas flank main section

- b. Side: direction: E
 - 1) bays: 1
 - 2) windows: none
 - 3) door(s): none
 - 4) other: N/A

- c. Side: direction: W
 - 1) bays: 1
 - 2) windows: none
 - 3) door(s): none
 - 4) other: N/A

- d. Rear: direction: N/A
 - 1) bays: N/A
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A


9. INTERIOR (if accessible):

- a) Floor plan N/A

- b) Partition/walls N/A

- c) Finishes N/A

- d) Furnishings/machinery N/A



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10031

1. ADDRESS/LOCATION: E side of Substation Rd, S of Road 353

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 1920 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
N/A	N/A	0

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. N/A	0
b.	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood framing
- b. Number of stories 1
- c. Wall coverings clapboards
- d. Foundation N/A
- e. Roof
 - structural system gable with exposed rafter ends, roof of hen house adjoins part of south slope
 - coverings asphalt
 - openings N/A

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: W
 - 1) bays: 2
 - 2) windows: none
 - 3) door(s): two sliding wood doors
 - 4) other: N/A

- b. Side: direction: N
 - 1) bays: 1
 - 2) windows: 1 centered with four-light, original wood sash
 - 3) door(s): none
 - 4) other: N/A

- c. Side: direction: S
 - 1) bays: 1
 - 2) windows: 1 centered with four-light, original wood sash
 - 3) door(s): none
 - 4) other: N/A

- d. Rear: direction: E
 - 1) bays: 1
 - 2) windows: none
 - 3) door(s): none
 - 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan N/A

b) Partition/walls N/A

c) Finishes N/A

d) Furnishings/machinery N/A



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10031

1. ADDRESS/LOCATION: E side of Substation Rd, S of Road 353

2. FUNCTION(S): historic chicken house current chicken house

3. YEAR BUILT: 1900 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
N/A	N/A	0

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. N/A	0
b.	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood frame
- b. Number of stories 1
- c. Wall coverings clapboards
- d. Foundation N/A
- e. Roof
 - structural system gable, north slope abuts south slope of garage
 - coverings corrugated metal over wood shingles
 - openings N/A

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: W
 - 1) bays: 1
 - 2) windows: none
 - 3) door(s): vertical board door on north side
 - 4) other: N/A

- b. Side: direction: N
 - 1) bays: 1
 - 2) windows: not visible
 - 3) door(s): not visible
 - 4) other: N/A

- c. Side: direction: S
 - 1) bays: 1
 - 2) windows: none
 - 3) door(s): small, central rectangular opening for chickens
 - 4) other: N/A

- d. Rear: direction: E
 - 1) bays: 1
 - 2) windows: none
 - 3) door(s): none
 - 4) other: N/A

9. INTERIOR (if accessible):

- a) Floor plan N/A
- b) Partition/walls N/A
- c) Finishes N/A
- d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10031

1. ADDRESS/LOCATION: E Side Of Substation Rd, S Of Road 353


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



Representative Photographs: T.N. Steel, Jr. House (S-10031)



1. Dwelling - View southwest of front and side facades.



2. Dwelling - View southeast of front and side facades.



3. Dwelling - View northwest of rear and side facades.



4. Barn - View north of front facade.



5. Garage - View northeast of front and side facades.



6. Chicken House - View northeast.



7. View northwest of chicken house and garage (rear façade) with barn in distance.

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-2454

Majority of earlier form not legible.

Named Harold Marvel House (current owner) on 1981 survey form.

Not on 1868 Beers' Atlas, on 1928 USGS.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-2454

1. ADDRESS/LOCATION: N side of Road 353, E of Substation Road

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1870 CIRCA?: ARCHITECT/BUILDER: Not Known

4. STYLE OR FLOOR PLAN: Massed-Plan Side-Gable

5. INTEGRITY: original site moved

if moved, from where
N/A

other location's CRS #
N/A

year
0

list major alterations and additions with years (if known)

a. multiple additions, appear to be 20th century year
0

b. year
0

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular original, multiple additions make irregular shape **Stories:** 2
Additions: multiple frame additions on front (S), E, and N (rear) elevations

b. Structural system (if known): balloon frame

c. Foundation: materials: brick
basement: full partial not visible no basement

d. Exterior walls (original if visible & any subsequent coverings): clapboards

e. Roof: shape: gable
materials: asphalt shingles
cornice: box, except front addition has exposed rafter ends
dormers: none
chimney: location(s): interior parged brick chimney at E side of original section

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: S

- 1) Bays not visible
- 2) Windows not visible on original
- fenestration tripartite at E side of front addition
- type 1/1 double-hung wood sash
- trim not visible
- shutters N/A

Facade (cont'd)

- 3) **Door(s)** not visible
location N/A
type N/A
trim N/A

4) **Porch(es)**b. **Side: Direction: E**

- 1)
- Bays**
- 4

2) **Windows**

- fenestration** original section has 2 symmetrical windows on second floor, first floor middle additions have 4 square windows, addition extending to N has 1 window
type sash missing from S second floor window of original section, other original second floor window has original 2/2, double-hung wood sash, middle additions have square sash, N addition has 1/1 double-hung wood sash
trim simple wood molding
shutters none
- 3) **Door(s)** 1
location on middle addition
type not visible
trim not visible
- 4) **Porch(es)** none

c. **Side: Direction: W**

- 1)
- Bays**
- 2

2) **Windows**

- fenestration** first floor of original section is not visible, second floor of original section has 1 central window, N addition has 1 central window
type 1/1 double-hung sash
trim simple wood molding
shutters none

- 3) **Door(s)** none
location N/A
type N/A
trim N/A
- 4) **Porch(es)** none

d. **Rear: Direction: N**

- 1)
- Bays**
- 3

2) **Windows**

- fenestration** 1 on first floor of original section
type not visible
trim N/A
shutters none

- 3) **Door(s)** 1
location on original section
type not visible
trim not visible
- 4) **Porch(es)** none

9. **INTERIOR:** N/A10. **LANDSCAPING:** over-grown trees and vegetation adjacent to house, agricultural field to north11. **OTHER COMMENTS:** Junk on property limited access to building exterior



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-2454

1. ADDRESS/LOCATION: N Side Of Road 353, E Of Substation Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



Representative Photographs: Harold Marvel House (S-2454)



1. View north of front and side facades.



2. View northwest of side facade.



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-2453

1. HISTORIC NAME/FUNCTION: Clifton Toomey House
2. ADDRESS/LOCATION: N side of Road 353, between Substation Road and Road 352
3. CURRENT CONDITION: excellent good fair poor demolished
4. INTEGRITY: same
-
5. SETTING INTEGRITY: Shed noted on earlier form is not present.
-

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
0	CRS 2 Main Building Form	N/A
0	CRS 3 Secondary Building Form	N/A
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

7. SURVEYOR INFORMATION:

Surveyor name: Martin Abbot And Rebecca Hunt

Principal Investigator name: Martin Abbot

Principal Investigator signature: _____

Organization: URS, King Of Prussia, PA Date: 5/1/2003

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-2453

Exterior architectural details suggest a circa 1950 construction date.

Named Clifton Toomey House on 1981 survey form.

Original Survey form identifies property on Frankford Quad, but it appears to be on Bethany Beach Quad.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∨ Contact Period (Native American)
 - 1630-1730∨ Exploration and Frontier Settlement
 - 1730-1770∨ Intensified and Durable Occupation
 - 1770-1830∨ Early Industrialization
 - 1830-1880∨ Industrialization and Early Urbanization
 - 1880-1940∨ Urbanization and Early Suburbanization
 - 1940-1960∨ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- Agriculture
 - Forestry
 - Trapping/Hunting
 - Mining/Quarrying
 - Fishing/Oystering
 - Manufacturing
 - Retailing/Wholesaling
 - Finance
 - Professional Services
 - Transportation and Communication
 - Settlement Patterns and Demographic Changes
 - Architecture, Engineering and Decorative Arts
 - Government
 - Religion
 - Education
 - Community Organizations
 - Occupational Organizations
 - Major Families, Individuals and Events



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-2453

1. ADDRESS/LOCATION: N Side Of Road 353, Between Substation Road And Road 352


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



Representative Photographs: Clifton Toomey House (S-2453)



1. View northeast of front and side facades.



2. View southwest of side and rear facades.



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10032
SPO Map 20-21-07
Hundred Baltimore
Quad Bethany Beach
Other 1-34-12-365

1. HISTORIC NAME/FUNCTION: Dwelling, W side of Road 352, 300' S of Bernice Rd.
2. ADDRESS/LOCATION: W side of Road 352, 300' S of Bernice Rd.
3. TOWN/NEAREST TOWN: Millville vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
DE Route 26 Alternate (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	single-family dwelling
2	CRS 3 Secondary Building Form	garage, shed
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

8. SURVEYOR INFORMATION:

Surveyor name: Martin Abbot And Rebecca Hunt

Principal Investigator name: Martin Abbot

Principal Investigator signature: _____

Organization: URS Corporation, King Of Prussia, PA Date: 5/1/2003

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-10032


Not shown on Beers' 1868 Map. Shown on 1928 USGS Map.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10032

1. ADDRESS/LOCATION: W side of Road 352, 300' S of Bernice Rd.
2. FUNCTION(S): historic single-family dwelling current single-family dwelling
3. YEAR BUILT: 1875 CIRCA?: ARCHITECT/BUILDER: Not Known
4. STYLE OR FLOOR PLAN: Massed-Plan Side-Gable dwelling with later rectangular additions to rear

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>other location's CRS #</u>	<u>year</u>
N/A	N/A	0

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. late 19 th -century 2-story rear addition forming T-shape	0
b. 1-story addition on N side of addition appears to date to 1 st half of 20 th century	0
c. 1-story addition on S side of addition appears to date to 2 nd half of 20 th century	0

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: original rectangular, then T-shaped, now rectangular Stories: 2 1/2
 Additions: 2-story rear addition with attached later 1-story additions on N and S sides

b. Structural system (if known): balloon frame

c. Foundation: materials: concrete block
 basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings):

e. Roof: shape: gable
 materials: asphalt shingles
 cornice: box
 dormers: none
 chimney: location(s): external modern concrete block flue on S elevation

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: E
 1) Bays 2
 2) Windows
 fenestration first floor not visible, 2 symmetrical windows on second floor
 Type replacement, 1/1 vinyl sash
 Trim vinyl
 shutters none

Facade (cont'd)

3) **Door(s)** first floor not visible, but probably is 1 door to access screened porch
location N/A
Type N/A
Trim N/A

4) **Porch(es)** Screened porch almost spanning full width of front elevation, 3-bays with tripartite grillework at top and enclosed with aluminum siding at base, hip roof with asphalt shingles

b. Side: Direction: N

1) **Bays** 4

2) **Windows**

fenestration regular on original section with 2 per floor, 1 on E side of 1-story addition, 2 symmetrical on second floor of addition

type 1/1 double-hung vinyl sash

trim vinyl

shutters none

3) **Door(s)** 1

location W side of 1-story addition

type glass-panels over wood panels

trim vinyl

4) **Porch(es)** N elevation of front screened porch has central door

c. Side: Direction: S

1) **Bays** 4

2) **Windows**

fenestration none of first floor of original section, central windows on second floor and attic of original section, 1 sliding window on W side of 1-story addition, small window on E side of 1-story addition, 2 symmetrical windows on second floor of addition.

type 1/1 double-hung vinyl, except original 2/2 double-hung wood sash at attic and sliding windows on first floor addition

trim vinyl

shutters none

3) **Door(s)** 1

location E side of 1-story addition, bay with door may be latest addition because it appears to have been added to adjoining 1-story section and wraps on to original section

type modern 6-panel

trim vinyl

4) **Porch(es)** S elevation of front screened porch has section similar to 3 on front/E elevation

d. Rear: Direction: W

1) **Bays** Not accessible

2) **Windows**

fenestration N/A

type N/A

trim N/A

shutters N/A

3) **Door(s)** N/A

location N/A

type N/A


trim N/A

4) **Porch(es)** N/A

9. **INTERIOR:** N/A

10. **LANDSCAPING:** minimal plantings adjacent to house

11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10032

1. ADDRESS/LOCATION: W side of Road 352, 300' S of Bernice Rd.

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 1st half of 20th century CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	<u>0</u>

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. <u>N/A</u>	<u>0</u>
b.	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood frame

b. Number of stories 1

c. Wall coverings vinyl siding

d. Foundation N/A

e. Roof

structural system gable
coverings asphalt shingles
openings none

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: E

1) bays: 1

2) windows: none

3) door(s): garage door opening

4) other: N/A

- b. Side: direction: N
 - 1) bays: 1
 - 2) windows: 1 with 4-light wood sash
 - 3) door(s): none
 - 4) other: N/A

- c. Side: direction: S
 - 1) bays: 1
 - 2) windows: 1 with 6-light wood sash
 - 3) door(s): none
 - 4) other: N/A

- d. Rear: direction: W
 - 1) bays: N/A
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan N/A

b) Partition/walls N/A

c) Finishes N/A

d) Furnishings/machinery N/A



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10032

1. ADDRESS/LOCATION: W side of Road 352, 300' S of Bernice Rd.

2. FUNCTION(S): historic Shed or hen house current shed

3. YEAR BUILT: 1920 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	<u>0</u>

<u>list major alterations and additions with years (if known)</u>		<u>year</u>
a.	<u>N/A</u>	<u>0</u>
b.		

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood frame

b. Number of stories 1

c. Wall coverings vinyl siding

d. Foundation N/A

e. Roof
structural system gable
coverings asphalt shingles
openings none

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: N
1) bays: 1
2) windows: none
3) door(s): 1 on E end
4) other: N/A

- b. Side: direction: E
 - 1) bays: 1
 - 2) windows: none
 - 3) door(s): none
 - 4) other: N/A

- c. Side: direction: W
 - 1) bays: N/A
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A

- d. Rear: direction: S
 - 1) bays: N/A
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A

9. INTERIOR (if accessible):

- a) Floor plan N/A
- b) Partition/walls N/A
- c) Finishes N/A
- d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-10032

1. ADDRESS/LOCATION: W Side Of Road 352, 300' S Of Bernice Rd.
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-10032

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9

Representative Photographs: Dwelling, W Side of Road 352, South of Bernice Road (S-10032)



1. View north of property from Windmill Road (Road 352).



2. View northwest of front and side facades.



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-2356

1. HISTORIC NAME/FUNCTION: J. Hall House
2. ADDRESS/LOCATION: W side of Road 352, S of Road 353
3. CURRENT CONDITION: excellent good fair poor demolished
4. INTEGRITY: earlier survey form notes machine sawn shingles on exterior walls but are probably existing asbestos shingles, porch now screened
5. SETTING INTEGRITY: same

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
0	CRS 2 Main Building Form	N/A
0	CRS 3 Secondary Building Form	N/A
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

7. SURVEYOR INFORMATION:

Surveyor name: Martin Abbot And Rebecca Hunt

Principal Investigator name: Martin Abbot

Principal Investigator signature: _____

Organization: URS, King Of Prussia, PA Date: 5/1/2003

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-2356

Original dwelling 2 1/2 story dwelling has a 2-story addition on the N gable end and a 1 1/2 story addition on the rear elevation. The majority of the exterior architectural features of the original dwelling are obscured by later additions and nearby trees. It would appear that the house is shown on the Beers' 1868 Atlas as the L. Furman house. It is shown on the 1928 USGS Map.

The gambrel-roofed frame barn is extant.

Named J. Hall House on 1981 survey form.

Tax map should be corrected to be 1-34-12 (not 1-34-16).

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∨ Contact Period (Native American)
 - 1630-1730∨ Exploration and Frontier Settlement
 - 1730-1770∨ Intensified and Durable Occupation
 - 1770-1830∨ Early Industrialization
 - 1830-1880∨ Industrialization and Early Urbanization
 - 1880-1940∨ Urbanization and Early Suburbanization
 - 1940-1960∨ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-2356

1. ADDRESS/LOCATION: W Side Of Road 352, S Of Road 353


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



Representative Photographs: J. Hall House (S-2356)



1. View south of property from Windmill Road (Road 352).



2. View south of front (at left) and side facades.



3. View east of rear and side facades.



4. Barn - View northwest of front and side facades.

DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901



CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10033
SPO Map 20-21-07
Hundred Baltimore
Quad Bethany Beach
Other 1-34-12-386

1. HISTORIC NAME/FUNCTION: Orville Quillen House
2. ADDRESS/LOCATION: E side of Road 352, 850' S of Road 353
3. TOWN/NEAREST TOWN: Millville vicinity?
4. MAIN TYPE OF RESOURCE: building structure
landscape district site object
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
DE Route 26 Alternate (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	single-family dwelling
1	CRS 3 Secondary Building Form	storage building
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

8. SURVEYOR INFORMATION:

Surveyor name: Martin Abbot And Rebecca Hunt

Principal Investigator name: Martin Abbot

Principal Investigator signature: _____

Organization: URS Corporation, King Of Prussia, PA Date: 5/1/2003

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-10033


Appearance on USGS maps is inconclusive.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S- 10033

1. ADDRESS/LOCATION: E side of Road 352, 850' S of Road 353
2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER: Not Known

4. STYLE OR FLOOR PLAN: Bungalow

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year
N/A N/A 0

list major alterations and additions with years (if known) year
a. various 20th century additions 0
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular with addition wings Stories: 1 1/2
Additions: 1-story additions on all elevations except front/W.
- b. Structural system (if known): balloon frame
- c. Foundation: materials: not visible
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): asbestos shingles on original section, clapboards on N and S additions, plywood on rear/E addition
- e. Roof: shape: gable
materials: asphalt shingles
cornice: box
dormers: none
chimney: location(s): concrete block exterior flue on S end of original section

8. DESCRIPTION OF ELEVATIONS:
a. Facade: Direction: W
1) Bays 3 + (first floor of original section not visible due to screened porch)
2) Windows
fenestration 1 on each addition (original section not visible)
type multiple-light wood sash and 1/1 double-hung sash
trim simple wood
shutters none

Facade (cont'd)

- 3) **Door(s)** 1
 location central on original section
 type not visible
 trim not visible

- 4) **Porch(es)** screened porch spans front of original section, shed roof covered with asphalt shingles continues from main slope,

b. Side: Direction: N

- 1) **Bays** 1+ (rear addition not visible)

- 2) **Windows**
 fenestration 1 slightly W of center on second floor of original section, 1 pair centered on addition
 type 1/1 double-hung sash
 trim simple wood trim
 shutters none

- 3) **Door(s)** none (rear addition not visible)
 location N/A
 type N/A
 trim N/A

- 4) **Porch(es)** none (rear addition not visible)

c. Side: Direction: S

- 1) **Bays** 2 (rear addition not visible)

- 2) **Windows**
 fenestration 1 on W half of second floor of original section, none visible on first floor
 type 1/1 double-hung sash
 trim simple wood trim
 shutters none

- 3) **Door(s)** 1
 location 1-story addition
 type not visible
 trim not visible

- 4) **Porch(es)** none

d. Rear: Direction: E

- 1) **Bays** Not Accessible

- 2) **Windows**
 fenestration N/A
 type N/A
 trim N/A
 shutters N/A


- 3) **Door(s)** N/A
 location N/A
 type N/A
 trim N/A

- 4) **Porch(es)** N/A

9. **INTERIOR:** N/A

10. **LANDSCAPING:** planting beds on front elevation

11. **OTHER COMMENTS:** agricultural fields on adjacent property to S



CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10033

1. ADDRESS/LOCATION: E side of Road 352, 850' S of Road 353

2. FUNCTION(S): historic storage current storage

3. YEAR BUILT: 1980 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	<u>0</u>

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. <u>N/A</u>	<u>0</u>
b.	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system masonry
- b. Number of stories 1
- c. Wall coverings paint over concrete block
- d. Foundation concrete block
- e. Roof
 - structural system gable
 - coverings asphalt shingles
 - openings none

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: W
 - 1) bays: 2
 - 2) windows: none
 - 3) door(s): 1 on S end
 - 4) other: N/A

- b. Side: direction: N
 - 1) bays: Not accessible
 - 2) windows: N/A

 - 3) door(s): N/A

 - 4) other: N/A

- c. Side: direction: S
 - 1) bays: 1
 - 2) windows: none

 - 3) door(s): none

 - 4) other: N/A

- d. Rear: direction: E
 - 1) bays: Not accessible
 - 2) windows: N/A

 - 3) door(s): N/A

 - 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan N/A

b) Partition/walls N/A

c) Finishes N/A

d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10033

1. ADDRESS/LOCATION: E Side Of Road 352, 850' S Of Road 353


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



Representative Photographs: Orville Quillen House (S-10033)



1. View southeast of front and side facades.



2. View northeast of front and side facades.



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-2342

1. HISTORIC NAME/FUNCTION: A. Clark House
2. ADDRESS/LOCATION: N side of Road 352 at intersection with Road 84
3. CURRENT CONDITION: excellent good fair poor demolished
4. INTEGRITY: Earlier survey form notes machine sawn shingles on exterior walls but are probably existing asbestos shingles. Earlier survey form does not mention modern frame shed and outdoor shower structure.
5. SETTING INTEGRITY: Current housing development behind property and across Road 84

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
0	CRS 2 Main Building Form	N/A
0	CRS 3 Secondary Building Form	N/A
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

7. SURVEYOR INFORMATION:

Surveyor name: Martin Abbot And Rebecca Hunt

Principal Investigator name: Martin Abbot

Principal Investigator signature: _____

Organization: URS, King Of Prussia, PA Date: 5/1/2003

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-2342

Exterior architectural details suggest a 2nd half of 19th century construction date. It would appear that the house is shown on the Beers' 1968 as the H.R. Johnson house. Thus, a circa 1860 construction date appears appropriate.

Named A. Clark House on 1981 survey form.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750∨ Contact Period (Native American)
- 1630-1730∨ Exploration and Frontier Settlement
- 1730-1770∨ Intensified and Durable Occupation
- 1770-1830∨ Early Industrialization
- 1830-1880∨ Industrialization and Early Urbanization
- 1880-1940∨ Urbanization and Early Suburbanization
- 1940-1960∨ Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-2342

1. ADDRESS/LOCATION: N Side Of Road 352 At Intersection With Road 84
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad-map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN




Representative Photographs: A. Clark House (S-2342)



1. View west of front façade.



2. View northeast of rear and side façades.



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-2355

1. HISTORIC NAME/FUNCTION: E. Chandler House
2. ADDRESS/LOCATION: W side of Road 84, south of Road 352
3. CURRENT CONDITION: excellent good fair poor demolished
4. INTEGRITY: 1-story, flat-roofed addition on rear. Details include: W elevation not accessible, no doors visible on other elevations, paired windows visible on N elevation, concrete block flue at W corner of N elevation.
5. SETTING INTEGRITY: Current housing development behind property and across SR 84

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
0	CRS 2 Main Building Form	N/A
4	CRS 3 Secondary Building Form	open garage, shed, chicken house type 1, chicken houses type 2 (small modern shed not surveyed)
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

7. SURVEYOR INFORMATION:

Surveyor name: Martin Abbot And Rebecca Hunt

Principal investigator name: Martin Abbot

Principal Investigator signature: _____

Organization: URS, King Of Prussia, PA Date: 5/1/2003

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-2355

Exterior architectural details suggest a 2nd half of 19th century construction date for dwelling. It would appear that the house is shown on the Beers' 1968 Atlas as the J. Short house. Shown on 1928 USGS map.

Named E. Chandler House on 1981 survey form.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∨ Contact Period (Native American)
 - 1630-1730∨ Exploration and Frontier Settlement
 - 1730-1770∨ Intensified and Durable Occupation
 - 1770-1830∨ Early Industrialization
 - 1830-1880∨ Industrialization and Early Urbanization
 - 1880-1940∨ Urbanization and Early Suburbanization
 - 1940-1960∨ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- Agriculture
 - Forestry
 - Trapping/Hunting
 - Mining/Quarrying
 - Fishing/Oystering
 - Manufacturing
 - Retailing/Wholesaling
 - Finance
 - Professional Services
 - Transportation and Communication
 - Settlement Patterns and Demographic Changes
 - Architecture, Engineering and Decorative Arts
 - Government
 - Religion
 - Education
 - Community Organizations
 - Occupational Organizations
 - Major Families, Individuals and Events



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-2355

1. ADDRESS/LOCATION: W side of Road 84, south of Road 352

2. FUNCTION(S): historic chicken house current chicken house

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
N/A	N/A	0

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. N/A	0
b.	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood frame
- b. Number of stories 1
- c. Wall coverings horizontal boards
- d. Foundation not visible
- e. Roof
 - structural system shed with exposed rafter ends
 - coverings not visible
 - openings not visible

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: E
 - 1) bays: 9
 - 2) windows: 6 pairs, 1 pair appears to have extant 1/1 double-hung wood sash, no other sash survives, no glazing survives
 - 3) door(s): 3 doorways, 1 boarded shut, 2 with no closure
 - 4) other: N/A

- b. Side: direction: N
 - 1) bays: 1
 - 2) windows: central grouping
 - 3) door(s): none
 - 4) other: N/A

- c. Side: direction: S
 - 1) bays: Not visible
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A

- d. Rear: direction: W
 - 1) bays: Not visible
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A


9. INTERIOR (if accessible):

- a) Floor plan N/A

- b) Partition/walls N/A

- c) Finishes N/A

- d) Furnishings/machinery N/A



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-2355

1. ADDRESS/LOCATION: W side of Road 84, south of Road 352

2. FUNCTION(S): historic chicken houses (2) current chicken houses (2)

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
N/A	N/A	0

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. N/A	0
b.	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood frame

b. Number of stories 1

c. Wall coverings sheeting over clapboards

d. Foundation not visible

e. Roof

structural system central shed-roofed section with flanking gable-roofed sections

coverings standing seam metal

openings none visible

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: E

1) bays: Not fully visible

2) windows: some pairs of fixed 12-light wood sash and 6/6 double-hung wood sash are visible

3) door(s): 2 plain board doors are visible

4) other: north end of east building has collapsed

- b. Side: direction: N
 - 1) bays: Not visible
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A

- c. Side: direction: S
 - 1) bays: Not visible
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A

- d. Rear: direction: W
 - 1) bays: Not visible
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan N/A

b) Partition/walls

c) Finishes N/A

d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-2355

1. ADDRESS/LOCATION: W side of Road 84, south of Road 352

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 3rd quarter, 20th century CIRCA?: ARCHITECT/BUILDER: Not known

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year
N/A N/A 0

list major alterations and additions with years (if known) year
a. N/A 0
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system telephone poles, wood frame, and masonry

b. Number of stories 1

c. Wall coverings paint over concrete block

d. Foundation concrete block

e. Roof
structural system shed with wood framing
coverings not visible
openings none

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: S
1) bays: 5
2) windows: none
3) door(s): none
4) other: N/A

- b. Side: direction: W
 - 1) bays: Not accessible
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A

- c. Side: direction: E
 - 1) bays: 1
 - 2) windows: none
 - 3) door(s): none
 - 4) other: N/A

- d. Rear: direction: N
 - 1) bays: Not accessible
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A

9. INTERIOR (if accessible):

- a) Floor plan N/A

- b) Partition/walls N/A

- c) Finishes N/A

- d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-2355

1. ADDRESS/LOCATION: W side of Road 84, south of Road 352

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	<u>0</u>

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
<u>a. N/A</u>	<u>0</u>
<u>b.</u>	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system concrete block

b. Number of stories 1

c. Wall coverings paint over concrete block

d. Foundation concrete block

e. Roof
structural system gable
coverings corrugated metal
openings none

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S
- 1) bays: 1
 - 2) windows: none
 - 3) door(s): 2 sliding wood doors
 - 4) other: N/A

- b. Side: direction: W
 - 1) bays: Not accessible
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A

- c. Side: direction: E
 - 1) bays: 1
 - 2) windows: none
 - 3) door(s): none
 - 4) other: N/A

- d. Rear: direction: N
 - 1) bays: Not accessible
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A

9. INTERIOR (if accessible):

- a) Floor plan N/A

- b) Partition/walls N/A

- c) Finishes N/A

- d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-2355

1. ADDRESS/LOCATION: W Side Of Road 84, South Of Road 352


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-2355

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9

Representative Photographs: E. Chandler House (S-2355)



1. View north of front and side facades.



2. View southwest of front and side facades.



3. View west of chicken houses.



4. View west of chicken houses (note partial collapse), storage building, and cart shed.



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10034
SPO Map 22-23-06
Hundred Baltimore
Quad Bethany Beach
Other 1-34-16-682

1. HISTORIC NAME/FUNCTION: Dwelling, S side of Road 368, 200' W of Road 362
2. ADDRESS/LOCATION: S side of Road 368, 200' W of Road 362
3. TOWN/NEAREST TOWN: Millville vicinity?
4. MAIN TYPE OF RESOURCE:

building <input checked="" type="checkbox"/>	structure <input type="checkbox"/>	site <input type="checkbox"/>	object <input type="checkbox"/>
landscape <input type="checkbox"/>	district <input type="checkbox"/>		
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
DE Route 26 Alternate (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	single-family dwelling
3	CRS 3 Secondary Building Form	garage, 2 sheds
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

8. SURVEYOR INFORMATION:

Surveyor name: Martin Abbot And Rebecca Hunt

Principal Investigator name: Martin Abbot

Principal Investigator signature: _____

Organization: URS Corporation, King Of Prussia, PA Date: 5/1/2003

9. OTHER NOTES OR OBSERVATIONS:


CRS# S-10034

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10034

1. ADDRESS/LOCATION: S side of Road 368, 200' W of Road 362

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1875 CIRCA?: ARCHITECT/BUILDER: Not Known

4. STYLE OR FLOOR PLAN: I-House

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>other location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	<u>0</u>

list major alterations and additions with years (if known) year

a. N/A 0

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular with multiple additions Stories: 2
Additions: 1-story additions on front and sides

b. Structural system (if known): balloon frame

c. Foundation: materials: not visible
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): synthetic siding

e. Roof: shape: gable, most of front roof slope has been raised to create a full second floor
materials: asphalt shingles
cornice: box
dormers: gabled
chimney: location(s): interior parged chimney at E gable end

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: N

1) Bays 7

2) Windows

fenestration no original windows visible, 1 on E addition, 1 on front entry addition, 1 replacement window on first floor of main section, 1 pair of windows and 1 single window on second floor of main section, 2 on W addition

type modern 1/1 sash

trim not visible

shutters on all windows except 2 on front entry addition

Facade (cont'd)

- 3) **Door(s)** 1
 location centered on front entry addition
 type diamond-shaped glass panels visible on top half
 trim not visible
- 4) **Porch(es)** none

b. Side: Direction: E

- 1) **Bays** 4
- 2) **Windows**
 fenestration 2 on rear addition, 1 on east addition, none on front entry addition
 type modern double-hung
 trim not visible
 shutters none
- 3) **Door(s)** none
 location N/A
 type N/A
 trim N/A
- 4) **Porch(es)** none

c. Side: Direction: W

- 1) **Bays** 2 visible
- 2) **Windows**
 fenestration 2 on west addition, none on front entry addition
 type modern double hung
 trim not visible
 shutters on both windows
- 3) **Door(s)** none
 location N/A
 type N/A
 trim N/A
- 4) **Porch(es)** none

d. Rear: Direction: S

- 1) **Bays** Not accessible
- 2) **Windows**
 fenestration N/A
 type N/A
 trim N/A
 shutters N/A
- 3) **Door(s)** N/A
 location N/A
 type N/A
 trim N/A
- 4) **Porch(es)** N/A

9. **INTERIOR:** N/A

10. **LANDSCAPING:** planting beds, modern housing development across street

11. **OTHER COMMENTS:** upper gable end of E elevation is only surviving evidence of historic building.



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10034

1. ADDRESS/LOCATION: S side of Road 368, 200' W of Road 362

2. FUNCTION(S): historic garage current workshop

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

if moved, from where

N/A

original location's CRS #

N/A

year

0

list major alterations and additions with years (if known)

a. finished interior, modern

year

0

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood fram

b. Number of stories 1

c. Wall coverings synthetic siding

d. Foundation not visible

e. Roof

structural system Gable with attached shed roof

coverings aphalt shingles

openings none

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: W

1) bays: 2

2) windows: none

3) door(s): modern sliding, paired wood doors under shed

4) other: N/A

- b. Side: direction: N
 - 1) bays: 1
 - 2) windows: 1, 1/1 double-hung sash
 - 3) door(s): none
 - 4) other: N/A

- c. Side: direction: S
 - 1) bays: Not visible
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A

- d. Rear: direction: E
 - 1) bays: Not visible
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A


9. INTERIOR (if accessible):

a) Floor plan N/A

b) Partition/walls N/A

c) Finishes N/A

d) Furnishings/machinery N/A



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10034

1. ADDRESS/LOCATION: S side of Road 368, 200' W of Road 362

2. FUNCTION(S): historic shed current shed

3. YEAR BUILT: 1990 CIRCA?: ARCHITECT/BUILDER: Not known

4. STYLE/FLOOR PLAN: Rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	<u>0</u>

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
<u>a. N/A</u>	<u>0</u>
<u>b.</u>	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood frame
- b. Number of stories 1
- c. Wall coverings synthetic siding
- d. Foundation not visible
- e. Roof
 - structural system gable
 - coverings asphalt shingle
 - openings none

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: N
 - 1) bays: Not accessible
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A

- b. Side: direction: E
 - 1) bays: 1
 - 2) windows: 1, double-hung sash with flanking shutters
 - 3) door(s): none
 - 4) other: N/A

- c. Side: direction: W
 - 1) bays: Not visible
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A

- d. Rear: direction: S
 - 1) bays: Not visible
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A

9. INTERIOR (if accessible):

- a) Floor plan N/A
- b) Partition/walls N/A
- c) Finishes N/A
- d) Furnishings/machinery N/A



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10034

1. ADDRESS/LOCATION: S side of Road 368, 200' W of Road 362

2. FUNCTION(S): historic shed current shed

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: Not known

4. STYLE/FLOOR PLAN: Rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
N/A	N/A	0

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. <u>N/A</u>	0
b.	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood frame
- b. Number of stories 1
- c. Wall coverings synthetic siding
- d. Foundation not visible
- e. Roof
 - structural system shed
 - coverings asphalt shingle
 - openings none

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: E
 - 1) bays: 1
 - 2) windows: none
 - 3) door(s): 1, 3-lights over stacked wood panels
 - 4) other: N/A

b. Side: direction: N

- 1) bays: Not visible
- 2) windows: N/A
- 3) door(s): N/A
- 4) other: N/A

c. Side: direction: S

- 1) bays: Not visible
- 2) windows: N/A
- 3) door(s): N/A
- 4) other: N/A

d. Rear: direction: E

- 1) bays: Not visible
- 2) windows: N/A
- 3) door(s): N/A
- 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan N/A

b) Partition/walls N/A

c) Finishes N/A

d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10034

1. ADDRESS/LOCATION: S Side Of Road 368, 200' W Of Road 362


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



Representative Photographs: Dwelling, S side of Road 368, West of Road 362 (S-10034)



1. View southwest of front and side facades.



2. View southeast of front and side facades.



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10035
SPO Map 20-21-07
Hundred Baltimore
Quad Bethany Beach
Other 1-34-16-297

1. HISTORIC NAME/FUNCTION: Dwelling, NW side of Road 362 at Road 368
2. ADDRESS/LOCATION: NW side of Road 362 at Road 368
3. TOWN/NEAREST TOWN: Millville vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
 landscape district
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
DE Route 26 Alternate (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	single-family dwelling
1	CRS 3 Secondary Building Form	garage
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

8. SURVEYOR INFORMATION:

Surveyor name: Martin Abbot And Rebecca Hunt

Principal Investigator name: Martin Abbot

Principal Investigator signature: _____

Organization: URS Corporation, King Of Prussia, PA Date: 5/1/2003

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-10035

Not shown on Beers' 1868 Atlas. Shown on 1928 USGS map.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S- 10035

1. ADDRESS/LOCATION: NW side of Road 362 at Road 368
2. FUNCTION(S): historic single-family dwelling current single-family dwelling
3. YEAR BUILT: 1875 CIRCA?: ARCHITECT/BUILDER: Not Known
4. STYLE OR FLOOR PLAN: 3-bay, single pile I-house with later rectangular additions to N side and rear

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>other location's CRS #</u>	<u>year</u>
N/A	N/A	0

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
<u>a. 2-story addition on rear of original section, may date to late 19th century</u>	<u>0</u>
<u>b. 2-story addition on N, may date to early 20th century</u>	<u>0</u>
<u>c. 1-story additions on S elevation and W elevation connecting to garage, dates unknown</u>	<u>0</u>

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular with rear hyphen Stories: 2
 Additions: 2-story additions on rear and N elevations of original section, 1-story additions on W and S elevations connecting to garage
- b. Structural system (if known): balloon frame
- c. Foundation: materials: parged masonry
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): aluminum siding
- e. Roof: shape: gable
 materials: asphalt shingles
 cornice: box
 dormers: none
 chimney: location(s): interior masonry chimney on N gable end

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: E
- 1) Bays 4
- 2) Windows
 fenestration regular with 2 on first floor and 4 on second floor
 type modern bay on W end of first floor, others are modern 6/6 double-hung sash
 trim modern aluminum
 shutters none

Facade (cont'd)

- 3) **Door(s)** 1
 location central
 type modern
 trim aluminum
- 4) **Porch(es)** gabled door hood with modern piers at front door

b. Side: Direction: N

- 1) **Bays** 5
- 2) **Windows**
 fenestration regular with 2 on first floor and 4 on second floor, hyphen not visible
 type 6/6 double-hung modern sash
 trim aluminum
 shutters none
- 3) **Door(s)** 1 (hyphen not visible)
 location N end
 type modern multi-light
 trim aluminum
- 4) **Porch(es)** none

c. Side: Direction: S

- 1) **Bays** 5
- 2) **Windows**
 fenestration 2 on each floor of original section, 2 on each floor of additions
 type 6/6 double-hung modern sash
 trim aluminum
 shutters none
- 3) **Door(s)** 1
 location central
 type modern
 trim aluminum
- 4) **Porch(es)** none


d. Rear: Direction: W

- 1) **Bays** Not visible
- 2) **Windows**
 fenestration N/A
 type N/A
 trim N/A
 shutters N/A
- 3) **Door(s)** N/A
 location N/A
 type N/A
 trim N/A
- 4) **Porch(es)** N/A

9. **INTERIOR:** N/A

10. **LANDSCAPING:** modern development to west

11. **OTHER COMMENTS:** Attached gable-roofed garage at rear of dwelling, aluminum siding, asphalt shingle roofing, screened enclosure on E elevation.



CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10035

1. ADDRESS/LOCATION: NW side of Road 362 at Road 368

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 1985 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	<u>0</u>

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
<u>a. N/A</u>	<u>0</u>
<u>b.</u>	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood frame
- b. Number of stories 1
- c. Wall coverings synthetic siding
- d. Foundation concrete
- e. Roof
 - structural system gable
 - coverings asphalt shingles
 - openings none

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S
 - 1) bays: 2
 - 2) windows: none
 - 3) door(s): 1 modern multi-light and 1 garage door
 - 4) other: N/A

- b. Side: direction: E
 - 1) bays: 1
 - 2) windows: 1, 1/1 double-hung sash
 - 3) door(s): none
 - 4) other: N/A

- c. Side: direction: W
 - 1) bays: 1
 - 2) windows: 1, 1/1 double-hung sash
 - 3) door(s): none
 - 4) other: N/A

- d. Rear: direction: N
 - 1) bays: Not visible
 - 2) windows: N/A
 - 3) door(s): N/A
 - 4) other: N/A

9. INTERIOR (if accessible):

- a) Floor plan N/A
- b) Partition/walls N/A
- c) Finishes N/A
- d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10035

1. ADDRESS/LOCATION: Nw Side Of Road 362 At Road 368


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



Representative Photographs: Dwelling, NW side of Road 362 at Road 368 (S-10035)



1. View southeast of front and side facades.



2. View northeast of front and side facades.



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10036
SPO Map 20-21-07
Hundred Baltimore
Quad Bethany Beach
Other 1-34-17-9

1. HISTORIC NAME/FUNCTION: Dwelling, E side of Road 361 at Road 368
2. ADDRESS/LOCATION: E side of Road 361 at Road 368
3. TOWN/NEAREST TOWN: Millville vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
 landscape district
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
DE Route 26 Alternate (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	single-family dwelling
0	CRS 3 Secondary Building Form	N/A
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

8. SURVEYOR INFORMATION:

Surveyor name: Martin Abbot And Rebecca Hunt

Principal Investigator name: Martin Abbot

Principal Investigator signature: _____

Organization: URS Corporation, King Of Prussia, Pa Date: 5/1/2003

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-10036

Shown on 1954 USGS map.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∨ Contact Period (Native American)
 - 1630-1730∨ Exploration and Frontier Settlement
 - 1730-1770∨ Intensified and Durable Occupation
 - 1770-1830∨ Early Industrialization
 - 1830-1880∨ Industrialization and Early Urbanization
 - 1880-1940∨ Urbanization and Early Suburbanization
 - 1940-1960∨ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10036

1. ADDRESS/LOCATION: E side of Road 361 at Road 368

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: Not Known

4. STYLE OR FLOOR PLAN: Minimal Traditional

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>other location's CRS #</u>	<u>year</u>
N/A	N/A	0

list major alterations and additions with years (if known)

a. N/A	<u>year</u>
b.	0

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1
Additions: none

b. Structural system (if known): balloon frame

c. Foundation: materials: concrete
basement: full partial not visible no basement

d. Exterior walls (original if visible & any subsequent coverings): vinyl siding

e. Roof: shape: gable
materials: asphalt shingles
cornice: box
dormers: none
chimney: location(s): 1 central parged, slightly off peak; 1 exterior parged at E gable end

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: W

1) Bays 2

2) Windows

fenestration 1

type 1/1 double-hung modern sash

trim vinyl

shutters none

Facade (cont'd)

- 3) **Door(s)** 1
 location s bay
 type modern paneled
 trim vinyl
- 4) **Porch(es)** front wood deck

b. Side: Direction: S

- 1) **Bays** 3
- 2) **Windows**
 fenestration 3 asymmetrical
 type 1/1 double-hung modern sash
 trim vinyl
 shutters none
- 3) **Door(s)** none
 location N/A
 type N/A
 trim N/A
- 4) **Porch(es)** none


c. Side: Direction: N

- 1) **Bays** 2 + (limited visibility)
- 2) **Windows**
 fenestration 2+ asymmetrical
 type 1/1 double-hung modern sash
 trim vinyl
 shutters none
- 3) **Door(s)** none
 location N/A
 type N/A
 trim N/A
- 4) **Porch(es)** none

d. Rear: Direction: E

- 1) **Bays** Not visible
- 2) **Windows** N/A
 fenestration N/A
 type N/A
 trim N/A
 shutters N/A
- 3) **Door(s)** N/A
 location N/A
 type N/A
 trim N/A
- 4) **Porch(es)** N/A

9. **INTERIOR:** N/A10. **LANDSCAPING:** within cluster of trees11. **OTHER COMMENTS:** N/A



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10036

1. ADDRESS/LOCATION: E Side Of Road 361 At Road 368


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



Representative Photographs: Dwelling, E side of Road 361 at Road 368 (S-10036)



1. View northeast of front and side facades.



2. View east of front facade.