

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-03963

1. HISTORIC NAME/FUNCTION: John Foreaker House

2. ADDRESS/LOCATION: 12847 Route 113

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: New siding, awnings and garage

5. SETTING INTEGRITY: not much – newer shed and deck in rear yard

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Kate Farnham

Principal Investigator name: Grace Ziesing

Principal Investigator signature:

Organization: John Milner Associates, Inc. Date: 4/3/2008

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03963

Resurveyed for US113 North/South Study, Delaware Department of Transportation, by John Milner Associates, Inc.

Possibly moved? Appears to have had substantial work done ca. 1930-1940s

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):


- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-03963.001

1. ADDRESS/LOCATION: 12847 Route 113

2. FUNCTION(S): historic Dwelling current dwelling

3. YEAR BUILT: 1890-1900 CIRCA?: ARCHITECT/BUILDER:

4. STYLE OR FLOOR PLAN: Hall-and-parlor

5. INTEGRITY: original site moved

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year
a. Aluminum siding and awnings; new infill door on façade (previously a window)
b. Extended rear porch and 2 side additions

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)


- a. Overall shape: T-plan Stories: 2.5
Additions: extended rear porch and 2 side additions
- b. Structural system (if known): wood-framed
- c. Foundation: materials: rusticated concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): aluminum siding
- e. Roof: shape: cross gable
materials: asphalt
cornice: boxed
dormers:
chimney: location(s): brick, int. gable

8. DESCRIPTION OF ELEVATIONS:

a.	Facade: Direction:	S
	1) Bays	3
	2) Windows	1 (1 st story), 3 (2 nd story)
	fenestration	regular
	type	double-hung, 2/2
	trim	wood, aluminum
	shutters	

Facade (cont'd)	
3)	Door(s) 2
	location center, SE side
	type wood and glass(1 light, 3 panels), fiberglass (modern infill for window)
	trim plain
4)	Porch(es) stoop, portico; concrete stoop with modern metal porch roof (flat) with aluminum posts
b.	Side: Direction: E
1)	Bays 2
	2)
2)	fenestration irregular
	type double-hung, 1/1, 3/1; fixed (paired 1-light attic windows)
	trim aluminum
	shutters
3)	Door(s) 0
	location
	type
	trim
4)	Porch(es) 0
c.	Side: Direction: W
1)	Bays 3
2)	Windows 5 (1 st story), 3 (2 nd story), 2 (3 rd story)
	fenestration regular
	type double-hung, 6/1, 4/4 ; fixed paired 1-light attic windows
	trim wood
	shutters
3)	Door(s) 1
	location center
	type wood and glass, 6-light, 3 panel
	trim plain
4)	Porch(es) inset, ca. 1930s, concrete floor, wrought iron column, steep shed roof
d.	Rear: Direction: N
1)	Bays 2
2)	Windows 2 on 2 nd story
	fenestration regular
	type double-hung 6/1
	trim wood
	shutters
3)	Door(s)
	location
	type
	trim
4)	Porch(es) shed-roof, full-width enclosed porch

9.	INTERIOR:
10.	LANDSCAPING: open lawn and circular crushed-shell driveway in front. Several specimens of shrubs and foundation plantings, tree line along both sides of the property
11.	OTHER COMMENTS: house appears to have been substantially remodeled in the 1940s



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03963.002

1. ADDRESS/LOCATION: 12847 Route 113

2. FUNCTION(S): historic Garage current garage

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Double pen

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. new garage doors
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-framed
- b. Number of stories 1
- c. Wall coverings wood siding (horizontal and vertical), board and batten
- d. Foundation poured concrete
- e. Roof
 - structural system gable front, boxed cornices
 - coverings asphalt
 - openings _____

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: W
 - 1) bays: 2
 - 2) windows: _____
 - 3) door(s): 2, fiberglass paneled garage doors (new)
 - 4) other: _____

- b. Side: direction: N
 - 1) bays: 0
 - 2) windows:
 - 3) door(s): 1, NE side, wood and glass, 3-light, 3 panel
 - 4) other:

- c. Side: direction: S
 - 1) bays: 1
 - 2) windows: 1, fixed 4-light, metal awning
 - 3) door(s):
 - 4) other:

- d. Rear: direction: E
 - 1) bays: 2
 - 2) windows: 2, fixed, 4-light
 - 3) door(s):
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-03963

1. ADDRESS/LOCATION: 12847 Route 113
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-03964

1. HISTORIC NAME/FUNCTION: Erasmus Arnold Farmstead

2. ADDRESS/LOCATION: Old Road, West of US Route 113

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: Modern vinyl siding, replacement windows and doors throughout; large 1 story addition on W side and SE corner, façade is now facing N toward 113

5. SETTING INTEGRITY: several modern buildings and modern trailer house

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Kate Farnham

Principal Investigator name: Grace Ziesing

Principal Investigator signature: 

Organization: John Milner Associates, Inc Date: 4/3/2008

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03964

Resurveyed for US113 North/South Study, Delaware Department of Transportation, by John Milner Associates, Inc.

Property is on both sides of what is mapped as VFW Rd. but is named Old Road (unpaved – dirt)

Owner says addition/ major renovations occurred in 1995

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):


- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-03964.001

1. ADDRESS/LOCATION: Old Road, West of US Route 113

2. FUNCTION(S): historic Agricultural Complex current Agricultural complex

3. YEAR BUILT: 1900 CIRCA?: ARCHITECT/BUILDER:

4. STYLE OR FLOOR PLAN: I-house

5. INTEGRITY: original site moved

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. new siding, windows, doors and porch; side porches have been enclosed

b. Façade now oriented toward 113 with new porch. Chimneys were removed

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: T-plan Stories: 2
Additions: new porch

b. Structural system (if known): wood-framed

c. Foundation: materials: brick
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): vinyl siding


e. Roof: shape: gable front, side gable, cross gable
materials: asphalt
cornice: boxed
dormers:
chimney: location(s): removed

8. DESCRIPTION OF ELEVATIONS:

a.	Facade: Direction:	E (this is the new facade direction, originally rear of house)		
	1)	Bays	3	
	2)	Windows	4 (2 per story)	
		fenestration	regular	
		type	double-hung, 1/1	
		trim	vinyl	
	shutters			

Facade (cont'd)	
3)	Door(s) 1
	location center
	type fiberglass, 9 light
	trim plain
4)	Porch(es) full-width, portico; hip-roofed full-width porch – all modern materials. Concrete floor and per-fab stoop, modern posts and balustrade, vinyl-clad ceiling
b. Side: Direction: N	
1)	Bays 3
2)	Windows 1 (1 st story), 3 (2 nd story)
	fenestration irregular
	type double-hung, 1/1, vinyl
	trim vinyl
	shutters
3)	Door(s) 0
	location
	type
	trim
4)	Porch(es) Enclosed shed-roofed and extended side porch – not original, cinderblock and concrete foundation, prefab steps, completely enclosed
c. Side: Direction: S	
1)	Bays 4
2)	Windows 1 (1 st story), 4 (2 nd story)
	fenestration irregular
	type double-hung, 1/1, vinyl
	trim vinyl
	shutters
3)	Door(s) 0
	location
	type
	trim
4)	Porch(es) enclosed and extended side porch – cinderblock foundation
d. Rear: Direction: W	
1)	Bays 3
2)	Windows none on 1 st story, 3 on 2nd
	fenestration regular
	type double-hung, 1/1, vinyl
	trim vinyl
	shutters
3)	Door(s) 0
	location
	type
	trim
4)	Porch(es)

9.	INTERIOR:
10.	LANDSCAPING: intersecting unpaved road and driveways with crushed oyster shells; lawn and open grassy areas on most of the property; agricultural fields to NW. 2 large cedar trees adjacent to the house, small foundation shrubs and plants. Farm outbuildings are arranged on either side of central road (Old Rd)
11.	OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03964.002

1. ADDRESS/LOCATION: Old Road, West of US Route 113

2. FUNCTION(S): historic Tool shed current Tool shed

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. plywood siding on façade
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-framed
- b. Number of stories 1
- c. Wall coverings wood siding (vertical), grooved plywood
- d. Foundation concrete block footers
- e. Roof
 - structural system gable front, boxed cornices
 - coverings asphalt
 - openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: N
 - 1) bays: 2
 - 2) windows: 1, fixed, 1-light
 - 3) door(s): 1, modern plywood door
 - 4) other:

- b. Side: direction: E
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: W
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: S
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03964.003

1. ADDRESS/LOCATION: Old Road, West of US Route 113

2. FUNCTION(S): historic Chicken house current shed

3. YEAR BUILT: 1960 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. altered to be an equipment shed – façade replaced with 2 pairs of large modern sliding doors

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-framed

b. Number of stories 1

c. Wall coverings wood siding (vertical)

d. Foundation concrete block footers

e. Roof
structural system shed, boxed cornices
coverings metal
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: S

1) bays: 5

2) windows: 2, screened, one single, one group of 4

3) door(s): 3, center, wood and metal; 2 pairs of corrugated metal sliding doors, 1 plywood door

4) other:

- b. Side: direction: W
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: E
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: N
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03964.004

1. ADDRESS/LOCATION: Old Road, West of US Route 113

2. FUNCTION(S): historic Horse barn current Horse barn

3. YEAR BUILT: 1900 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Center section with side sheds

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. plywood door on N shed
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-framed
- b. Number of stories _____
- c. Wall coverings wood siding (vertical)
- d. Foundation concrete block (not visible in most places)
- e. Roof
structural system gable front, shed
coverings metal
openings _____

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: E
 - 1) bays: 3
 - 2) windows: 0
 - 3) door(s): 3, center and both sides, 1 large sliding batten door, 1 plywood, and 1 missing
 - 4) other: _____

- b. Side: direction: N
 - 1) bays: 7
 - 2) windows: 5, regular, fixed, 9-light square sash
 - 3) door(s): 2, center, Dutch doors
 - 4) other:

- c. Side: direction: S
 - 1) bays: 7
 - 2) windows: 5, regular, fixed, 1-light replacement
 - 3) door(s): 2, boarded up openings
 - 4) other:

- d. Rear: direction: W
 - 1) bays: 3
 - 2) windows: 0
 - 3) door(s): 3, center and NW side, 2 Dutch doors, 1 open bay
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03964.005

1. ADDRESS/LOCATION: Old Road, West of US Route 113

2. FUNCTION(S): historic Agricultural Shed current storage

3. YEAR BUILT: 1920 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: One pen

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. bricktex siding, loss of window/door

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-framed

b. Number of stories 1

c. Wall coverings bricktex

d. Foundation none

e. Roof
structural system gable front, exposed rafter ends
coverings metal
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: SE
1) bays: 2
2) windows: 1, fixed, 2-light
3) door(s): 1, center, missing
4) other:

- b. Side: direction: NE
 - 1) bays:
 - 2) windows: 1, fixed, 2-light
 - 3) door(s): 0
 - 4) other:

- c. Side: direction: SW
 - 1) bays: 1
 - 2) windows: 1, fixed, 2-light, missing
 - 3) door(s): 0
 - 4) other:

- d. Rear: direction: NW
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03964.006

1. ADDRESS/LOCATION: Old Road, West of US Route 113

2. FUNCTION(S): historic Equipment shed current Equipment shed

3. YEAR BUILT: 1960 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: 4-bay

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. newer roofing, replacement support posts

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-framed
- b. Number of stories 1
- c. Wall coverings wood siding (vertical), metal
- d. Foundation none
- e. Roof structural system side gable, boxed cornice
coverings metal
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: SE
 - 1) bays: 4
 - 2) windows: 0
 - 3) door(s): 4 – open bays
 - 4) other:

- b. Side: direction: SW
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: NE
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: NW
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03964.007

1. ADDRESS/LOCATION: Old Road, West of US Route 113

2. FUNCTION(S): historic Tourist cabin current cottage

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: One pen

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. new storm windows and doors

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-framed

b. Number of stories 1

c. Wall coverings bricktex

d. Foundation concrete block footers

e. Roof
structural system gable front, boxed cornices
coverings metal
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: SE
1) bays: 2
2) windows: 1, double-hung, 1/1, aluminum
3) door(s): 1, center, aluminum storm door
4) other:

- b. Side: direction: SW
 - 1) bays: 1
 - 2) windows: 1, double-hung, 2/2, horizontal orig.
 - 3) door(s): 0
 - 4) other:

- c. Side: direction: NE
 - 1) bays: 1
 - 2) windows: 1, double-hung, 2/2, horizontal division – orig.
 - 3) door(s): 0
 - 4) other:

- d. Rear: direction: NW
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03964.008

1. ADDRESS/LOCATION: Old Road, West of US Route 113

2. FUNCTION(S): historic Milk house current Milk house

3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: One pen

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. salvage doors

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system concrete block

b. Number of stories 1

c. Wall coverings wood siding (vertical)

d. Foundation concrete block

e. Roof
structural system gable front
coverings metal
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: E

1) bays: 2

2) windows: 1, fixed, steel trim

3) door(s): 1, center, wood, 4-panel Victorian door, Italianate purple glass knob

4) other:

- b. Side: direction: S
 - 1) bays: 2
 - 2) windows: 1, fixed, 2/2
 - 3) door(s): 1, west side, 4-panel Victorian door - salvage
 - 4) other:

- c. Side: direction: N
 - 1) bays: 2
 - 2) windows: 2, fixed, 2/2
 - 3) door(s):
 - 4) other:

- d. Rear: direction: W
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-03964

1. ADDRESS/LOCATION: Old Road, West of US Route 113


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-03965

1. HISTORIC NAME/FUNCTION: Erasmus Arnold House

2. ADDRESS/LOCATION: VFW road at Old Road

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY:

5. SETTING INTEGRITY:


6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Kate Farnham

Principal Investigator name: Grace Ziesing

Principal Investigator signature: 

Organization: John Milner Associates, Inc Date: 4/3/2008

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03965

Resurveyed for US113 North/South Study, Delaware Department of Transportation, by John Milner Associates, Inc.

Demolished – rubble and fence still there

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750∇ Contact Period (Native American)
- 1630-1730∇ Exploration and Frontier Settlement
- 1730-1770∇ Intensified and Durable Occupation
- 1770-1830∇ Early Industrialization
- 1830-1880∇ Industrialization and Early Urbanization
- 1880-1940∇ Urbanization and Early Suburbanization
- 1940-1960∇ Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|--|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY