

DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11052
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 26 Seashore Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2005

9. OTHER NOTES OR OBSERVATIONS:


CRS# S-11052

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11052.001

1. ADDRESS/LOCATION: 26 Seashore Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: WWII-Era Cottage, central hall
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided in vinyl, replacement windows and doors, garage entrance on southeast corner of front façade

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Side Gable
materials: Composition
cornice:
dormers:
chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: south
- 1) Bays: 5
- 2) Windows: 3
Fenestration: regular
Type: double hung, 1/1
Trim: vinyl
Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 2
Location: center, side
Type: other: fiberglass & vinyl
Trim: plain
- 4) **Porch(es):** hood

b. Side: Direction: east

- 1) **Bays:** 2
- 2) **Windows:** 2
Fenestration: irregular
Type: double hung, 1/1
Trim: vinyl
Shutters:
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**

c. Side: Direction: west

- 1) **Bays:** 2
- 2) **Windows:** 2
Fenestration: regular
Type: double hung, 1/1
Trim: vinyl
Shutters: (vinyl,non-functional)
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**

d. Rear: Direction: north


- 1) **Bays:** 3
- 2) **Windows:** 2
Fenestration: regular
Type: double hung, 1/1
Trim: vinyl
Shutters:
- 3) **Door(s):** 1
Location: side
Type: other: fiberglass
Trim: plain
- 4) **Porch(es):**other: see porch details, concrete steps

9. INTERIOR:

- 10. **LANDSCAPING:** faces Seashore Hwy., paved driveway to east side of property, shrubs planted across front façade, trees shade rear and side lawn

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**


CRS # S-11052

1. ADDRESS/LOCATION: 26 Seashore Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11053
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 28 Seashore Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building <input checked="" type="checkbox"/>	structure <input type="checkbox"/>	site <input type="checkbox"/>	object <input type="checkbox"/>
landscape <input type="checkbox"/>	district <input type="checkbox"/>		
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#: Form:	List property types:
X CRS 2 Main Building Form	
X CRS 3 Secondary Building Form	
CRS 4 Archaeological Site Form	
CRS 5 Structure (Building-Like) Form	
CRS 6 Structure (Land Feature) Form	
CRS 7 Object Form	
CRS 8 Landscape Elements Form	
X CRS 9 Map Form	N/A
CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11053.001

1. ADDRESS/LOCATION: 28 Seashore Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, WWII-Era Cottage, Cape Cod
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. resided in vinyl, replacement windows and doors, porch enclosure on east gable end of house, covered in vinyl with modern windows, 1-room in size
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Side Gable
materials: Composition
cornice:
dormers: gabled wall dormer on front facade with modern 6/6 window; large, full-width shed-dormer across rear with modern 1/1 windows
chimney: location(s): exterior, gable, brick

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: south
- 1) Bays: 3
- 2) Windows: 2
Fenestration: regular
Type: double hung, other: bay, 6/6, 4/4
Trim: vinyl
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 Location: center
 Type: other: fiberglass
 Trim: plain
- 4) **Porch(es):** hood

b. Side: Direction: east

- 1) **Bays:**
- 2) **Windows:** , 2
 Fenestration: regular
 Type: double hung, other: obscured by enclosure, 6/6
 Trim: vinyl
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**other: see porch details, enclosed porch: 1-story, shed-roof, 1-room in size

c. Side: Direction: west

- 1) **Bays:** 3
- 2) **Windows:** 3, 1
 Fenestration: regular
 Type: double hung, 6/6
 Trim: vinyl
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**


d. Rear: Direction: north

- 1) **Bays:** 4
- 2) **Windows:** 3
 Fenestration: regular
 Type: double hung, 1/1
 Trim: vinyl
 Shutters:
- 3) **Door(s):** 1
 Location: center
 Type: wood & glass
 Trim: plain
- 4) **Porch(es):**other: metal awning, concrete steps

9. INTERIOR:

- 10. **LANDSCAPING:** faces Seashore Hwy., paved driveway to west side of property, trees and shrubs planted across front lawn, large gardens to rear

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11053.002

1. ADDRESS/LOCATION: 28 Seashore Highway

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1945 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Asbestos

d. Foundation concrete block

e. Roof
structural system Gable Front
coverings Composition
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: south

1) bays: 1

2) windows:

3) door(s): Count: 1; Location: center ; Type: other: aluminum garage door

4) other:

- b. Side: direction: west
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: east
 - 1) bays: 1
 - 2) windows: Count: 1; regular ; double hung, 1/1
 - 3) door(s):
 - 4) other:

- d. Rear: direction: north
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901


CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11053


1. ADDRESS/LOCATION: 28 Seashore Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.
(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11054
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

- HISTORIC NAME/FUNCTION: dwelling
- ADDRESS/LOCATION: 30 Seashore Highway
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
- MAIN FUNCTION OF PROPERTY: domestic
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11054.001

1. ADDRESS/LOCATION: 30 Seashore Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1935 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman, Vernacular, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided in asbestos, porch enclosure on front with hopper windows

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: panel-faced concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Asbestos
- e. Roof: shape: Gable Front
materials: Asphalt
cornice:
dormers:
chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: south
- 1) Bays:
- 2) Windows: 1
Fenestration: regular
Type: double hung, other: obscured by porch enclosure, 4/1
Trim: wood
Shutters:

Facade (cont'd)

- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):** full-width

b. Side: Direction: east

- 1) **Bays:** 3
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 4/1
 - Trim:** wood
 - Shutters:** other: metal awnings
- 3) **Door(s):** 1
 - Location:** corner
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):** other: see porch details, concrete steps

c. Side: Direction: west

- 1) **Bays:** 3
- 2) **Windows:** 3
 - Fenestration:** regular
 - Type:** double hung, 4/1
 - Trim:** wood
 - Shutters:** other: metal awnings
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**


d. Rear: Direction: north

- 1) **Bays:** 2
- 2) **Windows:** 2, 1
 - Fenestration:** regular
 - Type:** double hung, 4/1, 3/1
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

- 10. **LANDSCAPING:** faces Seashore Hwy., paved driveway along east side of dwelling, trees and plantings to front and rear lawns

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11054.002

1. ADDRESS/LOCATION: 30 Seashore Highway

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1935 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. resided in asbestos, garage door replacements

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Asbestos

d. Foundation concrete block

e. Roof
structural system Gable Front
coverings Composition
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: east

1) bays: 2

2) windows:

3) door(s): Count: 2; Location: other: side by side ; Type: other: aluminum garage door

4) other:

- b. Side: direction: south
 - 1) bays: 2
 - 2) windows: Count: 1; regular ; hopper
 - 3) door(s): Count: 1; Location: corner ; Type: wood
 - 4) other:

- c. Side: direction: north
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: west
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

T-Plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-11054

1. ADDRESS/LOCATION: 30 Seashore Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11054

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11055
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

- HISTORIC NAME/FUNCTION: Sussex County Habitat for Humanity/Bridge Counseling Center
- ADDRESS/LOCATION: 32 Seashore Highway
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE: building structure site object
landscape district
- MAIN FUNCTION OF PROPERTY: dwelling
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11055.001

1. ADDRESS/LOCATION: 32 Seashore Highway
2. FUNCTION(S): historic current government, other: community
3. YEAR BUILT: 1935 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman, Vernacular, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. resided in vinyl, replaced windows and doors, front porch enclosure, modern 1-story gabled addition attached to rear, approximately 4-rooms in size, inset porch between main block and addition
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Gable Front
materials: Asphalt
cornice: other: enclosed
dormers:
chimney: location(s): exterior, gable, brick

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: south
- 1) Bays:
- 2) Windows: 1
Fenestration: regular
Type: double hung, other: sliding/obscured by porch enclosure, 1/1
Trim: vinyl
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 Location: center
 Type: metal
 Trim: plain
- 4) **Porch(es):** full-width

b. Side: Direction: east

- 1) **Bays:** 4
- 2) **Windows:** 4
 Fenestration: regular
 Type: double hung, 4/1
 Trim: wood
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

c. Side: Direction: west

- 1) **Bays:** 3
- 2) **Windows:** 2
 Fenestration: regular
 Type: double hung, 4/1
 Trim: wood
 Shutters:
- 3) **Door(s):** 1
 Location: corner
 Type: other: fiberglass
 Trim: plain
- 4) **Porch(es):**

d. Rear: Direction: north


- 1) **Bays:**
- 2) **Windows:** 0, 1
 Fenestration: regular
 Type: double hung, other: obscured by addition, 1/1
 Trim: vinyl
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

9. INTERIOR:

- 10. **LANDSCAPING:** faces Seashore Hwy., paved driveway to east side of building, parking to front and rear, commercial car lot to west side of property

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**


CRS # S-11055

1. ADDRESS/LOCATION: 32 Seashore Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11055

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11057
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

- HISTORIC NAME/FUNCTION: dwelling
- ADDRESS/LOCATION: 210 Ennis Street
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
- MAIN FUNCTION OF PROPERTY: domestic
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:

Organization: John Milner Associates Inc. Date: 09/2005

9. OTHER NOTES OR OBSERVATIONS:


CRS# S-11057

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11057.001

1. ADDRESS/LOCATION: 210 Ennis Street
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, WWII-Era Cottage, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Gable Front
materials: Asphalt
cornice:
dormers:
chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: south
- 1) Bays: 4
- 2) Windows: 3, 1
Fenestration: regular
Type: double hung, 1/1
Trim: wood
Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood
 - Trim:** plain
- 4) **Porch(es):** other: see porch details

b. Side: Direction: west

- 1) **Bays:** 2
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, other: obscured by rear addition, 1/1
 - Trim:** wood
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: east

- 1) **Bays:** 1
- 2) **Windows:** 1
 - Fenestration:** regular
 - Type:** double hung, other: obscured by enclosed sun-porch, 1/1
 - Trim:** wood
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**other: see porch details, enclosed sun-porch, aluminum trim fixed windows, 1-room in size


d. Rear: Direction: north

- 1) **Bays:** 3
- 2) **Windows:** 3, 1
 - Fenestration:** regular
 - Type:** double hung, 2/2
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: faces Ennis St., tall trees to front and side lawns, shrubs planted along front façade

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11057.002

1. ADDRESS/LOCATION: 210 Ennis Street

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. rear extension, 1-room in size

b. _____

6. CURRENT CONDITION: excellent good _____ fair _____ poor _____

7. DESCRIPTION:

a. Structural system concrete block

b. Number of stories 1

c. Wall coverings

d. Foundation concrete block

e. Roof
structural system Gable Front
coverings Asphalt
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: south

1) bays: 2

2) windows:

3) door(s): Count: 2; Location: other: side by side ; Type: wood & glass, other: garage

4) other:

- b. **Side: direction:** east
 - 1) **bays:** 1
 - 2) **windows:** Count: 1; regular ; double hung, other: sliding, 1/1
 - 3) **door(s):**
 - 4) **other:**

- c. **Side: direction:** west
 - 1) **bays:** 1
 - 2) **windows:** Count: 1; regular ; double hung, other: sliding, 1/1
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** north, no access
 - 1) **bays:**
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11057

1. ADDRESS/LOCATION: 210 Ennis Street


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11057

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11058
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

- HISTORIC NAME/FUNCTION: dwelling
- ADDRESS/LOCATION: Ennis Street
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
- MAIN FUNCTION OF PROPERTY: dwelling
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11058.001

1. ADDRESS/LOCATION: Ennis Street
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, WWII-Era Cottage, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided in vinyl, replacement windows and doors, sun-porch enclosure on east end

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Side Gable
materials: Asphalt
cornice:
dormers:
chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: south
- 1) Bays: 3
- 2) Windows: 2
Fenestration: regular
Type: double hung, 6/6
Trim: vinyl
Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):** vestibule (enclosed entrance)

b. Side: Direction: west

- 1) **Bays:** 2
- 2) **Windows:** 2, 1
 - Fenestration:** regular
 - Type:** double hung, 6/6
 - Trim:** vinyl
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: east

- 1) **Bays:**
- 2) **Windows:** 0, 1
 - Fenestration:** regular
 - Type:** double hung, other: obscured by sun-porch enclosure, 6/6
 - Trim:** vinyl
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):** 1
 - Location:**
 - Type:** wood
 - Trim:** plain
- 4) **Porch(es):** other: see porch details, enclosed sun-porch, brick siding, jalousie windows

d. Rear: Direction: north


- 1) **Bays:** 4
- 2) **Windows:** 3
 - Fenestration:** regular
 - Type:** double hung, other: jalousie, 6/6
 - Trim:** aluminum, vinyl
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** side
 - Type:** other: fiberglass
 - Trim:** plain
- 4) **Porch(es):** other: see porch details, 1-story, shed-roof screen porch

9. INTERIOR:

10. **LANDSCAPING:** faces Ennis St., paved driveway to east side, shrubs planted across front facade

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**


CRS # S-11058

1. ADDRESS/LOCATION: Ennis Street
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11216
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 508 East Market Street
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Doug McVarish

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:


Organization: John Milner Associates Inc. Date: 08/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11216.001

1. ADDRESS/LOCATION: 508 East Market Street
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Colonial Revival, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. aluminum siding, gabled 1-story addition

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 2
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: brick
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Side Gable
materials:
cornice:
dormers: 2 shed dormers 8x8
chimney: location(s): interior, gable, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: southeast
- 1) Bays: 5
- 2) Windows: 4, 2
Fenestration: regular
Type: double hung, 8/8
Trim: aluminum
Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** other: fiberglass
 - Trim:** sidelights
- 4) **Porch(es):** full-width

b. Side: Direction: northeast

- 1) **Bays:** 2
- 2) **Windows:** 2, 2
 - Fenestration:** regular
 - Type:** double hung, 8/8
 - Trim:** aluminum
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: southwest

- 1) **Bays:**
- 2) **Windows:** 1, 2
 - Fenestration:** regular
 - Type:** double hung, 6/6, 8/8
 - Trim:** aluminum
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**


d. Rear: Direction: northwest

- 1) **Bays:**
- 2) **Windows:** 4, 3
 - Fenestration:** regular
 - Type:** double hung, 8/8, 6/6
 - Trim:** aluminum
 - Shutters:** vinyl,non-functional
- 3) **Door(s):** 1
 - Location:** center
 - Type:** other: fiberglass
 - Trim:**
- 4) **Porch(es):**other: see porch details, wood frames rear door

9. INTERIOR:

10. LANDSCAPING: mature trees in front yard, side driveway, front garden with concrete benches

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11216.002

1. ADDRESS/LOCATION: 508 East Market Street

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good _____ fair _____ poor _____

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1
- c. Wall coverings Wood Siding Horizontal
- d. Foundation poured concrete
- e. Roof structural system Side Gable
coverings Composition
openings _____

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: southeast
 - 1) bays: 2
 - 2) windows: _____
 - 3) door(s): Count: 2; Location: other: side by side ; Type: wood, other: sliding
 - 4) other: _____

b. Side: direction: southwest

1) bays: 2

2) windows: Count: 1; regular ; double hung, 6/1

3) door(s): Count: 1; Location: side ; Type: wood & glass

4) other:

c. Side: direction: northeast

1) bays:

2) windows:

3) door(s):

4) other:

d. Rear: direction: northwest

1) bays:

2) windows:

3) door(s):

4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11216

1. ADDRESS/LOCATION: 508 East Market Street


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11216

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11217
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: Bedford Associates
2. ADDRESS/LOCATION: 510 East Market Street
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic domestic complex
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Doug McVarish

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:


Organization: John Milner Associates Inc. Date: 08/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11217.001

1. ADDRESS/LOCATION: 510 East Market Street
2. FUNCTION(S): historic domestic complex current domestic
3. YEAR BUILT: 1920 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman, side hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Wood Siding Horizontal
- e. Roof: shape: Gable Front
materials: Asphalt
cornice: exposed rafter ends
dormers:
chimney: location(s): exterior, gable; center, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: southwest
- 1) Bays: 5
- 2) Windows: 4, 2
Fenestration: irregular
Type: casement, other: transom, 6 light casement
Trim: wood
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 Location: side
 Type: wood
 Trim: sidelights
- 4) **Porch(es):** entry

b. Side: Direction: northeast

- 1) **Bays:** 3
- 2) **Windows:** 5, 1
 Fenestration: irregular
 Type: double hung, 9 and 3 light fixed, 9/1
 Trim: wood
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

c. Side: Direction: southwest

- 1) **Bays:**
- 2) **Windows:** 7
 Fenestration: irregular
 Type: double hung, 1/1, 9/1
 Trim: wood
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**


d. Rear: Direction: northwest

- 1) **Bays:** 3
- 2) **Windows:** 2
 Fenestration: irregular
 Type: double hung, 9/1
 Trim: wood
 Shutters:
- 3) **Door(s):** 2
 Location: center
 Type: wood
 Trim: plain
- 4) **Porch(es):** stoop, gable roof, modern wood frame stoop, 1/1 side windows

9. INTERIOR:

10. LANDSCAPING: side driveway on east side of property, evergreen tree in front, plantings on foundation

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11217.002

1. ADDRESS/LOCATION: 510 East Market Street

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1920 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular, one pen

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____

a. replacement 2 leaf doors

b. _____

6. CURRENT CONDITION: excellent _____ good X fair _____ poor _____

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Wood Siding Vertical

d. Foundation poured concrete

e. Roof structural system Center Gable
coverings Asphalt
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southeast

1) bays: 1

2) windows:

3) door(s): Count: 2; Location: center ; Type: wood
Details: vertical board

4) other:

- b. **Side: direction:** southwest
 - 1) **bays:** 3
 - 2) **windows:** Count: 2; regular ; fixed, 4 light fixed
 - 3) **door(s):** Count: 1; Location: side ; Type: wood
Details: vertical board
 - 4) **other:**

- c. **Side: direction:** northeast
 - 1) **bays:**
 - 2) **windows:** Count: 2; regular ; fixed, 4 light fixed
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** northwest
 - 1) **bays:** 1
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle ; one pen

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11217.003

1. ADDRESS/LOCATION: 510 East Market Street

2. FUNCTION(S): historic chicken house current _____

3. YEAR BUILT: 1920 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Wood Siding Vertical

d. Foundation other: concrete block piers

e. Roof
structural system Shed
coverings Other: metal
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southeast

1) bays: 5

2) windows: Count: 4; regular ; double hung, fixed, 6/6, 4 pane fixed

3) door(s): Count: 1; Location: side ; Type: wood

4) other:

- b. Side: direction: southwest
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: northeast
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: northwest, no access
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11217

1. ADDRESS/LOCATION: 510 East Market Street


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11217

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11218
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: Blakely's Garage
2. ADDRESS/LOCATION: 509 West Market Street
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: independent garage
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Doug McVarish

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 08/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11218


red flag, gas station

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | X | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11218.001

1. ADDRESS/LOCATION: 509 West Market Street
2. FUNCTION(S): historic automobile related current commerce/trade
3. YEAR BUILT: 1920 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman, one pen
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. concrete block addition to rear - 2 bays, overhead doors, rear wall, (4) 18-light metal-framed windows, gabled front, rusticated concrete block garage, center rear roll down door, boarded over doors, front center wood entry door placed in boarded over gar
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: complex Stories: 1
Additions:
- b. Structural system (if known): wood-frame, concrete block
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Wood Siding Vertical
- e. Roof: shape: Gable Front
materials: Asphalt
cornice:
dormers:
chimney: location(s): interior, gable, other: stucco

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: northwest
- 1) Bays: 3
- 2) Windows: 2, 2
Fenestration: regular
Type: double hung, 1/1
Trim: wood
Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** commercial glass
 - Trim:** plain
- 4) **Porch(es):** porte-cochere

b. Side: Direction: southwest

- 1) **Bays:** 4
- 2) **Windows:** 4
 - Fenestration:** regular
 - Type:** double hung, other: obscured by rear addition, 1/1
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: northeast

- 1) **Bays:** 4
- 2) **Windows:** 4
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

d. Rear: Direction: southeast


- 1) **Bays:**
- 2) **Windows:**
 - Fenestration:**
 - Type:** other: obscured, not visible
 - Trim:**
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: front parking area, side-driveway, rear gravel parking area

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # S-11218

1. ADDRESS/LOCATION: 509 West Market Street


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11220
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

- 1. HISTORIC NAME/FUNCTION: dwelling
- 2. ADDRESS/LOCATION: 116 West North Street
- 3. TOWN/NEAREST TOWN: Georgetown vicinity?
- 4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
- 5. MAIN FUNCTION OF PROPERTY: domestic
- 6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:


Organization: John Milner Associates Inc. Date: 08/2008

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11220.001

1. ADDRESS/LOCATION: 116 West North Street
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1935 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman, Vernacular, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided in aluminum, replacement doors and windows

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Gable Front
materials: Composition
cornice: exposed rafter ends
dormers:
chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: south
- 1) Bays: 3
- 2) Windows: 2
Fenestration: regular
Type: double hung, 1/1
Trim: wood
Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 Location: center
 Type: wood
 Trim:
- 4) **Porch(es):** full-width

b. Side: Direction: east

- 1) **Bays:** 3
- 2) **Windows:** 3
 Fenestration: regular
 Type: double hung, 1/1
 Trim: wood
 Shutters: (vinyl,non-functional)
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

c. Side: Direction: west

- 1) **Bays:** 3
- 2) **Windows:** 3
 Fenestration: regular
 Type: double hung, 1/1
 Trim: wood
 Shutters: (vinyl,non-functional)
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**


d. Rear: Direction: north

- 1) **Bays:**
- 2) **Windows:** 1, 1
 Fenestration: regular
 Type: double hung, other: obscured by porch enclosure, 1/1
 Trim: wood
 Shutters:
- 3) **Door(s):** 1
 Location:
 Type:
 Trim:
- 4) **Porch(es):** other: see porch details, shed-roof porch enclosure on rear; 1-room; aluminum siding

9. INTERIOR:

10. LANDSCAPING: east side of Rt. 113, faces roadway, commercial and residential development mixed area

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11220.002

1. ADDRESS/LOCATION: 116 West North Street

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1935 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____

a. replacement doors on front; plywood

b. _____

6. CURRENT CONDITION: excellent _____ good X fair _____ poor _____

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Wood Siding Horizontal

d. Foundation rusticated concrete block

e. Roof
structural system Gable Front
coverings Other: metal
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: east

1) bays: 1

2) windows:

3) door(s): Count: 1; Location: center ; Type: wood

4) other:

- b. Side: direction: south
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: north
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: west
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11220

1. ADDRESS/LOCATION: 116 West North Street


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-11220

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9