

DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11283
SPO Map 14-15-11
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 19855 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Doug McVarish

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 10/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11283

prefab corrugated metal light manufacturing building across drive to south (1990s), second prefab building


10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
1630-1730- Exploration and Frontier Settlement
1730-1770- Intensified and Durable Occupation
1770-1830- Early Industrialization
1830-1880- Industrialization and Early Urbanization
1880-1940- Urbanization and Early Suburbanization
X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11283.001

1. ADDRESS/LOCATION: 19855 Dupont Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1950 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Ranch, central hall
5. INTEGRITY: original site moved X
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. moved to this location

b.

6. CURRENT CONDITION: excellent good X fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
 Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block, other: wood
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Wood Siding Vertical
- e. Roof: shape: Shed
 materials: Other: not visible
 cornice: boxed
 dormers: shed (cathedral ceiling)- large 1-light window
 chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: southeast
- 1) Bays: 7
- 2) Windows: 7
 Fenestration: irregular
 Type: fixed, hopper, 1 light fixed over hopper, 6/6
 Trim: wood
 Shutters: vinyl,functional

Facade (cont'd)

- 3) **Door(s):** 2
 - Location:** center
 - Type:** wood
 - Trim:** plain
- 4) **Porch(es):** stoop, inset, other

b. Side: Direction: southwest

- 1) **Bays:** 5
- 2) **Windows:** 5
 - Fenestration:** irregular
 - Type:** double hung, fixed, hopper, 1/1, 1 light fixed, 1 row of hopper windows
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: northeast

- 1) **Bays:** 4
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 6/6
 - Trim:** aluminum
 - Shutters:** (vinyl, non-functional)
- 3) **Door(s):** 2
 - Location:** center
 - Type:** other
 - Trim:** plain
- 4) **Porch(es):**

d. Rear: Direction: northwest


- 1) **Bays:** 2
- 2) **Windows:** 1
 - Fenestration:** irregular
 - Type:** awning, hopper, 8 light, 1 hopper
 - Trim:** steel
 - Shutters:**
- 3) **Door(s):** 2
 - Location:** side
 - Type:** metal, other
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: driveway/parking area to south, shrubs and trees to south and west, split rail fence in front

11. OTHER COMMENTS:

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11283

1. ADDRESS/LOCATION: 19855 Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11469
SPO Map 12-13-11
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: 18381 Deer Forest Road
3. TOWN/NEAREST TOWN: between Ellendale and Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Scott M. Pickens

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 12/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11469.001

1.	ADDRESS/LOCATION:	18381 Deer Forest Road
----	-------------------	------------------------

2.	FUNCTION(S):	historic: domestic	current: domestic
----	--------------	--------------------	-------------------

3.	YEAR BUILT:	1940	CIRCA?:	X	ARCHITECT/BUILDER:	
----	-------------	------	---------	---	--------------------	--

4.	STYLE OR FLOOR PLAN:	Colonial Revival
----	----------------------	------------------

5.	INTEGRITY:	original site	X	moved	
----	------------	---------------	---	-------	--

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. front vestibule added

b.

6.	CURRENT CONDITION:	excellent		good	X	fair		poor	
----	--------------------	-----------	--	------	---	------	--	------	--

7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
----	--

a. Overall shape: square Stories: 1
Additions:

b. Structural system (if known): wood-framed

c. Foundation: materials: panel-faced concrete block
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): vinyl siding

e. Roof: shape: side gable
materials: asphalt shingles
cornice: boxed
dormers:
chimney: brick, center

8.	DESCRIPTION OF ELEVATIONS:
----	----------------------------


a.	Facade: Direction: southeast
1)	Bays: 3
2)	Windows: 4
	Fenestration: regular
	Type: 1/1 double-hung sash
	Trim: wood, aluminum
	Shutters: vinyl, non-functional

	Facade (cont'd)
3)	Door(s): 1 Location: center Type: wood-and-glass (1 large light) Trim:
4)	Porch(es): vestibule at center of façade
b.	Side: Direction: northeast
1)	Bays: 3
2)	Windows: 2 Fenestration: regular Type: 1/1 double-hung sash Trim: wood, aluminum Shutters: vinyl, non-functional; aluminum awnings
3)	Door(s): 1 Location: northeast end Type: wood (4 panels) Trim:
4)	Porch(es): wood deck
c.	Side: Direction: southwest
1)	Bays: 2
2)	Windows: 2 Fenestration: regular Type: double-hung sash Trim: wood, aluminum Shutters: aluminum awnings
3)	Door(s): Location: Type: Trim:
4)	Porch(es):
d.	Rear: Direction: northwest
1)	Bays: 2
2)	Windows: 2 Fenestration: regular Type: 1/1 double-hung sash Trim: wood, aluminum Shutters: aluminum awnings
3)	Door(s): Location: Type: Trim:
4)	Porch(es):

9.	INTERIOR:
----	-----------

10.	LANDSCAPING:
-----	--------------

11.	OTHER COMMENTS:
-----	-----------------



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11469

1. ADDRESS/LOCATION: 18381 Deer Forest Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11471
SPO Map 12-13-11
Hundred Georgetown
Quad Georgetown
Other _____

- HISTORIC NAME/FUNCTION: Commercial Building
- ADDRESS/LOCATION: Route 113
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
- MAIN FUNCTION OF PROPERTY: commercial
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Scott Pickens

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:

Organization: John Milner Associates Inc. Date: 12/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11471

Redden Furniture; house with concrete block structure added, houses, trailers, and appliances in rear


10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
1630-1730- Exploration and Frontier Settlement
1730-1770- Intensified and Durable Occupation
1770-1830- Early Industrialization
1830-1880- Industrialization and Early Urbanization
1880-1940- Urbanization and Early Suburbanization
X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|--|
| <ul style="list-style-type: none">AgricultureForestryTrapping/HuntingMining/QuarryingFishing/OysteringManufacturingX Retailing/WholesalingFinanceProfessional Services | <ul style="list-style-type: none">Transportation and CommunicationSettlement Patterns and Demographic ChangesArchitecture, Engineering and Decorative ArtsGovernmentReligionEducationCommunity OrganizationsOccupational OrganizationsMajor Families, Individuals and Events |
|--|--|



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11471.001

1. ADDRESS/LOCATION: Route 113
2. FUNCTION(S): historic commercial current commerce/trade
3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN:
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. large concrete building addition to house

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: L-Plan Stories: 1
 Additions:
- b. Structural system (if known): wood-frame, concrete block
- c. Foundation: materials: concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Other: exposed concrete block
- e. Roof: shape: Hipped
 materials: Asphalt
 cornice: boxed
 dormers:
 chimney: location(s): center; other: exterior/northwest side/center of original house, concrete block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: southwest
- 1) Bays: 4
- 2) Windows: 3
 Fenestration: regular
 Type: awning, fixed, 9 light awning
 Trim: wood, steel
 Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
Location: center
Type: commercial glass
Trim: plain
- 4) **Porch(es):**

b. Side: Direction: southeast

- 1) **Bays:** 4
- 2) **Windows:** 3
Fenestration: regular
Type: fixed
Trim: steel
Shutters:
- 3) **Door(s):** 1
Location:
Type: commercial glass
Trim: plain
- 4) **Porch(es):**

c. Side: Direction: northwest

- 1) **Bays:** 6
- 2) **Windows:** 6
Fenestration: irregular
Type: double hung, awning, fixed, 2/2, 4/1, 6 pane awning
Trim: wood, steel
Shutters:
- 3) **Door(s):**
Location: corner
Type: wood
Trim: plain
- 4) **Porch(es):**


d. Rear: Direction: northeast

- 1) **Bays:** 6
- 2) **Windows:** 3
Fenestration: regular
Type: double hung, 4/1
Trim: wood
Shutters:
- 3) **Door(s):** 4
Location: center, side, corner
Type: wood, wood & glass
Trim: plain, other
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: many old appliances in rear

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11471.002

1. ADDRESS/LOCATION: Route 113

2. FUNCTION(S): historic unknown current

3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular

5. INTEGRITY: original site X moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor X

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Asphalt, Asbestos

d. Foundation

e. Roof

structural system Shed, Other: jerkinhead

coverings Asphalt

openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: northwest

1) bays: 3

2) windows: Count: 2; irregular ; double hung, 1/1

3) door(s): Count: 1; Location: center ; Type: wood & glass
Details: 2 lights over 4 panels

4) other:

b. Side: direction: northwest

1) bays: 3

2) windows: Count: 3; regular ; double hung, hopper, 1/1

3) door(s):

4) other:

c. Side: direction: southeast

1) bays: 2

2) windows: Count: 2; irregular ; fixed, other: sliding glass

3) door(s):

4) other:

d. Rear: direction: southwest

1) bays: 3

2) windows: Count: 3; regular ; double hung, 1/1

3) door(s):

4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11471.003

1. ADDRESS/LOCATION: Route 113

2. FUNCTION(S): historic unknown current _____

3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular, one pen

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor X

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Asbestos

d. Foundation concrete block

e. Roof
structural system Hipped
coverings Asphalt
openings _____

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southwest
1) bays: 1
2) windows: _____
3) door(s): Count: 1; Location: center ; Type: wood
Details: solid 4 panels
4) other: _____

- b. **Side: direction:** northwest
 - 1) **bays:** 1
 - 2) **windows:** Count: 1; regular ; fixed
 - 3) **door(s):**
 - 4) **other:**

- c. **Side: direction:** southeast
 - 1) **bays:** 1
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** northwest
 - 1) **bays:** 1
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

square ; one pen

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11471.004

1. ADDRESS/LOCATION: Route 113

2. FUNCTION(S): historic unknown current

3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Asbestos

d. Foundation concrete block

e. Roof

structural system Side Gable

coverings Asphalt

openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southeast

1) bays:

2) windows: ; irregular ; double hung, fixed, 1/1, 6 light

3) door(s): Count: 2; Location: corner ; Type: metal, other: missing
Details: metal storm door

4) other:

- b. **Side: direction:** southwest
 - 1) **bays:** 3
 - 2) **windows:** Count: 3; irregular ; double hung, fixed, 2/2,4 light, 1 light
 - 3) **door(s):**
 - 4) **other:**

- c. **Side: direction:** northeast
 - 1) **bays:** 2
 - 2) **windows:** Count: 2; regular ; fixed, 12 light, 6 light
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** northwest
 - 1) **bays:** 4
 - 2) **windows:** Count: 4; regular ; double hung, fixed, 1/1, 6 light
 - 3) **door(s):** Count: 1
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11471.005

1. ADDRESS/LOCATION: Route 113

2. FUNCTION(S): historic unknown current

3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular, one pen

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Asbestos

d. Foundation concrete block

e. Roof

structural system Hipped

coverings Asphalt

openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southeast

1) bays: 1

2) windows:

3) door(s): Count: 1; Location: center ; Type: wood
Details: solid 5 panel

4) other:

b. Side: direction: northeast

1) bays: 1

2) windows:

3) door(s):

4) other:

c. Side: direction: southwest

1) bays: 1

2) windows: Count: 1; regular ; fixed

3) door(s):

4) other:

d. Rear: direction: northwest

1) bays: 1

2) windows:

3) door(s):

4) other:

9. INTERIOR (if accessible):


a) Floor plan

square ; one pen

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11471.006

1. ADDRESS/LOCATION: Route 113

2. FUNCTION(S): historic unknown current _____

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings

d. Foundation

e. Roof
structural system
coverings
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southeast

1) bays: 3

2) windows: Count: 3; regular ; double hung, 1/1

3) door(s): Count: 1; Location: center ; Type: wood & glass
Details: 4 lighth over 4 panel

4) other:

- b. **Side: direction:** northeast
 - 1) **bays:** 4
 - 2) **windows:** Count: 2; irregular ; double hung, 1/1
 - 3) **door(s):** Count: 2; Location: side, corner ; Type: wood, other: missing
Details: solid wood door, missing garage door
 - 4) **other:**

- c. **Side: direction:** southwest
 - 1) **bays:** 4
 - 2) **windows:** Count: 4; irregular ; double hung, 1/1
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** northwest
 - 1) **bays:** 2
 - 2) **windows:** Count: 1; irregular ; other: missing
 - 3) **door(s):** Count: 1; Location: corner ; Type: wood & glass
Details: 4 lights over 4 panels
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11471

1. ADDRESS/LOCATION: Route 113


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11472
SPO Map 12-13-11
Hundred Georgetown
Quad Georgetown
Other _____

- HISTORIC NAME/FUNCTION: Store
- ADDRESS/LOCATION: 18283 Dupont Boulevard
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE: building structure site object
landscape district
- MAIN FUNCTION OF PROPERTY: commercial building
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Sarah Traum
Principal Investigator name: Grace H. Ziesing
Principal Investigator signature:
Organization: John Milner Associates Inc. Date: 08/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11472


Currently the Redden Package Store

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|--|
| <ul style="list-style-type: none"> Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing X Retailing/Wholesaling Finance Professional Services | <ul style="list-style-type: none"> Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and Events |
|--|--|



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11472.001

1. ADDRESS/LOCATION: 18283 Dupont Boulevard
2. FUNCTION(S): historic commercial current commerce/trade
3. YEAR BUILT: 1950 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, other: open/store
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: square Stories: 1
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials:
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Wood Shingle, Vinyl Siding, Asbestos
- e. Roof: shape: Gable Front
materials: Other: metal/corrugated
cornice: boxed
dormers:
chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 3
- 2) Windows: 2
Fenestration: regular
Type: fixed
Trim: wood
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** commercial glass
 - Trim:** plain
- 4) **Porch(es):** vestibule (enclosed entrance)

b. Side: Direction: south

- 1) **Bays:** 2
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** awning
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: north

- 1) **Bays:** none
- 2) **Windows:**
 - Fenestration:**
 - Type:**
 - Trim:**
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

d. Rear: Direction: east


- 1) **Bays:** [obscured by 1-story shed-roof addition and attached trailer]
- 2) **Windows:**
 - Fenestration:**
 - Type:**
 - Trim:**
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

10. **LANDSCAPING:** faces west towards Dupont Blvd., asphalt drive leads to parking area in front of store

11. OTHER COMMENTS:

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11472

1. ADDRESS/LOCATION: 18283 Dupont Boulevard


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11472

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11473
SPO Map 12-13-11
Hundred Georgetown
Quad Georgetown
Other _____

- HISTORIC NAME/FUNCTION: Former Dwelling
- ADDRESS/LOCATION: 18245 Dupont Boulevard
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE: building structure site object
landscape district
- MAIN FUNCTION OF PROPERTY: dwelling
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Sarah Traum
Principal Investigator name: Grace H. Ziesing
Principal Investigator signature:
Organization: John Milner Associates Inc. Date: 08/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11473

Currently a commercial building (K&L Sales, Inc.)


10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
1630-1730- Exploration and Frontier Settlement
1730-1770- Intensified and Durable Occupation
1770-1830- Early Industrialization
1830-1880- Industrialization and Early Urbanization
1880-1940- Urbanization and Early Suburbanization
X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11473.001

1. ADDRESS/LOCATION: 18245 Dupont Boulevard
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1957 CIRCA?: N ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Ranch, other: ranch
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided, some windows replaced, single story shed-roof addition across east elevation

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
 Additions: single story shed-roof addition across east elevation
- b. Structural system (if known): wood-frame
- c. Foundation: materials: other: brick veneer
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Wood Shingle, Aluminum Siding, Vinyl Siding
- e. Roof: shape: Side Gable
 materials: Asphalt
 cornice: boxed
 dormers:
 chimney: location(s): exterior, gable, concrete block

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: west
- 1) Bays: 9
- 2) Windows: 8
 Fenestration: irregular
 Type: double hung, awning, 8/8, 1/1
 Trim: aluminum
 Shutters: vinyl, non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** side
 - Type:** metal
 - Trim:** plain
- 4) **Porch(es):** stoop

b. Side: Direction: south

- 1) **Bays:** 3
- 2) **Windows:** 3
 - Fenestration:** regular
 - Type:** awning
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: north

- 1) **Bays:** 2
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 1/1, 6/6
 - Trim:** aluminum
 - Shutters:** (vinyl, non-functional)
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

d. Rear: Direction: east


- 1) **Bays:** [obscured by multiple shed-roof additions to east elevation]
- 2) **Windows:**
 - Fenestration:**
 - Type:**
 - Trim:**
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

- 10. **LANDSCAPING:** faces west towards Rt. 113 with gravel parking area in front of driveways to north and south of house, commercial establishment surrounds property

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**


CRS # S-11473

1. ADDRESS/LOCATION: 18245 Dupont Boulevard
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11473

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11483
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: Bramhall Road
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2006

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11483.001

1. ADDRESS/LOCATION: Bramhall Road
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1957 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided in vinyl, replacement windows throughout, fenestration altered, replacement doors

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Cross Gable
materials: Asphalt
cornice:
dormers:
chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: south
- 1) Bays: 3
- 2) Windows: 3
Fenestration: irregular
Type: double hung, fixed, other: , 1/1
Trim: vinyl
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 Location: center, corner
 Type: other
 Trim: plain
- 4) **Porch(es):**

b. Side: Direction: east

- 1) **Bays:** 4
- 2) **Windows:** 4
 Fenestration: irregular
 Type: casement, 1/1
 Trim: vinyl
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

c. Side: Direction: west

- 1) **Bays:** 8
- 2) **Windows:** 8
 Fenestration: irregular
 Type: double hung, casement, 1/1
 Trim: vinyl
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

d. Rear: Direction: north


- 1) **Bays:** 4
- 2) **Windows:** 1
 Fenestration: irregular
 Type: double hung, 1/1
 Trim: vinyl
 Shutters:
- 3) **Door(s):** 2
 Location: other: irregular
 Type: other: fiberglass
 Trim: sidelights
- 4) **Porch(es):** other, metal awnings

9. INTERIOR:

10. LANDSCAPING: faces roadway, paved driveway to east side, shrubs across front façade, tall trees to front and rear lawn

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**


CRS # S-11483

1. ADDRESS/LOCATION: Bramhall Road
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN

S-11483





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11484
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

- HISTORIC NAME/FUNCTION: dwelling
- ADDRESS/LOCATION: Dupont Highway Route 113
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE: building structure site object
landscape district
- MAIN FUNCTION OF PROPERTY: dwelling
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2006

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11484.001

1. ADDRESS/LOCATION: Dupont Highway Route 113
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1952 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, Cape Cod, central hall
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. sun porch on south end enclosed, gabled breezeway extends from rear of house with entrance attached to 3 car garage

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: L-Plan Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Cross Gable
materials: Composition
cornice:
dormers:
chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 3
- 2) Windows: 2
Fenestration: regular
Type: double hung, 3/1
Trim: wood
Shutters: other: metal awning

Facade (cont'd)

- 3) **Door(s):** 1
 Location: center
 Type: wood
 Trim: plain
- 4) **Porch(es):** portico

b. Side: Direction: north

- 1) **Bays:** 2
- 2) **Windows:** 2, 1
 Fenestration: regular
 Type: double hung, 3/1
 Trim: wood
 Shutters: other: metal awning
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

c. Side: Direction: south

- 1) **Bays:**
- 2) **Windows:** 2, 1
 Fenestration: regular
 Type: double hung, 3/1
 Trim: wood
 Shutters: other: metal awning
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):** other, gabled single-story sun porch, enclosed with wood pane siding and hopper windows

d. Rear: Direction: east


- 1) **Bays:**
- 2) **Windows:** 1
 Fenestration: regular
 Type: double hung, 1/1
 Trim: wood
 Shutters:
- 3) **Door(s):** 4
 Location:
 Type: other
 Trim: plain
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: faces Rt. 113, shrubs planted across front façade, trees to all sides, paved driveway to rear and east side

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**


CRS # S-11484

1. ADDRESS/LOCATION: Dupont Highway Route 113
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11486
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

- HISTORIC NAME/FUNCTION: dwelling
- ADDRESS/LOCATION: 25190/3 Governor Stockley Road
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
- MAIN FUNCTION OF PROPERTY: dwelling
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11486


similar to other houses in area, this house has oval formed concrete openings in foundation to provide ventilation

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11486.001

1. ADDRESS/LOCATION: 25190/3 Governor Stockley Road
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman, Ranch, other: irregular
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. asbestos siding, small prefabricated lattice and front porch.

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Asbestos
- e. Roof: shape: Complex Gable
materials: Asphalt
cornice: exposed rafter ends
dormers:
chimney: location(s): other: rear/bottom of roof slope, concrete block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: south
- 1) Bays: 4
- 2) Windows: 3
Fenestration: regular
Type: double hung, 1/1
Trim: wood
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 Location: side
 Type: wood, wood & glass
 Trim: plain
- 4) **Porch(es):** entry

b. Side: Direction: east

- 1) **Bays:** 2
- 2) **Windows:** 2
 Fenestration: irregular
 Type: double hung, 1/1
 Trim: wood
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

c. Side: Direction: west

- 1) **Bays:** 1
- 2) **Windows:**
 Fenestration: irregular
 Type:
 Trim:
 Shutters:
- 3) **Door(s):** 1
 Location: side
 Type: wood, wood & glass
 Trim: plain
- 4) **Porch(es):** stoop, 3 cinderblock steps

d. Rear: Direction: north


- 1) **Bays:** 3
- 2) **Windows:** 3
 Fenestration: regular
 Type: double hung, 1/1
 Trim: wood
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: set in lawn with one or two tall trees next to farm fields

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # S-11486

1. ADDRESS/LOCATION: 25190/3 Governor Stockley Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN

S-11486





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11728
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

- HISTORIC NAME/FUNCTION: commerce/trade
- ADDRESS/LOCATION: Dupont Highway
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE: building landscape structure district site object
- MAIN FUNCTION OF PROPERTY: commerce/trade
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:

Organization: John Milner Associates Inc. Date: 11/2006

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11728

garage where Melvin Joseph started his business; it was rented by Mr. Joseph in 1940, who lived with his family in the house that once stood next to the garage

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


1600-1750- Contact Period (Native American)
1630-1730- Exploration and Frontier Settlement
1730-1770- Intensified and Durable Occupation
1770-1830- Early Industrialization
1830-1880- Industrialization and Early Urbanization
1880-1940- Urbanization and Early Suburbanization
1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

Agriculture	Transportation and Communication
Forestry	Settlement Patterns and Demographic Changes
Trapping/Hunting	Architecture, Engineering and Decorative Arts
Mining/Quarrying	Government
Fishing/Oystering	Religion
Manufacturing	Education
Retailing/Wholesaling	Community Organizations
Finance	Occupational Organizations
Professional Services	Major Families, Individuals and Events



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11728

1. ADDRESS/LOCATION: Dupont Highway

2. FUNCTION(S): historic commerce/trade current _____

3. YEAR BUILT: _____ CIRCA?: _____ ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____

a. new roofing; new doors on façade

b. _____

6. CURRENT CONDITION: excellent _____ good x _____ fair _____ poor _____

7. DESCRIPTION:

a. Structural system concrete block

b. Number of stories 1

c. Wall coverings

d. Foundation rusticated concrete block

e. Roof
structural system gable front
coverings asphalt
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: west
1) bays: 1
2) windows: Count: none
3) door(s): Count: 1; Location: NW side ; Type: wood
Details: double doors
4) other:

- b. Side: direction: north
 - 1) bays: no
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: south
 - 1) bays: 1
 - 2) windows: Count: none
 - 3) door(s): Count: 1; Location: SW side ; Type: wood
 - 4) other:

- d. Rear: direction: east
 - 1) bays: no
 - 2) windows:
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11728

1. ADDRESS/LOCATION: Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11827
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: Arrow Safety Building
2. ADDRESS/LOCATION: corner U.S. 113 and Arrow Safety Road
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: manufacturing plant/warehouse
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Kate Farnham

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 05/2007

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11827

according to plant manager, built c. 1953 and always owned by Arrow Safety Device Company; company started in 1930 in New Jersey and manufactures automotive safety lighting; building recently sold


10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
1630-1730- Exploration and Frontier Settlement
1730-1770- Intensified and Durable Occupation
1770-1830- Early Industrialization
1830-1880- Industrialization and Early Urbanization
1880-1940- Urbanization and Early Suburbanization
X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|--|
| <ul style="list-style-type: none">AgricultureForestryTrapping/HuntingMining/QuarryingFishing/OysteringX ManufacturingRetailing/WholesalingFinanceProfessional Services | <ul style="list-style-type: none">Transportation and CommunicationSettlement Patterns and Demographic ChangesX Architecture, Engineering and Decorative ArtsGovernmentReligionEducationCommunity OrganizationsOccupational OrganizationsMajor Families, Individuals and Events |
|--|--|



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11827.001

1. ADDRESS/LOCATION: corner U.S. 113 and Arrow Safety Road
2. FUNCTION(S): historic current manufacturing plant/warehouse
3. YEAR BUILT: 1953 CIRCA?: N ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: commercial/industrial
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. newer corrugated-metal garage doors
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: complex Stories: 1
Additions:
- b. Structural system (if known): concrete block
- c. Foundation: materials: concrete block, poured concrete
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings):
- e. Roof: shape: flat
materials: composition
cornice:
dormers:
chimney: location(s): interior, gable; brick (square smokestack)

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 7
- 2) Windows: 7
- Fenestration: regular
Type: fixed multilight steel sash with hopper
Trim: steel
Shutters:

Facade (cont'd)

- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

b. Side: Direction: north

- 1) **Bays: 10**
- 2) **Windows: 6**
 - Fenestration:** irregular
 - Type:** fixed, multilight steel sash with hopper
 - Trim:** steel
 - Shutters:**
- 3) **Door(s): 4**
 - Location:** center, NE side
 - Type:** metal, wood & glass
 - Trim:** plain
- 4) **Porch(es):** portico; flat roofed extension of main roof above main entrance and loading dock, inset within end walls; has concrete slab floor and metal support columns

c. Side: Direction: south

- 1) **Bays: 9**
- 2) **Windows: 8**
 - Fenestration:**
 - Type:** fixed multilight steel sash with hopper
 - Trim:** steel
 - Shutters:**
- 3) **Door(s): 1**
 - Location:** center
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):** portico; flat-roofed entry porch with concrete slab floor, steel support columns


d. Rear: Direction: east

- 1) **Bays: 10**
- 2) **Windows: 9**
 - Fenestration:** irregular
 - Type:** casement and fixed multilight steel sash
 - Trim:** steel
 - Shutters:** wood awnings on a few windows
- 3) **Door(s): 1**
 - Location:** center
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):** portico; original flat-roofed entry porch with concrete slab floor and steel support columns

9. INTERIOR:

10. LANDSCAPING: set on a large, open, level lot with grassy lawn facing U.S. 113 and Arrow Safety Road; gravel driveway and parking area off Arrow Safety Road; fenced yard on east side of building with picnic tables nearby

11. OTHER COMMENTS:



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # S-11827

1. ADDRESS/LOCATION: corner U.S. 113 and Arrow Safety Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11828
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: south corner Stockley and Bethesda Roads
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Kate Farnham

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 05/2007

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11828

house moved to site since 2003 as evidenced on aerial photographs; outbuildings new

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


1600-1750- Contact Period (Native American)
1630-1730- Exploration and Frontier Settlement
1730-1770- Intensified and Durable Occupation
1770-1830- Early Industrialization
1830-1880- Industrialization and Early Urbanization
1880-1940- Urbanization and Early Suburbanization
1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11828.001

1. ADDRESS/LOCATION: south corner Stockley and Bethesda Roads
2. FUNCTION(S): historic current dwelling
3. YEAR BUILT: 1935-1940 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman; double pen
5. INTEGRITY: original site moved X
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. new foundation, siding, windows, and doors; front and rear porches fully enclosed

b.

6. CURRENT CONDITION: excellent good X fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1-
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): vinyl siding
- e. Roof: shape: gable front
materials: asphalt
cornice: boxed
dormers:
chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: northwest
- 1) Bays: (0
- 2) Windows: 1, second story
Fenestration: regular
Type: 6/6 (replacement), double hung
Trim: vinyl
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** vinyl clad with leaded glass light (in p
 - Trim:** plain
- 4) **Porch(es):** stoop, full width

b. Side: Direction: northeast

- 1) **Bays:** 2
- 2) **Windows:** 3, first story
 - Fenestration:** regular
 - Type:** 8/8 & 6/6, double hung
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: southwest

- 1) **Bays:** 3
- 2) **Windows:** 3, first story
 - Fenestration:** regular
 - Type:** 6/6, double hung
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

d. Rear: Direction: southeast


- 1) **Bays:** 1
- 2) **Windows:** 1, second story
 - Fenestration:** regular
 - Type:** 6/6, double hung
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):** vestibule (enclosed entrance), stoop; gabled, fully enclosed porch with prefabricated stoop

9. INTERIOR:

10. LANDSCAPING: open, grassy corner lot; rural setting with open grass fields nearby and a few other houses; modern prefabricated garage and shed; dog pen at rear; board fence on southwest side

11. OTHER COMMENTS:

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11828

1. ADDRESS/LOCATION: south corner Stockley and Bethesda Roads


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11912
SPO Map 12-13-11
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: South side of Redden Road
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Kate Farnham

Principal Investigator name: Grace Ziesing

Principal Investigator signature: 

Organization: John Milner Associates, Inc Date: 9/5/2008

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11912

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II


 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11912.001

1. ADDRESS/LOCATION: South side of Redden Road

2. FUNCTION(S): historic domestic current domestic

3. YEAR BUILT: 1940-1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: WWII-era cottage

5. INTEGRITY: original site moved

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. new windows, siding and shutters

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: complex Stories: 1.5
Additions: _____

b. Structural system (if known): wood-framed

c. Foundation: materials: concrete block (probably - veneer over it)
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): brick veneer


e. Roof: shape: side gable
materials: asphalt
cornice: boxed
dormers: _____
chimney: location(s): ext. gable, brick

8. DESCRIPTION OF ELEVATIONS:

a.	Facade: Direction: <u>N</u>	
	1)	Bays <u>3</u>
	2)	Windows <u>2 (pairs)</u>
		fenestration <u>regular</u>
		type <u>double hung, 6/6 vinyl and 4/4 wood</u>
		trim <u>vinyl, wood</u>
shutters <u>vinyl, non-functional</u>		

Facade (cont'd)		
3)	Door(s)	1
	location	center
	type	wood and glass, 1-light with iron scrollwork in pane
	trim	plain
4)	Porch(es)	shallow shed-roofed porch with concrete and brick foundation, slate floor, wrought iron columns and balustrade
b.	Side: Direction:	E
1)	Bays	4
	2)	Windows
2)	fenestration	regular
	type	double hung, 6/6 vinyl
	trim	vinyl
	shutters	vinyl, non-functional
3)	Door(s)	n/a
	location	
	type	
	trim	
4)	Porch(es)	n/a
c.	Side: Direction:	W
1)	Bays	5
2)	Windows	3
	fenestration	irregular
	type	double hung, 6/6 vinyl
	trim	vinyl
	shutters	vinyl, non-functional
3)	Door(s)	2
	location	center
	type	wood and glass; 6-light, 2 panel and half-wheel, 4 panel
	trim	plain
4)	Porch(es)	carport – porte-cochere at rear beyond patio – connects house to garage; concrete floor and original wrought iron support columns
d.	Rear: Direction:	S
1)	Bays	5
2)	Windows	4
	fenestration	irregular
	type	double hung, 6/6
	trim	vinyl
	shutters	
3)	Door(s)	1
	location	center
	type	wood and glass, 9-light, 2 panel
	trim	plain
4)	Porch(es)	concrete stoop

9.	INTERIOR:
10.	LANDSCAPING: open lot with a few small trees; agricultural fields on both sides and at rear; set back from road; wide paved driveway leads to double garage; paved sidewalk to front door; modern shed at rear SE corner of yard; fencing around sides and back
11.	OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11912.002

1. ADDRESS/LOCATION: South side of Redden Road

2. FUNCTION(S): historic Garage current garage

3. YEAR BUILT: 1940-1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Colonial revival

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. vinyl gable siding and eave cladding

b. modern garage bay doors

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-framed

b. Number of stories 1.5

c. Wall coverings vinyl siding, brick veneer

d. Foundation poured concrete

e. Roof
structural system gable front
coverings asphalt
openings ext. gable at rear, brick

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: N

1) bays: 2

2) windows: 1 (2nd story)

3) door(s): 2 garage bays, center, vinyl-clad overhead doors, 4-lights, 12 panels

4) other:

b. Side: direction: W

- 1) bays: 2
- 2) windows: 2, double hung, 6/6 wood - original, vinyl non-functional shutters
- 3) door(s): n/a
- 4) other:

c. Side: direction: E

- 1) bays: 1
- 2) windows: n/a
- 3) door(s): 1, wood and glass, 6-lights, 2 panels - original
- 4) other: porte-cochere hyphen connects garage to house, concrete slab floor, gabled roof, wrought iron corner posts

d. Rear: direction: S

- 1) bays: 2
- 2) windows: 2, double hung, 6/6 original
- 3) door(s): n/a
- 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11912

1. ADDRESS/LOCATION: South side of Redden Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN

