



**CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM**

CRS # S03533

1. **HISTORIC NAME/FUNCTION:** Johnson/ Rust Dwelling

2. **ADDRESS/LOCATION:** 18672 Harbeson Road

3. **CURRENT CONDITION:** excellent good fair poor demolished

4. **INTEGRITY:** heavily altered

5. **SETTING INTEGRITY:** maintained

6. **FORMS ADDED (give number of forms completed for each):**

#:	Form:	List property types:
1	CRS 2 Main Building Form	
1	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. **SURVEYOR INFORMATION:**

Surveyor name: Courtney L. Clark

Principal Investigator name: Courtney L. Clark

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. **Date:** September 2012

8. OTHER NOTES OR OBSERVATIONS:

CRS# S03533

Resurveyed for the US 9 and SR 5 Intersection Improvements project, Delaware Department of Transportation.

Rear of property (4+-acres) is registered as wildlife preserve

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750∇ Contact Period (Native American)
- 1630-1730∇ Exploration and Frontier Settlement
- 1730-1770∇ Intensified and Durable Occupation
- 1770-1830∇ Early Industrialization
- 1830-1880∇ Industrialization and Early Urbanization
- 1880-1940∇ Urbanization and Early Suburbanization
- 1940-1960∇ Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S3533.001

1. ADDRESS/LOCATION: 18672 Harbeson Road

2. FUNCTION(S): historic Dwelling current dwelling

3. YEAR BUILT: 1898 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: Vernacular, Folk Victorian

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year
a. roof replacement over ell (between main block and rear addition)
b. Shed-roof addition to north side; Gabled addition across rear w/ screen porch addition to south end 1985

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular Stories: 2.5
Additions: 1-story, shed-roof addition on north wall; covered in vinyl w/ multiple openings on each side; 2.5-story gabled addition across rear w/ shed-roof screened porch on south end; covered in vinyl; varying window types throughout
- b. Structural system (if known): frame
- c. Foundation: materials:
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): vinyl
- e. Roof: shape: gabled-front pierced by skylights
materials: asphalt
cornice: boxed
dormers:
chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:
a. Facade: Direction: East
1) Bays: 4
2) Windows: 1, entrance level; 2, second floor; 1, attic level
fenestration : irregular
Type: modern 3-D bay; 1/1, double-hung; 1/1, double-hung stained-glass peaked
Trim: vinyl; wood
Shutters: paneled, vinyl, non-functional

Facade (cont'd)

3) **Door(s): 0**
 location
 type
 trim

4) **Porch(es)**

b. Side: Direction: North (obscured by addition)

1) **Bays: 3**

2) **Windows: 2, second floor of main block; 1, entrance level of rear ell**
 fenestration : irregular
 Type: 1/1, double-hung; modern 3-d bay
 Trim: vinyl
 Shutters: paneled, vinyl, non-functional

3) **Door(s)**
 location
 type
 trim

4) **Porch(es)**

c. Side: Direction: South

1) **Bays: 7**

2) **Windows: 6**
 fenestration : irregular
 Type: 1/1, double-hung; casement
 Trim: vinyl
 Shutters: paneled, vinyl, non-functional

3) **Door(s): 1**
 Location: w/in rear ell
 Type: wood w/ large single pane
 Trim: wood

4) **Porch(es):**

d. Rear: Direction: West (obscured by rear addition)

1) **Bays**

2) **Windows**
 fenestration
 type
 trim
 shutters

3) **Door(s)**
 location
 type
 trim

4) **Porch(es)**

9. **INTERIOR:** renovated throughout; exposed remnants of brick chimney remain in kitchen (in rear ell)

10. **LANDSCAPING:** house faces east toward road; gravel driveway to south side of house; decorative landscaping on all sides of dwelling w/ mix of tall shade trees; fenced flower garden to rear of dwelling, centered w/ decorative outbuilding; 1-story garage to rear of garden

11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S03533.002

1. ADDRESS/LOCATION: 18672 Harbeson Road

2. FUNCTION(S): historic Railroad station privy current Garden structure

3. YEAR BUILT: 1868 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved

if moved, from where original location's CRS # year
Site of former Railroad station

list major alterations and additions with years (if known) year

a. open sidewalls

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system: frame

b. Number of stories: 1

c. Wall coverings: board-and-batten

d. Foundation

e. Roof: gabled w/ central ventilated cupola and pinnacles at each end
structural system
Coverings: asphalt
Openings:

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: wall removed/open

1) bays:

2) windows:

3) door(s):

4) other:

b. Side: direction: North

- 1) **bays:** 0
- 2) **windows:** 0

- 3) **door(s):** 0

- 4) **other:**

c. Side: direction: South

- 1) **bays:** 0
- 2) **windows:** 0

- 3) **door(s):** 0

- 4) **other:**

d. Rear: direction: wall removed/open

- 1) **bays:**
- 2) **windows:**

- 3) **door(s):**

- 4) **other:**

9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery **multiple seats (2-3)**



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # S03533

1. ADDRESS/LOCATION: 18672 Harbeson Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S03533

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE DIVISION OF HISTORICAL AND CULTURAL AFFAIRS
STATE HISTORIC PRESERVATION OFFICE
21 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S03533

Date July 2012 Surveyor/Photographer Courtney L. Clark



S03533: dwelling (.001) façade and north side, looking southwest.



S03533: dwelling (.001) façade, looking west.



S03533: dwelling (.001) south side, looking northwest.



S03533: dwelling (.001) north side, looking south.



S03533: dwelling (.001) rear and north side and rear lawn structure (.002), looking southeast.



S03533: rear lawn structure (.002), looking south.



DELAWARE DIVISION OF HISTORICAL AND CULTURAL AFFAIRS
STATE HISTORIC PRESERVATION OFFICE
21 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S03533

Date July 2012 Surveyor/Photographer Courtney L. Clark



S03533: modern garage with attached shed, looking east.