



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S03534

1. HISTORIC NAME/FUNCTION: Dwelling

2. ADDRESS/LOCATION: 18678 Harbeson Road

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: altered

5. SETTING INTEGRITY: maintained

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	
1	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney L. Clark

Principal Investigator name: Courtney L. Clark

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: September 2012

8. OTHER NOTES OR OBSERVATIONS:

CRS# S03534

Resurveyed for the US 9 and SR 5 Intersection Improvements project, Delaware Department of Transportation.

According to neighbor, house has been vacant for 18 months.

Last surveyed by K. Goddard, September 1983:

.001 – House

.002 – garage - - NOW DEMOLISHED

.003 – shed

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750∇ Contact Period (Native American)
- 1630-1730∇ Exploration and Frontier Settlement
- 1730-1770∇ Intensified and Durable Occupation
- 1770-1830∇ Early Industrialization
- 1830-1880∇ Industrialization and Early Urbanization
- 1880-1940∇ Urbanization and Early Suburbanization
- 1940-1960∇ Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S03534.001

1. ADDRESS/LOCATION: 18678 Harbeson Road

2. FUNCTION(S): historic Dwelling current Dwelling (vacant)

3. YEAR BUILT: 1900 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: Vernacular, Folk Victorian

5. INTEGRITY: original site moved

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. replacement porch on facade

b. porch expansion and enclosure to rear

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: L-plan Stories: 2
Additions: 1-story, shed-roof porch enclosure on façade; sided in wood shingles (different than main block); pierced by storm windows and door; 1-story porch expansion and enclosure to rear, partially covered in same siding as house and partially in vinyl; openings on south wall; 1-story shed-roof addition, sheltering water tanks
- b. Structural system (if known): frame
- c. Foundation: materials: brick
basement: full partial not visible no basement
- d. Exterior walls (original if visible & any subsequent coverings): staggered wood shingles
- e. Roof: shape: gabled
materials: asphalt shingles
cornice: exposed curved brackets
dormers:
chimney: location(s): (1) center of rear gable, parged; (1) center exterior of south wall, concrete-block

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: East
 - 1) Bays: 6
 - 2) Windows: 2, entrance level; 3, second floor
fenestration : regular
Type: 2/2, double-hung
Trim: wood
shutters

Facade (cont'd)**3) Door(s): 1**

Location: near NE corner, fronted by screen door

Type: fiberglass (2 pane/4-panel)
trim**4) Porch(es): replacement; 1-story, shed-roof porch; enclosed w/ wood-shingles siding and 1/1 double-hung storm windows and storm door; concrete block foundation topped by concrete pad****b. Side: Direction: North****1) Bays: 4****2) Windows: 3, entrance level; 1, second level**

Fenestration: irregular

Type: 1/1, double-hung

Trim: vinyl
shutters**3) Door(s): 0**

location

type

trim

4) Porch(es)**c. Side: Direction: South - somewhat obscured by enclosure****1) Bays: 2****2) Windows: 1, entrance level; 1, second level**

Fenestration: irregular

Type: 2/2, double-hung; 1/1 double-hung

Trim: wood; vinyl
shutters**3) Door(s)**

location

type

trim

4) Porch(es): 1-story porch expansion and enclosure; sided in vinyl; (1) 3-pane/3-panel door opening; (3) casement windows**d. Rear: Direction: West****1) Bays: 1****2) Windows: 1, second floor**

Fenestration: irregular

Type: 2/2, double-hung

Trim: wood
shutters**3) Door(s)**

location

type

trim

4) Porch(es): continuation of side porch expansion; sided in wood shingles like main block of dwelling; (1) 1/1 double-hung window**9. INTERIOR:****10. LANDSCAPING:** house faces east toward road; grass driveway to south side of dwelling; pedestrian walkway across front of property; sides of property shaded by tall trees; open rear lawn; 2-outbuildings to rear of house**11. OTHER COMMENTS:**

USE BLACK INK ONLY

CRS-2



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S03534.002

1. ADDRESS/LOCATION: 18678 Harbeson Road

2. FUNCTION(S): historic Garage/workshop current vacant

3. YEAR BUILT: 1960 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved

if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system concrete-block

b. Number of stories 1

c. Wall coverings

d. Foundation poured concrete

e. Roof: flat
structural system
Coverings: corrugated metal
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: East

1) bays: 1

2) windows:

3) door(s): centralized door opening; vertical wood-slat door

4) other: full-width, shed-roof porch, supported by wood corner posts on a concrete pad

b. Side: direction: North

- 1) **bays:** 0
- 2) **windows:**

- 3) **door(s):**

- 4) **other:**

c. Side: direction: South

- 1) **bays:** 1
- 2) **windows:** triple-sash, aluminum-framed awning window; concrete sill below opening

- 3) **door(s):**

- 4) **other:**

d. Rear: direction: West

- 1) **bays:** 0
- 2) **windows:**

- 3) **door(s):**

- 4) **other:**

9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # S03534

1. ADDRESS/LOCATION: 18678 Harbeson Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE DIVISION OF HISTORICAL AND CULTURAL AFFAIRS
STATE HISTORIC PRESERVATION OFFICE
21 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S03534

Date July 2012 Surveyor/Photographer Courtney L. Clark



S03534: dwelling (.001) façade, looking west.



S03534: dwelling (.001) north side, looking southwest.



S03534: detail of decorative curved gables along roof ridge of dwelling.



S03534: dwelling (.001) south side, looking north.



S03534: dwelling (.001) rear wall, looking east.



S03534: shed and outbuilding (.002), looking west.



DELAWARE DIVISION OF HISTORICAL AND CULTURAL AFFAIRS
STATE HISTORIC PRESERVATION OFFICE
21 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S03534

Date July 2012 Surveyor/Photographer Courtney L. Clark



S03534: dwelling (.001) rear, outbuilding (.002) and shed, looking northeast.