



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SURVEY UPDATE FORM

CRS # S03564

1. HISTORIC NAME/FUNCTION: Rust dwelling

2. ADDRESS/LOCATION: 18675 Harbeson Road

3. CURRENT CONDITION: excellent  good  fair  poor  demolished

4. INTEGRITY: altered  
\_\_\_\_\_

5. SETTING INTEGRITY: maintained  
\_\_\_\_\_

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	
3	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney L. Clark

Principal Investigator name: Courtney L. Clark

Principal Investigator signature: \_\_\_\_\_

Organization: John Milner Associates, Inc. Date: September 2012

8. OTHER NOTES OR OBSERVATIONS:

CRS# S03564

Resurveyed for the US 9 and SR 5 Intersection Improvements project, Delaware Department of Transportation.

Property currently used and occupied as rental. Owner lives in matching style dwelling to immediate south (surname RUST).

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750∇ Contact Period (Native American)
- 1630-1730∇ Exploration and Frontier Settlement
- 1730-1770∇ Intensified and Durable Occupation
- 1770-1830∇ Early Industrialization
- 1830-1880∇ Industrialization and Early Urbanization
- 1880-1940∇ Urbanization and Early Suburbanization
- 1940-1960∇ Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                         |
| <input type="checkbox"/> Forestry              | <input type="checkbox"/> Settlement Patterns and Demographic Changes              |
| <input type="checkbox"/> Trapping/Hunting      | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                  |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                               |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                   |



CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S03564.001

1. ADDRESS/LOCATION: 18675 Harbeson Road

2. FUNCTION(S): historic Dwelling current dwelling

3. YEAR BUILT: 1930 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE OR FLOOR PLAN: Bungalow

5. INTEGRITY: original site  moved   
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. exterior walls resided in vinyl; some replacement windows

b. porch enclosed with jalousie windows

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1.5  
Additions: n/a

b. Structural system (if known): frame

c. Foundation: materials: brick  
basement: full  partial  not visible  no basement

d. Exterior walls (original if visible& any subsequent coverings): vinyl

e. Roof: shape: side gable  
materials: standing-seam metal  
cornice: decorative wood brackets  
dormers: gabled (façade); double-hung, 1/1 vinyl sash  
chimney: location(s): brick, center

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: West  
1) Bays: 3  
2) Windows: 2, entry level; 1, upper level (dormer)  
Fenestration: regular  
Type: 3/1 double-hung; 1/1 double-hung  
Trim: wood; vinyl  
Shutters:

**Facade (cont'd)**

- 3) **Door(s): 1**
  - Location: center**
  - Type: 16-pane**
  - Trim: wood**
- 4) **Porch(es): inset; enclosed with jalousie windows**

**b. Side: Direction: South**

- 1) **Bays: 4**
- 2) **Windows: 3, entry level; 1, upper level**
  - fenestration : regular**
  - Type: 1/1 double-hung**
  - Trim: vinyl sash**
  - Shutters:**
- 3) **Door(s):**
  - Location:**
  - Type:**
  - Trim:**
- 4) **Porch(es):**

**c. Side: Direction: North**

- 1) **Bays: 4**
- 2) **Windows: 3, entry level; 1, upper level**
  - Fenestration: regular**
  - Type: 1/1 double-hung**
  - Trim: vinyl**
  - Shutters:**
- 3) **Door(s):**
  - Location:**
  - Type:**
  - Trim:**
- 4) **Porch(es):**

**d. Rear: Direction: East**

- 1) **Bays: 2**
- 2) **Windows: 1**
  - Fenestration: irregular**
  - Type: 1/1 double-hung**
  - Trim: vinyl**
  - Shutters:**
- 3) **Door(s): 1**
  - Location: center**
  - Type: fiberglass**
  - Trim:**
- 4) **Porch(es): metal awning hangs over entry; small wood stoop front entrance**

**9. INTERIOR:**

**10. LANDSCAPING:** dwelling faces west toward road; gravel drive to north side of house; property is open with no landscaping, a few decorative plantings along façade

**11. OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S03564.002

1. ADDRESS/LOCATION: 18675 Harbeson Road

2. FUNCTION(S): historic Garage current Garage

3. YEAR BUILT: 1940s CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site  moved   
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year  
a. exterior walls resided in vinyl  
b.

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:  
a. Structural system frame  
b. Number of stories 1  
c. Wall coverings vinyl  
d. Foundation no visible, covered by exterior siding  
e. Roof: gable  
Structural system:  
Coverings: standing-seam metal  
Openings:

8. DESCRIPTION OF ELEVATIONS:  
a. Facade: direction: West  
1) bays: 1  
2) windows:  
3) door(s): 1, multi-panel garage door  
4) other:

**b. Side: direction: North**

- 1) bays: 0
- 2) windows:
- 3) door(s):
- 4) other:

**c. Side: direction: South**

- 1) bays: 1
- 2) windows: 1/1 double-hung, vinyl sash
- 3) door(s):
- 4) other:

**d. Rear: direction: East**

- 1) bays:
- 2) windows:
- 3) door(s):
- 4) other: shed-roof addition

**9. INTERIOR (if accessible):**

**a) Floor plan**

**b) Partition/walls**

**c) Finishes**

**d) Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S03564.003

1. ADDRESS/LOCATION: 18675 Harbeson Road

2. FUNCTION(S): historic Agricultural animal shed/stable current unknown

3. YEAR BUILT: 1940s CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site  moved

if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:

a. Structural system frame

b. Number of stories 1

c. Wall coverings horizontal and vertical wood planksiding

d. Foundation none

e. Roof : shed

Structural system:

Coverings: Standing-seam metal

Openings:

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: South

1) bays: 6

2) windows:

3) door(s): 6, combination of swing-hinge and sliding

4) other:

**b. Side: direction: West**

- 1) bays: 0
- 2) windows:
- 3) door(s):
- 4) other:

**c. Side: direction: East**

- 1) bays: 0
- 2) windows:
- 3) door(s):
- 4) other:

**d. Rear: direction: North**

- 1) bays: 4
- 2) windows: 4, swing-hinge
- 3) door(s):
- 4) other:

**9. INTERIOR (if accessible):**

**a) Floor plan**

**b) Partition/walls**

**c) Finishes**

**d) Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S03564.004

1. ADDRESS/LOCATION: 18675 Harbeson Road

2. FUNCTION(S): historic Shed current unknown

3. YEAR BUILT: 1950 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site  moved   
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:

- a. Structural system frame
- b. Number of stories 1
- c. Wall coverings standing-seam metal
- d. Foundation no visible, covered by exterior siding
- e. Roof gable  
Structural system:  
Coverings: standing-seam metal  
Openings:

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: North
  - 1) bays: 1
  - 2) windows:
  - 3) door(s): 1
  - 4) other:

**b. Side: direction: East**

- 1) bays: 0
- 2) windows:
- 3) door(s):
- 4) other:

**c. Side: direction: West**

- 1) bays: 0
- 2) windows:
- 3) door(s):
- 4) other:

**d. Rear: direction: South**

- 1) bays: 0
- 2) windows:
- 3) door(s):
- 4) other:

**9. INTERIOR (if accessible):**

**a) Floor plan**

**b) Partition/walls**

**c) Finishes**

**d) Furnishings/machinery**



**CULTURAL RESOURCE SURVEY  
MAP FORM**

CRS # S03564

1. ADDRESS/LOCATION: 18675 Harbeson Road


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE DIVISION OF HISTORICAL AND CULTURAL AFFAIRS  
STATE HISTORIC PRESERVATION OFFICE  
21 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
DIGITAL PHOTOGRAPHS FORM

CRS # S03564

Date July 2012 Surveyor/Photographer Courtney L. Clark



**S03564:** dwelling (.001) façade and north side and outbuilding (.002), looking east.



**S03564:** dwelling (.001) façade and south side, looking east-northeast.



**S03564:** dwelling (.001) rear and north side, looking southwest.



**S03564:** detail of decorative bracket along roof ridge of dwelling.



**S03564:** dwelling (.001) south side and rear outbuildings (.002,.003,.004), looking northeast.



**S03564:** garage (.002) façade and north side, looking southeast.