



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S03645

1. HISTORIC NAME/FUNCTION: Dwelling

2. ADDRESS/LOCATION: 18557 Harbeson Road

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: altered

5. SETTING INTEGRITY: altered

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney L. Clark

Principal Investigator name: Courtney L. Clark

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: September 2012

8. OTHER NOTES OR OBSERVATIONS:

CRS# S03645

Resurveyed for the US 9 and SR 5 Intersection Improvements project, Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S03645

1. ADDRESS/LOCATION: 18557 Harbeson Road

2. FUNCTION(S): historic Dwelling current dwelling

3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: Bungalow

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. addition on north wall

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1.5
Additions: 1-story, shed-roof addition extending from north wall; sided in same siding as main block

b. Structural system (if known): frame

c. Foundation: materials: rusticated concrete-block
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): staggered wood shingles

e. Roof: shape: side-gabled
materials: asphalt
cornice:
dormers: façade – gabled w/ triple 1/1, double-hung bays
chimney: location(s): brick; center

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: West
1) Bays: 3
2) Windows: 2
Fenestration: regular
Type: 1/1, double hung
Trim: wood
Shutters:

Facade (cont'd)

- 3) **Door(s): 1**
 - Location: center**
 - Type: 12-pane glass**
 - Trim: wood**
- 4) **Porch(es): full-width, inset, screened; supported by brick pillars w/ wood posts**

b. Side: Direction: South

- 1) **Bays: 4**
- 2) **Windows: 2, entrance level; 1, upper level**
 - Fenestration: regular**
 - Type: 1/1, double hung**
 - Trim: wood**
 - Shutters:**
- 3) **Door(s): 1**
 - Location: on west end of extended bay**
 - Type: single pane/ three cross-panels**
 - Trim: wood**
- 4) **Porch(es)**

c. Side: Direction: North

- 1) **Bays: 2**
- 2) **Windows: 1, entrance level; 2, upper level**
 - Fenestration: regular**
 - Type: 1/1, double hung**
 - Trim: wood**
 - Shutters:**
- 3) **Door(s): 0**
 - location**
 - type**
 - trim**
- 4) **Porch(es)**

d. Rear: Direction: East - NO ACCESS

- 1) **Bays**
- 2) **Windows**
 - fenestration**
 - type**
 - trim**
 - shutters**
- 3) **Door(s)**
 - location**
 - type**
 - trim**
- 4) **Porch(es)**

9. INTERIOR:

10. LANDSCAPING: dwelling faces west toward road; shrubs are planted along the façade; dirt drive to south side of house; south side of drive and rear of property overgrown with trees and shrubs

11. OTHER COMMENTS:



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # S03645

1. ADDRESS/LOCATION: 18557 Harbeson Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH




4. SITE PLAN:

CRS # S03645

INDICATE NORTH ON PLAN

S03645

Harbeson Road



dirt drive

retaining wall



Not to scale

--- Drive
— Road

□ Structure
— Roofline
■ Chimney

USE BLACK INK ONLY

CRS-9



DELAWARE DIVISION OF HISTORICAL AND CULTURAL AFFAIRS
STATE HISTORIC PRESERVATION OFFICE
21 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S03645

Date July 2012 Surveyor/Photographer Courtney L. Clark



S03645: dwelling façade and north side, looking east.



S03645: dwelling south side, looking northeast.



S03645: dwelling north side, looking southeast.