



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S12261
SPO Map 16-17-11
Hundred Broadkill
Quad Harbeson
Other _____

1. HISTORIC NAME/FUNCTION: Culvert
2. ADDRESS/LOCATION: Harbeson Road
3. TOWN/NEAREST TOWN: Harbeson vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input type="checkbox"/>	structure	<input checked="" type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: Culvert
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US 9 and SR 5 Intersection Improvements/ Section 106 Initiation and Compliance

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
1	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney L. Clark

Principal Investigator name: Courtney L. Clark

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: September 2012

9. OTHER NOTES OR OBSERVATIONS:

CRS# S12261

DelDot contracts indicate a 42" reinforced concrete pipe was added; headwalls were removed; c. 1957, under contract no. 1433.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input checked="" type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
STRUCTURE (LAND FEATURE) FORM

CRS # S12261

1. ADDRESS/LOCATION: Harbeson Road (State Route 5)

2. FUNCTION: Culvert

3. YEAR BUILT: _____ CIRCA?: ARCHITECT/BUILDER: _____

4. INTEGRITY:

list major changes with years (if known)

a. reinforced concrete pipe (42") installed

year

1957

b. headwalls removed

1957

5. CURRENT CONDITION: excellent good fair poor

6. DESCRIPTION:

a) Circulation system: Structure extends in east-west direction across roadway; traffic crosses north-south across top of structure; Beaver Dam Creek flows in eastern direction through structure

b) Spatial subdivisions:

c) Retaining wall/lining material(s): Reinforced concrete

d) Other: Culvert opening, approximately 42"; asphalt decking; metal guard railings flank roadway to east and west;



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S12261

1. ADDRESS/LOCATION: Harbeson Road; Route 5
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE DIVISION OF HISTORICAL AND CULTURAL AFFAIRS
STATE HISTORIC PRESERVATION OFFICE
21 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S12261

Date July 2012 Surveyor/Photographer Courtney L. Clark



S12261: culvert along west side of Harbeson Road, looking south.



S12261: view of culvert along west side of Harbeson Road, looking southwest.



S12261: view of culvert opening along east side of Harbeson Road, looking southwest.