



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S12262  
SPO Map 16-17-11  
Hundred Broadkill  
Quad Harbeson  
Other \_\_\_\_\_

- HISTORIC NAME/FUNCTION: Agricultural Feed Store
- ADDRESS/LOCATION: East side of Harbeson Road; north of SR 404 intersection
- TOWN/NEAREST TOWN: Harbeson vicinity?
- MAIN TYPE OF RESOURCE:
 

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
- MAIN FUNCTION OF PROPERTY: Commercial
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):  
US 9 and SR 5 Intersection Improvements/ Section 106 Initiation and Compliance

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
1	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney L. Clark

Principal Investigator name: Courtney L. Clark

Principal Investigator signature: \_\_\_\_\_

Organization: John Milner Associates, Inc. Date: September 2012

9. OTHER NOTES OR OBSERVATIONS:

CRS# S12262

Property owner lives across the street, address: 18570 Harbeson Road (S12267).  
Building in midst of being demolished by owner.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
  
  - 1600-1750∇ Contact Period (Native American)
  - 1630-1730∇ Exploration and Frontier Settlement
  - 1730-1770∇ Intensified and Durable Occupation
  - 1770-1830∇ Early Industrialization
  - 1830-1880∇ Industrialization and Early Urbanization
  - 1880-1940∇ Urbanization and Early Suburbanization
  - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- |   |   |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication                         |
| <input type="checkbox"/> Forestry               | <input type="checkbox"/> Settlement Patterns and Demographic Changes              |
| <input type="checkbox"/> Trapping/Hunting       | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying       | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering      | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing          | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling  | <input type="checkbox"/> Community Organizations                                  |
| <input type="checkbox"/> Finance                | <input type="checkbox"/> Occupational Organizations                               |
| <input type="checkbox"/> Professional Services  | <input type="checkbox"/> Major Families, Individuals and Events                   |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S12262.001

1. ADDRESS/LOCATION: East side of Harbeson Road; north of US9 & SR 404 intersection

2. FUNCTION(S): historic Agricultural Feed store current Half-demolished

3. YEAR BUILT: 1935 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE OR FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site  moved   
if moved, from where other location's CRS # year

list major alterations and additions with years (if known)

a. demolition in progress 2012  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1  
Additions:

b. Structural system (if known): frame

c. Foundation: materials: concrete block  
basement: full  partial  not visible  no basement

d. Exterior walls (original if visible& any subsequent coverings): vertical wood siding

e. Roof: shape: side-gabled  
materials: metal  
cornice:  
dormers:  
chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: West  
1) Bays: 1  
2) Windows  
fenestration  
type  
trim  
shutters

**Facade (cont'd)**

- 3) **Door(s): 1**
  - Location: center
  - Type: sliding, wood trim
- 4) **Porch(es)**

**b. Side: Direction: South – half-demolished**

- 1) **Bays**
- 2) **Windows**
  - fenestration
  - type
  - trim
  - shutters
- 3) **Door(s)**
  - location
  - type
  - trim
- 4) **Porch(es)**

**c. Side: Direction: North – half-demolished**

- 1) **Bays**
- 2) **Windows**
  - fenestration
  - type
  - trim
  - shutters
- 3) **Door(s)**
  - location
  - type
  - trim
- 4) **Porch(es)**

**d. Rear: Direction: East - demolished**

- 1) **Bays**
- 2) **Windows**
  - fenestration
  - type
  - trim
  - shutters
- 3) **Door(s)**
  - location
  - type
  - trim
- 4) **Porch(es)**

**9. INTERIOR:**

**10. LANDSCAPING:** building faces west toward road; building remnants and north side of property overgrown by tall trees and brush; trees line east side of property and along creek bed, to the south; open in middle of property

**11. OTHER COMMENTS:**



CULTURAL RESOURCE SURVEY  
STRUCTURE (LAND FEATURE) FORM

CRS # S12262.002

1. ADDRESS/LOCATION: East side of Harbeson Road; north of US9 & SR 404 intersection

2. FUNCTION: Weigh station/ platform

3. YEAR BUILT: 1930s CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. INTEGRITY:  
list major changes with years (if known) \_\_\_\_\_ year  
a. \_\_\_\_\_  
b. \_\_\_\_\_

5. CURRENT CONDITION:      excellent       good       fair       poor

6. DESCRIPTION:

a) Circulation system: linear (drive-on/drive-off)

b) Spatial subdivisions: woods to immediate east; creek to the south; Harbeson road to the west; building to north-northeast

c) Retaining wall/lining material(s): concrete with steel mechanism(s) in center

d) Other: size of 3 feet x 2.5 feet; not covered, exposed to elements



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAP FORM

CRS # S12262

1. ADDRESS/LOCATION: East side of Harbeson Road; Route 5


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE DIVISION OF HISTORICAL AND CULTURAL AFFAIRS  
STATE HISTORIC PRESERVATION OFFICE  
21 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
DIGITAL PHOTOGRAPHS FORM

CRS # S12262

Date July 2012 Surveyor/Photographer Courtney L. Clark



**S12262:** former feed store (001) façade and remaining south end, looking northeast.



**S12262:** former feed store (001) façade, looking southeast.



**S12262:** former weigh station (002), looking south-southeast.