



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S12263
SPO Map 16-17-11
Hundred Broadkill
Quad Harbeson
Other _____

1. HISTORIC NAME/FUNCTION: Auto Garage/ Allserve Auto LLC
2. ADDRESS/LOCATION: 26539 Lewes-Georgetown Highway
3. TOWN/NEAREST TOWN: Harbeson vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: Commercial
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US 9 and SR 5 Intersection Improvements/ Section 106 Initiation and Compliance

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney L. Clark

Principal Investigator name: Courtney L. Clark

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: September 2012

9. OTHER NOTES OR OBSERVATIONS:

CRS# S12263

Large, 4-bay wide, side-gabled building to rear of property, circa 1995:
C.M.W. Auto Body, 26533 Lewes-Georgetown Highway

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input checked="" type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S12263

1. ADDRESS/LOCATION: 26539 Lewes-Georgetown Highway
2. FUNCTION(S): historic Auto garage current Auto garage
3. YEAR BUILT: 1960 CIRCA?: ARCHITECT/BUILDER: _____
4. STYLE OR FLOOR PLAN: _____
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. additions to both sidewalls

b. addition to rear

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangular Stories: 1
 Additions: small, one-room, concrete addition on east wall w/ openings on south wall; shed-roof addition along west wall covered in vinyl w/ openings on all sides; concrete-block, shed-roof addition to rear w/ openings on east and north walls
- b. Structural system (if known): concrete block
- c. Foundation: materials: concrete block & poured concrete
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): concrete block
- e. Roof: shape: flat
 materials: unknown
 cornice:
 dormers:
 chimney: location(s): concrete block; exterior of east wall

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: South
 1) Bays: 3
 2) Windows:
 Fenestration:
 Type:
 Trim:
 Shutters:

- 3) Door(s): 3
Location:
Type: 2- metal garage; 1- fiberglass pedestrian
Trim: wood

- 4) Porch(es):

b. Side: Direction: East

- 1) Bays: 3
- 2) Windows: 3, ventilation bays
Fenestration: regular
Type: double-pane, fixed
Trim: vinyl
Shutters:

- 3) Door(s):
location
type
trim

- 4) Porch(es)

c. Side: Direction: West – obscured by addition

- 1) Bays:
- 2) Windows:
Fenestration:
Type:
Trim:
Shutters:

- 3) Door(s):
location
type
trim

- 4) Porch(es)

d. Rear: Direction: North

- 1) Bays: 2
- 2) Windows: 2
Fenestration: regular
Type: 6/6, double-hung
Trim: vinyl; concrete sills
Shutters: decorative, non-functional

- 3) Door(s)
location
type
trim

- 4) Porch(es)

9. INTERIOR:

10. LANDSCAPING: building faces south toward road; a few shrubs are planted along façade corners; remainder of property open; large gravel parking area to front w/ driveway leading to rear of property

11. OTHER COMMENTS:



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # S12263

1. ADDRESS/LOCATION: 26533-26539 Lewes-Georgetown Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE DIVISION OF HISTORICAL AND CULTURAL AFFAIRS
STATE HISTORIC PRESERVATION OFFICE
21 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S12263

Date August 2012 Surveyor/Photographer Courtney L. Clark



S12263: building façade and west side, looking north.



S12263: building façade and east side, looking north-northwest.



S12263: building rear and parts of east side, looking south-southwest.



S12263: building rear, looking south.



S12263: modern secondary building on property, looking north.