


APPENDIX C
CRS FORMS FOR HISTORIC ARCHITECTURAL RESOURCES



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-861

1. ADDRESS/LOCATION: 18186 Lewes Georgetown Hwy, Georgetown, DE 19947
2. FUNCTION(S): historic barn current barn
3. YEAR BUILT: 1947 CIRCA?: ARCHITECT/BUILDER: unknown
4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
- | <u>if moved, from where</u> | <u>original location's CRS #</u> | <u>year</u> |
|-----------------------------|----------------------------------|-------------|
| N/A | N/A | |

- | <u>list major alterations and additions with years (if known)</u> | <u>year</u> |
|-------------------------------------------------------------------|-------------|
| a. large cow loafing shed added to west side of barn | |
| b. ice cream stand added to northeast corner of barn | 2007 |

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
- a. Structural system frame
 - b. Number of stories 2
 - c. Wall coverings aluminum siding
 - d. Foundation concrete block
 - e. Roof structural system gambrel
coverings metal
openings 2 ventilators on roof ridge

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: direction: EAST
 - 1) bays: 3
 - 2) windows: 6 (2 single 6/6 sash; 2 paired 6/6 sash)
 - 3) door(s): 2 (1 sliding bay; 1 haymow)
 - 4) other: N/A

- b. Side: direction: NORTH (ice cream stand)
- 1) bays: 4
 - 2) windows: 3 (1 for orders)
 - 3) door(s): 1
 - 4) other: freezer unit
- c. Side: direction: SOUTH
- 1) bays: 11
 - 2) windows: 9 (6/6 sash)
 - 3) door(s): 2
 - 4) other: haymow opening
- d. Rear: direction: WEST (cow loafing shed addition)
- 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A

9. INTERIOR (if accessible):

- a) Floor plan N/A
- b) Partition/walls N/A
- c) Finishes N/A
- d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY

CRS # S-861


MAP FORM

1. ADDRESS/LOCATION: 18186 Lewes Georgetown Hwy, Georgetown, DE 19947
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-861

1. HISTORIC NAME/FUNCTION: Hopkins Farm / farm

2. ADDRESS/LOCATION: 18186 Lewes Georgetown Hwy, Georgetown, DE 19947

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: The farm complex has been completely rebuilt since 1970. The dairy barn is the only remaining feature of the earlier farmstead. Since the resource was inventoried in 1979, there have been several new structures added to the farm complex, including a 1-story double-pile house, which replaced the earlier 2-story farmhouse.

5. SETTING INTEGRITY: This dwelling is on the northwest corner of US 9 (Lewes-Georgetown Hwy) and Dairy Farm Road. New residences have been constructed along US 9 in the vicinity of the farm and an electric substation sits across the highway from the farm.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
0	CRS 2 Main Building Form	
1	CRS 3 Secondary Building Form	Barn
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Wendy Zug-Gilbert

Principal Investigator name: Wendy Zug-Gilbert

Principal Investigator signature: Michael C. Hahn, AICP for Wendy Zug-Gilbert

Organization: A&HC, Inc. Date: Nov. 2009

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-861

Originally surveyed for by the Sussex County Planning Commission in 1979.

Resurveyed for the US 9 Intersection Improvements Project by A&HC, Inc.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|-------------------------------------------------|-----------------------------------------------------------------------------------|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-861

Date Nov. 2009 & Surveyor/Photographer Wendy Zug-Gilbert, Nathaniel Delesline and
October, 2010 Michael Hahn

Insert photographs; note file name and brief description of view: 1: dairy barn and silo east gambrel end. 2: dairy barn south elevation. 3: modern loafing shed west elevation of barn. 4: loafing shed west elevation. (size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

Page 1 of 4

1: dairy barn and silo east gambrel end



2: dairy barn south elevation



3: modern loafing shed west elevation of barn



4: loafing shed west elevation





CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-861

Date Nov. 2009 & October, 2010 Surveyor/Photographer Wendy Zug-Gilbert, Nathaniel Delesline and Michael Hahn

Insert photographs; note file name and brief description of view: 5: modern farm house façade south elevation. 6: interior gambrel connection. 7: interior rafter on resting plate. 8: interior infill east gable. (size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

Page 2 of 4

5: modern farm house façade south elevation



6: interior gambrel connection



7: interior rafter on resting plate



8: interior infill east gable





CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-861

Date Nov. 2009 & October, 2010 Surveyor/Photographer Wendy Zug-Gilbert, Nathaniel Delesline and Michael Hahn

Insert photographs; note file name and brief description of view: 9: interior east gable end – altered loft door. 10: interior gable tie beams & hay pick. 11: interior 1st floor upper loft. 12: interior 1st floor southwest. (size photograph 3” on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

Page 3 of 4

9: interior east gable end – altered loft door



10: interior gable tie beams & hay pick



11: interior 1st floor upper loft



12: interior 1st floor southwest





DELAWARE DIVISION OF HISTORICAL AND CULTURAL AFFAIRS
STATE HISTORIC PRESERVATION OFFICE
21 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-861

Date Nov. 2009 & October, 2010 Surveyor/Photographer Wendy Zug-Gilbert, Nathaniel Delesline and Michael Hahn

Insert photographs; note file name and brief description of view: 13: 1st floor partition and window. 14: west gable shed connection elevation. 15: S-848, Hopkins Covered Bridge Farm
(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

Page 4 of 4

13: 1st floor partition and window



14: west gable shed connection elevation



15: S-848, Hopkins Covered Bridge Farm





CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-8491

1. HISTORIC NAME/FUNCTION: Dwelling, NW Corner, Intersection of Rte 404 & Rd 30 (previous form)

2. ADDRESS/LOCATION: NW corner of US 9 & Gravel Hill Road, Gravel Hill, DE

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY:

5. SETTING INTEGRITY:

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
0	CRS 2 Main Building Form	
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
0	CRS 9 Map Form	
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Wendy Zug-Gilbert

Principal Investigator name: Wendy Zug-Gilbert

Principal Investigator signature: Michael C. Hahn, AICP for Wendy Zug-Gilbert

Organization: A&HC, Inc. Date: Nov. 2009

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-8491

Originally surveyed for the Sussex East-West Corridor Study in 1994.

Resurveyed for the US 9 Intersection Improvements Project by A&HC, Inc.
Known to be the mid-19th-century farm of William Hancock

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|------------------------------------------------|------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-8492

1. ADDRESS/LOCATION: 24603 Lewes Georgetown Hwy, Georgetown, DE 19947
2. FUNCTION(S): historic single-family dwelling current: same
3. YEAR BUILT: 1924 CIRCA?: ARCHITECT/BUILDER: unknown
4. STYLE OR FLOOR PLAN: Gable-front double-pile cottage
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. rear additions

b. replacement windows, aluminum storms, vinyl shutters

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe resource as completely as possible. Use N/A for not applicable; leave no blanks)
- a. Overall shape: rectangular (main block), with gabled wings on S (façade) & W sides, and 2 successive shed-roof additions on rear (N) Stories: 1½
 Additions: 1-story shed-roof full-width addition on rear (N) of main block;
 1-story shed-roof partial-width addition on the rear (N) of the larger addition
- b. Structural system (if known): frame
- c. Foundation: materials: not visible
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): asbestos siding (majority of dwelling); wood clapboards (smaller shed-roof addition on rear)
- e. Roof: shape: gable
 materials: asphalt shingle
 cornice: N/A
 dormers: N/A
 chimney: location(s): 1 interior brick chimney in smaller shed-roof addition on rear

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: SOUTH
- 1) Bays 4
- 2) Windows 3
- fenestration irregular
- type 1/1 wood sash
- trim wood
- shutters louvered plastic

Facade (cont'd)


- 3) Door(s) 1
 location SE corner of main block
 type wood panel door with 6-divided lights in upper 1/3
 trim wood
- 4) Porch(es) brick and flagstone pad by front door

- b. Side: Direction: WEST
- 1) Bays 4
- 2) Windows 6 (2 paired & 2 single)
 fenestration irregular
 type 1/1 wood sash; jalousie (rearmost addition)
 trim wood
 shutters louvered plastic
- 3) Door(s) 0
 location N/A
 type N/A
 trim N/A
- 4) Porch(es) N/A
- c. Side: Direction: EAST
- 1) Bays 5
- 2) Windows 5
 fenestration regular
 type 1/1 wood sash; jalousie (rearmost addition)
 trim wood
 shutters louvered plastic
- 3) Door(s) 0
 location N/A
 type N/A
 trim N/A
- 4) Porch(es) N/A
- d. Rear: Direction: NORTH
- 1) Bays 3
- 2) Windows 0
 fenestration N/A
 type N/A
 trim N/A
 shutters N/A
- 3) Door(s) 1
 location rearmost addition
 type steel 6-panel door
 trim wood
- 4) Porch(es) N/A

9. INTERIOR: N/A

10. LANDSCAPING: Dwelling sits on a half-acre lot on the northeast corner of the Gravel Hill Road-Lewes Georgetown Hwy. A semi-circular driveway arcs from the corner of the intersection to a point north on Gravel Hill Road. Several trees are clustered at the northeast corner of the property.

11. OTHER COMMENTS: There is a mid-20th-century garage to the northwest of the house.



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-8492

1. ADDRESS/LOCATION: 24603 Lewes Georgetown Hwy, Georgetown, DE 19947

2. FUNCTION(S): historic garage current same

3. YEAR BUILT: 1960 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
-------------------------------------------------------------------	-------------

a. N/A

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system frame

b. Number of stories 1

c. Wall coverings wood clapboards

d. Foundation concrete block

e. Roof
structural system front-gable
coverings asphalt shingle
openings N/A

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: SOUTH

1) bays: 2

2) windows: 0

3) door(s): 2 overhead garage bay doors

4) other: N/A

- b. Side: direction: WEST
- 1) bays: 1
 - 2) windows: 1 (1/1-sash window with wood trim & plastic shutters centered on elevation)
 - 3) door(s): 0
 - 4) other: N/A

- c. Side: direction: EAST
- 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 1 (steel door at S corner of elevation)
 - 4) other: N/A

- d. Rear: direction: NORTH
- 1) bays: 3
 - 2) windows: 1 (1/1-sash window with wood trim centered on elevation)
 - 3) door(s): 0
 - 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan N/A

b) Partition/walls N/A

c) Finishes N/A

d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY

CRS # S-8492

MAP FORM

1. ADDRESS/LOCATION: 24603 Lewes Georgetown Hwy, Georgetown, DE 19947


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-8492

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-8492

1. HISTORIC NAME/FUNCTION: Dwelling, NW Corner, Intersection of Rte 404 & Rd 30 (previous survey)
Howard Stewart House / residence

2. ADDRESS/LOCATION: 24603 Lewes Georgetown Hwy, Georgetown, DE 19947

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: Asbestos siding, asphalt-shingle roof, replacement 1/1 windows, vinyl shutters, additions on each elevation (except east); c. 1960 garage

5. SETTING INTEGRITY: This dwelling sits on the northeast corner of the US 9 (Lewes Georgetown Hwy) and Gravel Hill Road intersection. It was one of the earliest dwellings in the village of Gravel Hill. Modern "model" display home on northwest corner and Mexican restaurant & grocery on southwest corner.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
1	CRS 3 Secondary Building Form	Garage
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Wendy Zug-Gilbert

Principal Investigator name: Wendy Zug-Gilbert

Principal Investigator signature: Michael C. Hahn, AICP for Wendy Zug-Gilbert

Organization: A&HC, Inc. Date: Nov. 2009

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-8492

Originally surveyed for the Sussex East-West Corridor Study in 1994.

Resurveyed for the US 9 Intersection Improvements Project by A&HC, Inc.

Resource given the name "Howard Stewart House" after the first home owner.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-8492

Date Nov. 2009 Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 1: Howard Steward House façade, s/w elevation. 2: rear - n/w elevation. 3: garage south elevation.
(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

1: façade south west elevation



2: rear- n/w elevation



3: garage south elevation





CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-8493

- 1. ADDRESS/LOCATION: 24606 Lewes Georgetown Hwy, Georgetown, DE 19947
- 2. FUNCTION(S): historic single-family dwelling current: same
- 3. YEAR BUILT: 1880s CIRCA?: ARCHITECT/BUILDER: unknown
- 4. STYLE OR FLOOR PLAN: shotgun cottage

- 5. INTEGRITY: original site moved
- | | | |
|-----------------------------|-------------------------------|-------------|
| <u>if moved, from where</u> | <u>other location's CRS #</u> | <u>year</u> |
| <u>unknown</u> | | |

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
<u>a. shed-roof addition</u>	<u>c. 1935</u>
<u>b. asbestos siding; asphalt-shingle roof; replacement 1/1 windows</u>	<u>c. 1950</u>
<u>c. rebuilt front porch; rear deck</u>	<u>c. 2000</u>

- 6. CURRENT CONDITION: excellent good fair poor
- 7. DESCRIPTION: (Describe resource as completely as possible. Use N/A for not applicable; leave no blanks)
 - a. Overall shape: rectangular Stories: 1
Additions: shed-roof, full-width addition on rear (south) gable end
 - b. Structural system (if known): frame
 - c. Foundation: materials: concrete
basement: full partial not visible no basement
 - d. Exterior walls (original if visible& any subsequent coverings): asbestos siding
 - e. Roof: shape: front gable
materials: asphalt shingle
cornice: N/A
dormers: N/A
chimney: location(s): 2 brick chimneys on ridge of roof

- 8. DESCRIPTION OF ELEVATIONS:
 - a. Facade: Direction: NORTH
 - 1) Bays 2
 - 2) Windows 1
 - fenestration irregular
 - type 1/1 wood sash
 - trim wood
 - shutters wood

Facade (cont'd)

- 3) Door(s) 1
 location off-center
 type wood panel with aluminum storm door
 trim wood
- 4) Porch(es) shed-roof, full-width porch with vinyl supports and railing

b. Side: Direction: EAST

- 1) Bays 4
- 2) Windows 4
 fenestration regular
 type 1/1 wood sash
 trim wood
 shutters N/A
- 3) Door(s) 0
 location N/A
 type N/A
 trim N/A
- 4) Porch(es) N/A

c. Side: Direction: WEST

- 1) Bays 4
- 2) Windows 4
 fenestration regular
 type 1/1 wood sash
 trim wood
 shutters N/A
- 3) Door(s) 0
 location N/A
 type N/A
 trim N/A
- 4) Porch(es) N/A

d. Rear: Direction: SOUTH

- 1) Bays 2
- 2) Windows 1
 fenestration irregular
 type 1/1 wood sash
 trim wood
 shutters N/A
- 3) Door(s) 1
 location off-center
 type wood panel door with aluminum storm door
 trim wood
- 4) Porch(es) partial-width deck with vinyl railing

9. INTERIOR: N/A

10. LANDSCAPING: Dwelling sits on a 3.57-acre lot at the southeast corner of the intersection of Gravel Hill Road with Lewes-Georgetown Hwy. This house shares the lot with another house to its east. The two residences are separated by a paved driveway. Some mature trees are scattered near the houses with mowed yard at the rear and west portions of the property.

11. OTHER COMMENTS:



CULTURAL RESOURCE SURVEY

CRS # S-8493

MAP FORM

1. ADDRESS/LOCATION: 24606 Lewes Georgetown Hwy, Georgetown, DE 19947


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH




4. SITE PLAN:

CRS # S-8493


INDICATE NORTH ON PLAN

S-8493

US 9 (Lewes - Georgetown Highway)



 = Modern (post - 1962)



USE BLACK INK ONLY

CRS-9



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-8493

1. HISTORIC NAME/FUNCTION: Dwelling Complex, SE Corner of Rte 404 & Rte 9 (from previous survey)
Pearl Koeppel House / residence

2. ADDRESS/LOCATION: 24606 Lewes Georgetown Hwy, Georgetown, DE 19947

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: Asbestos siding, asphalt-shingle roof, replacement 1/1 windows, rebuilt front porch (with vinyl supports & railing), shed-roof addition and modern deck on rear. Also, the presence of a concrete foundation beneath the structure appears to indicate that it has been moved from another location.

5. SETTING INTEGRITY: This dwelling is on the southeast corner of Gravel Hill Rd (SR 30) and Lewes-Georgetown Hwy (US 9). It was one of the earlier dwellings in the village of Gravel Hill. A modern "model" display home on northwest corner and a Mexican restaurant & grocery is on southwest corner.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Wendy Zug-Gilbert

Principal Investigator name: Wendy Zug-Gilbert

Principal Investigator signature: Michael C. Hahn, AICP for Wendy Zug-Gilbert

Organization: A&HC, Inc. Date: Nov. 2009

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-8493

Originally surveyed for the Sussex East-West Corridor Study in 1994.

Resurveyed for the US 9 Intersection Improvements Project by A&HC, Inc.

This resource was given the name "Pearl Koepfel House" after the first known owner.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-8493

Date Nov. 2009 Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 1: Pearl Koeppel House Façade n/e elevation. 2: north elevation. 3: rear south elevation.
(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

1: Façade n/e elevation



2: north elevation



3: rear south elevation





CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-8494

- 1. ADDRESS/LOCATION: 24616 Gravel Hill Road, Georgetown, DE 19947
- 2. FUNCTION(S): historic single-family dwelling current: same
- 3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: unknown
- 4. STYLE OR FLOOR PLAN: Cape Cod

- 5. INTEGRITY: original site moved
- | | | |
|-----------------------------|-------------------------------|-------------|
| <u>if moved, from where</u> | <u>other location's CRS #</u> | <u>year</u> |
| N/A | | |

- | | | |
|-------------------------------------------------------------------|--|-------------|
| <u>list major alterations and additions with years (if known)</u> | | <u>year</u> |
| a. sunroom addition on east gable end | | unknown |
| b. vinyl siding & shutters, rebuilt front porch & rear stoop | | unknown |

- 6. CURRENT CONDITION: excellent good fair poor

- 7. DESCRIPTION: (Describe resource as completely as possible. Use N/A for not applicable; leave no blanks)

- a. Overall shape: rectangular Stories: 1½
Additions: shed-roof, partial-width sunroom addition on south gable end; concrete-block foundation; lined with jalousie windows
- b. Structural system (if known): frame
- c. Foundation: materials: rusticated concrete
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): vinyl siding
- e. Roof: shape: side gable
materials: asphalt shingle
cornice: N/A
dormers: 2 gabled dormers on façade; 1 shed-roof wall dormer on rear
chimney: location(s): 1 brick chimney on rear

- 8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: NORTH
- 1) Bays 3
- 2) Windows 2
- fenestration regular
- type 6/1 wood sash
- trim wood
- shutters vinyl louvered

Facade (cont'd)

- 3) Door(s) 1
 location central bay
 type wood panel with vinyl storm door and 3-light transom
 trim wood
- 4) Porch(es) gable-roof hood with arched cornice at door; vinyl posts and railing

b. Side: Direction: EAST

- 1) Bays 4
- 2) Windows 5 (1 in end gable; 1 in rear wing; 3 in sunroom addition)
 fenestration regular
 type 6/1 wood sash; jalousie (sunroom addition)
 trim wood
 shutters vinyl louvered (end gable)
- 3) Door(s) 0
 location N/A
 type N/A
 trim N/A
- 4) Porch(es) N/A

c. Side: Direction: WEST

- 1) Bays 3
- 2) Windows 4
 fenestration regular
 type 6/1 wood sash
 trim wood
 shutters vinyl louvered
- 3) Door(s) 1
 location sunroom addition
 type 9-light wood panel
 trim wood
- 4) Porch(es) elevated concrete pad on concrete-block foundation with vinyl railing


d. Rear: Direction: SOUTH

- 1) Bays 3
- 2) Windows 4
 fenestration irregular
 type 6/1 wood sash
 trim wood
 shutters vinyl louvered
- 3) Door(s) 0
 location N/A
 type N/A
 trim N/A
- 4) Porch(es) N/A

9. INTERIOR: N/A

10. LANDSCAPING: Dwelling sits on a 3.57-acre lot at the southeast corner of the intersection of Gravel Hill Road with Lewes-Georgetown Hwy. This house shares the lot with another house to its west. The two residences are separated by a paved driveway. Some mature trees are scattered near the houses with mowed yard at the rear and west portions of the property.

11. OTHER COMMENTS: A wooden playhouse and garage are located to the rear of the dwelling.



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-8494

1. ADDRESS/LOCATION: 24616 Lewes Georgetown Hwy, Georgetown, DE 19947

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

if moved, from where
N/A

original location's CRS # year
N/A

list major alterations and additions with years (if known)

year

a. N/A

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system frame

b. Number of stories 1½

c. Wall coverings vinyl siding

d. Foundation concrete block

e. Roof
structural system front gable
coverings asphalt shingle
openings 2 gabled dormers on north slope

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: EAST

1) bays: 1

2) windows: 0

3) door(s): 1 (opening, no door)

4) other: N/A

- b. Side: direction: NORTH
 - 1) bays: 2
 - 2) windows: 4 (6/1 wood sash)
 - 3) door(s): 0
 - 4) other: N/A

- c. Side: direction: SOUTH
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A

- d. Rear: direction: WEST
 - 1) bays: 2
 - 2) windows: 3 (6/1 wood sash)
 - 3) door(s): 0
 - 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan N/A

b) Partition/walls N/A

c) Finishes N/A

d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY

CRS # S-8494

MAP FORM

1. ADDRESS/LOCATION: 24616 Lewes Georgetown Hwy, Georgetown, DE 19947


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-8494

1. HISTORIC NAME/FUNCTION: Dwelling, S Side of Route 404 & Route 9 (from previous survey)
Pearl Dodd Property / residence

2. ADDRESS/LOCATION: 24616 Lewes Georgetown Hwy, Georgetown, DE 19947

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: Vinyl siding and shutters, rebuilt front porch (with vinyl supports & railing), large sunroom addition on east gable end, rebuilt stoop on rear.

5. SETTING INTEGRITY: This dwelling is on the southeast corner of Gravel Hill Rd (SR 30) and Lewes-Georgetown Hwy (US 9). A modern "model" display home is on northwest corner and a Mexican restaurant & grocery is on southwest corner.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
1	CRS 3 Secondary Building Form	Garage
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Wendy Zug-Gilbert

Principal Investigator name: Wendy Zug-Gilbert

Principal Investigator signature: Michael C. Hahn, AICP for Wendy Zug-Gilbert

Organization: A&HC, Inc. Date: Nov. 2009

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-8494

Originally surveyed for the Sussex East-West Corridor Study in 1994.

Resurveyed for the US 9 Intersection Improvements Project by A&HC, Inc.

This resource was given the name "Pearl Dodd Property" after the first owner.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-8494

Date Nov 2009 Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 1: Pearl Dodd House façade n/e. 2: rear s/w. elevation. 3: west elevation. 4: garage n/e elevation.
(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

Page 1 of 2

1: Pearl Dodd House façade n/e



2: rear s/w elevation



3: west elevation



4: garage n/e elevation





DELAWARE DIVISION OF HISTORICAL AND CULTURAL AFFAIRS
STATE HISTORIC PRESERVATION OFFICE
21 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-8494

Date Nov. 2009 Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 5: garage s/w elevation.
(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

Page 2 of 2
5: garage s/w elevation





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-8495
SPO Map 16-17-11
Hundred Georgetown
Quad Harbeson
Other 1-35-11.00-79.00

1. HISTORIC NAME/FUNCTION: James Koeppel House
2. ADDRESS/LOCATION: 20041 Gravel Hill Road, Georgetown, DE 19947
3. TOWN/NEAREST TOWN: Gravel Hill vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: residential
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
SR 9 Safety Improvements Project, Sussex County, Delaware

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
3	CRS 3 Secondary Building Form	Garages
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Wendy Zug-Gilbert

Principal Investigator name: Wendy Zug-Gilbert

Principal Investigator signature: Michael C. Hahn, AICP for Wendy Zug-Gilbert

Organization: A&HC, Inc. Date: Nov 2009

9. OTHER NOTES OR OBSERVATIONS:

CRS# S - 8 4 9 5

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY

CRS-1



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-8495

1. ADDRESS/LOCATION: 20041 Gravel Hill Road, Georgetown, DE 19947
2. FUNCTION(S): historic single-family dwelling current: same
3. YEAR BUILT: 1938 CIRCA?: ARCHITECT/BUILDER: unknown
4. STYLE OR FLOOR PLAN: Gable-front double-pile cottage
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known)

year

- a. large gable-roof full-width frame addition on S side of the main block c. 1970
- b. small shed-roof addition (utility shed) off rear (E) of the larger addition c. 1970

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe resource as completely as possible. Use N/A for not applicable; leave no blanks)
- a. Overall shape: rectangular (main block), with 1-story wings Stories: 1½
on façade (W) & rear (S), and large addition on S side elev
Additions: gable-roof full-width addition on the S side of the main block;
small shed-roof (utility shed) addition on the rear (E) of the large addition
- b. Structural system (if known): frame
- c. Foundation: materials: rusticated concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): asbestos siding
- e. Roof: shape: gable
materials: asphalt shingle
cornice: N/A
dormers: N/A
chimney: location(s): 1 interior concrete-block chimney at SE corner of main block where it
joins with large and small additions and rear wing

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: WEST
- 1) Bays 4 (3 symmetrical bays in main block & 1 in S side addition)
- 2) Windows 6 (3 paired)
fenestration irregular
type 1/1 wood sash (main block); 1/1 vinyl sash (addition)
trim wood (main block); vinyl (addition)
shutters N/A

Facade (cont'd)


- 3) Door(s) 1
 location central bay of main block
 type wood 6-panel door with aluminum & glass storm door
 trim wood
- 4) Porch(es) N/A

- b. Side: Direction: NORTH
- 1) Bays 6 (4 in the main block & 1 each in the entry and rear extensions)
- 2) Windows 8 (2 paired & 4 single)
 fenestration regular
 type 1/1 wood sash
 trim wood
 shutters N/A
- 3) Door(s) 0
 location N/A
 type N/A
 trim N/A
- 4) Porch(es) N/A
- c. Side: Direction: SOUTH
- 1) Bays 5 (3 in addition & 1 each in entry and rear extensions)
- 2) Windows 8 (3 paired & 2 single)
 fenestration irregular
 type 1/1 wood sash (extensions); 1/1 vinyl sash (addition)
 trim wood (extensions); vinyl (addition)
 shutters N/A
- 3) Door(s) 0
 location N/A
 type N/A
 trim N/A
- 4) Porch(es) N/A
- d. Rear: Direction: EAST
- 1) Bays 5 (3 in main block; 1 in S addition; 1 in utility shed addition)
- 2) Windows 3 (3 single)
 fenestration irregular
 type 1/1 wood sash (main block); 1/1 vinyl sash (S addition)
 trim wood (main block); vinyl (S addition)
 shutters N/A
- 3) Door(s) 2
 location central bay of main block; utility shed addition
 type wood 6-panel door with aluminum & glass storm door (main block);
 hollow-core wood (utility shed addition)
 trim wood (main block); vinyl (utility shed addition)
- 4) Porch(es) N/A

9. INTERIOR: N/A

10. LANDSCAPING: Dwelling sits on a 1-acre lot on the east side of Gravel Hill Road with a paved driveway along its north side to access outbuildings at rear.

11. OTHER COMMENTS: There are 3 garages (2 modern) and a gazebo behind the house.



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-8495

1. ADDRESS/LOCATION: 20041 Gravel Hill Road, Georgetown, DE 19947

2. FUNCTION(S): historic garage current same

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. <u>N/A</u>	
b.	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system masonry (concrete block)
- b. Number of stories 1
- c. Wall coverings concrete block & aluminum siding (gables)
- d. Foundation concrete block
- e. Roof structural system front-gable
- coverings asphalt shingle
- openings N/A

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: SOUTH
 - 1) bays: 2
 - 2) windows: 0
 - 3) door(s): 2 overhead garage bay doors slightly off-center along elevation
 - 4) other: N/A

- b. Side: direction: WEST
- 1) bays: 2
 - 2) windows: 1 single 1/1-sash window with wood trim centered on elevation
 - 3) door(s): 1 single wood plank door to right of window
 - 4) other: N/A
- c. Side: direction: EAST
- 1) bays: 1
 - 2) windows: 1 single 1/1-sash window with wood trim centered on elevation
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: NORTH
- 1) bays: 1
 - 2) windows: 1 single 1/1-sash window with wood trim centered on elevation
 - 3) door(s): 0
 - 4) other: N/A

9. INTERIOR (if accessible):

- a) Floor plan N/A
- b) Partition/walls N/A
- c) Finishes N/A
- d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY

CRS # S-8495

MAP FORM

1. ADDRESS/LOCATION: 20041 Gravel Hill Road, Georgetown, DE 19947


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-8495

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-8495

1. HISTORIC NAME/FUNCTION: Dwelling, E Side of Road 30 (from previous survey)
James Koeppel House / residence

2. ADDRESS/LOCATION: 20041 Gravel Hill Road, Georgetown, DE 19947

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: Vinyl siding, asphalt-shingle roof, replacement 1/1 windows, enclosed front porch, rear handicap access ramp, large full-width addition on south elevation, utility shed addition on rear; 2 modern garages and gazebo

5. SETTING INTEGRITY: Modern commercial properties are located across the road to the west (including a modern mobile home) and to the south. DelDOT's Gravel Hill Maintenance Yard is beyond the commercial property to the west.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
1	CRS 3 Secondary Building Form	Garage
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Wendy Zug-Gilbert

Principal Investigator name: Wendy Zug-Gilbert

Principal Investigator signature: Michael C. Hahn, AICP for Wendy Zug-Gilbert

Organization: A&HC, Inc. Date: Nov. 2009

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-8495

Originally surveyed for the Sussex East-West Corridor Study in 1994.

Resurveyed for the US 9 Intersection Improvements Project by A&HC, Inc.
Resource given the name "James Koepfel House" after the first home owner

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-8495

Date Nov. 2009 Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 1. James Koeppel House Façade north/west elevation. 2. Rear - east elevation. 3. rear south/east elevation. 4: south elevation.
(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

Page 1 of 2

1: Façade north/west elevation



2: Rear - east elevation



3: south/east elevation



4: south elevation





DELAWARE DIVISION OF HISTORICAL AND CULTURAL AFFAIRS
STATE HISTORIC PRESERVATION OFFICE
21 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-8495

Date Nov. 2009 Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 5: three garages at the rear of the dwelling facing east. 6: garage - south west elevation.
(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

Page 2 of 2

5: three garages to the rear of dwelling facing east



6: garage - south west elevation





CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-8496

- 1. ADDRESS/LOCATION: 20059 Gravel Hill Road, Georgetown, DE 19947
- 2. FUNCTION(S): historic single-family dwelling current: same
- 3. YEAR BUILT: 1951 CIRCA?: ARCHITECT/BUILDER: unknown
- 4. STYLE OR FLOOR PLAN: Minimal Traditional

- 5. INTEGRITY: original site moved
if moved, from where N/A other location's CRS # year

- list major alterations and additions with years (if known) year
- a. N/A
- b.

- 6. CURRENT CONDITION: excellent good fair poor
- 7. DESCRIPTION: (Describe resource as completely as possible. Use N/A for not applicable; leave no blanks)

- a. Overall shape: square, consisting of a rectangular side-gable front portion with rear portion under a combo shed & gable roof
 Stories: 1
 Additions: N/A
- b. Structural system (if known): frame
- c. Foundation: materials: concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): asbestos siding
- e. Roof: shape: gable
 materials: asphalt shingle
 cornice: N/A
 dormers: N/A
 chimney: location(s): 1 massive exterior brick chimney on N gable end

- 8. DESCRIPTION OF ELEVATIONS:
 - a. Facade: Direction: WEST
 - 1) Bays 3
 - 2) Windows 4 (1 triple unit with central picture window; 1 single window)
 - fenestration irregular
 - type 6/1 wood sash (single); 4/1 wood sash (flanking picture window)
 - trim wood
 - shutters N/A

Facade (cont'd)

- 3) Door(s) 1
location centered on façade
type wood 4-panel door with upper fanlight window; glass storm door
trim wood
- 4) Porch(es) shallow gabled hood with arched cornice supported by slightly tapered wood posts on concrete pad (Colonial Revival elements)
- b. Side: Direction: NORTH
- 1) Bays 2
- 2) Windows 3 (a triple unit with larger central window)
fenestration irregular
type triple unit consists of central 6/1-sash window flanked by narrow 4/1-sash windows
trim wood
shutters N/A
- 3) Door(s) 0
location N/A
type N/A
trim N/A
- 4) Porch(es) N/A
- c. Side: Direction: SOUTH
- 1) Bays 3
- 2) Windows 3
fenestration irregular
type 6/1 wood sash
trim wood
shutters N/A
- 3) Door(s) 0
location N/A
type N/A
trim N/A
- 4) Porch(es) N/A
- d. Rear: Direction: EAST
- 1) Bays 5 (4 bays in shed-roof section; 1 bay in gable-roof section)
- 2) Windows 4
fenestration irregular
type large single-pane fixed sash flanking the door; 6/1 wood sash in outer bays
trim wood
shutters N/A
- 3) Door(s) 1
location centered on elevation
type wood 6-panel door with aluminum & glass storm door
trim wood
- 4) Porch(es) N/A

9. INTERIOR: N/A

10. LANDSCAPING: Dwelling sits on a 0.96-acre lot (96ft x450ft) on the east side of Gravel Hill Road with a gravel driveway along its south side to access a parking area at the rear.

11. OTHER COMMENTS: There is a modern pressure-treated shed to the rear of the dwelling.



CULTURAL RESOURCE SURVEY

CRS # S-8496

MAP FORM

1. ADDRESS/LOCATION: 20059 Gravel Hill Road, Georgetown, DE 19947


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-8496

INDICATE NORTH ON PLAN



USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-8496

1. HISTORIC NAME/FUNCTION: Dwelling, E Side of Road 30 (from previous survey)
Henry Graves House / residence

2. ADDRESS/LOCATION: 20059 Gravel Hill Road, Georgetown, DE 19947

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: One of the two pre-fab sheds in the rear is gone.

5. SETTING INTEGRITY: Modern commercial properties are located across the road to the west (including a modern mobile home) and to the south. DelDOT's Gravel Hill Maintenance Yard is beyond the commercial property to the west.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Wendy Zug-Gilbert

Principal Investigator name: Wendy Zug-Gilbert

Principal Investigator signature: Michael C. Hahn, AICP for Wendy Zug-Gilbert

Organization: A&HC, Inc. Date: Nov. 2009

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-8496

Originally surveyed for the Sussex East-West Corridor Study in 1994.

Resurveyed for the US 9 Intersection Improvements Project by A&HC, Inc.
Resource given the name "Henry Graves House" after the first home owner

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-8496

Date Nov 2009 Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 1: Façade - west elevation. 2: Rear - east elevation.

(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

1: Façade - west elevation



2: Rear- east elevation





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-12232
SPO Map 16-17-11
Hundred Georgetown
Quad Harbeson
Other 1-35-11.00-83.00

- 1. HISTORIC NAME/FUNCTION: Gravel Hill Commercial Property / garage
- 2. ADDRESS/LOCATION: 24572-24580 Lewes Georgetown Hwy, Georgetown, DE 19947
- 3. TOWN/NEAREST TOWN: Gravel Hill vicinity?
- 4. MAIN TYPE OF RESOURCE: building structure site object
landscape district
- 5. MAIN FUNCTION OF PROPERTY: Mexican Restaurant (Zunsal) & Grocery
- 6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US 9 Intersection Improvements Project, Sussex County, Delaware

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Commercial building
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Wendy Zug-Gilbert

Principal Investigator name: Wendy Zug-Gilbert

Principal Investigator signature: Michael C. Hahn, AICP for Wendy Zug-Gilbert

Organization: A&HC, Inc. Date: Nov 2009

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-12232

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|-----------------------------------------------------------|------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input checked="" type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-12232

1. ADDRESS/LOCATION: 24572-24580 Lewes Georgetown Hwy, Georgetown, DE 19947
2. FUNCTION(S): historic garage current restaurant/grocery
3. YEAR BUILT: 1945 CIRCA? ARCHITECT/BUILDER: unknown
4. STYLE OR FLOOR PLAN: vernacular commercial
5. INTEGRITY: original site moved
 if moved, from where _____ other location's CRS # year

list major alterations and additions with years (if known)

	<u>year</u>
a. west end (former barber shop)	unknown
b. infill addition to connect 2 outer structures	unknown

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangular (main block), but additions make the current shape irregular Stories: 1
 Additions: 4 separate 1-story masonry additions off the west side of the original structure
- b. Structural system (if known): masonry / concrete-block
- c. Foundation: materials: not visible
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): wood siding (in vertical & diagonal patterns); wood shingle detailing; concrete-block (rear); corrugated metal (roofless enclosure)
- e. Roof: shape: flat
 materials: tarred
 cornice: false pent roof
 dormers: N/A
 chimney: location(s): 1 exterior concrete-block chimney at SW corner; 2 interior concrete-block chimneys on main block

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: NORTH
- 1) Bays 9
- 2) Windows fenestration 5
 type plate; 2/2 sash
 trim metal
 shutters vinyl louvered

Facade (cont'd)

- | | | |
|----|-----------|---------------------------------------------------------|
| 3) | Door(s) | 3 |
| | location | 2 in the original block & 1 in the westernmost addition |
| | type | glass |
| | trim | metal |
| 4) | Porch(es) | N/A |

b. Side: Direction: EAST

- | | | |
|----|--------------|-----|
| 1) | Bays | 3 |
| 2) | Windows | 0 |
| | fenestration | N/A |
| | type | N/A |
| | trim | N/A |
| | shutters | N/A |
| 3) | Door(s) | 0 |
| | location | N/A |
| | type | N/A |
| | trim | N/A |
| 4) | Porch(es) | N/A |

c. Side: Direction: WEST

- | | | |
|----|--------------|-----|
| 1) | Bays | 3 |
| 2) | Windows | 0 |
| | fenestration | N/A |
| | type | N/A |
| | trim | N/A |
| | shutters | N/A |
| 3) | Door(s) | 0 |
| | location | N/A |
| | type | N/A |
| | trim | N/A |
| 4) | Porch(es) | N/A |

d. Rear: Direction: SOUTH

- | | | |
|----|--------------|--------------------------------------|
| 1) | Bays | 2 |
| 2) | Windows | |
| | fenestration | irregular |
| | type | small 2-pane units under the cornice |
| | trim | metal |
| | shutters | N/A |
| 3) | Door(s) | |
| | location | |
| | type | |
| | trim | N/A |
| 4) | Porch(es) | N/A |

9. INTERIOR: N/A

10. LANDSCAPING: building sits approximately 10 feet off US 9 in the middle of a large gravel parking lot

11. OTHER COMMENTS: modern garage & mobile home sit to the rear (south) of the building



CULTURAL RESOURCE SURVEY

CRS # S-12232

MAP FORM

1. ADDRESS/LOCATION: 24572-24580 Lewes Georgetown Hwy, Georgetown, DE 19947


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # **S-12232**

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-12232

Date Nov. 2009 Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 1: Commercial Property Façade north/east.
2: east elevation. 3: east and rear elevation. 4: rear west elevation.
(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

Page 1 of 2

1: Façade north/east



2: east elevation



3: east elevation



4: west elevation





DELAWARE DIVISION OF HISTORICAL AND CULTURAL AFFAIRS
STATE HISTORIC PRESERVATION OFFICE
21 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-12232

Date Nov. 2009 Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 5: rear elevation looking northwest. 6: rear elevation looking northeast
(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

Page 2 of 2

5: rear elevation looking northwest



6: rear elevation looking northeast





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-12233
SPO Map 16-17-11
Hundred Georgetown
Quad Harbeson
Other 1-35-11.00-77.00

- HISTORIC NAME/FUNCTION: Alice Hancock House / residence
- ADDRESS/LOCATION: 24634 Lewes Georgetown Hwy, Georgetown, DE 19947
- TOWN/NEAREST TOWN: Gravel Hill vicinity?
- MAIN TYPE OF RESOURCE: building structure site object
landscape district
- MAIN FUNCTION OF PROPERTY: residential
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US 9 Intersection Improvements Project, Sussex County, Delaware

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Wendy Zug-Gilbert

Principal Investigator name: Wendy Zug-Gilbert

Principal Investigator signature: Michael C. Hahn, AICP for Wendy Zug-Gilbert

Organization: A&HC, Inc. Date: Nov 2009

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-12233

1. ADDRESS/LOCATION: 24634 Lewes Georgetown Hwy, Georgetown, DE 19947
2. FUNCTION(S): historic single-family dwelling current: same
3. YEAR BUILT: 1945 CIRCA?: ARCHITECT/BUILDER: unknown
4. STYLE OR FLOOR PLAN: Double-pile cottage with front extension
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. shed-roofed wall dormer on rear unknown
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe resource as completely as possible. Use N/A for not applicable; leave no blanks)
- a. Overall shape: L-shaped Stories: 1½
Additions:
- b. Structural system (if known): unknown
- c. Foundation: materials: not visible
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): brick (house) & aluminum siding (wall dormer)
- e. Roof: shape: hipped with front-gable wing at NW corner
materials: asphalt shingle
cornice: N/A
dormers: 3-bay shed-roof frame wall dormer on rear (S) slope
chimney: location(s): 1 massive exterior brick chimney on facade

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: NORTH
- | | |
|--------------|---------------|
| 1) Bays | 5 |
| 2) Windows | 4 |
| fenestration | irregular |
| type | 1/1 wood sash |
| trim | wood |
| shutters | N/A |

Facade (cont'd)

- 3) Door(s) 1
location in a small projecting front-gable vestibule adjacent to the left (E) of front-gable wing
type wood with strap hinges & aluminum storm door
trim wood; framed by a arched opening featuring a triple course of brick; wooden "sunburst" fanlight in arch above door
- 4) Porch(es) N/A
- b. Side: Direction: WEST
- 1) Bays 3
- 2) Windows 2 (1 paired)
fenestration irregular
type single-pane crank-out
trim wood
shutters N/A
- 3) Door(s) 0
location N/A
type N/A
trim N/A
- 4) Porch(es) full-width porch forms the easternmost bay of the dwelling – front half is open with arched openings and rear half is screened
- c. Side: Direction: EAST
- 1) Bays 4
- 2) Windows 4
fenestration regular
type 1/1 wood sash
trim wood
shutters N/A
- 3) Door(s) 0
location N/A
type N/A
trim N/A
- 4) Porch(es) N/A
- d. Rear: Direction: SOUTH
- 1) Bays 6
- 2) Windows 5
fenestration regular
type 1/1 wood sash
trim wood
shutters N/A
- 3) Door(s) 0
location N/A
type N/A
trim N/A
- 4) Porch(es) screened porch in easternmost bay of this elevation

9. INTERIOR: N/A

10. LANDSCAPING: This dwelling sits on a 1.62-acre lot on the south side of the Lewes Georgetown Hwy with a gravel drive to the east of the house.

11. OTHER COMMENTS: To the rear (south) of the house is a large modern gambrel-roof horse barn. In 2009, a modern double-wide dwelling was built on the east half of the lot.



CULTURAL RESOURCE SURVEY

CRS # S 12233

MAP FORM

1. ADDRESS/LOCATION: 24634 Lewes Georgetown Hwy, Georgetown, DE 19947


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-12233

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-12233

Date Nov 2009 Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 1:Alice Hancock House. Façade n/w. 2: east elevation. 3: Rear south elevation.
(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

1: Façade n/w



2: east elevation



3: Rear south elevation





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-12234
SPO Map 16-17-11
Hundred Georgetown
Quad Harbeson
Other 1-35-11.00-76.00

1. HISTORIC NAME/FUNCTION: Joseph Clauser House / residence
2. ADDRESS/LOCATION: 24664 Lewes Georgetown Hwy, Georgetown, DE 19947
3. TOWN/NEAREST TOWN: Gravel Hill vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: residential
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US 9 Intersection Improvements Project, Sussex County, Delaware

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
1	CRS 3 Secondary Building Form	Shed
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Wendy Zug-Gilbert

Principal Investigator name: Wendy Zug-Gilbert

Principal Investigator signature: Michael C. Hahn, AICP for Wendy Zug-Gilbert

Organization: A&HC, Inc. Date: Nov 2009

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-12234

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY

CRS-1



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-12234

1. ADDRESS/LOCATION: 24664 Lewes Georgetown Hwy, Georgetown, DE 19947
2. FUNCTION(S): historic single-family dwelling current: same
3. YEAR BUILT: 1953 CIRCA?: ARCHITECT/BUILDER: unknown
4. STYLE OR FLOOR PLAN: Minimal Ranch
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. enclosed carport at W end main block	1970
b. sunroom addition and deck at rear	1980

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe resource as completely as possible. Use N/A for not applicable; leave no blanks)
- a. Overall shape: L-shape (rectangular main block & rear addition) Stories: 1
 Additions: sunroom & deck added to rear of main block
- b. Structural system (if known): frame
- c. Foundation: materials: concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): asbestos siding
- e. Roof: shape: side-gable
 materials: asphalt shingle
 cornice: N/A
 dormers: N/A
 chimney: location(s): 1 interior brick chimney on rear slope of roof at W end of main block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: NORTH
- 1) Bays 4
- 2) Windows 7 (3 in bay window & 2 paired)
- fenestration irregular
- type 1/1 wood sash
- trim wood
- shutters vinyl louvered

Facade (cont'd)


- 3) Door(s) 1
 location off-center, in 3rd bay of façade
 type wood panel with aluminum storm door and vinyl louvered shutters
 trim wood
- 4) Porch(es) concrete stoop

- b. Side: Direction: WEST
- 1) Bays 5
- 2) Windows 5 (2 paired & 1 greenhouse attachment)
 fenestration irregular
 type 1/1 wood sash (main block); paired jalousie (sunroom addition)
 trim wood
 shutters vinyl louvered
- 3) Door(s) 2
 location 1 in main block & 1 in sunroom addition
 type wood with aluminum storm door
 trim wood
- 4) Porch(es) ground-level shed-roof with squared wood posts and concrete pad at door in main block; elevated shed-roof wood deck porch at sunroom door
- c. Side: Direction: EAST
- 1) Bays 4
- 2) Windows 3
 fenestration regular
 type 1/1 wood sash (main block) & jalousie (sunroom addition)
 trim wood
 shutters vinyl louvered
- 3) Door(s) 1
 location sunroom addition
 type wood with aluminum storm door
 trim wood
- 4) Porch(es) wooden deck
- d. Rear: Direction: SOUTH
- 1) Bays 6
- 2) Windows 7 (3 single; 1 paired; 2 jalousie)
 fenestration irregular
 type 1/1 wood sash & jalousie
 trim wood
 shutters vinyl louvered
- 3) Door(s) 0
 location N/A
 type N/A
 trim N/A
- 4) Porch(es) wooden deck

9. INTERIOR: N/A

10. LANDSCAPING: This dwelling sits on a 1.09-acre lot on the south side of Lewes Georgetown Hwy with a gravel driveway at its west side to access the rear. The property has a number of scrubby pines filling the back yard and forming the west property line. The east property line, along the driveway, is also delineated by a row of mature trees.

11. OTHER COMMENTS: There are 3 sheds, 2 of which are modern, to the rear (south) of the house.



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-12234

1. ADDRESS/LOCATION: 24664 Lewes Georgetown Hwy, Georgetown, DE 19947
2. FUNCTION(S): historic chicken house current shed
3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: unknown
4. STYLE/FLOOR PLAN: rectangular (2 shed-roof sections at different pitches)

5. INTEGRITY: original site moved
- | | | |
|-----------------------------|----------------------------------|-------------|
| <u>if moved, from where</u> | <u>original location's CRS #</u> | <u>year</u> |
| <u>N/A</u> | <u>N/A</u> | |

- | | |
|-------------------------------------------------------------------|-------------|
| <u>list major alterations and additions with years (if known)</u> | <u>year</u> |
| a. <u>N/A</u> | |
| b. | |

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system frame
- b. Number of stories 1
- c. Wall coverings wood shingles
- d. Foundation concrete block
- e. Roof structural system shallow shed-roof
coverings asphalt shingle
openings N/A

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: SOUTH
- 1) bays: 2
- 2) windows: 0
- 3) door(s): 2 wood plank doors
- 4) other: N/A

- b. Side: direction: WEST
 - 1) bays: 1
 - 2) windows: 1 (jalousie)
 - 3) door(s): 0
 - 4) other: N/A

- c. Side: direction: EAST
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A

- d. Rear: direction: NORTH
 - 1) bays: 2
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan N/A

b) Partition/walls N/A

c) Finishes N/A

d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY

CRS # S-12234

MAP FORM

1. ADDRESS/LOCATION: 24664 Lewes Georgetown Hwy, Georgetown, DE 19947


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-12234

Date Nov. 2009 Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 1: Joseph Clauser House Façade looking n/w. 2: west elevation. 3: east elevation. 4: Former chicken house that is used as shed.
(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

1: façade looking n/w



2: west elevation



3: east elevation



4: Former chicken house used as shed





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-12235
SPO Map 16-17-11
Hundred Georgetown
Quad Harbeson
Other 1-35-11.00-63.00

- 1. HISTORIC NAME/FUNCTION: Floyd Harris House / residence
- 2. ADDRESS/LOCATION: 24617 Lewes Georgetown Hwy, Georgetown, DE 19947
- 3. TOWN/NEAREST TOWN: Gravel Hill vicinity?
- 4. MAIN TYPE OF RESOURCE: building structure site object
landscape district
- 5. MAIN FUNCTION OF PROPERTY: residential
- 6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US 9 Intersection Improvements Project, Sussex County, Delaware

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
1	CRS 3 Secondary Building Form	Garage
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Wendy Zug-Gilbert

Principal Investigator name: Wendy Zug-Gilbert

Principal Investigator signature: Michael C. Hahn, AICP for Wendy Zug-Gilbert

Organization: A&HC, Inc. Date: Nov 2009

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-12235

1. ADDRESS/LOCATION: 24617 Lewes Georgetown Hwy, Georgetown, DE 19947
2. FUNCTION(S): historic single-family dwelling current: same
3. YEAR BUILT: 1956 CIRCA?: ARCHITECT/BUILDER: unknown
4. STYLE OR FLOOR PLAN: Minimal Ranch
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. converted garage at west end of main block	1970
b. sunroom addition at west end of former garage	1980
c. utility room addition off rear of main block	1980

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe resource as completely as possible. Use N/A for not applicable; leave no blanks)
- a. Overall shape: rectangular main block with additions on west end and rear Stories: 1
 Additions: shed-roof sunroom added to SW corner of main block
- b. Structural system (if known): frame
- c. Foundation: materials: concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): aluminum siding
- e. Roof: shape: side-gable
 materials: asphalt shingle
 cornice: N/A
 dormers: N/A
 chimney: location(s): N/A

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: SOUTH
- 1) Bays 6
- 2) Windows 8 (2 single; 1 paired; 1 multi-pane picture; 3 large jalousie)
- fenestration irregular
- type 1/1 wood sash
- trim wood
- shutters aluminum louvered

Facade (cont'd)

- 3) Door(s) 1
 location slightly off-center (to west)
 type wood panel with 6-divided lights in upper quarter & aluminum storm door
 trim wood
- 4) Porch(es) small gabled hood with squared wood posts and wood balustrade on sides;
 concrete pad floor

b. Side: Direction:

WEST

- 1) Bays 3
- 2) Windows 4 (single & 3 jalousie)
 fenestration irregular
 type 1/1 wood sash; jalousie (sunroom addition)
 trim wood
 shutters aluminum louvered
- 3) Door(s) 1
 location in rear bay of main block
 type wood with aluminum storm door
 trim wood
- 4) Porch(es) screened vestibule under overhanging gabled roof; concrete pad floor

c. Side: Direction:

EAST

- 1) Bays 2
- 2) Windows 2
 fenestration regular
 type 1/1 wood sash
 trim wood
 shutters aluminum louvered
- 3) Door(s) 0
 location N/A
 type N/A
 trim N/A
- 4) Porch(es) 0

d. Rear: Direction:

NORTH

- 1) Bays 4
- 2) Windows 3
 fenestration irregular
 type 1/1 wood sash
 trim wood
 shutters aluminum louvered
- 3) Door(s) 1
 location projecting utility room
 type paneled steel
 trim wood
- 4) Porch(es) 0

9. INTERIOR: N/A

10. LANDSCAPING: dwelling sits on a 0.45-acre lot on the north side of Lewes Georgetown Hwy with a gravel driveway at its west side accessing a free-standing garage to the rear.

11. OTHER COMMENTS:

USE BLACK INK ONLY

CRS-2



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-12235

1. ADDRESS/LOCATION: 24617 Gravel Hill Road, Georgetown, DE 19947

2. FUNCTION(S): historic garage current same

3. YEAR BUILT: 1956 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. <u>N/A</u>	
b.	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system frame
- b. Number of stories 1
- c. Wall coverings aluminum siding
- d. Foundation concrete block
- e. Roof structural system front-gable
- coverings asphalt shingle
- openings N/A

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: SOUTH
 - 1) bays: 2
 - 2) windows: 0
 - 3) door(s): 2 overhead garage bay doors
 - 4) other: N/A

- b. Side: direction: WEST
- 1) bays: 1
 - 2) windows: 1 single 1/1-sash window with wood trim centered on elevation
 - 3) door(s): 0
 - 4) other: N/A

- c. Side: direction: EAST
- 1) bays: 1
 - 2) windows: 1 single 1/1-sash window with wood trim centered on elevation
 - 3) door(s): 0
 - 4) other: N/A

- d. Rear: direction: NORTH
- 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan N/A

b) Partition/walls N/A

c) Finishes N/A

d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY

CRS # S-12235

MAP FORM

1. ADDRESS/LOCATION: 24617 Lewes Georgetown Hwy, Georgetown, DE 19947


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-12235

INDICATE NORTH ON PLAN



US 9 (Lewes - Georgetown Highway)

 = Modern (post - 1962)



USE BLACK INK ONLY

CRS-9



CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-12235

Date Nov. 2009 Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 1:Floyd Harris House Façade- south. 2: west elevation. 3: east elevation. 4: Two bay garage south elevation.
(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

1: Façade - south



2: west elevation



3: east elevation



4: Two bay garage south elevation





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-12236
SPO Map 16-17-11
Hundred Georgetown
Quad Harbeson
Other 1-35-11.00-64.00

- HISTORIC NAME/FUNCTION: Samuel Burns Property / residence & equipment storage garage
- ADDRESS/LOCATION: 24631-24635 Lewes Georgetown Hwy, Georgetown, DE 19947
- TOWN/NEAREST TOWN: Gravel Hill vicinity?
- MAIN TYPE OF RESOURCE: building structure site object
landscape district
- MAIN FUNCTION OF PROPERTY: residential / commercial
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US 9 Intersection Improvements Project, Sussex County, Delaware

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
2	CRS 2 Main Building Form	Dwelling; Commercial
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Wendy Zug-Gilbert

Principal Investigator name: Wendy Zug-Gilbert

Principal Investigator signature: Michael C. Hahn, AICP for Wendy Zug-Gilbert

Organization: A&HC, Inc. Date: Nov 2009

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|-----------------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input checked="" type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-12236

- 1. ADDRESS/LOCATION: 24631 Lewes Georgetown Hwy, Georgetown, DE 19947
- 2. FUNCTION(S): historic single-family dwelling current: same
- 3. YEAR BUILT: 1922 CIRCA?: ARCHITECT/BUILDER: unknown
- 4. STYLE OR FLOOR PLAN: Bungalow

- 5. INTEGRITY: original site moved
- | | | |
|-----------------------------|-------------------------------|-------------|
| <u>if moved, from where</u> | <u>other location's CRS #</u> | <u>year</u> |
| N/A | | |

<u>list major alterations and additions with years (if known)</u>		<u>year</u>
a. eastern 1-bay block added to main block		1950s
b. sunroom addition off rear (N) of main block		1970s
c.		

- 6. CURRENT CONDITION: excellent good fair poor
- 7. DESCRIPTION: (Describe resource as completely as possible. Use N/A for not applicable; leave no blanks)

- a. Overall shape: L-shaped (rectangular with rear addition) Stories: 1½
Additions: 1-bay block added to east gable end of dwelling
gable-roof sunroom added on rear of main block
- b. Structural system (if known): frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): brick; aluminum siding
- e. Roof: shape: side-gable
materials: asphalt shingle
cornice: N/A
dormers: shed dormer on façade and rear
chimney: location(s): exterior brick chimney on western gable end

- 8. DESCRIPTION OF ELEVATIONS:
 - a. Facade: Direction: SOUTH
 - 1) Bays 3
 - 2) Windows 2
 - fenestration irregular
 - type 8/8 wood sash; large multi-pane picture window
 - trim wood
 - shutters N/A

Facade (cont'd)

- 3) Door(s) 1
location center bay
type wood panel with 9-divided lights in upper half
trim wood
- 4) Porch(es) partial width, concrete-pad porch under overhanging roof of main block;
wood tapered column supports
- b. Side: Direction: WEST
- 1) Bays 6 (3 in house; 3 in sunroom addition)
- 2) Windows 6
fenestration regular
type 1 - 8/8 wood sash; 1 - 6/6 wood sash; 1 casement; 3 jalousie (sunroom)
trim wood
shutters N/A
- 3) Door(s) 0
location N/A
type N/A
trim N/A
- 4) Porch(es) 0
- c. Side: Direction: EAST
- 1) Bays 7 (3 in house; 4 in sunroom addition)
- 2) Windows 5
fenestration regular
type 2 - 8/8 wood sash; 3 jalousie (sunroom)
trim wood
shutters N/A
- 3) Door(s) 1
location central bay of house
type wood panel with 9-divided lights in upper half & aluminum storm door
trim wood
- 4) Porch(es) 0
- d. Rear: Direction: NORTH
- 1) Bays 5
- 2) Windows 4
fenestration irregular
type jalousie
trim wood
shutters N/A
- 3) Door(s) 1
location sunroom
type aluminum storm door
trim wood
- 4) Porch(es) 0

9. INTERIOR: N/A

10. LANDSCAPING: This dwelling sits on a fenced 1.12-acre lot on the north side of Lewes Georgetown Hwy, which it shares with a large commercial building that sits near the rear of the lot. The property is heavily wooded around the house. A gravel parking area is located to the east of the house, in front of the store.

11. OTHER COMMENTS: Associated with this residence are a modern shed, pergola, and in-ground swimming pool at the rear of the property.

USE BLACK INK ONLY

CRS-2



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-12236

- 1. ADDRESS/LOCATION: 24635 Lewes Georgetown Hwy, Georgetown, DE 19947
- 2. FUNCTION(S): historic garage current: pet store
- 3. YEAR BUILT: 1954 CIRCA?: ARCHITECT/BUILDER: unknown
- 4. STYLE OR FLOOR PLAN: vernacular; square block

- 5. INTEGRITY: original site moved
if moved, from where N/A other location's CRS # year

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. numerous additions to create current form (under one roof)	1970-90
b. office addition off west side	1980s
c.	

- 6. CURRENT CONDITION: excellent good fair poor
- 7. DESCRIPTION: (Describe resource as completely as possible. Use N/A for not applicable; leave no blanks)
 - a. Overall shape: square Stories: 1
Additions: numerous additions
 - b. Structural system (if known): concrete block
 - c. Foundation: materials: concrete block
basement: full partial not visible no basement
 - d. Exterior walls (original if visible& any subsequent coverings): aluminum siding; corrugated metal
 - e. Roof: shape: front-gable (shallow slopes at different angles); pent roof along full length of facade
materials: unknown
cornice: N/A
dormers: N/A
chimney: location(s): N/A

- 8. DESCRIPTION OF ELEVATIONS:
 - a. Facade: Direction: SOUTH
 - 1) Bays 4
 - 2) Windows 1
 - fenestration irregular
 - type plate glass
 - trim wood
 - shutters N/A

Facade (cont'd)

- 3) Door(s) 3
 location
 type 2 steel; 1 wood with 9-divided lights in upper half;
 trim wood
- 4) Porch(es) concrete pad along facade

b. Side: Direction: WEST

- 1) Bays 4
- 2) Windows 3
 fenestration irregular
 type large single-pane fixed sash
 trim wood
 shutters N/A
- 3) Door(s) 1
 location near center of elevation
 type boarded over
 trim wood
- 4) Porch(es) 0

c. Side: Direction: EAST

- 1) Bays 2
- 2) Windows 0
 fenestration irregular
 type N/A
 trim N/A
 shutters N/A
- 3) Door(s) 2
 location near center of elevation
 type 1 steel with 9-divided light in upper half; 1 overhead garage bay door
 trim wood
- 4) Porch(es) gabled hood at steel door

d. Rear: Direction: NORTH

- 1) Bays 1
- 2) Windows 0
 fenestration N/A
 type N/A
 trim N/A
 shutters N/A
- 3) Door(s) 0
 location N/A
 type N/A
 trim N/A
- 4) Porch(es) 0

9. INTERIOR: N/A

10. LANDSCAPING: This large commercial building sits near the rear of the lot with a graveled parking area in front of it. The house on this parcel sits to the southwest of the store, along the highway.

11. OTHER COMMENTS:

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY

CRS # S-12236

MAP FORM

1. ADDRESS/LOCATION: 24631-24635 Lewes Georgetown Hwy, Georgetown, DE 19947


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-12236

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-12236

Date Nov. 2009

Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 1: Samuel Burns Property Façade south elevation. 2: south and east elevation. 3: west elevation. 4: rear north east elevation (size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

Page 1 of 3

1: Samuel Burns Property Façade south elevation



2: south and east elevation



3: west elevation



4: rear north east elevation





CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-12236

Date Nov. 2009

Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 5: Façade – Burns Pet Shop south and east elevation. 6: east elevation. 7: rear north elevation. 8: west elevation.
(size photograph 3” on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

Page 2 of 3

5: Façade - Burns Pet Shop south and east elevation



6: east elevation



7: rear north elevation



8: west elevation





CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-12236

Date Nov. 2009

Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 9: south and west elevation.
(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

Page 3 of 3

9: south and west elevation





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-12237
SPO Map 16-17-11
Hundred Georgetown
Quad Harbeson
Other 1-35-11.00-75.00

1. HISTORIC NAME/FUNCTION: Harry Larson House / residence
2. ADDRESS/LOCATION: 24676 Lewes Georgetown Hwy, Georgetown, DE 19947
3. TOWN/NEAREST TOWN: Gravel Hill vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: residential
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US 9 Intersection Improvements Project, Sussex County, Delaware

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
1	CRS 3 Secondary Building Form	Shed
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Wendy Zug-Gilbert

Principal Investigator name: Wendy Zug-Gilbert

Principal Investigator signature: Michael C. Hahn, AICP for Wendy Zug-Gilbert

Organization: A&HC, Inc. Date: Nov 2009

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-12237

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY

CRS-1



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-12237

1. ADDRESS/LOCATION: 24676 Lewes Georgetown Hwy, Georgetown, DE 19947
2. FUNCTION(S): historic single-family dwelling current: same
3. YEAR BUILT: 1947 CIRCA?: ARCHITECT/BUILDER: unknown
4. STYLE OR FLOOR PLAN: Minimal Ranch
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. addition on east gable end of main block	unknown
b. addition on west gable end and façade of main block	unknown

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe resource as completely as possible. Use N/A for not applicable; leave no blanks)
- a. Overall shape: irregular Stories: 1
Additions: additions on east and west/facade sides of main block
 - b. Structural system (if known): frame
 - c. Foundation: materials: concrete block
basement: full partial not visible no basement
 - d. Exterior walls (original if visible& any subsequent coverings): asbestos siding
 - e. Roof: shape: side-gable
materials: asphalt shingle
cornice: N/A
dormers: N/A
chimney: location(s): 2 exterior concrete-block chimneys on rear wall of main block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: NORTH
 - 1) Bays 5
 - 2) Windows 8 (2 Chicago-style windows w/3 in each & 2 single)
 - fenestration irregular
 - type 1/1 wood sash
 - trim wood
 - shutters plastic louvered (on Chicago-style windows only)

Facade (cont'd)

- 3) Door(s) 1
 location in inverse corner made by the main block and west addition
 type wood with aluminum storm door
 trim wood
- 4) Porch(es) concrete stoop

b. Side: Direction: WEST

- 1) Bays 4
- 2) Windows 6 (2 single; 2 paired)
 fenestration irregular
 type 1/1 wood sash; 6-pane casement window (1 of the paired)
 trim wood
 shutters N/A
- 3) Door(s) 0
 location N/A
 type N/A
 trim N/A
- 4) Porch(es) N/A

c. Side: Direction: EAST

- 1) Bays 5
- 2) Windows 4
 fenestration irregular
 type 1/1 wood sash
 trim wood
 shutters N/A
- 3) Door(s) 1
 location L-shaped wing
 type wood
 trim wood
- 4) Porch(es) N/A

d. Rear: Direction: SOUTH


- 1) Bays 7
- 2) Windows 7 (5 single; 1 paired)
 fenestration irregular
 type 1/1 wood sash
 trim wood
 shutters N/A
- 3) Door(s) 1
 location eastern addition
 type wood
 trim wood
- 4) Porch(es) N/A

9. INTERIOR: N/A

10. LANDSCAPING: This dwelling sits on a 1.1-acre lot on the south side of Lewes Georgetown Hwy with a gravel driveway at its east side. The property is heavily wooded with scrubby pine. The land behind and to the east of the property is also heavily wooded.

11. OTHER COMMENTS:

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-12237

1. ADDRESS/LOCATION: 24676 Lewes Georgetown Hwy, Georgetown, DE 19947

2. FUNCTION(S): historic shed current shed

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
-------------------------------------------------------------------	-------------

a. N/A

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system frame

b. Number of stories 1

c. Wall coverings vertical wood boards

d. Foundation on concrete blocks

e. Roof
 structural system front gable
 coverings asphalt shingle
 openings N/A

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: NORTH
- 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 1 (opening, no door)
 - 4) other: N/A

b. Side: direction: WEST
1) bays: 1
2) windows: 1 (opening, no window)
3) door(s): 0
4) other: N/A

c. Side: direction: EAST
1) bays: 1
2) windows: 1 (opening, no window)
3) door(s): 0
4) other: N/A

d. Rear: direction: NORTH
1) bays: 1
2) windows: 0
3) door(s): 0
4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan N/A

b) Partition/walls N/A

c) Finishes N/A

d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY

CRS # S-12237

MAP FORM

1. ADDRESS/LOCATION: 24676 Lewes Georgetown Hwy, Georgetown, DE 19947


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-12237

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-12237

Date Nov. 2009 Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 1: Harry Larson House Façade north. 2: rear s/e elevation. 3: west elevation. 4: sheds to the rear of the property.
(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

1: Façade north



2: rear south east elevation



3: west elevation



4: sheds to the rear of the property





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-12238
SPO Map 16-17-11
Hundred Georgetown
Quad Harbeson
Other 1-35-11.00-40.00

1. HISTORIC NAME/FUNCTION: Frances Graves House / residence
2. ADDRESS/LOCATION: 19050 Gravel Hill Road, Georgetown, DE 19947
3. TOWN/NEAREST TOWN: Gravel Hill vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
landscape district
5. MAIN FUNCTION OF PROPERTY: residential
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US 9 Intersection Improvements Project, Sussex County, Delaware

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
4	CRS 3 Secondary Building Form	Workshop, Garage, Shed
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Wendy Zug-Gilbert

Principal Investigator name: Wendy Zug-Gilbert

Principal Investigator signature: Michael C. Hahn, AICP for Wendy Zug-Gilbert

Organization: A&HC, Inc. Date: Nov 2009

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-12238

1. ADDRESS/LOCATION: 19050 Gravel Hill Road, Georgetown, DE 19947
2. FUNCTION(S): historic single-family dwelling current: same
3. YEAR BUILT: 1958 CIRCA?: ARCHITECT/BUILDER: unknown
4. STYLE OR FLOOR PLAN: Minimal Ranch
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. sunroom addition on rear elevation c. 1980
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe resource as completely as possible. Use N/A for not applicable; leave no blanks)
- a. Overall shape: irregular Stories: 1
Additions: sunroom
- b. Structural system (if known): unknown
- c. Foundation: materials: unknown
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): brick (veneer?); aluminum siding (gables)
- e. Roof: shape: side-gable
materials: asphalt shingle
cornice: N/A
dormers: N/A
chimney: location(s): exterior brick chimney centered on south gable end

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: WEST
- 1) Bays 4
- 2) Windows 7 (2 paired sets; 1 Chicago-style with large central window flanked by normal-size windows)
- fenestration irregular
- type 6/6 double-hung wood sash (paired); 4/4 double-hung wood sash (Chicago)
- trim wood
- shutters vinyl louvered


Facade (cont'd)

- | | | |
|----|------------------|----------------------------------------------------------------------------------------------------------|
| 3) | Door(s) | 1 |
| | location | in inverse corner made by the main block and front-gabled wing |
| | type | wood with aluminum storm door |
| | trim | wood |
| 4) | Porch(es) | brick-floored porch recessed under the front-gabled wing overhang and supported by a slender wooden post |
| b. | Side: Direction: | SOUTH |
| 1) | Bays | 6 |
| 2) | Windows | 6 (1 single & 5 casement) |
| | fenestration | irregular |
| | type | 6/6 wood sash; double casement |
| | trim | wood |
| | shutters | vinyl louvered |
| 3) | Door(s) | 0 |
| | location | N/A |
| | type | N/A |
| | trim | N/A |
| 4) | Porch(es) | N/A |
| c. | Side: Direction: | NORTH |
| 1) | Bays | 7 (3 in main house; 4 in sunroom) |
| 2) | Windows | 8 |
| | fenestration | irregular |
| | type | 6/6 wood sash; double casement |
| | trim | wood |
| | shutters | vinyl louvered |
| 3) | Door(s) | 1 |
| | location | sunroom |
| | type | glass |
| | trim | wood |
| 4) | Porch(es) | N/A |
| d. | Rear: Direction: | EAST |
| 1) | Bays | 9 (5 in house; 4 in sunroom) |
| 2) | Windows | 10 (3 single; 2 paired; 3 casement) |
| | fenestration | irregular |
| | type | 6/6 wood sash; double casement |
| | trim | wood |
| | shutters | vinyl louvered |
| 3) | Door(s) | 1 |
| | location | sunroom |
| | type | glass |
| | trim | wood |
| 4) | Porch(es) | N/A |

9. INTERIOR: N/A

10. LANDSCAPING: This dwelling sits on a 3.74-acre lot on the west side of Gravel Hill Road with a paved driveway at its north side to access the outbuildings to the rear (west). The property has heavy tree cover at the rear with watered-filled gravel pits of DeIDOT behind the property.

11. OTHER COMMENTS: There are 2 workshops, 1 garage, and 1 shed (all mid-20th century) associated with this property.



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-12238

1. ADDRESS/LOCATION: 19050 Gravel Hill Road, Georgetown, DE 19947

2. FUNCTION(S): historic workshop current shed

3. YEAR BUILT: 1958 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. <u>N/A</u>	
b.	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system concrete block
- b. Number of stories 1
- c. Wall coverings painted concrete block; aluminum siding in gables
- d. Foundation concrete blocks
- e. Roof structural system front gable
- coverings asphalt shingle
- openings N/A


8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: EAST
 - 1) bays: 2
 - 2) windows: 1 (8/8 wood sash)
 - 3) door(s): 1 (9-light steel unit)
 - 4) other: N/A

- b. Side: direction: **SOUTH**
1) bays: **1**
2) windows: **2 (2/2 metal sash)**
3) door(s): **0**
4) other: **N/A**
- c. Side: direction: **NORTH**
1) bays: **1**
2) windows: **2 (2/2 metal sash)**
3) door(s): **0**
4) other: **N/A**
- d. Rear: direction: **WEST**
1) bays: **1**
2) windows: **0**
3) door(s): **0**
4) other: **exterior concrete-block chimney**

9. **INTERIOR (if accessible):**

- a) Floor plan **N/A**
- b) Partition/walls **N/A**
- c) Finishes **N/A**
- d) Furnishings/machinery **N/A**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-12238

1. ADDRESS/LOCATION: 19050 Gravel Hill Road, Georgetown, DE 19947

2. FUNCTION(S): historic workshop current shed

3. YEAR BUILT: 1961-68 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
-------------------------------------------------------------------	-------------

a. N/A

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system frame

b. Number of stories 1½

c. Wall coverings vinyl siding

d. Foundation metal skirting covering foundation

e. Roof
structural system front gable
coverings asphalt shingle
openings N/A

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: EAST
- 1) bays: 1
 - 2) windows: 1 (1/1 wood sash in end gable)
 - 3) door(s): 1 (9-light steel unit)
 - 4) other: N/A

b. Side: direction: SOUTH
1) bays: 1
2) windows: 1 (6/6 wood sash)
3) door(s): 0
4) other: N/A

c. Side: direction: NORTH
1) bays: 1
2) windows: 1 (6/6 wood sash)
3) door(s): 0
4) other: N/A

d. Rear: direction: WEST
1) bays: 1
2) windows: 0
3) door(s): 0
4) other: N/A


9. INTERIOR (if accessible):

a) Floor plan N/A

b) Partition/walls N/A

c) Finishes N/A

d) Furnishings/machinery N/A



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-12238

1. ADDRESS/LOCATION: 19050 Gravel Hill Road, Georgetown, DE 19947

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 1961-68 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
-------------------------------------------------------------------	-------------

a. N/A

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system concrete block

b. Number of stories 1

c. Wall coverings painted concrete block

d. Foundation concrete block

e. Roof
structural system shed roof
coverings metal
openings N/A

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: SOUTH

1) bays: 2

2) windows: 0


3) door(s): 2 overhead garage bay doors

4) other: N/A

- b. Side: direction: WEST
1) bays: 1
2) windows: 2 (2/2 metal sash)
3) door(s): 0
4) other: N/A
- c. Side: direction: EAST
1) bays: 1
2) windows: 0
3) door(s): 1 (metal)
4) other: N/A
- d. Rear: direction: NORTH
1) bays: 2
2) windows: 2 (single-pane fixed metal sash)
3) door(s): 0
4) other: exterior concrete-block chimney

9. INTERIOR (if accessible):

- a) Floor plan N/A
- b) Partition/walls N/A
- c) Finishes N/A
- d) Furnishings/machinery N/A



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-12238

1. ADDRESS/LOCATION: 19050 Gravel Hill Road, Georgetown, DE 19947

2. FUNCTION(S): historic shed current shed

3. YEAR BUILT: 1961-68 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. <u>N/A</u>	
b.	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system concrete block
- b. Number of stories 1
- c. Wall coverings painted concrete block
- d. Foundation concrete block
- e. Roof structural system shed roof
- coverings metal
- openings N/A

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: EAST
 - 1) bays: 3
 - 2) windows: 2 (6-pane metal sash; 2-pane metal sash)
 - 3) door(s): 1 (wooden plank)
 - 4) other: N/A

- b. Side: direction: SOUTH
 - 1) bays: 1
 - 2) windows: 1 (6-pane metal sash)
 - 3) door(s): 0
 - 4) other: N/A

- c. Side: direction: NORTH
 - 1) bays: 1
 - 2) windows: 1 (2-pane metal sash)
 - 3) door(s): 0
 - 4) other: N/A

- d. Rear: direction: WEST
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan N/A

b) Partition/walls N/A

c) Finishes N/A

d) Furnishings/machinery N/A



CULTURAL RESOURCE SURVEY

CRS # S-12238

MAP FORM

1. ADDRESS/LOCATION: 19050 Gravel Hill Road, Georgetown, DE 19947


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-12238

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-12238

Date Nov. 2009 Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 1: Frances Graves House Façade east. 2: rear s/w elevation. 3: west elevation. 4: out buildings rear of house.
(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

Page 1 of 2

1: Façade east



2: rear s/w



3: west elevation



4: out buildings rear of house





CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-12238

Date Nov. 2009 Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 5: workshop façade s/e. 6: workshop façade s/e wall. 7: garage south. 8: shed façade and south wall
(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

Page 2 of 2

5: workshop façade s/e



6: workshop façade s/e wall



7: garage south elevation



8: shed east facade





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-12239
SPO Map 16-17-11
Hundre Georgetown
Quad Harbeson
Other 1-35-11.00-41.00

- 1. HISTORIC NAME/FUNCTION: Evaleah Barr House / residence
- 2. ADDRESS/LOCATION: 19028 Gravel Hill Road, Georgetown, DE 19947
- 3. TOWN/NEAREST TOWN: Gravel Hill vicinity?
- 4. MAIN TYPE OF RESOURCE: building structure site object
landscape district
- 5. MAIN FUNCTION OF PROPERTY: residential
- 6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US 9 Intersection Improvements Project, Sussex County, Delaware

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Wendy Zug-Gilbert

Principal Investigator name: Wendy Zug-Gilbert

Principal Investigator signature: Michael C. Hahn, AICP for Wendy Zug-Gilbert

Organization: A&HC, Inc. Date: Nov 2009

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-12239

1. ADDRESS/LOCATION: 19028 Gravel Hill Road, Georgetown, DE 19947
2. FUNCTION(S): historic single-family dwelling current: same
3. YEAR BUILT: 1958 CIRCA?: ARCHITECT/BUILDER: unknown
4. STYLE OR FLOOR PLAN: Minimal Ranch

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

- a.
b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe resource as completely as possible. Use N/A for not applicable; leave no blanks)

- a. Overall shape: irregular Stories: 1
Additions:
- b. Structural system (if known): unknown
- c. Foundation: materials: unknown
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): brick (vener?); vinyl siding (front gable)
- e. Roof: shape: side-gable
materials: asphalt shingle
cornice: N/A
dormers: N/A
chimney: location(s): interior brick chimney on front slope at south end

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: WEST
1) Bays 3
2) Windows 5 (1 Chicago-style; 1 paired)
fenestration irregular
type 6/6 double-hung wood sash (paired); 4/4 double-hung wood sash (Chicago)
trim wood
shutters vinyl

Facade (cont'd)

- | | | |
|----|-----------|----------------------------------------------------------------------------------------------------------------------|
| 3) | Door(s) | 1 |
| | location | in inverse corner made by the main block and front-gabled wing |
| | type | wood with glass storm door |
| | trim | wood |
| 4) | Porch(es) | brick-floored porch recessed under the front-gabled wing overhang with decorative wrought iron supports and railings |
- b. Side: Direction: SOUTH
- | | | |
|----|--------------|------------------------------------------------------------------|
| 1) | Bays | 3 |
| 2) | Windows | 4 |
| | fenestration | irregular |
| | type | 8/8 wood sash (1 st floor); 6/6 wood sash (end gable) |
| | trim | wood |
| | shutters | vinyl |
| 3) | Door(s) | 0 |
| | location | N/A |
| | type | N/A |
| | trim | N/A |
| 4) | Porch(es) | N/A |
- c. Side: Direction: NORTH
- | | | |
|----|--------------|---------------|
| 1) | Bays | 4 |
| 2) | Windows | 4 |
| | fenestration | irregular |
| | type | 6/1 wood sash |
| | trim | wood |
| | shutters | vinyl |
| 3) | Door(s) | 0 |
| | location | N/A |
| | type | N/A |
| | trim | N/A |
| 4) | Porch(es) | N/A |
- d. Rear: Direction: EAST
- | | | |
|----|--------------|---------------|
| 1) | Bays | 3 |
| 2) | Windows | 2 |
| | fenestration | irregular |
| | type | 6/1 wood sash |
| | trim | wood |
| | shutters | N/A |
| 3) | Door(s) | 1 |
| | location | rear wing |
| | type | glass |
| | trim | wood |
| 4) | Porch(es) | brick stoop |

9. INTERIOR: N/A

10. LANDSCAPING: This dwelling sits on a 0.3-acre lot on the west side of Gravel Hill Road with a paved driveway at its north side. The property is open with some plantings, and is visually sheltered from the water-filled gravel pits on DeIDOT property by a dense strip of woodlot.

11. OTHER COMMENTS: 2 modern pre-fabricated sheds are associated with this property.



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-12239

1. ADDRESS/LOCATION: 19028 Gravel Hill Road, Georgetown, DE 19947
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-12239

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



CULTURAL RESOURCE SURVEY
DIGITAL PHOTOGRAPHS FORM

CRS # S-12239

Date Nov. 2009 Surveyor/Photographer Wendy Zug-Gilbert

Insert photographs; note file name and brief description of view: 1:Evaleah Barr House façade, east. 2: south elevation.

(size photograph 3" on longest side; MAINTAIN ASPECT RATIO – DO NOT STRETCH PHOTO)

1: façade east



2: south elevation

