

APPENDIX IV:

**DELAWARE STATE HISTORIC
PRESERVATION OFFICE
CULTURAL RESOURCE SURVEY FORMS:
ARCHITECTURE**



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # N-13328

1. HISTORIC NAME/FUNCTION: S. Otts House (Beer Atlas)
2. ADDRESS/LOCATION: 922 Otts Chapel Road (0 Otts Chapel Road - Assessment Office)
3. CURRENT CONDITION: excellent good fair poor demolished
4. INTEGRITY: vinyl siding; modern doors; addition to the W side with attached garage
-
5. SETTING INTEGRITY: Large modern dwelling with outbuildings have been built to the south of the property, along Otts Chapel Road; A modern development has been built along the east side of Otts Chapel Road (the rear facades of these houses face Otts Chapel Road).

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
0	CRS 2 Main Building Form	
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
0	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney L. Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

8. OTHER NOTES OR OBSERVATIONS:

CRS# N-13328

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

DELAWARE STATE HISTORIC PRESERVATION OFFICE


PHOTOGRAPHIC INVENTORY

CRS # N-13328 Date 11/17/03 Photo Roll # C-4563 Surveyor Courtney Clark

Description View of front, E side and S side of dwelling

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-14160
SPO Map 04-05-33
Hundred Pencader
Quad Newark West
Other 1101200004

1. HISTORIC NAME/FUNCTION: Orzada Farms Wholesale Nursery
2. ADDRESS/LOCATION: 1463 Otts Chapel Road
3. TOWN/NEAREST TOWN: Newark vicinity?
4. MAIN TYPE OF RESOURCE: building landscape structure district site object
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
I-95/ Newark Toll Plaza Project (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	dwelling
2	CRS 3 Secondary Building Form	garages
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Douglas C. McVarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

9. OTHER NOTES OR OBSERVATIONS:

CRS# N-14160

The current owner purchased the property from two brothers who apparently grew up on the property. At the time of the current owners acquisition of the property both brothers were still alive and were estimated to be in their 70s. The property has always been used for some form of farming.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-14160

1. ADDRESS/LOCATION: 1463 Otts Chapel Road

2. FUNCTION(S): historic single family dwelling current single family dwelling

3. YEAR BUILT: 1920 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE OR FLOOR PLAN: three bay; center passage; vernacular cottage

5. INTEGRITY: original site moved
if moved, from where _____ other location's CRS # _____ year _____

list major alterations and additions with years (if known) year _____

a. Full-width addition across the front, E side

b. Full-width addition across the rear, W side

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1 1/2
Additions: 1-story, shed-roof addition across the E side; aluminum siding; modern brick chimney on the exterior of the N end; 1-story shed-roof addition on the W side; aluminum siding

b. Structural system (if known): frame, light-timber

c. Foundation: materials: concrete block
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): asbestos on main block; aluminum siding on the additions

e. Roof: shape: side gabled
materials: rolled asphalt on main block and E addition; standing-seam metal roofing on W addition
cornice: open
dormers: n/a
chimney: location(s): centered concrete-block chimney on the exterior of the S side

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: E

1) Bays three

2) Windows

fenestration regular w/ 2 windows flanking the centered entrance
type double-hung 2-over-2 horizontal, pane sashes
trim aluminum storm windows
shutters none

Facade (cont'd)

- 3) **Door(s)** one
 location centered
 type wood, pane-and-panel
 trim none
- 4) **Porch(es)** gable-front hood over entrance; aluminum siding; partial concrete deck

b. Side: Direction: N

- 1) **Bays** three
- 2) **Windows**
 fenestration regular w/ 2 windows in main block; 1 window in rear addition; 1 small window centered in the upper level of the main block
 type double-hung 1/1 sash; six-pane casement sash
 trim aluminum storm windows
 shutters none
- 3) **Door(s)** one
 location NW corner of main block
 type bulkhead; wood; double-doors
 trim none
- 4) **Porch(es)** n/a

c. Side: Direction: S

- 1) **Bays** three
- 2) **Windows**
 fenestration 1 window in rear addition; 1 window in main block; 1 pair of side-by-side windows in front addition; 2 small windows in the upper level of the main block flanking the chimney
 type double-hung 1/1 sash; four-pane casement sash
 trim aluminum storm windows
 shutters none
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a

d. Rear: Direction: W

- 1) **Bays** three
- 2) **Windows**
 fenestration 1 window at N end; 1 small window adjacent to entrance
 type double-hung 1/1 sash; four-pane casement sash
 trim aluminum storm windows
 shutters none
- 3) **Door(s)** one
 location S end
 type wood; pane-and-panel
 trim none
- 4) **Porch(es)** modern shed-roof porch sheltering door and casement window, supported by metal piping on concrete decking; plastic corrugated roofing

9. **INTERIOR:** no access

10. **LANDSCAPING:** large parcel of land; split-rail fencing across the front, E property boundary and flanking the dirt driveway; driveway lies to N side of dwelling (between dwelling and garages); shrubs are planted along each; Nursery (with potted plants and trees) to rear, W side of the dwelling; large open land to S side of dwelling.

11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-14160

1. ADDRESS/LOCATION: 1463 Otts Chapel Road

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE/FLOOR PLAN: rectangular shaped building

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system frame- light timber

b. Number of stories 1 1/2

c. Wall coverings aluminum siding on both sides; asphalt shingles w/ brick pattern on front, S side

d. Foundation obscured

e. Roof

structural system gabled-front; exposed wood rafter-ends along both sides

coverings standing-seam metal

openings n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: S

1) bays: one

2) windows: none

3) door(s): single door centered; plywood with swing-hinge opening

4) other: none

b. Side: direction: E

- 1) **bays:** two
- 2) **windows:** double-light, wood frame, fixed windows; one on S-end and one on N-end
- 3) **door(s):** none
- 4) **other:** none

c. Side: direction: W

- 1) **bays:** two
- 2) **windows:** double-light, wood frame, fixed windows; one on S-end and one on N-end
- 3) **door(s):** none
- 4) **other:** none

d. Rear: direction: N

- 1) **bays:** one
- 2) **windows:** double-light, wood frame, fixed window; centered
- 3) **door(s):** none
- 4) **other:** none


9. INTERIOR (if accessible):

a) **Floor plan** **single room; open**

b) **Partition/walls** **none**

c) **Finishes** **no access**

d) **Furnishings/machinery** **no access**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-14160

1. ADDRESS/LOCATION: 1463 Otts Chapel Road

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE/FLOOR PLAN: rectangular shaped building

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. 1-story gabled addition to N side; multiple open-bays; tree trunk supports; corrugated metal roofing 1940
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system frame- light timber
- b. Number of stories 1 1/2
- c. Wall coverings asphalt siding in brick pattern on both sides; vertical wood paneling on front, S side
- d. Foundation obscured
- e. Roof
 - structural system gabled-front; exposed wood rafter-ends along both sides
 - coverings standing-seam metal
 - openings none

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S
 - 1) bays: one
 - 2) windows: Fixed, single-light window in the upper level
 - 3) door(s): plywood, sliding double-doors
 - 4) other: Modern 1-story full-width porch across the S side; supported by wood posts

- b. **Side: direction: E**
 - 1) **bays:** one
 - 2) **windows:** double-light, wood frame, fixed window
 - 3) **door(s):** none
 - 4) **other:** none

- c. **Side: direction: W**
 - 1) **bays:** no access
 - 2) **windows:** no access
 - 3) **door(s):** no access
 - 4) **other:** no access

- d. **Rear: direction: N**
 - 1) **bays:** no access
 - 2) **windows:** no access
 - 3) **door(s):** no access
 - 4) **other:** no access

9. **INTERIOR (if accessible):**

a) **Floor plan** **no access**

b) **Partition/walls** **no access**

c) **Finishes** **no access**

d) **Furnishings/machinery** **no access**



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # N-14160

1. ADDRESS/LOCATION: 1463 Otts Chapel Road
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

Card 1 of 2

CRS # N-14160 Date 11/17/03 Photo Roll # C-4563 Surveyor Courtney Clark

Description View of front, E side and N side of dwelling; View of NE sides of both garages; View of rear, W side and S side of dwelling

Negative location (if other than SHPO) _____

Attach contact print(s):





doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE
PHOTOGRAPHIC INVENTORY

CRS # N-14160
Card 2 of 2





CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # N-13343

1. HISTORIC NAME/FUNCTION: Dwelling

2. ADDRESS/LOCATION: 1636 Otts Chapel Road

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: vinyl siding; modern doors and windows; enclosure to rear, E side of the dwelling

5. SETTING INTEGRITY: Modern dwellings have been constructed to the north side of the property.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	dwelling
1	CRS 3 Secondary Building Form	shed
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney L. Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750∇ Contact Period (Native American)
- 1630-1730∇ Exploration and Frontier Settlement
- 1730-1770∇ Intensified and Durable Occupation
- 1770-1830∇ Early Industrialization
- 1830-1880∇ Industrialization and Early Urbanization
- 1880-1940∇ Urbanization and Early Suburbanization
- 1940-1960∇ Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-13343

1. ADDRESS/LOCATION: 1636 Otts Chapel Road

2. FUNCTION(S): historic single-family dwelling current vacant

3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: Not Known

4. STYLE OR FLOOR PLAN: three bay; center-passage

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. none

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1 1/2
Additions: none

b Structural system (if known): wood-frame

c. Foundation: materials: obscured by poured concrete
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): vinyl siding

e. Roof: shape: gable-front
materials: rolled asphalt
cornice: enclosed, boxed vinyl
dormers: wall dormers across the middle of dwelling
chimney: location(s): covered in concrete; center interior of dwelling

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: W
1) Bays three
2) Windows
fenestration regular w/ 2 windows flanking centered entrance
type modern double-hung 1/1 sash
trim vinyl surround
shutters none

Facade (cont'd)

- 3) **Door(s)** one
 location center of main block
 type wood-and-glass
 trim none
- 4) **Porch(es)** Full-width, 1-story hipped-roof porch; exposed rafter ends; wood post supports on wood deck w/ concrete-block piers as under-support; brick steps

b. Side: Direction: N

- 1) **Bays** two
- 2) **Windows**
 fenestration irregular
 type modern double-hung 1/1 sash
 trim none
 shutters none
- 3) **Door(s)** one (basement entrance)
 location center
 type unknown; covered by plywood
 trim none
- 4) **Porch(es)** n/a

c. Side: Direction: S

- 1) **Bays** three
- 2) **Windows**
 fenestration regular
 type modern double-hung 1/1 sash
 trim none
 shutters none
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a

d. Rear: Direction: E

- 1) **Bays** three
- 2) **Windows**
 fenestration regular
 type modern double-hung 1/1 sash
 trim none
 shutters none
- 3) **Door(s)** one
 location near NE end
 type vinyl-and-glass
 trim
- 4) **Porch(es)** inset on NE corner; single wood post support; wood deck w/ concrete pier under-supports

9. **INTERIOR:** no access

10. **LANDSCAPING:** deep, rectangular lot; woods to the rear, E end of the boundary; tall trees planted across the front of property boundary, obscuring immediate sight of house.

11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-13343

1. ADDRESS/LOCATION: 1636 Otts Chapel Road

2. FUNCTION(S): historic storage shed current unused

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. 1-story gable-front addition across front, W side

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories one-story

c. Wall coverings plywood

d. Foundation concrete

e. Roof
structural system gable-front
coverings rolled asphalt
openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: W
- 1) bays: unknown; obscured by front addition
 - 2) windows: unknown
 - 3) door(s): unknown
 - 4) other: ADDITION has (1) pair of wood, swinge-hinge doors

b. Side: direction: N

- 1) **bays:** n/a
- 2) **windows:** n/a

- 3) **door(s):** n/a

- 4) **other:** n/a

c. Side: direction: S

- 1) **bays:** n/a
- 2) **windows:** n/a

- 3) **door(s):** n/a

- 4) **other:** n/a

d. Rear: direction: E

- 1) **bays:** inaccessible
- 2) **windows:** inaccessible

- 3) **door(s):** inaccessible

- 4) **other:** n/a

9. INTERIOR (if accessible):

a) Floor plan inaccessible

b) Partition/walls inaccessible

c) Finishes inaccessible

d) Furnishings/machinery inaccessible



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # N-13343

1. ADDRESS/LOCATION: 1636 Otts Chapel Road
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

Card 1 of 2


PHOTOGRAPHIC INVENTORY

CRS # N-13343 Date 11/17/03 Photo Roll # C-4563 Surveyor Courtney Clark

Description View of front, W side and S side of dwelling; View of rear, E side and N side of dwelling; View of front, W side and N side of shed

Negative location (if other than SHPO) _____

Attach contact print(s):





doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE
PHOTOGRAPHIC INVENTORY

CRS # N-13343
Card 2 of 2





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # N-13319

1. HISTORIC NAME/FUNCTION: Barber House (Pomeroy & Beer Atlas)

2. ADDRESS/LOCATION: 123 Tall Pines Road

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: modern brick chimney on the SE corner of the dwelling; modern windows; addition attached to W side and S side of dwelling

5. SETTING INTEGRITY: The dwelling is setback from Tall Pines Road. Historically, the house and associated agricultural buildings were located off of Chestnut Hill Road. Over the years the multiple-acre property was subdivided. No outbuildings remain. The dwelling is situated amongst a 1960/1970s neighborhood development.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	dwelling
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
1	CRS 7 Object Form	water pump
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney L. Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

8. OTHER NOTES OR OBSERVATIONS:

CRS# N-13319


Currently the dwelling is rented out to a single tenant. The owner lives in Europe.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-13319

1. ADDRESS/LOCATION: 123 Tall Pines Road

2. FUNCTION(S): historic dwelling current dwelling

3. YEAR BUILT: 1868 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE OR FLOOR PLAN: three bay; center passage; vernacular farmhouse

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. addition across rear, W facade

b. one-story, shed roof porch addition on N end

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 2 1/2
Additions: One-story, shed-roofed porch attached to N end; full-width addition attached to rear W; second-level wood deck constructed to SE corner of the dwelling

b. Structural system (if known): wood-frame

c. Foundation: materials: covered by poured concrete
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): horizontal wood-siding

e. Roof: shape: side-gable
materials: asphalt shingles
cornice: n/a
dormers: n/a
chimney: location(s): modern brick chimney on exterior of S gable-end

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: E
1) Bays three
2) Windows
fenestration regular w/ 2 windows on 1st floor flanking entrance; 4 windows across 2nd floor
type modern double-hung 1/1 sash
trim wood surround
shutters non-functional ; wood; louvered panels

Facade (cont'd)

- 3) **Door(s)** one
 location centered on main block
 type pane-and-panel, wood
 trim flanked by three-light, half-length sidelights
- 4) **Porch(es)** shed-roofed, single story vestibule; pierced on each side by six-over-six, double hung sash windows

b. Side: Direction: S

- 1) **Bays** two
- 2) **Windows**
 fenestration irregular; one on each corner end of 1st level
 type modern chicago bays (centered fixed sash with flanking double-hung 1/1 sash , and centered fixed 12-pane sash with flanking double-hung 4/4 sash)
 trim none
 shutters none
- 3) **Door(s)** bulkhead
 location attached to SW corner of main block
 type metal; double-door
 trim
- 4) **Porch(es)** 2nd level wood deck attached to SW corner; supported by wood posts

c. Side: Direction: N

- 1) **Bays** three
- 2) **Windows**
 fenestration irregular; one pair and one single window
 type modern double-hung 1/1 sash
 trim none
 shutters 2nd level window have wood awnings
- 3) **Door(s)** one
 location centered along N end addition
 type pane-and-panel; wood
 trim wood
- 4) **Porch(es)** full-width, one-story, shed-roof screen porch; attached open wood deck to west end

d. Rear: Direction: W

- 1) **Bays** four
- 2) **Windows**
 fenestration irregular; one set, and two single windows
 type one-set, and one single - modern double-hung 1/1 sash; one- awning style window
 trim none
 shutters none
- 3) **Door(s)** one
 location towards NW end
 type pane-and-panel, wood
 trim wood
- 4) **Porch(es)** one-story, shed-roof enclosure sheltering the entrance

9. **INTERIOR:** not accessible

10. **LANDSCAPING:** trees and low-lying plants planted in an arch-shaped formation around the dwelling; circular gravel driveway in front lawn; tall trees grow along perimeter of property boundaries

11. **OTHER COMMENTS:**



CULTURAL RESOURCE SURVEY
OBJECT FORM

CRS # N-13319

1. ADDRESS/LOCATION: 123 Tall Pines Road
2. TYPE/FUNCTION/TITLE: well/ pump
3. YEAR: Construction: 1870 Circa? Installation: _____ Circa?
Previous location(s): _____
4. DESIGNER/FOUNDER/SCULPTOR: n/a
5. SPONSOR/OWNER: John Barber
6. STYLE: n/a
7. CURRENT CONDITION: excellent good fair poor

8. DESCRIPTION:

a) Object

form
technology and materials cast iron
surface finish painted black
decoration none
dimensions 36" tall x 6" diameter
alterations or changes n/a

b) Base

form square
technology and materials concrete
surface finish smooth
decoration n/a
dimensions 24" x 24"
alterations or changes n/a

8. DESCRIPTION (cont'd):

CRS # **N-13319**

c) Inscriptions

**1) location n/a
lettering n/a
text n/a**

**2) location n/a
lettering n/a
text n/a**

**3) location n/a
lettering n/a
text n/a**

d) Other n/a



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # N-13319

1. ADDRESS/LOCATION: 123 Tall Pines Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

Card 1 of 2


PHOTOGRAPHIC INVENTORY

CRS # N-13319 Date 11/17/03 Photo Roll # C-4563 Surveyor Courtney Clark

Description View of front, E side and S side of dwelling; View of rear, W side and N side of dwelling; View of an iron water pump located adjacent to S end of dwelling.

Negative location (if other than SHPO) _____

Attach contact print(s):





doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE
PHOTOGRAPHIC INVENTORY

CRS # N-13319
Card 2 of 2





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # N-13340

1. HISTORIC NAME/FUNCTION: Dwelling

2. ADDRESS/LOCATION: 357 Welsh Tract Road

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: Asbestos siding to core of the dwelling, vertical wood paneling covers the additions; Additions extend from the E and W side of the dwelling; 1960s replacement windows; modern doors

5. SETTING INTEGRITY: rear of property used as junkyard.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	dwelling
1	CRS 3 Secondary Building Form	outbuilding
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney L. Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-13340

1. ADDRESS/LOCATION: 357 Welsh Tract Road

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1900 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE OR FLOOR PLAN: three bay; center-passage

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. 1 1/2-story gabled addition to rear, S side

b. 1-story shed-roof addition to E side

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 2
Additions: 1 1/2-story gabled addition to rear, S side; covered in asbestos shingles; (2) gabled dormers; (1) shed-roof dormer; fixed, multi-pane windows; 1-story shed-roof addition along entire E side; wood panel siding; awning style windows; 1-story shed-roof addition to W side of main block and gabled addition; she-roof porch enclosure on S end.

b. Structural system (if known): wood-frame

c. Foundation: materials: obscured by poured concrete
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): asbestos shingles

e. Roof: shape: side-gable
materials: rolled asphalt
cornice: open
dormers: see additions
chimney: location(s): covered in concrete; center interior of dwelling

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: N

1) Bays three

2) Windows

fenestration regular w/ 2 windows flanking centered entrance
type modern casement; multi-pane on upper level
trim wood frame
shutters none

Facade (cont'd)

- 3) **Door(s)** one
 location center of main block
 type modern sliding glass; double-door
 trim vinyl surround
- 4) **Porch(es)** n/a

b. Side: Direction: E

- 1) **Bays** unknown; obscured by addition
- 2) **Windows** unknown; obscured by addition
 fenestration unknown
 type unknown
 trim unknown
 shutters
- 3) **Door(s)** unknown; obscured by addition
 location unknown
 type unknown
 trim unknown
- 4) **Porch(es)** n/a

c. Side: Direction: W

- 1) **Bays** one
- 2) **Windows** **fenestration** regular; centered in the gable end of main block
 type multi-pane
 trim wood-frame
 shutters n/a
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a

d. Rear: Direction: S

- 1) **Bays** unknown; obscured by addition
- 2) **Windows** unknown; obscured by addition
 fenestration unknown
 type unknown
 trim unknown
 shutters unknown
- 3) **Door(s)** unknown; obscured by addition
 location unknown
 type unknown
 trim unknown
- 4) **Porch(es)** n/a

9. **INTERIOR:** no access

10. **LANDSCAPING:** rectangular lot; deep; wooded w/ overgrown brush to the rear; front lawn planted w/ various vegetation; row of planted trees mark the E property boundary

11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-13340

1. ADDRESS/LOCATION: 357 Welsh Tract Road
2. FUNCTION(S): historic vehicle shed current garage
3. YEAR BUILT: 1910 CIRCA?: ARCHITECT/BUILDER: _____
4. STYLE/FLOOR PLAN: rectangular
5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. _____

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories one-story
- c. Wall coverings Vertical wood paneling
- d. Foundation unknown
- e. Roof
 structural system side-gable
 coverings rolled asphalt
 openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: NE
- 1) bays: two
- 2) windows: n/a
- 3) door(s): (1) modern roll-down vinyl garage door; (1) modern vinyl door
- 4) other: n/a

b. Side: direction: NW

- 1) **bays:** n/a
- 2) **windows:** n/a

- 3) **door(s):** n/a

- 4) **other:** n/a

c. Side: direction: SE

- 1) **bays:** inaccessible
- 2) **windows:** inaccessible

- 3) **door(s):** inaccessible

- 4) **other:** n/a

d. Rear: direction: SW

- 1) **bays:** inaccessible
- 2) **windows:** inaccessible

- 3) **door(s):** inaccessible

- 4) **other:** n/a

9. INTERIOR (if accessible):

a) Floor plan inaccessible

b) Partition/walls inaccessible

c) Finishes inaccessible

d) Furnishings/machinery inaccessible



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # N-13340

1. ADDRESS/LOCATION: 357 Welsh Tract Road
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

Card 1 of 2

PHOTOGRAPHIC INVENTORY

CRS # N-13340 Date 11/17/ 03 Photo Roll # C-4563 Surveyor Courtney Clark

Description View of front, N side of dwelling; View of rear, S side and E side of dwelling; View of front, NE side of garage.

Negative location (if other than SHPO) _____

Attach contact print(s):





doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE
PHOTOGRAPHIC INVENTORY

CRS # N-13340
Card 2 of 2





CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # N-13342

1. HISTORIC NAME/FUNCTION: L. Walton House (Beer Atlas)

2. ADDRESS/LOCATION: 316 Welsh Tract Road

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: aluminum and asbestos siding; rolled asphalt roofing

5. SETTING INTEGRITY: Historically the property was used farming purposes, today the ronly agricultural emaining outbuilding is in poor, delapidated condition. Two modern garages have been built and are located NW of the dwelling.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	dwelling
3	CRS 3 Secondary Building Form	barn; (2) garages
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney L. Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

8. OTHER NOTES OR OBSERVATIONS:

CRS# N-13342

August and Pauline Zistl purchased the property in the 1940s. They used the barn for raising chickens. The barn is no longer used, as its condition is very poor. August died a number of years back (date unknown). Currently, Pauline lives in the dwelling with her daughter. She says that she and her husband used to own a lot more land but the construction of I-95 split the property in two. Pauline is an artist.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-13342

1. ADDRESS/LOCATION: 316 Welsh Tract Road
2. FUNCTION(S): historic single-family dwelling current single-family dwelling
3. YEAR BUILT: 1890 CIRCA?: ARCHITECT/BUILDER: unknown
4. STYLE OR FLOOR PLAN: three bay; center-passage; Victorian
5. INTEGRITY: original site moved
if moved, from where _____ other location's CRS # _____ year _____

list major alterations and additions with years (if known)

- a. 1-story hipped-roofed enclosure on W side _____ year _____
- b. Large 2-story gabled addition on N side _____ year _____

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangular Stories: 2 1/2
Additions: 1-story hipped-roofed porch enclosure on W side; aluminum siding; Large, full-width 2-story gabled addition on N side; aluminum siding; Multi-pane windows
- b. Structural system (if known): wood-frame
- c. Foundation: materials: obscured
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): aluminum; asbestos shingles
- e. Roof: shape: cross-gable
materials: rolled asphalt
cornice: enclosed by vinyl
dormers: none
chimney: location(s): (2) brick chimneys; interior of E gable-end; exterior of N side

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: S
- 1) Bays three
- 2) Windows fenestration regular w/ 2 windows flanking centered entrance
type double-hung 6/6 sash
trim wood surrounds
shutters none

Facade (cont'd)

- 3) **Door(s)** one
 location center of main block
 type wood-and-glass
 trim flat wood door surround; flanking pilasters topped by a pediment
- 4) **Porch(es)** n/a

b. Side: Direction: E

- 1) **Bays** four
- 2) **Windows**
 fenestration irregular
 type double-hung 6/6 sash
 trim wood surrounds
 shutters none
- 3) **Door(s)** two
 location addition portion of dwelling; bulkhead at NE corner of main block
 type wood-and-glass; metal double-door bulkhead
 trim wood screen door
- 4) **Porch(es)** modern wood deck along addition

c. Side: Direction: W

- 1) **Bays** one
- 2) **Windows**
 fenestration irregular
 type triple window; double-hung 6/6 sash
 trim wood surround; wood-frame screen
 shutters
- 3) **Door(s)** see below
 location see below
 type see below
 trim see below
- 4) **Porch(es)** 1-story, hipped-roof porch enclosure; aluminum siding 1-room in size; (1) wood-and-glass door flanked by double-hung 6/6 sash windows; pair of windows on S end; wood door w/ no level exit on N end;

d. Rear: Direction: N

- 1) **Bays** unknown; obscured by addition
- 2) **Windows** unknown; obscured by addition
 fenestration unknown
 type unknown
 trim unknown
 shutters unknown
- 3) **Door(s)** unknown; obscured by addition
 location unknown
 type unknown
 trim unknown
- 4) **Porch(es)** n/a

9. **INTERIOR:** no access

10. **LANDSCAPING:** Large lot; Circular driveway on W side of dwelling; house nicely shaded by tall trees on all sides

11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-13342

1. ADDRESS/LOCATION: 316 Welsh Tract Road

2. FUNCTION(S): historic _____ current garage

3. YEAR BUILT: 1970 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. none
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system wood-frame
b. Number of stories one-story
c. Wall coverings vinyl siding
d. Foundation concrete
e. Roof
structural system side-gable
coverings rolled asphalt
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: S
1) bays: four
2) windows: n/a
3) door(s): (3) modern roll-down vinyl garage door; (1) modern vinyl door
4) other: n/a

b. Side: direction: E

- 1) **bays:** n/a
- 2) **windows:** n/a

- 3) **door(s):** n/a

- 4) **other:** n/a

c. Side: direction: W

- 1) **bays:** n/a
- 2) **windows:** n/a

- 3) **door(s):** n/a

- 4) **other:** n/a

d. Rear: direction: N

- 1) **bays:** inaccessible
- 2) **windows:** inaccessible

- 3) **door(s):** inaccessible

- 4) **other:** n/a

9. INTERIOR (if accessible):

a) Floor plan inaccessible

b) Partition/walls inaccessible

c) Finishes inaccessible

d) Furnishings/machinery inaccessible



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-13342

1. ADDRESS/LOCATION: 316 Welsh Tract Road

2. FUNCTION(S): historic _____ current garage

3. YEAR BUILT: 1970 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. I-story addition to E end

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories one-story

c. Wall coverings vinyl-siding

d. Foundation concrete

e. Roof
structural system side-gable
coverings rolled asphalt
openings n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: S

1) bays: three

2) windows: n/a

3) door(s): (2) modern roll-down vinyl garage door; (1) modern vinyl door

4) other: ADDITION has (1) vinyl door; (1) vinyl garage door; (2) pairs of modern casement windows

- b. Side: direction: E
- 1) bays: one
 - 2) windows: modern casement
 - 3) door(s): n/a
 - 4) other: n/a

- c. Side: direction: W
- 1) bays: n/a
 - 2) windows: n/a
 - 3) door(s): n/a
 - 4) other: n/a

- d. Rear: direction: N
- 1) bays: inaccessible
 - 2) windows: inaccessible
 - 3) door(s): inaccessible
 - 4) other: n/a

9. INTERIOR (if accessible):

a) Floor plan inaccessible

b) Partition/walls inaccessible

c) Finishes inaccessible

d) Furnishings/machinery inaccessible



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-13342

1. ADDRESS/LOCATION: 316 Welsh Tract Road

2. FUNCTION(S): historic barn current unused

3. YEAR BUILT: 1890 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. none
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 3 1/2
- c. Wall coverings asbestos shingles
- d. Foundation stone
- e. Roof
 - structural system side-gable
 - coverings asphalt
 - openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: E
 - 1) bays: seven
 - 2) windows: inaccessible
 - 3) door(s): inaccessible
 - 4) other: n/a

- b. **Side: direction: N**
- 1) **bays:** inaccessible
 - 2) **windows:** inaccessible
 - 3) **door(s):** inaccessible
 - 4) **other:** n/a

- c. **Side: direction: S**
- 1) **bays:** inaccessible
 - 2) **windows:** inaccessible
 - 3) **door(s):** inaccessible
 - 4) **other:** n/a

- d. **Rear: direction: W**
- 1) **bays:** inaccessible
 - 2) **windows:** inaccessible
 - 3) **door(s):** inaccessible
 - 4) **other:** n/a

9. **INTERIOR (if accessible):**

a) **Floor plan** **inaccessible**

b) **Partition/walls** **inaccessible**

c) **Finishes** **inaccessible**

d) **Furnishings/machinery** **inaccessible**



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # N-13342

1. ADDRESS/LOCATION: 316 Welsh Tract Road
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

Card 1 of 3


PHOTOGRAPHIC INVENTORY

CRS # N-13342 Date 11/17/2003 Photo Roll # C-4564 Surveyor Courtney Clark

Description View of front, S side and W side of dwelling; View of E side of former barn; View of SE side of both garages; View of rear, N side of dwelling

Negative location (if other than SHPO) _____

Attach contact print(s):




doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE
PHOTOGRAPHIC INVENTORY

CRS # N-13342
Card 2 of 3



DELAWARE STATE HISTORIC PRESERVATION OFFICE
PHOTOGRAPHIC INVENTORY

CRS # N-13342
Card 3 of 3





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-14165
SPO Map 04-05-33
Hundred Pencader
Quad Newark West
Other 1101300001

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: 248 Welsh Tract Road
3. TOWN/NEAREST TOWN: Newark vicinity?
4. MAIN TYPE OF RESOURCE: building structure site
landscape district object
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
I-95/ Newark Toll Plaza Project (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	dwelling
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____


Organization: John Milner Associates, Inc. Date: 11/1/2003

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-14165

1. ADDRESS/LOCATION: 248 Welsh Tract Road

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE OR FLOOR PLAN: vernacular cottage; single-pile

5. INTEGRITY: original site moved
if moved, from where _____ other location's CRS # _____ year _____

list major alterations and additions with years (if known) year

- a. corner enclosure on the SE side
- b. modern handicapped ramp across the SE side

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: L-shape Stories: 1 1/2
Additions: corner enclosure at crossing of gables on SE side; wood panel siding; modern doorsheltered by modern shed-roof porch over entrance
- b. Structural system (if known): brick
- c. Foundation: materials:
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): brick
- e. Roof: shape: side-gable
materials: rolled asphalt
cornice: open
dormers: n/a
chimney: location(s): brick, exterior chimney centered on SW gable-end

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: SE
 - 1) Bays five
 - 2) Windows
 - fenestration two windows on S end; one window centered within gabled-ell on E-end
 - type double-hung, 6/1 sash
 - trim aluminum storm windows; brick sills
 - shutters none

Facade (cont'd)

- 3) **Door(s)** two
 location centered on main block
 type wood pane-and-panel
 trim modern storm door
- 4) **Porch(es)** partial inset porch; supported by lattice woodwork post on S corner; brick and poured concrete decking; shed-roof enclosed vestibule shelters additional entrance; plywood siding; w/ modern storm door entrance

b. Side: Direction: NE

- 1) **Bays** three
- 2) **Windows**
 fenestration regular spacing of 3 windows on 1st floor; 1 - window centered in upper level of gable-end
 type double-hung 6/1 sash
 trim aluminum storm windows
 shutters none
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a

c. Side: Direction: SW

- 1) **Bays** two
- 2) **Windows**
 fenestration regular spacing of 2 windows on 1st floor, flanking chimney; 1-window centered in upper level of gable-end
 type double-hung 6/1 sash
 trim aluminum storm windows
 shutters n/a
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a

d. Rear: Direction: NW

- 1) **Bays** inaccessible
- 2) **Windows** inaccessible
 fenestration inaccessible
 type inaccessible
 trim inaccessible
 shutters inaccessible
- 3) **Door(s)** inaccessible
 location inaccessible
 type inaccessible
 trim inaccessible
- 4) **Porch(es)** inaccessible

9. **INTERIOR:** no access

10. **LANDSCAPING:** tall trees and overgrown brush surround the dwelling on all sides; dirt driveway along SW side of dwelling

11. **OTHER COMMENTS:**



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # N-14165

1. ADDRESS/LOCATION: 248 Welsh Tract Road
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # N-14165 Date 11/24/03 Photo Roll # C-4566 Surveyor Courtney Clark

Description View of front, SE side and SW side of dwelling

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-14174
SPO Map 04-05-33
Hundred Pencader
Quad Newark West
Other 1100900055

1. HISTORIC NAME/FUNCTION: State Of Delaware, Department Of Transportation, Toll Operations
2. ADDRESS/LOCATION: 1200ss Whittaker Road
3. TOWN/NEAREST TOWN: Newark vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
landscape district
5. MAIN FUNCTION OF PROPERTY: commercial - transportation
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
I-95/ Newark Toll Plaza Project (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	administration and toll collection building
1	CRS 3 Secondary Building Form	storage shed
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
1	CRS 7 Object Form	monument
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

9. OTHER NOTES OR OBSERVATIONS:

CRS# N-14174

According to the Toll Systems Administrator (Jon Osbourne), the Administration Building was built in the 1960s. In the past 4 years the building has undergone interior changes and improvements for security purposes. All of the windows in building have been replaced. An addition was constructed to the northeast corner of the building, adding a few additional offices spaces. An additional enclosed walkway was attached to the northeast corner of the building, extending approximately 200-yards north. The walkway leads to additional secondary toll booths lanes. The entrance level of the building contains administrative offices, an E-Z pass sales desk, a monitor and security room (with security monitors, and officers monitoring on-coming and exiting vechiles and toll collectors) and bathrooms. There is a full basement below the ground-level. The basement contains a tunnel leading to access of the individual toll booths, storage rooms, a computer equipment room, one office, and a maintenannce room. Originally there were 6 toll booths across I-95 (three for each direction of travel), today there are fourteen.

A large photograph from the dedication service of the facility opening, with President John F. Kennedy cutting the ribbon, is located in the office area of the building. A painting of the former President and a plaque regarding the dedication are located in the small entrance area of the building.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|--|
| <input type="checkbox"/> Agriculture | <input checked="" type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input checked="" type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

Facade (cont'd)

- 3) **Door(s)** one
 location corner of L; central
 type commercial glass-plate
 trim steel frame
- 4) **Porch(es)** concrete deck/ sidewalk

b. Side: Direction: SW

- 1) **Bays** two
- 2) **Windows** n/a
 fenestration n/a
 type n/a
 trim n/a
 shutters n/a
- 3) **Door(s)**
 location central
 type steel
 trim n/a
- 4) **Porch(es)** concrete deck/ sidewalk

c. Side: Direction: NE

- 1) **Bays** none
- 2) **Windows** n/a
 fenestration n/a
 type n/a
 trim n/a
 shutters n/a
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)**

d. Rear: Direction: SE

- 1) **Bays** three
- 2) **Windows**
 fenestration 2 window bays flanking the entrance
 type large commercial glass-plate
 trim steel frame
 shutters n/a
- 3) **Door(s)** double
 location central
 type commercial glass-plate
 trim steel frame
- 4) **Porch(es)** concrete deck/sidewalk

9. **INTERIOR:** Upon entering the building there is a small waiting area with soda and snack machines along the walls; a large, open Toll Collection Administration room with video recordation, complete overview of the roadways and a small interior window for distribution and sales of electronic transponders occupy the NW corner of the building; Administration offices occupy the remaining ground level of the building; the basement contains rooms for storage, 1 office, 1 maintenance/ supply room and an underground tunnel to the respective toll booths; the interior was recently (2001) redesigned, for security purposes
10. **LANDSCAPING:** Beds of mixed vegetation are planted across each side of the building; A large parking lot lies to the SE side of the building; I-95 lies to the immediate NW of the property; Tall trees bound the SW and NE sides of the property.
11. **OTHER COMMENTS:** Other buildings associated with this property located on different (nearby) parcel of land are described on secondary building and object forms.



CULTURAL RESOURCE SURVEY
OBJECT FORM

CRS # N-14174

1. ADDRESS/LOCATION: In The Grass Median Of I-95 At The Maryland/ Delaware State Borders; Between Otts Chapel Road And Route 279
2. TYPE/FUNCTION/TITLE: I-95 dedication monument
3. YEAR: Construction: 1963 Circa? Installation: _____ Circa?
Previous location(s): _____
4. DESIGNER/FOUNDER/SCULPTOR: n/a
5. SPONSOR/OWNER: State of Delaware
6. STYLE: Modern contemporary
7. CURRENT CONDITION: excellent good fair poor

8. DESCRIPTION:

a) Object

form elongated, rectangle w/ slight pyramidal top (monument)
technology and materials cast concrete
surface finish vertical raked grooves in the center; horizontal raked grooves along the edges
decoration molded emblems on each side (both are different)
dimensions monument (38" tall x 12" wide x 12" wide)
alterations or changes n/a

b) Base

form rectangle
technology and materials cast concrete
surface finish smooth
decoration cast iron plaques inset on the E and W ends
dimensions ground base (6" tall x 18" wide x 36" long) monumnet base (4" tall x 15" wide x 15" long)
alterations or changes n/a

8. DESCRIPTION (cont'd):

CRS # N-14174

c) Inscriptions

1) location E end of ground base

lettering block

text Maryland NE Expressway dedicated by The President of the United States, John F. Kennedy, November 14, 1963; J. Millard Tawes - Governor; State Roads Commission, John B. Funk - Chairman Director, Paul J. Bailey, Harley P. Parinsfield, Lansdale G. Clagett, Leslie H. Evans, John D. McMullen, William P. Owings; Thomas N. Kay - Chief Administration Officer; David H Fisher; Authorized by General Assembly 1955

2) location W end of ground base

lettering block

text Delaware Turnpike dedicated by The President of United States, John F. Kennedy, November 14, 1963; Elbert N. Carvel, Governor; State Highway Department, N. Maxson Terry, Chairman, Lemuel H. Hickman, Vice Chairman, Thurman Adams, Jr., Harry Bonk, Anthony B. Carroll, Jr., C. Warren Gass, Aubrey B. Lank, Frank H. Mackie, Jr., Albert S. Moor, Elmer Fratt, William J. Hopkins; William J. Miller, Jr., Director of Operations, Ernest A. Davidson, Chief Engineer, James J. Deputy, Controller; Authorized by General Assembly 1961

3) location

lettering

text n/a

d) Other

n/a



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-14174

1. ADDRESS/LOCATION: 1200 SS Whittaker Road
2. FUNCTION(S): historic _____ current toll booths
3. YEAR BUILT: 1963 CIRCA?: ARCHITECT/BUILDER: Rupert Construction Company; Howard, Needles, Tammen and Bergendoff
4. STYLE/FLOOR PLAN: rectangular
5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known)

year

a. Expansion to the number of drive-thru lanes

b. Constuction of an additional tollbooth for EZ Pass users

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system concrete, steel framing

b. Number of stories 1

c. Wall coverings Steel panels

d. Foundation concrete

e. Roof

structural system canopy

coverings unknown

openings n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: W

1) bays: one

2) windows: one - glass plate

3) door(s): n/a

4) other: n/a

- b. **Side: direction: E**
 - 1) **bays:** one
 - 2) **windows:** one- glass plate
 - 3) **door(s):** n/a
 - 4) **other:** n/a

- c. **Side: direction: N**
 - 1) **bays:** one
 - 2) **windows:** n/a
 - 3) **door(s):** sliding glass doors
 - 4) **other:** n/a

- d. **Rear: direction: S**
 - 1) **bays:** one
 - 2) **windows:** one - glass plate
 - 3) **door(s):** n/a
 - 4) **other:** N/a

9. **INTERIOR (if accessible):**

a) **Floor plan** **small, single-man rooms**

b) **Partition/walls** **n/a**

c) **Finishes** **n/a**

d) **Furnishings/machinery** **register/ cash drawer for collecting money for tolls and making change**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-14174

1. ADDRESS/LOCATION: 1200 SS Whittaker Road
2. FUNCTION(S): historic _____ current garage
3. YEAR BUILT: 2000 CIRCA?: ARCHITECT/BUILDER: not known
4. STYLE/FLOOR PLAN: rectangular
5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known)

year

a.

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system concrete-block

b. Number of stories 1

c. Wall coverings concrete-block

d. Foundation concrete

e. Roof

structural system hipped

coverings asphalt

openings n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: NE

1) bays: one

2) windows: n/a

3) door(s): modern vinyl garage door, centered

4) other: n/a

b. Side: direction: SE

- 1) **bays:** none
- 2) **windows:** n/a

- 3) **door(s):** n/a

- 4) **other:** n/a

c. Side: direction: NW

- 1) **bays:** none
- 2) **windows:** n/a

- 3) **door(s):** n/a

- 4) **other:** n/a

d. Rear: direction: SW

- 1) **bays:** none
- 2) **windows:** n/a

- 3) **door(s):** n/a

- 4) **other:** n/a

9. INTERIOR (if accessible):

a) Floor plan no access

b) Partition/walls no access

c) Finishes no access

d) Furnishings/machinery no access



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # N-14174

1. ADDRESS/LOCATION: 1200 Ss Whittaker Road
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

Card 1 of 2


PHOTOGRAPHIC INVENTORY

CRS # N-14174 Date 11/24/03 Photo Roll # C-4567 Surveyor Courtney Clark

Description At Toll Plaza site:View of front, NW side of Administration Building; View of E side of Toll Booths; View of entrance into underground tunnel from center toll booth; View looking N from center of underground tunnel; View looking NW at SE end of underground tunnel; View of a typical office within Administrative Building; View of a typical office within Administrative Building (**same office, different angle); View of rear, SE side of Administration Building; View of front, NE side of garage



At Delaware/ Maryland State Borders: View of W side of I-95 Dedication Monument; View of E side of I-95 Dedication Monument


Negative location (if other than SHPO)



DELAWARE STATE HISTORIC PRESERVATION OFFICE
PHOTOGRAPHIC INVENTORY

CRS # N-14174
Card 2 of 2





CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # N-12868

1. HISTORIC NAME/FUNCTION: Dwelling

2. ADDRESS/LOCATION: 180 Welsh Tract Road

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: All historic fabric has been retained.

5. SETTING INTEGRITY: The property's integrity of location, setting and feeling has been retained; the property is nicely landscaped and fairly remote.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
0	CRS 2 Main Building Form	
1	CRS 3 Secondary Building Form	shed
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney L. Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

8. OTHER NOTES OR OBSERVATIONS:

CRS# N-12868

A small modern shed has been constructed at the rear of the property. The building possesses architectural features that mimic details seen in the dwelling and garage.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-12868

1. ADDRESS/LOCATION: 180 Welsh Tract Road

2. FUNCTION(S): historic _____ current garage

3. YEAR BUILT: 1995 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

if moved, from where

original location's CRS # year

list major alterations and additions with years (if known)

year

a.

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories one-story

c. Wall coverings board-and-batten

d. Foundation concrete

e. Roof

structural system side-gable

coverings rolled asphalt

openings n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: E

1) bays: two

2) windows: (1) pair of fixed, 8-pane sash windows; wood-framed

3) door(s): (1) pair of vertical wood-slat swing-hinge doors

4) other: n/a

b. Side: direction: S

- 1) **bays:** one
- 2) **windows:** (1) single fixed, 8-pane sash window; wood-framed
- 3) **door(s):** n/a
- 4) **other:** n/a

c. Side: direction: N

- 1) **bays:** one
- 2) **windows:** (1) single fixed, 8-pane sash window; wood-framed
- 3) **door(s):** n/a
- 4) **other:** n/a

d. Rear: direction: N

- 1) **bays:** inaccessible
- 2) **windows:** inaccessible
- 3) **door(s):** inaccessible
- 4) **other:** n/a

9. INTERIOR (if accessible):

a) Floor plan inaccessible

b) Partition/walls inaccessible

c) Finishes inaccessible

d) Furnishings/machinery inaccessible



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # N-12868

1. ADDRESS/LOCATION: 180 Welsh Tract Road
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

Card 1 of 2

PHOTOGRAPHIC INVENTORY

CRS # N-12868 Date 11/17/03 Photo Roll # C-4564 Surveyor Courtney Clark

Description View of front, SE side and NE side of dwelling; View of front, E side and S side of garage;View of rear, NW side and NE side of dwelling.

Negative location (if other than SHPO) _____

Attach contact print(s):




doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE
PHOTOGRAPHIC INVENTORY

CRS # N-12868
Card 2 of 2





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-14164
SPO Map 04-05-33
Hundred Pencader
Quad Newark West
Other 1100900045

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: 159 Welsh Tract Road
3. TOWN/NEAREST TOWN: Newark vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
landscape district
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
I-95/ Newark Toll Plaza Project (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	dwelling
1	CRS 3 Secondary Building Form	outbuilding
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-14164

1. ADDRESS/LOCATION: 159 Welsh Tract Road

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE OR FLOOR PLAN: Ranch

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. Carport attachment on E end

b. porch enclosure on N side

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: L-shape Stories: 1
Additions: 1-story gabled carport addition on E end

b. Structural system (if known): brick

c. Foundation: materials: covered by poured concrete
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): brick

e. Roof: shape: L-shape
materials: rolled asphalt
cornice: open
dormers: n/a
chimney: location(s): brick chimney located in center interior of dwelling

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: NW

1) Bays four

2) Windows

fenestration 1 -window in front gable-end on NE end; 1- window in corner of crossing gables; 1-pair of windows at NW end of dwelling

type 2 - Chicago bays w/ flanking double-hung 1/1 sashes; pair of double-hung 1/1 sash

trim none

shutters n/a

Facade (cont'd)

- 3) **Door(s)** one
 location within front gable-end on NE end of dwelling
 type wood pane-and-panel
 trim wood storm door
- 4) **Porch(es)** enclosed inset corner porch; on NW corner of front gable-end; vinyl siding

b. Side: Direction: SW

- 1) **Bays** two
- 2) **Windows**
 fenestration regular w/ 2 windows
 type double hung 1/1 sash
 trim brick sills
 shutters
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a

c. Side: Direction: NE

- 1) **Bays** two
- 2) **Windows**
 fenestration regular w/ 2 windows
 type double-hung 1/1 sash
 trim brick sills
 shutters
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a

d. Rear: Direction: SE

- 1) **Bays** five
- 2) **Windows**
 fenestration 1- window on SE end sheltered by sunporch; 3- regular windows on exterior of main block
 type double-hung 1/1 sash
 trim brick sills
 shutters none
- 3) **Door(s)** one
 location door on SE end sheltered by sunporch
 type wood; pane-and-panel
 trim none
- 4) **Porch(es)** 1-story, shed-roof sunporch; enclosed by awning glass-pane windows and vinyl siding

9. **INTERIOR:** no access

10. **LANDSCAPING:** Tall trees and woods surround the dwelling on all sides; planted hedges across N side; paved driveway lies to the E side of the dwelling

11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-14164

1. ADDRESS/LOCATION: 159 Welsh Tract Road

2. FUNCTION(S): historic _____ current shed

3. YEAR BUILT: 1990 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. none
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system frame - light timber

b. Number of stories 1

c. Wall coverings vinyl siding

d. Foundation wood

e. Roof
structural system side-gable
coverings rolled asphalt
openings n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: SW

1) bays: three

2) windows: 2 - modern double-hung 4/4 sash windows flanking by modern, non-functional shutters

3) door(s): 1 - pair of double-doors; wood; swing hinge

4) other: none

b. Side: direction: NW

- 1) **bays:** none
- 2) **windows:** n/a

- 3) **door(s):** n/a

- 4) **other:** n/a

c. Side: direction: SE

- 1) **bays:** none
- 2) **windows:** n/a

- 3) **door(s):** n/a

- 4) **other:** n/a

d. Rear: direction: NE

- 1) **bays:** none
- 2) **windows:** n/a

- 3) **door(s):** n/a

- 4) **other:** n/a

9. INTERIOR (if accessible):

a) Floor plan no access

b) Partition/walls no access

c) Finishes no access

d) Furnishings/machinery no access



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # N-14164

1. ADDRESS/LOCATION: 159 Welsh Tract Road
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

Card 1 of 2


PHOTOGRAPHIC INVENTORY

CRS # N-14164 Date 11/17/03 Photo Roll # C-4565 Surveyor Courtney Clark

Description View of front, NW side of dwelling; View of rear, SE side and NE side of dwelling; View of front, SW side and NW side of shed

Negative location (if other than SHPO) _____

Attach contact print(s):





doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE
PHOTOGRAPHIC INVENTORY

CRS # N-14164
Card 2 of 2





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-14163
SPO Map 04-05-33
Hundred Pencader
Quad Newark West
Other 1100900047

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: 147 Welsh Tract Road
3. TOWN/NEAREST TOWN: Newark vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
 landscape district
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
I-95/ Newark Toll Plaza Project (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	dwelling
1	CRS 3 Secondary Building Form	garage
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-14163

1. ADDRESS/LOCATION: 147 Welsh Tract Road

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE OR FLOOR PLAN: vernacular - gable front, 3-bay, center-passage

5. INTEGRITY: original site moved
if moved, from where _____ other location's CRS # _____ year _____

list major alterations and additions with years (if known) year

- a. Full-width, shed-roof addition across rear, E side
- b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular Stories: 1 1/2
Additions: Vertical wood panel siding; modern double-hung, 4/4 windows on the N and S-ends; pane-and-panel wood door in SW corner sheltered by modern shed-roof porch on wood deck
- b Structural system (if known): light-timber frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): stucco on all sides; horizontal aluminum in W gable-end
- e. Roof: shape: gable-front
materials: rolled asphalt
cornice: open
dormers: none
chimney: location(s): S side interior, brick chimney

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: NW
 - 1) Bays three
 - 2) Windows
 - fenestration regular w/ 2 windows flanking the entrance; upper level window over door
 - type double-hung, 2/2 sash
 - trim aluminum storm windows; brick sills
 - shutters none

Facade (cont'd)

- 3) Door(s) one
 - location centered
 - type pane-and-panel wood
 - trim aluminum storm door
- 4) Porch(es) full-width concrete deck

b. Side: Direction: SW

- 1) Bays two
- 2) Windows
 - fenestration regular w/ 2 windows on 1st floor
 - type double-hung, 2/2 sash
 - trim aluminum storm windows; brick sills; aluminum awnings
 - shutters
- 3) Door(s) n/a
 - location n/a
 - type n/a
 - trim n/a
- 4) Porch(es) n/a

c. Side: Direction: NE

- 1) Bays two
- 2) Windows
 - fenestration regular w/ 2 windows on 1st floor
 - type double-hung, 2/2 sash
 - trim aluminum storm windows; brick sills; aluminum awnings
 - shutters
- 3) Door(s) n/a
 - location n/a
 - type n/a
 - trim n/a
- 4) Porch(es) n/a

d. Rear: Direction: SE

- 1) Bays part of interior; no access
- 2) Windows part of interior; no access
 - fenestration part of interior
 - type part of interior
 - trim part of interior
 - shutters part of interior
- 3) Door(s) part of interior; no access
 - location part of interior
 - type part of interior
 - trim part of interior
- 4) Porch(es) none

9. INTERIOR: no access

10. LANDSCAPING: Tall trees grow to rear of property

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-14163

1. ADDRESS/LOCATION: 147 Welsh Tract Road

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: rectangular shaped building

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. none
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system concrete-block
b. Number of stories 1
c. Wall coverings exposed concrete-block on all sides with horizontal aluminum siding in W gable-end
d. Foundation concrete-block
e. Roof
structural system gabled-front
coverings corrugated metal roofing
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: NW
1) bays: one
2) windows: none
3) door(s): centered open bay entrance
4) other: none

- b. **Side: direction: SW**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible

 - 3) **door(s):** inaccessible

 - 4) **other:** n/a

- c. **Side: direction: NE**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible

 - 3) **door(s):** inaccessible

 - 4) **other:** n/a

- d. **Rear: direction: SE**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible

 - 3) **door(s):** inaccessible

 - 4) **other:** n/a

9. **INTERIOR (if accessible):**

a) **Floor plan** **inaccessible**

b) **Partition/walls** **inaccessible**

c) **Finishes** **inaccessible**

d) **Furnishings/machinery** **inaccessible**



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # N-14163

1. ADDRESS/LOCATION: 147 Welsh Tract Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # N-14163 Date 11/24/03 Photo Roll # C-4567 Surveyor Courtney Clark

Description View of front, NW side and SW side of dwelling; view of front, NW side of garage

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-14162
SPO Map 04-05-33
Hundred Pencader
Quad Newark West
Other 1100900031

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: 92 Welsh Tract Road
3. TOWN/NEAREST TOWN: Newark vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
 landscape district
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
I-95/ Newark Toll Plaza Project (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	dwelling
1	CRS 3 Secondary Building Form	garage
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-14162

1. ADDRESS/LOCATION: 92 Welsh Tract Road

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: vernacular

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

<u>list major alterations and additions with years (if known)</u>		<u>year</u>
a. porch enclosure on NE end		1970
b.		

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular Stories: 1 1/2
Additions: 1 1/2-story gabled addition on NE end; vinyl siding; Chicago bay window w/ flanking double-hung 1/1 windows on SE side; modern slab door with stepping lights, adjacent to window; modern wood stoop; modern double-hung 1/1 window on NE end, double-hung 1/1 window in upper level; one pair of modern double-hung 1/1 windows centered on NW side
- b. Structural system (if known): light-timber frame
- c. Foundation: materials: covered by poured concrete
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): vinyl-siding
- e. Roof: shape: side-gable
materials: rolled asphalt
cornice: open
dormers: 1-shed-roof dormer on NW side
chimney: location(s): centered , interior; covered in stucco

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: SE
 - 1) Bays three
 - 2) Windows
 - fenestration regular w/ 3 windows on 1st floor
 - type modern double-hung, 1/1 sash
 - trim none
 - shutters none

Facade (cont'd)

- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a

b. Side: Direction: NE

- 1) **Bays** **two**
- 2) **Windows** **part of interior; no access**
 fenestration **part of interior**
 type **part of interior**
 trim **part of interior**
 shutters **part of interior**
- 3) **Door(s)** **part of interior; no access**
 location **part of interior**
 type **part of interior**
 trim **part of interior**
- 4) **Porch(es)** n/a

c. Side: Direction: SW

- 1) **Bays** **two**
- 2) **Windows**
 fenestration **regular w/ 2 windows on 1st floor; one window in upper level**
 type **modern double-hung, 1/1 sash**
 trim **none**
 shutters **none**
- 3) **Door(s)** **N/A**
 location **N/A**
 type **N/A**
 trim **N/A**
- 4) **Porch(es)** **N/A**


d. Rear: Direction: NW

- 1) **Bays** **three**
- 2) **Windows**
 fenestration **regular w/ 2 windows on 1st floor flanking entrance**
 type **modern double-hung 1/1 sash**
 trim **none**
 shutters **none**
- 3) **Door(s)** **one**
 location **centered on main block**
 type **modern vinyl pane-and-panel**
 trim **modern storm door**
- 4) **Porch(es)** **1-story, shed-roof screen porch w/ entrance on NW side**

9. **INTERIOR:** no access

10. **LANDSCAPING:** Tall trees planted across the front, SE lawn; Tall trees grow along SW property boundary obscuring view of I-95 and toll plaza

11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-14162

1. ADDRESS/LOCATION: 92 Welsh Tract Road
2. FUNCTION(S): historic garage current garage
3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: unknown
4. STYLE/FLOOR PLAN: rectangular shaped building
5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known)

year

a.

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system unknown

b. Number of stories 1

c. Wall coverings stucco siding

d. Foundation unknown

e. Roof

structural system side-gable

coverings rolled asphalt

openings n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: SE

1) bays: three

2) windows: none

3) door(s): two modern vinyl garage doors; one modern vinyl, pane-and panel door centered on SE side

4) other: none

- b. **Side: direction: NE**
 - 1) **bays:** one
 - 2) **windows:** fixed, aluminum framed single-light window on N-end
 - 3) **door(s):** n/a
 - 4) **other:** n/a

- c. **Side: direction: SW**
 - 1) **bays:** one
 - 2) **windows:** fixed, aluminum framed single-light window on W side
 - 3) **door(s):** n/a
 - 4) **other:** n/a

- d. **Rear: direction: NW**
 - 1) **bays:** two
 - 2) **windows:** regular w/2 fixed, aluminum framed single-light windows
 - 3) **door(s):** n/a
 - 4) **other:** n/a

9. **INTERIOR (if accessible):**

- a) **Floor plan** **no access**

- b) **Partition/walls** **no access**

- c) **Finishes** **no access**

- d) **Furnishings/machinery** **no access**



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # N-14162

1. ADDRESS/LOCATION: 92 Welsh Tract Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # N-14162

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9

DELAWARE STATE HISTORIC PRESERVATION OFFICE

Card 1 of 2


PHOTOGRAPHIC INVENTORY

CRS # N-14162 Date 11/17/03 Photo Roll # C-4564 Surveyor Courtney Clark

Description View of front, SW side and SE side of dwelling; view of rear, NE side and SE side of dwelling; view of front, SW side and SE side of garage

Negative location (if other than SHPO) _____

Attach contact print(s):




doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE
PHOTOGRAPHIC INVENTORY

CRS # N-14162
Card 2 of 2





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-14161
SPO Map 04-05-33
Hundred Pencader
Quad Newark West
Other 1100900033

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: 46 Welsh Tract Road
3. TOWN/NEAREST TOWN: Newark vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
 landscape district
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
I-95/ Newark Toll Plaza Project (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	dwelling
1	CRS 3 Secondary Building Form	garage
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-14161

1. ADDRESS/LOCATION: 46 Welsh Tract Road

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE OR FLOOR PLAN: 3-bay, center passage, with Colonial Revival detailing

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. large addition on rear, N side

b. entrance addition to E side with garage attachment

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1 1/2
Additions: 1 1/2-story, gabled addition to N side; vinyl siding; modern double-hung 1/1 windows; metal double-door bulkhead attached to N side; 1-story, gabled addition to E side with shed-roof enclosure across N side; vinyl siding; modern doors; modern louvered glass-pane windows; attached modern wood deck to N side

b Structural system (if known): frame, light-timber

c. Foundation: materials: covered by poured concrete
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): vinyl-siding

e. Roof: shape: side-gable
materials: rolled asphalt
cornice: enclosed with vinyl
dormers: 2 - gable-front on S side; 1 - large gable-front on N side
chimney: location(s): brick chimney on exterior of E side

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: S

1) Bays three

2) Windows

fenestration regular w/ 2 windows on 1st floor flanking entrance; dormers on upper level
type 1-pair of modern double-hung 1/1 sash; 1-modern Chicago bay flanked by double-hung 1/1 sash

trim none

shutters none

Facade (cont'd)

- 3) **Door(s)** one
 location centered on main block
 type modern vinyl covered pane-and-panel
 trim none
- 4) **Porch(es)** 1-story, gable-front porch; supported by wood posts on concrete deck

b. Side: Direction: E

- 1) **Bays** one
- 2) **Windows**
 fenestration window on S end of main block
 type modern double-hung 1/1 sash
 trim none
 shutters none
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a

c. Side: Direction: W

- 1) **Bays** two
- 2) **Windows**
 fenestration regular w/ 2 windows on 1st floor
 type modern double-hung, 1/1 sash
 trim none
 shutters none
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a

d. Rear: Direction: N

- 1) **Bays** two
- 2) **Windows**
 fenestration windows on W end of main block; dormer on upper level
 type modern double-hung 1/1 sash
 trim none
 shutters none
- 3) **Door(s)** none
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** none

9. **INTERIOR:** no access

10. **LANDSCAPING:** Garden planted to the E side of dwelling; garden planted to the N side of dwelling; tall trees and woods to the rear N end of property boundary

11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-14161

1. ADDRESS/LOCATION: 46 Welsh Tract Road
2. FUNCTION(S): historic _____ current garage
3. YEAR BUILT: 1980 CIRCA?: ARCHITECT/BUILDER: unknown
4. STYLE/FLOOR PLAN: rectangular
5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known)

year

a. none

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood frame

b. Number of stories one-story

c. Wall coverings vinyl-siding

d. Foundation unknown

e. Roof

structural system gable-front

coverings asphalt

openings n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: S

1) bays: one

2) windows: none

3) door(s): vinyl garage door centered; multi-paneled

4) other: n/a

b. Side: direction: E

- 1) **bays:** n/a
- 2) **windows:** none
- 3) **door(s):** none
- 4) **other:** n/a

c. Side: direction: W

- 1) **bays:** n/a
- 2) **windows:** none
- 3) **door(s):** none
- 4) **other:** n/a

d. Rear: direction: N

- 1) **bays:** three
- 2) **windows:** regular modern double-hung 1/1 flanking the garage door
- 3) **door(s):** vinyl garage door centered; multi-paneled
- 4) **other:** n/a

9. INTERIOR (if accessible):

a) Floor plan **inaccessible**

b) Partition/walls **inaccessible**

c) Finishes **inaccessible**

d) Furnishings/machinery **inaccessible**



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # N-14161

1. ADDRESS/LOCATION: 46 Welsh Tract Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

Card 1 of 2

CRS # N-14161 Date 11/17/03 Photo Roll # C-4565 Surveyor Courtney Clark

Description View of front, S side and E side of dwelling; view of rear, N side of dwelling and garage

Negative location (if other than SHPO) _____

Attach contact print(s):




doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE
PHOTOGRAPHIC INVENTORY

CRS # N-14161
Card 2 of 2





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # N-12870

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: 36 Welsh Tract Road
3. CURRENT CONDITION: excellent good fair poor demolished
4. INTEGRITY: In 1992 vinyl siding was added to the exterior, and modern doors and windows were installed; one-and-one-half-story gabled-roof addition to N side; one-story shed-roof addition to S side; wood deck addition to the W side
5. SETTING INTEGRITY: outbuildings to rear of dwelling; Welsh Tract Baptist Church across the street (SE of the dwelling); Welsh Tract Church Caretaker's Cottage E of the dwelling

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
0	CRS 2 Main Building Form	
2	CRS 3 Secondary Building Form	garages
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney L. Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-12870

1. ADDRESS/LOCATION: 36 Welsh Tract Road

2. FUNCTION(S): historic _____ current garage

3. YEAR BUILT: 1980 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. none

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood frame

b. Number of stories one-story

c. Wall coverings vinyl-siding

d. Foundation unknown

e. Roof

structural system gable-front

coverings asphalt

openings n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: S

1) bays: one

2) windows: fixed, octogonal-shaped window in upper portion of gable-end

3) door(s): vinyl garage door centered; multi-paneled

4) other: none

- b. **Side: direction: E**
- 1) **bays:** n/a
 - 2) **windows:** none
 - 3) **door(s):** none
 - 4) **other:** one-story one-room shed-roof addition; sliding glass doors, and single wood door with wood surround; vinyl-siding sheathes entire addition; asphalt roofing
- c. **Side: direction: W**
- 1) **bays:** n/a
 - 2) **windows:** none
 - 3) **door(s):** none
 - 4) **other:** n/a
- d. **Rear: direction: N**
- 1) **bays:** inaccessible
 - 2) **windows:** inaccessible
 - 3) **door(s):** inaccessible
 - 4) **other:** inaccessible

9. **INTERIOR (if accessible):**

a) **Floor plan** **inaccessible**

b) **Partition/walls** **inaccessible**

c) **Finishes** **inaccessible**

d) **Furnishings/machinery** **inaccessible**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-12870

1. ADDRESS/LOCATION: 36 Welsh Tract Road
2. FUNCTION(S): historic _____ current garage
3. YEAR BUILT: 1990 CIRCA?: ARCHITECT/BUILDER: unknown
4. STYLE/FLOOR PLAN: rectangular
5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known)

- a. none _____ year
- b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood frame
- b. Number of stories one-story
- c. Wall coverings horizontal wood-siding
- d. Foundation wood
- e. Roof
 structural system side-gable
 coverings asphalt
 openings faux four-sided ventilator

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: E
- 1) bays: three
- 2) windows: modern double-hung windows with faux four-over-four vinyl mullions
- 3) door(s): one modern pair of wood swing-hinge doors
- 4) other: none

- b. **Side: direction: N**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible

 - 3) **door(s):** inaccessible

 - 4) **other:** inaccessible

- c. **Side: direction: S**
 - 1) **bays:** none
 - 2) **windows:** none

 - 3) **door(s):** none

 - 4) **other:** n/a

- d. **Rear: direction: W**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible

 - 3) **door(s):** inaccessible

 - 4) **other:** inaccessible

9. **INTERIOR (if accessible):**

a) **Floor plan** **inaccessible**

b) **Partition/walls** **inaccessible**

c) **Finishes** **inaccessible**

d) **Furnishings/machinery** **inaccessible**



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # N-12870

1. ADDRESS/LOCATION: 36 Welsh Tract Road
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

Card 1 of 2


PHOTOGRAPHIC INVENTORY

CRS # N-12870 Date 11/24/03 Photo Roll # C-4566 Surveyor Courtney Clark

Description View of front, S side and W side of the dwelling; view of front, S side and W side of garage #1; view of S end and front, E side of garage #2

Negative location (if other than SHPO) _____

Attach contact print(s):




doc # 20-06-01-05-12

CRS-13

DELAWARE STATE HISTORIC PRESERVATION OFFICE
PHOTOGRAPHIC INVENTORY

CRS # N-12870
Card 2 of 2





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-14166
SPO Map 08-09-34
Hundred White Clay Crk.
Quad Newark East
Other 0903000071

1. HISTORIC NAME/FUNCTION: Dwelling, 104 Stanton Christiana Road
2. ADDRESS/LOCATION: 104 Stanton Christiana Road
3. TOWN/NEAREST TOWN: Christiana vicinity?
4. MAIN TYPE OF RESOURCE: building structure
 landscape district site object
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
I-95/ Newark Toll Plaza Project (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	dwelling
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-14166

1. ADDRESS/LOCATION: 104 Stanton Christiana Road (S.R. 7)

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE OR FLOOR PLAN: Ranch-style

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. none

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1
Additions: none

b. Structural system (if known): brick

c. Foundation: materials: poured concrete
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): brick

e. Roof: shape: side-gable
materials: asphalt
cornice: open
dormers: none
chimney: location(s): brick; interior of S end

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: W
1) Bays four
2) Windows
fenestration irregular
type (1) Chicago bay w/ fixed center sash and flanking double-hung 1/1 sashes; to S side of entrance; (2) double-hung 2/2 horizontal pane sashes; towards N end
trim brick sills
shutters non-functional; vinyl; louvered panels

Facade (cont'd)

- 3) **Door(s)** **one**
 location **center**
 type **wood**
 trim **none**
- 4) **Porch(es)** **inset, open porch from center to S end of front side of dwelling**

b. Side: Direction: S

- 1) **Bays** **no access**
- 2) **Windows** **no access**
 fenestration **no access**
 type **no access**
 trim **no access**
 shutters **no access**
- 3) **Door(s)** **no access**
 location **no access**
 type **no access**
 trim **no access**
- 4) **Porch(es)** **n/a**

c. Side: Direction: N

- 1) **Bays** **no access**
- 2) **Windows** **no access**
 fenestration **no access**
 type **no access**
 trim **no access**
 shutters **no access**
- 3) **Door(s)** **no access**
 location **no access**
 type **no access**
 trim **no access**
- 4) **Porch(es)** **no access**

d. Rear: Direction: E

- 1) **Bays** **no access**
- 2) **Windows** **no access**
 fenestration **no access**
 type **no access**
 trim **no access**
 shutters **no access**
- 3) **Door(s)** **no access**
 location **no access**
 type **no access**
 trim **no access**
- 4) **Porch(es)** **no access**

9. **INTERIOR:** no access

10. **LANDSCAPING:** heavily overgrown lot; tall trees shade dwelling from all sides; dwelling set back from the road w/ curved dirt driveway leading to house

11. **OTHER COMMENTS:**



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # N-14166

1. ADDRESS/LOCATION: 104 Stanton Christiana Road (S.R. 7)
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # N-14166 Date 12/01/03 Photo Roll # C-4567 Surveyor Courtney Clark

Description View of front, W side of dwelling

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-14167
SPO Map 08-09-34
Hundred White Clay Crk.
Quad Newark East
Other 0903000068

1. HISTORIC NAME/FUNCTION: Dwelling, 120 Stanton Christiana Road
2. ADDRESS/LOCATION: 120 Stanton Christiana Road
3. TOWN/NEAREST TOWN: Christiana vicinity?
4. MAIN TYPE OF RESOURCE: building landscape structure district site object
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
I-95/ Newark Toll Plaza Project

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	dwelling
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-14167

1. ADDRESS/LOCATION: 120 Stanton Christiana Road (S.R. 7)
2. FUNCTION(S): historic single-family dwelling current single-family dwelling
3. YEAR BUILT: 1956 CIRCA?: ARCHITECT/BUILDER: not known
4. STYLE OR FLOOR PLAN: Ranch-style
5. INTEGRITY: original site moved
 if moved, from where _____ other location's CRS # _____ year _____

list major alterations and additions with years (if known)

- | | <u>year</u> |
|--|-------------|
| a. addition to rear, E side (in-law suite) | 1975 |
| b. | |

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangular Stories: 1
 Additions: 1-story gabled addition to rear, E side; 3-room interior; aluminum siding; double-hung 2/2 horizontal pane sashes; vinyl-covered door w/ one sidelight
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete-block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible & any subsequent coverings): aluminum siding
- e. Roof: shape: side-gable
 materials: asphalt
 cornice: boxed and enclosed w/ wood
 dormers: n/a
 chimney: location(s): brick chimney; center, interior

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: W
- 1) Bays six
- 2) Windows fenestration irregular
 type (1) Chicago bay w/ fixed center sash and flanking double-hung 1/1 sashes; (1) awning style windows on NW end; louvered glass-panes in enclosed porch (center of front)
 trim none
 shutters none

Facade (cont'd)

3) **Door(s)** one
 location N side of enclosed porch
 type modern vinyl covered door
 trim

4) **Porch(es)** enclosed gable-front sun porch; 1-story; louvered-glass pane window bays;
 modern vinyl door

b. Side: Direction: S

1) **Bays** no access

2) **Windows** no access
 fenestration no access
 type no access
 trim no access
 shutters no access

3) **Door(s)** no access
 location no access
 type no access
 trim no access

4) **Porch(es)** n/a

c. Side: Direction: N

1) **Bays** n/a

2) **Windows**
 fenestration n/a
 type n/a
 trim n/a
 shutters n/a

3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a

4) **Porch(es)** n/a

d. Rear: Direction: E

1) **Bays** four

2) **Windows**
 fenestration irregular
 type (1) Chicago Bay w/ centered fixed sash and flanking double-hung 1/1 sashes;
 (1) pair of double-hung 1/1 sash; (1) awning-style window on NE end
 trim n/a
 shutters n/a

3) **Door(s)** two
 location (1) door on NE end of dwelling; (1) bulkhead in centered of exterior
 type (1) vinyl-and-glass; (1) metal double-door bulkhead
 trim n/a

4) **Porch(es)** n/a

9. **INTERIOR:** no access

10. **LANDSCAPING:** deep, rectangular-shaped lot; tall trees sporadically planted throughout property

11. **OTHER COMMENTS:**



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # N-14167

1. ADDRESS/LOCATION: 120 Stanton Christiana Road (S.R. 7)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE


PHOTOGRAPHIC INVENTORY

CRS # N-14167 Date 12/01/03 Photo Roll # C-4567 Surveyor Courtney Clark

Description View of front, W side of dwelling; View of rear, E side of dwelling

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-14168
SPO Map 08-09-34
Hundred White Clay Crk.
Quad Newark East
Other 0903000066

1. HISTORIC NAME/FUNCTION: Dwelling, 128 Stanton Christiana Road
2. ADDRESS/LOCATION: 128 Stanton Christiana Road
3. TOWN/NEAREST TOWN: Christiana vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
landscape district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
I-95/ Newark Toll Plaza Project (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	
1	CRS 3 Secondary Building Form	garage
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-14168

1. ADDRESS/LOCATION: 128 Stanton Christiana Road (S.R. 7)

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1956 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: 3-bay, center passage, with Cape cod detailing

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. small, porch enclosed addition on SE corner of E side

b. small entrance addition to basement on E corner of S side

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular Stories: 1 1/2
Additions: 1-story, porch enclosed addition to SE corner of E side; shed-roof; modern storm door; brick decking; 1-story addition to E corner of S side; gabled; appears slightly embanked
- b. Structural system (if known): brick
- c. Foundation: materials: poured concrete
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): brick
- e. Roof: shape: side-gable
materials: rolled asphalt
cornice: open
dormers: (2) gable-front dormers on W side; (1) large gable-front dormer on E side
chimney: location(s): brick chimney on exterior of N side

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: W
 - 1) Bays three
 - 2) Windows
 - fenestration regular w/ windows flanking entrance on 1st floor; dormers on upper level
 - type (1) pair of modern double-hung 1/1 sash; (1) Chicago bay w/ fixed center pane and flanking double-hung 1/1 sash
 - trim concrete slab sill; soldier brick lintels
 - shutters none

Facade (cont'd)

- 3) **Door(s)** one
 location centered on main block
 type modern pane-and-panel; vinyl
 trim none
- 4) **Porch(es)** concrete slab w/ steps

b. Side: Direction: N

- 1) **Bays** two
- 2) **Windows**
 fenestration regular w/ 2 windows flanking chimney on 1st floor
 type modern double-hung 1/1 sash
 trim concrete slab sill; soldier brick lintels
 shutters
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a

c. Side: Direction: S

- 1) **Bays** two
- 2) **Windows**
 fenestration regular w/ 2 windows on 1st floor
 type (1) single modern double-hung 1/1 sash; (1) pair of modern double-hung 1/1 sash
 trim concrete slab sill; soldier brick lintels
 shutters none
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a


d. Rear: Direction: E

- 1) **Bays** three
- 2) **Windows**
 fenestration regular w/ two window and corner entrance
 type (1) single modern double-hung 1/1 sash; (1) pair of modern double-hung 1/1 sash
 trim concrete slab sill; soldier brick lintels
 shutters
- 3) **Door(s)** one
 location SE corner
 type modern, pane-and-panel door; vinyl
 trim
- 4) **Porch(es)** porch enclosure (see above)

9. **INTERIOR:** no access

10. **LANDSCAPING:** rectangular lot; semi-circular driveway across front lawn w/ extension along S side; pool to rear, E side of dwelling; tall holly trees flank front entrance; multiple trees planted within semi-circle of front lawn

11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-14168

1. ADDRESS/LOCATION: 128 Stanton Christiana Road (S.R. 7)
2. FUNCTION(S): historic _____ current garage
3. YEAR BUILT: 1970 CIRCA?: ARCHITECT/BUILDER: unknown
4. STYLE/FLOOR PLAN: square
5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known)

year

a. 1-story shed-roof addition to rear, E side

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood frame
- b. Number of stories one-story
- c. Wall coverings vertical wood paneling
- d. Foundation unknown
- e. Roof
structural system side-gable
coverings asphalt
openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: W
- 1) bays: two
- 2) windows: n/a
- 3) door(s): (2) pane-and-panel garage doors; wood
- 4) other: none

- b. **Side: direction: N**
 - 1) **bays:** two
 - 2) **windows:** double-hung 1/1 sash

 - 3) **door(s):** n/a

 - 4) **other:** n/a

- c. **Side: direction: S**
 - 1) **bays:** none
 - 2) **windows:** n/a

 - 3) **door(s):** n/a

 - 4) **other:** n/a

- d. **Rear: direction: E**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible

 - 3) **door(s):** inaccessible

 - 4) **other:** inaccessible

9. **INTERIOR (if accessible):**

a) **Floor plan** **inaccessible**

b) **Partition/walls** **inaccessible**

c) **Finishes** **inaccessible**

d) **Furnishings/machinery** **inaccessible**



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # N-14168

1. ADDRESS/LOCATION: 128 Stanton Christiana Road (S.R. 7)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE


PHOTOGRAPHIC INVENTORY

CRS # N-14168 Date 12/01/03 Photo Roll # C-4567 Surveyor Courtney Clark

Description View of front, W side of dwelling; View of rear, E and S side of dwelling; View of front, W side of garage

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # N-6783

1. HISTORIC NAME/FUNCTION: Lewis Weldon Farm/ Stafford Farm

2. ADDRESS/LOCATION: 857 Churchmans Road

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: This property lacks integrity. Only one structure remains standing from the former farm.

5. SETTING INTEGRITY: The last remaining structure of the former farm stands along the north side of I-95, between the roadway and the rear of modern hotel/ motels.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
0	CRS 2 Main Building Form	
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
1	CRS 5 Structure (Building-Like) Form	silo
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Miler Associates, Inc., Date: 12/1/2003

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
STRUCTURE (BUILDING-LIKE) FORM

CRS # N-6783

1. ADDRESS/LOCATION: 857 Churchmans Road; N side of I-95

2. FUNCTION: agricultural; silo IN USE?
no

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/PLAN: cylindrical

5. INTEGRITY: original site moved

if moved, from where original location's CRS # year

list major alterations and additions with dates (if known) year

a. none

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION (describe the structure as completely as possible):

a) Overall shape cylindrical
height 4-stories
length n/a
width n/a

b) Structural system: concrete-stave

c) Foundation:

d) Exterior covering: exposed concrete-staves; metal, standing-seam dome-shaped roof

e) Openings opening in cap

f) Other features hemispherical metal cap



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # N-6783

1. ADDRESS/LOCATION: 857 Churchmans Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # N-6783 Date 11/17/2003 Photo Roll # C-4567 Surveyor Courtney Clark

Description View of silo along N side of I-95; former Stafford Farm property (857 Churchmans Road)

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # N-12904

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: Churchmans Road; N Corner Of Churchmans Road And County Commerce Drive
3. CURRENT CONDITION: excellent good fair poor demolished
4. INTEGRITY: integrity of material has been comprised with the insertion of replacement windows, and the construction of the side, concrete-block addition.
-
5. SETTING INTEGRITY: the property's integrity of location, setting and feeling as a residential property has been altered. the buildings is vacant and unused. a large water company is located on the same legal tax boundary and modern commercial buildings across the street.
-

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	building
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney L. Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization
- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)
- c) Historic period theme(s)
- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-12904

1. ADDRESS/LOCATION: Churchmans Road; N Corner Of Churchmans Road And County Commerce Drive

2. FUNCTION(S): historic single-family dwelling current vacant

3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: 3-bay, side-hall

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. concrete-block attached to E side (embanked)
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1 1/2
Additions: two sided, L-shaped concrete-block wall attached to E side of dwelling; embanked

b. Structural system (if known): unknown

c. Foundation: materials: concrete
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): stucco

e. Roof: shape: side-gable
materials: rolled asphalt
cornice: open
dormers: none
chimney: location(s): large chimney on W gable-end; covered in stucco

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: S
1) Bays three
2) Windows fenestration irregular w/ 2 windows and a corner entrance
type (2) small modern double-hung 1/1 sash
trim none
shutters remanats of shutters; hardware still intact

Facade (cont'd)

- 3) **Door(s)** one
 location west end
 type pane-and-panel; wood
 trim wood frame
- 4) **Porch(es)** n/a

b. Side: Direction: W

- 1) **Bays** two
- 2) **Windows**
 fenestration irregular w/ windows flanking chimney
 type (1) modern double-hung 1/1 sash; (1) pair of modern double-hung 6/6 sash; (1) fixed 12-pane sash centered in upper portion of gable-end
 trim none
 shutters none
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a

c. Side: Direction: E

- 1) **Bays** two
- 2) **Windows**
 fenestration regular w/ 2 windows on 1st floor
 type (1) fixed, 12-pane sash; (1) pair of fixed, 8-pane sash
 trim n/a
 shutters none
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a

d. Rear: Direction: N

- 1) **Bays** three
- 2) **Windows**
 fenestration irregular
 type fixed, 12-pane sash
 trim none
 shutters n/a
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a

9. **INTERIOR:** no access

10. **LANDSCAPING:** located in the southern portion of the Artesian Water Company property, situated perpendicular to Churchmans Road; varied ground elevation on all sides of property; Artesian Water Company E of dwelling

11. **OTHER COMMENTS:**



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # N-12904

1. ADDRESS/LOCATION: Churchmans Road; N Corner Of Churchmans Road And County Commerce Drive


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # N-12904 Date 12/01/03 Photo Roll # C-4567 Surveyor Courtney Clark

Description View of front, S and portion of W side of dwelling; View of rear, N and E side of dwelling

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # N-1603

1. HISTORIC NAME/FUNCTION: Henry L. Churchmans House ; Jarber House

2. ADDRESS/LOCATION: 648 Churchmans Road

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: all historic fabric intact; attached 3-bay wide garage on NW end

5. SETTING INTEGRITY: modern development surrounds the property

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	dwelling
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney L. Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

8. OTHER NOTES OR OBSERVATIONS:

CRS# N-1603

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-1603

1. ADDRESS/LOCATION: 648 Churchmans Road

2. FUNCTION(S): historic dwelling current dwelling

3. YEAR BUILT: 1850 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE OR FLOOR PLAN: five-bay; center-hall

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year
a. 3-bay garage attached to NW gable-end 1980
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular Stories: 2 1/2
Additions: 1-story, 3-bay garage attached to NW gable-end; wood-and-glass garage doors; stucco siding
- b. Structural system (if known): unknown
- c. Foundation: materials: sheathed by concrete
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): stucco
- e. Roof: shape: side-gable
materials: asphalt shingles
cornice: n/a
dormers: (3) regular gable-front dormers w/ double-hung 2/2 gothic sashes
chimney: location(s): in both gable-ends; stucco covered

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: SW
 - 1) Bays five
 - 2) Windows fenestration regular w/ 2 single windows flanking entrance on 1st floor; 5 windows across 2nd floor
type double-hung 2/2 sash
trim wood surrounds; wood storm windows
shutters functional; wood panel

Facade (cont'd)

- 3) **Door(s)** one
 location centered on main block
 type pane-and-panel, wood
 trim none
- 4) **Porch(es)** small one-story, gable-front porch; wood post supports; wood deck

b. Side: Direction: SE

- 1) **Bays** three
- 2) **Windows**
 fenestration unknown; limited access; 3 regular windows across 2nd floor; 1 small window centered w/in gable peak
 type double-hung 2/2 sash
 trim none
 shutters functional wood panel
- 3) **Door(s)** two
 location within screened porch
 type wood-and-glass
 trim none
- 4) **Porch(es)** one-story flat roof enclosed sun porch; deck on roof-top w/ wood slat hand railing

c. Side: Direction: NW

- 1) **Bays** three
- 2) **Windows**
 fenestration 3 regular windows across 2nd floor; 1 small window centered within gable peak
 type double hung 2/2 sash
 trim none
 shutters none
- 3) **Door(s)** none
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** none

d. Rear: Direction: NE

- 1) **Bays** five
- 2) **Windows**
 fenestration regular with 2 single windows flanking entrance on 1st floor; 5 windows across 2nd floor
 type double hung 2/2 sash
 trim wood surrounds; wood storm windows
 shutters functional; wood panel
- 3) **Door(s)** one
 location centered on main block
 type panel, wood
 trim transom and flanking sidelights
- 4) **Porch(es)** none

9. **INTERIOR:** center hall with large parlor on NW end; library and kitchen SE end; 4 bedrooms on 2nd floor; 3rd floor inaccessible
10. **LANDSCAPING:** tall trees are planted close to the dwelling on all sides; hedges are planted across the front side; U- shaped driveway in front lawn
11. **OTHER COMMENTS:**



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # N-1603

1. ADDRESS/LOCATION: 648 Churchmans Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # N-1603 Date 11/17/03 Photo Roll # C-4567 Surveyor Courtney Clark

Description View of front, SW and SE side of dwelling

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-14173
SPO Map 08-09-34
Hundred Christiana
Quad Wilmington So.
Other 1000800025

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: 423 Old Airport Road
3. TOWN/NEAREST TOWN: Newport vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
 landscape district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
I-95/ Newark Toll Plaza Project (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	
0	CRS 3 Secondary Building Form	
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-14173

1. ADDRESS/LOCATION: 423 Old Airport Road

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: 3-bay, center-passage, with Cape Cod detailing

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

- a. none
- b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1 1/2
Additions:

b Structural system (if known): unknown

c. Foundation: materials: covered by stucco
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): stucco w/ asbestos shinngles in the gable ends

e. Roof: shape: side-gable
materials: rolled asphalt
cornice: open
dormers: (2) gable-front on SE side covered in vinyl siding
chimney: location(s): brick; exterior on NE side

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: SE
 - 1) Bays three
 - 2) Windows fenestration regular w/ 2 windows flanking entrance
type (2) pairs of double-hung 6/1 sash
trim brick sills
shutters none

Facade (cont'd)

- 3) **Door(s)** **one**
 location **center**
 type **wood-and-glass**
 trim **wood surround w/ flanking pilasters**
- 4) **Porch(es)** **open vestibule w/ attached shed-roofed hood**

b. Side: Direction: SW

- 1) **Bays** **two**
- 2) **Windows**
 fenestration **regular w/ 2 windows on the 1st floor and one window in upper portion of gable**
 type **(2) single double-hung 6/1 sash; (1) pair of double-hung 6/1 sash**
 trim **brick sills**
 shutters **none**
- 3) **Door(s)** **n/a**
 location **n/a**
 type **n/a**
 trim **n/a**
- 4) **Porch(es)** **n/a**

c. Side: Direction: NE

- 1) **Bays** **no access**
- 2) **Windows** **no access**
 fenestration **no access**
 type **no access**
 trim **no access**
 shutters **no access**
- 3) **Door(s)** **no access**
 location **no access**
 type **no access**
 trim **no access**
- 4) **Porch(es)** **no access**

d. Rear: Direction: NW

- 1) **Bays** **no access**
- 2) **Windows** **no access**
 fenestration **no access**
 type **no access**
 trim **no access**
 shutters **no access**
- 3) **Door(s)** **no access**
 location **no access**
 type **no access**
 trim **no access**
- 4) **Porch(es)** **no access**

9. **INTERIOR: no access**

10. **LANDSCAPING: slightly overgrown, flat lot planted in bushes and grass**

11. **OTHER COMMENTS:**

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # N-14173

1. ADDRESS/LOCATION: 423 Old Airport Road
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # N-14173 Date 12/01/03 Photo Roll # C-4567 Surveyor Courtney Clark

Description View of front, SE and NE side of dwelling.


Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-14172
SPO Map 08-09-34
Hundred Christiana
Quad Wilmington So.
Other 1000800038

1. HISTORIC NAME/FUNCTION: Dwelling, 424 Airport Road
2. ADDRESS/LOCATION: 424 Airport Road
3. TOWN/NEAREST TOWN: Newport vicinity?
4. MAIN TYPE OF RESOURCE: building structure
 landscape district site object
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
I-95/ Newark Toll Plaza Project (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	dwelling
1	CRS 3 Secondary Building Form	garage
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-14172

1. ADDRESS/LOCATION: 424 Old Airport Road
2. FUNCTION(S): historic single-family dwelling current single-family dwelling
3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: _____
4. STYLE OR FLOOR PLAN: 3-bay, center-passage
5. INTEGRITY: original site moved
 if moved, from where _____ other location's CRS # _____ year _____

list major alterations and additions with years (if known)

- a. porch enclosure on NW side _____ year _____
- b. _____

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangular Stories: 1 1/2
 Additions: porch enclosure on the NW side; aluminum siding; aluminum framed awning glass windows
- b. Structural system (if known): unknown
- c. Foundation: materials: sheathed in stucco
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): stucco
- e. Roof: shape: gable-front
 materials: rolled asphalt
 cornice: enclosed by vinyl
 dormers: none
 chimney: location(s): exterior on SE side

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: NW
- 1) Bays three
- 2) Windows fenestration regular w/ 2 windows flanking entrance, a window in gable peak; small, louvered wood vent in apex of gable
 type double-hung 6/6 sash
 trim brick sills
 shutters none

Facade (cont'd)

- 3) Door(s) one
location center
type wood-and-glass
trim none
- 4) Porch(es) enclosed gable-front porch; covered by aluminum siding; aluminum-framed awning windows

b. Side: Direction: NE

- 1) Bays four
- 2) Windows
fenestration regular
type double-hung 6/6 sash
trim brick sills
shutters none
- 3) Door(s) n/a
location n/a
type n/a
trim n/a
- 4) Porch(es) n/a

c. Side: Direction: SW

- 1) Bays no access
- 2) Windows no access
fenestration no access
type no access
trim no access
shutters no access
- 3) Door(s) no access
location no access
type no access
trim no access
- 4) Porch(es) no access


d. Rear: Direction: SE

- 1) Bays no access
- 2) Windows no access
fenestration no access
type no access
trim no access
shutters no access
- 3) Door(s) no access
location no access
type no access
trim no access
- 4) Porch(es) no access

9. INTERIOR: no access

10. LANDSCAPING: small lawn area to the front and rear of the dwelling; I-95 abuts rear of property boundary; small hedges are planted across the front and side lawn

11. OTHER COMMENTS: Machine shop adjacent to dwelling, to the NE side



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-14172

1. ADDRESS/LOCATION: 424 Old Airport Road

2. FUNCTION(S): historic garage current machine shop

3. YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: square

5. INTEGRITY: original site moved

if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

- a. one-story addition to NE side
- b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system concrete

b. Number of stories 2

c. Wall coverings stucco

d. Foundation

e. Roof
structural system flat
coverings unknown
openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: NW
 - 1) bays: two
 - 2) windows: (3) on 2nd level; metal-framed; awning windows
 - 3) door(s): (2) vinyl roll-down garage doors
 - 4) other: none

- b. **Side: direction: NE**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible

 - 3) **door(s):** inaccessible

 - 4) **other:** none

- c. **Side: direction: SW**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible

 - 3) **door(s):** inaccessible

 - 4) **other:** none

- d. **Rear: direction: SE**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible

 - 3) **door(s):** inaccessible

 - 4) **other:** none

9. **INTERIOR (if accessible):**

a) **Floor plan** **inaccessible**

b) **Partition/walls** **inaccessible**

c) **Finishes** **inaccessible**

d) **Furnishings/machinery** **inaccessible**



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # N-14172

1. ADDRESS/LOCATION: 424 Old Airport Road
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE


PHOTOGRAPHIC INVENTORY

CRS # N-14172 Date 12/01/03 Photo Roll # C-4567 Surveyor Courtney Clark

Description View of front, NW and NE side of dwelling; View of front, NW side of garage.


Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-14171
SPO Map 08-09-34
Hundred Christiana
Quad Wilmington So.
Other 1000800023

1. HISTORIC NAME/FUNCTION: Dwellings, 431 Airport Road
2. ADDRESS/LOCATION: 431 Airport Road
3. TOWN/NEAREST TOWN: Newport vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
 landscape district
5. MAIN FUNCTION OF PROPERTY: Dwellings
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
I-95/ Newark Toll Plaza Project (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	dwellings
1	CRS 3 Secondary Building Form	apartment
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

9. OTHER NOTES OR OBSERVATIONS:

CRS# N-14171

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-14171

1. ADDRESS/LOCATION: 431 Old Airport Road

2. FUNCTION(S): historic single-family dwelling current vacant

3. YEAR BUILT: 1935 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE OR FLOOR PLAN: 3-bay, center-passage

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. one-story addition attached to NW side

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1 1/2
Additions: one-story addition attached to NW side; shed-roof; stucco siding; one-room in size

b. Structural system (if known): unknown

c. Foundation: materials: sheathed in stucco
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): stucco

e. Roof: shape: gable-front
materials: rolled asphalt
cornice: open
dormers: none
chimney: location(s): brick; center, interior

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: SE
1) Bays three
2) Windows
fenestration irregular w/ 2 windows flanking entrance, a window in gable peak
type double-hung 1/1 sash
trim concrete slab sills
shutters none

Facade (cont'd)

- 3) **Door(s)** **one**
 location **center**
 type **modern wood-and-glass**
 trim **none**
- 4) **Porch(es)** **concrete steps and small pad; vinyl awning sheltering door**

b. Side: Direction: NE

- 1) **Bays** **three**
- 2) **Windows**
 fenestration **regular**
 type **(2) pairs of double-hung 1/1 sash; (1) single double-hung 1/1 sash**
 trim **concrete slab sills**
 shutters **none**
- 3) **Door(s)** **n/a**
 location **n/a**
 type **n/a**
 trim **n/a**
- 4) **Porch(es)** **n/a**

c. Side: Direction: SW

- 1) **Bays** **four**
- 2) **Windows**
 fenestration **regular**
 type **double-hung 1/1 sash**
 trim **concrete slab sills**
 shutters **none**
- 3) **Door(s)** **n/a**
 location **n/a**
 type **n/a**
 trim **n/a**
- 4) **Porch(es)** **n/a**

d. Rear: Direction: NW

- 1) **Bays** **inaccessible**
- 2) **Windows** **inaccessible**
 fenestration **inaccessible**
 type **inaccessible**
 trim **inaccessible**
 shutters **inaccessible**
- 3) **Door(s)** **inaccessible**
 location **inaccessible**
 type **inaccessible**
 trim **inaccessible**
- 4) **Porch(es)** **inaccessible**

9. **INTERIOR: inaccessible**

10. **LANDSCAPING: flat, rectangular lot; abuts the Christiana River to the rear of the lot; tree shaded; overgrown landscape**

11. **OTHER COMMENTS: all buildings vacant and appear unused; lot for sale (2-acres)**



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-14171

1. ADDRESS/LOCATION: 431 Old Airport Road

2. FUNCTION(S): historic single-family dwelling current vacant

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE OR FLOOR PLAN: Ranch

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

- a.
- b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1
Additions: none

b. Structural system (if known): brick

c. Foundation: materials: not visible
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): stucco

e. Roof: shape: side-gable
materials: rolled asphalt
cornice: open
dormers: none
chimney: location(s): brick; interior

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: SE
 - 1) Bays four
 - 2) Windows fenestration irregular
type (2) single double-hung 1/1 sash; (1) pair double-hung 1/1 sash
trim brick sills
shutters none

Facade (cont'd)

- 3) **Door(s)** one
 location off center; towards NE end
 type vinyl-and-glass
 trim none
- 4) **Porch(es)** partial screen porch ; one-story; shed-roof w/ wood posts supports; concrete deck

b. Side: Direction: NE

- 1) **Bays** three
- 2) **Windows**
 fenestration irregular
 type double-hung 1/1 sash
 trim brick sills
 shutters none
- 3) **Door(s)** one
 location off-center
 type wood-and-glass
 trim none
- 4) **Porch(es)** one-story, shed-roof porch w/ plastic pipie supports; concrete deck

c. Side: Direction: SW

- 1) **Bays** no access
- 2) **Windows** no access
 fenestration no access
 type no access
 trim no access
 shutters no access
- 3) **Door(s)** no access
 location no access
 type no access
 trim no access
- 4) **Porch(es)** no access

d. Rear: Direction: NW

- 1) **Bays** no access
- 2) **Windows** no access
 fenestration no access
 type no access
 trim no access
 shutters no access
- 3) **Door(s)** no access
 location no access
 type no access
 trim no access
- 4) **Porch(es)** no access

9. **INTERIOR:** no access

10. **LANDSCAPING:** flat, rectangular lot; abuts the Christiana River to the rear of the lot; tree shaded; overgrown landscape

11. **OTHER COMMENTS:** all buildings vacant and appear unused; lot for sale (2-acres)



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-14171

1. ADDRESS/LOCATION: 431 Old Airport Road

2. FUNCTION(S): historic outbuilding/ apartment current vacant

3. YEAR BUILT: 1935 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. one-story addition to NW side
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system unknown
b. Number of stories 1
c. Wall coverings stucco
d. Foundation wood
e. Roof
structural system gable-front
coverings tar paper
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: SE
1) bays: two
2) windows: double-hung 2/2 sash
3) door(s): wood-and-glass
4) other: none

- b. **Side: direction: NE**
- 1) **bays:** two
 - 2) **windows:** double-hung 2/2 sash
 - 3) **door(s):** n/a
 - 4) **other:** none

- c. **Side: direction: SW**
- 1) **bays:** no access
 - 2) **windows:** no access
 - 3) **door(s):** no access
 - 4) **other:** none

- d. **Rear: direction: NW**
- 1) **bays:** no access
 - 2) **windows:** no access
 - 3) **door(s):** no access
 - 4) **other:** none

9. **INTERIOR (if accessible):**

a) **Floor plan** **no access**

b) **Partition/walls** **no access**

c) **Finishes** **no access**

d) **Furnishings/machinery** **no access**



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # N-14171

1. ADDRESS/LOCATION: 431 Old Airport Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE


PHOTOGRAPHIC INVENTORY

CRS # N-14171 Date 12/01/03 Photo Roll # C-4567 Surveyor Courtney Clark

Description View of front, SE and NE side of dwelling on east side of property;View of front, SE and NE side of dwelling on west side of property;View of front, SE and NE side of secondary building, behind above mentioned dwelling

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-14170
SPO Map 08-09-34
Hundred Christiana
Quad Wilmington So.
Other 1000800022

1. HISTORIC NAME/FUNCTION: Dwelling, 433 Airport Road
2. ADDRESS/LOCATION: 433 Airport Road
3. TOWN/NEAREST TOWN: Newport vicinity?
4. MAIN TYPE OF RESOURCE: building structure
landscape district site object
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
I-95/ Newark Toll Plaza Project (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	
1	CRS 3 Secondary Building Form	garage
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____


Organization: John Milner Associates, Inc. Date: 11/1/2003

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-14170

1. ADDRESS/LOCATION: 433 Old Airport Road

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE OR FLOOR PLAN: center-passage

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. Full-width porch across rear, NW side

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1 1/2
Additions: Full-width, shed-roof porch attached to NW side; enclosed by storm windows; concrete deck

b. Structural system (if known): brick

c. Foundation: materials: obscured by stucco
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): stucco

e. Roof: shape: side-gable
materials: rolled asphalt
cornice: open
dormers: none
chimney: location(s): (1) brick; center, interior; (1) concrete-block chimney; NE agble-end, exterior

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: SE

1) Bays four

2) Windows

fenestration irregular

type modern double-hung 1/1 sash

trim brick sills

shutters modern shutter; vinyl; louvered wood-slats; non-functional

Facade (cont'd)

- 3) **Door(s)** one
 location in vestibule
 type modern wood-and-glass
 trim none
- 4) **Porch(es)** gable-front, brick vestibule w/ decorative wood surround; broken pediment
 and pilasters

b. Side: Direction: SW

- 1) **Bays** two
- 2) **Windows**
 fenestration regular w/ 1 window centered in upper level of gable peak
 type modern double-hung 1/1 sash; double-hung 6/1 sash in upper level
 trim brick sills
 shutters modern shutter; vinyl; louvered wood-slats; non-functional
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a

c. Side: Direction: NE

- 1) **Bays** two
- 2) **Windows**
 fenestration regular w/ 1 window centered in upper level of gable peak
 type modern double-hung 1/1 sash; double-hung 6/1 sash in upper level
 trim brick sills
 shutters none
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a


d. Rear: Direction: NW

- 1) **Bays** four
- 2) **Windows**
 fenestration irregular
 type modern double-hung 1/1 sash
 trim n/a
 shutters none
- 3) **Door(s)**
 location center
 type wood and glass
 trim n/a
- 4) **Porch(es)** full-width, shed-roof porch; one-story; concrete deck; enclosed by storm
 windows; inset corner entrance on W end

9. **INTERIOR:** inaccessible

10. **LANDSCAPING:** flat; rear of property abuts the Christiana River; fenced-in front lawn; assorted vegetation planted throughout the property

11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-14170

1. ADDRESS/LOCATION: 433 Old Airport Road
2. FUNCTION(S): historic garage current garage
3. YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER: built by current owner
4. STYLE/FLOOR PLAN: rectangular
5. INTEGRITY: original site moved
 if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known)

year

a. none

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system concrete-block
- b. Number of stories 1
- c. Wall coverings exposed concrete-block
- d. Foundation concrete
- e. Roof
 structural system side-gable
 coverings rolled asphalt
 openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: SE
- 1) bays: three
- 2) windows: n/a
- 3) door(s): (3) roll-down vinyl, garage doors
- 4) other: none

- b. **Side: direction: NE**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible

 - 3) **door(s):** inaccessible

 - 4) **other:** none

- c. **Side: direction: SW**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible

 - 3) **door(s):** inaccessible

 - 4) **other:** none

- d. **Rear: direction: NW**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible

 - 3) **door(s):** inaccessible

 - 4) **other:** none

9. **INTERIOR (if accessible):**

a) **Floor plan** **inaccessible**

b) **Partition/walls** **inaccessible**

c) **Finishes** **inaccessible**

d) **Furnishings/machinery** **inaccessible**



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # N-14170

1. ADDRESS/LOCATION: 433 Old Airport Road
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE


PHOTOGRAPHIC INVENTORY

CRS # N-14170 Date 12/01/03 Photo Roll # C-4567 Surveyor Courtney Clark

Description View of front, SE side and SW side of dwelling; View of front, SE side of garage

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-14169
SPO Map 08-09-34
Hundred Christiana
Quad Wilmington So.
Other 1000800010

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: 467 Old Airport Road
3. TOWN/NEAREST TOWN: Newport vicinity?
4. MAIN TYPE OF RESOURCE: building structure
 landscape district site object
5. MAIN FUNCTION OF PROPERTY: residential/ commercial
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
I-95/ Newark Toll Plaza Project (Section 106)

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	dwelling
4	CRS 3 Secondary Building Form	shed; vechile shed; garage; outbuilding
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-14169

1. ADDRESS/LOCATION: 467 Old Airport Road

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1953 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE OR FLOOR PLAN: side hall

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year
a. Gabled addition to NE side of main block
b. Shed-roof screened porch on SE side of main block

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular Stories: 1
Additions: Gabled addition attached to NE side of main block; one-story; concrete-block chimney in center interior; vertical wood paneling siding; modern shed-roof screened porch attached to SE side of main block
- b. Structural system (if known): brick
- c. Foundation: materials: concrete
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): stucco
- e. Roof: shape: side-gable
materials: rolled asphalt
cornice: open
dormers: none
chimney: location(s): concrete-block chimney; exterior; SW side of main block

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: SE
 - 1) Bays three
 - 2) Windows fenestration irregular
type (1) pair of modern double-hung 6/6 sash; (1) modern double-hung 6/6 sash
trim none
shutters none

Facade (cont'd)

3) **Door(s)** **one**
 location **within screened porch**
 type **modern vinyl-and-glass**
 trim

4) **Porch(es)** **Modern shed-roof screen porch attached across SE side of main block; wood post supports; wrap-around handicap accessible ramp on S corner; wood**

b. Side: Direction: SW

1) **Bays** **two**

2) **Windows**
 fenestration **regular w/ pairs of windows flanking the chimney**
 type **(2) pairs of double-hung 1/1 sash windows**
 trim **none**
 shutters **none**

3) **Door(s)** **n/a**
 location **n/a**
 type **n/a**
 trim **n/a**

4) **Porch(es)** **n/a**

c. Side: Direction: NE

1) **Bays** **inaccessible**

2) **Windows** **inaccessible**
 fenestration **inaccessible**
 type **inaccessible**
 trim **inaccessible**
 shutters **inaccessible**

3) **Door(s)** **n/a**
 location **n/a**
 type **n/a**
 trim **n/a**

4) **Porch(es)** **n/a**

d. Rear: Direction: NW

1) **Bays** **five**

2) **Windows**
 fenestration **irregular**
 type **(2) pairs of double-hung 1/1 sash; (1) single double-hung 6/6 sash**
 trim **none**
 shutters **n/a**

3) **Door(s)** **two**
 location **west corner of main block; center of side addition**
 type **wood-and-glass**
 trim **none**

4) **Porch(es)** **Full-width, shed-roof open carport; supported by doric wood columns**

9. **INTERIOR: inaccessible**

10. **LANDSCAPING: large, deep lot; lots of abandoned cars; several outbuildings to rear of dwelling**

11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # _____

1. ADDRESS/LOCATION: 467 Old Airport Road
2. FUNCTION(S): historic garage current vacant
3. YEAR BUILT: 1953 CIRCA?: ARCHITECT/BUILDER: _____
4. STYLE/FLOOR PLAN: rectangular
5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known)

year

a. none

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system concrete-block
- b. Number of stories 1
- c. Wall coverings exposed concrete-block
- d. Foundation concrete-block
- e. Roof
structural system gable-front
coverings rolled asphalt
openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: SE
- 1) bays: three
- 2) windows: (1) double-hung 6/6 sash windows
- 3) door(s): (1) garage door; wood-and-glass; (1) wood-and-glass door
- 4) other: none

- b. **Side: direction: NE**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible
 - 3) **door(s):** inaccessible
 - 4) **other:** none

- c. **Side: direction: SW**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible
 - 3) **door(s):** inaccessible
 - 4) **other:** none

- d. **Rear: direction: NW**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible
 - 3) **door(s):** inaccessible
 - 4) **other:** none


9. **INTERIOR (if accessible):**

a) **Floor plan** **inaccessible**

b) **Partition/walls** **inaccessible**

c) **Finishes** **inaccessible**

d) **Furnishings/machinery** **inaccessible**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-14169

1. ADDRESS/LOCATION: 467 Old Airport Road

2. FUNCTION(S): historic _____ current shed

3. YEAR BUILT: 1980 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____
a. none
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system wood-frame
b. Number of stories 1
c. Wall coverings vertical wood paneling
d. Foundation none
e. Roof
structural system gable-front
coverings rolled asphalt
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: SW
1) bays: one
2) windows: n/a
3) door(s): metal swing-hinge doors
4) other: none

b. Side: direction: SE

- 1) **bays:** n/a
- 2) **windows:** n/a

- 3) **door(s):** n/a

- 4) **other:** none

c. Side: direction: NW

- 1) **bays:** inaccessible
- 2) **windows:** inaccessible

- 3) **door(s):** inaccessible

- 4) **other:** none

d. Rear: direction: NE

- 1) **bays:** inaccessible
- 2) **windows:** inaccessible

- 3) **door(s):** inaccessible

- 4) **other:** none

9. INTERIOR (if accessible):

a) Floor plan inaccessible

b) Partition/walls inaccessible

c) Finishes inaccessible

d) Furnishings/machinery inaccessible



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-14169

1. ADDRESS/LOCATION: 467 Old Airport Road

2. FUNCTION(S): historic vehicle shed current storage shed

3. YEAR BUILT: 1953 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. none
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system wood-frame
b. Number of stories 1
c. Wall coverings plywood
d. Foundation n/a
e. Roof
structural system shed-roof
coverings corrugated metal
openings n/a

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: SE
1) bays: one
2) windows: square-shaped open bay
3) door(s): none
4) other: none

- b. **Side: direction: NE**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible
 - 3) **door(s):** inaccessible
 - 4) **other:** none

- c. **Side: direction: SW**
 - 1) **bays:** one
 - 2) **windows:** n/a
 - 3) **door(s):** open drive-in bay
 - 4) **other:** none

- d. **Rear: direction: NW**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible
 - 3) **door(s):** inaccessible
 - 4) **other:** none

9. **INTERIOR (if accessible):**

a) **Floor plan** **inaccessible**

b) **Partition/walls** **inaccessible**

c) **Finishes** **inaccessible**

d) **Furnishings/machinery** **inaccessible**



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # N-14169

1. ADDRESS/LOCATION: 467 Old Airport Road
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE


PHOTOGRAPHIC INVENTORY

CRS # N-14169 Date 12/01/03 Photo Roll # C-4567 Surveyor Courtney Clark

Description View of front, SE side and SW side of dwelling; View of SE sides of outbuildings located at rear of property; View of front, NE side of outbuilding located W of dwelling

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # N-12907

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: 491-495 Old Airport Road
3. CURRENT CONDITION: excellent good fair poor demolished
4. INTEGRITY: integrity of the houses has been comprised with the insertion of replacement doors and windows to one and the application of modern siding to the other
-
5. SETTING INTEGRITY: integrity of setting and feeling as a former automotive shop has been compromised with the change of use of the outbuildings and the abandoned cars and junkyard that has built up around the property.
-

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
2	CRS 2 Main Building Form	dwelling
2	CRS 3 Secondary Building Form	garages
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney L. Clark

Principal Investigator name: Douglas C. Mcvarish

Principal Investigator signature: _____

Organization: John Milner Associates, Inc. Date: 11/1/2003

8. OTHER NOTES OR OBSERVATIONS:

CRS# N-12907

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-12907

1. ADDRESS/LOCATION: 495 Old Airport Road

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: not known

4. STYLE OR FLOOR PLAN: three bay; center-passage; Cape Cod

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year
a. none
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangular Stories: 1 1/2
Additions: none
- b. Structural system (if known): brick
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): brick
- e. Roof: shape: side-gable
materials: rolled asphalt
cornice: open
dormers: (2) gable-front dormers covered in vinyl
chimney: location(s): none

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: SE
 - 1) Bays three
 - 2) Windows
 - fenestration regular w/ bay windows flanking entrance
 - type (2) modern angled bay windows
 - trim n/a
 - shutters none

Facade (cont'd)

- 3) **Door(s)** one
 location center
 type modern vinyl
 trim none
- 4) **Porch(es)** Modern wood deck at entrance

b. Side: Direction: SW

- 1) **Bays** two
- 2) **Windows**
 fenestration regular
 type (2) double-hung 1/1 sash
 trim none
 shutters none
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a

c. Side: Direction: NE

- 1) **Bays** two
- 2) **Windows**
 fenestration regular
 type (2) double-hung 1/1 sash
 trim none
 shutters none
- 3) **Door(s)** n/a
 location n/a
 type n/a
 trim n/a
- 4) **Porch(es)** n/a


d. Rear: Direction: NW

- 1) **Bays** three
- 2) **Windows**
 fenestration irregular
 type (2) double-hung 1/1 sash
 trim none
 shutters none
- 3) **Door(s)** one
 location center
 type vinyl-and-glass
 trim none
- 4) **Porch(es)** fenced-in open patio

9. **INTERIOR:** inaccessible

10. **LANDSCAPING:** large, deep lot; lots of abandoned cars; several outbuildings to rear of dwelling

11. **OTHER COMMENTS:**



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-12907

1. ADDRESS/LOCATION: 491 Old Airport Road

2. FUNCTION(S): historic single-family dwelling current single-family dwelling

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE OR FLOOR PLAN: three bay; center passage; w/ Colonial Revival detailing

5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangular Stories: 1 1/2
Additions: none

b. Structural system (if known): unknown

c. Foundation: materials: sheathed in stucco
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): stucco

e. Roof: shape: side-gable
materials: rolled asphalt
cornice: open
dormers: (2) wall dormers on 2nd story
chimney: location(s): concrete; exterior; SW gable-end

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: SE
1) Bays three
2) Windows
fenestration regular w/ windows flanking the entrance
type (2) pair double-hung 8/8 sash windows on 1st story; (2) double-hung 6/6 sash in dormers
trim none
shutters none

Facade (cont'd)

- 3) **Door(s)** **one**
 - location** **center**
 - type** **wood-and-glass**
 - trim** **none**
- 4) **Porch(es)** **concrete-block deck**

b. Side: Direction: SW

- 1) **Bays** **three**
- 2) **Windows**
 - fenestration** **regular**
 - type** **(3) double-hung 6/6 sash windows on both the 1st and 2nd stories**
 - trim** **none**
 - shutters** **none**
- 3) **Door(s)** **n/a**
 - location** **n/a**
 - type** **n/a**
 - trim** **n/a**
- 4) **Porch(es)** **n/a**

c. Side: Direction: NE

- 1) **Bays** **three**
- 2) **Windows**
 - fenestration** **regular**
 - type** **(3) double-hung 6/6 sash windows on both the 1st and 2nd stories**
 - trim** **none**
 - shutters** **none**
- 3) **Door(s)** **n/a**
 - location** **n/a**
 - type** **n/a**
 - trim** **n/a**
- 4) **Porch(es)** **n/a**

d. Rear: Direction: NW

- 1) **Bays** **inaccessible**
- 2) **Windows** **inaccessible**
 - fenestration** **inaccessible**
 - type** **inaccessible**
 - trim** **inaccessible**
 - shutters** **inaccessible**
- 3) **Door(s)** **inaccessible**
 - location** **inaccessible**
 - type** **inaccessible**
 - trim** **inaccessible**
- 4) **Porch(es)** **inaccessible**

9. **INTERIOR:** inaccessible

10. **LANDSCAPING:** large, deep lot; abandoned cars to rear of dwelling

11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-12907

1. ADDRESS/LOCATION: 495 Old Airport Road
2. FUNCTION(S): historic automotive garage current storage
3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____
4. STYLE/FLOOR PLAN: rectangular
5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known)

year

a. none

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system concrete-block

b. Number of stories 2

c. Wall coverings stucco

d. Foundation concrete

e. Roof

structural system flat

coverings not visible

openings not visible

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: SW

1) bays: three

2) windows: (3) double-hung 6/3 sash; steel framed; on 2nd floor

3) door(s): (1) steel door towards W end; (2) wood-and-glass roll-down, garage doors

4) other: none

- b. **Side: direction: NW**
- 1) **bays:** inaccessible
 - 2) **windows:** inaccessible
 - 3) **door(s):** inaccessible
 - 4) **other:** none

- c. **Side: direction: SE**
- 1) **bays:** inaccessible
 - 2) **windows:** inaccessible
 - 3) **door(s):** inaccessible
 - 4) **other:** none

- d. **Rear: direction: NE**
- 1) **bays:** inaccessible
 - 2) **windows:** inaccessible
 - 3) **door(s):** inaccessible
 - 4) **other:** none

9. **INTERIOR (if accessible):**

a) **Floor plan** **inaccessible**

b) **Partition/walls** **inaccessible**

c) **Finishes** **inaccessible**

d) **Furnishings/machinery** **inaccessible**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N-12907

1. ADDRESS/LOCATION: 495 Old Airport Road
2. FUNCTION(S): historic automotive garage current storage
3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____
4. STYLE/FLOOR PLAN: rectangular
5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known)

year

a. none

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system concrete-block

b. Number of stories 2

c. Wall coverings stucco

d. Foundation concrete

e. Roof

structural system flat

coverings unknown

openings n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: SW

1) bays: three

2) windows: (3) modern double-hung 1/1 sash on 2nd level

3) door(s): (2) wood-and-glass roll down, garage doors; (1) steel door towards S end

4) other: none

- b. **Side: direction: SE**
 - 1) **bays:** two
 - 2) **windows:** (2) modern double-hung 1/1 sash on 1st and 2nd levels
 - 3) **door(s):** n/a
 - 4) **other:** none

- c. **Side: direction: NW**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible
 - 3) **door(s):** inaccessible
 - 4) **other:** none

- d. **Rear: direction: NE**
 - 1) **bays:** inaccessible
 - 2) **windows:** inaccessible
 - 3) **door(s):** inaccessible
 - 4) **other:** none

9. **INTERIOR (if accessible):**

a) **Floor plan** **inaccessible**

b) **Partition/walls** **inaccessible**

c) **Finishes** **inaccessible**

d) **Furnishings/machinery** **inaccessible**



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # N-12907

1. ADDRESS/LOCATION: 491-495 Old Airport Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # N-12907 Date 12/01/03 Photo Roll # C-4567 Surveyor Courtney Clark

Description View of front, SW side of garage #1; View of front, SW side of garage #2; View of front, SE side of dwelling #1; View of front, SE side and SW side of dwelling #2

Negative location (if other than SHPO) _____

Attach contact print(s):



doc # 20-06-01-05-12

CRS-13