



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N00121.01

1. ADDRESS/LOCATION: 4677 Summit Bridge Road

2. FUNCTION(S): historic Single Family Dwelling current Single Family Dwelling

3. YEAR BUILT: 1830 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE OR FLOOR PLAN: Italianate

5. INTEGRITY: original site moved

<u>If moved, from where</u>	<u>other location's CRS #</u>	<u>year</u>
N/A	N/A	N/A
N/A	N/A	N/A

<u>List major alterations and additions with years (if known)</u>	<u>year</u>
a. The east (rear) porch was enclosed.	c. 1960
b. The posts of the west (front) Greek Revival porch replaced in-kind.	c. 2004
c. A shed roof porch enclosed with wooden paneling stretches the entire north elevation of the rear block.	c. 1970

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: L-shaped Stories: Two-and-a-half (2.5)
Additions: The front block was added to the original dwelling and rear ell circa 1850.
- b. Structural system (if known): Frame
- c. Foundation: Materials: Brick
Basement: full partial not visible no basement
- d. Exterior walls (original if visible & any subsequent coverings): Running-stretcher brick bond on the front block; common brick bond on the rear block.
- e. Roof: shape: Shallow hip roof (front block); High-pitched gable with the ridge perpendicular to Summit Bridge Road; gable return on east end (rear ell)
Materials: Corrugated Metal
Cornice: Plain, Boxed, Wooden with decorative wooden brackets on both front and rear blocks
Dormers: N/A
Chimney: Location(s): A brick interior chimney is located at each end (north and south) of the front block. A brick interior chimney is located at the east end of the rear ell.

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: W
 - 1) Bays: Five (5)
 - 2) Windows:
 - Fanestration: Regular
 - Type: 1st Floor: (4) Tall 4/4 DHS wooden; 2nd Floor: (5) 2/2 DHS wooden; (5) 2-light wooden casement in frieze band
 - Trim: Plain, Flat, Wooden surround; Wooden sills and lintels
 - Shutters: 1st Floor: 3-panel wooden original; 2nd Floor: wooden louvered

Facade (cont'd):

- 3) **Door(s): One (1)**
Location: Center Bay
Type: Double-leaf; arched recessed panel over square recessed panel; wooden with 4-light transom
Trim: 3 light/1 panel sidelights; bracketed Italianate door surround
- 4) **Porch(es):** A one-story, three-bay, vernacular Greek Revival porch, with square wooden posts, is located on the west elevation.
- b. **Side: Direction: S**
- 1) **Bays: Nine (9)**
- 2) **Windows:**
Fenestration: Irregular
Type: (6) 4/4 DHS wooden; (6) 6/6 DHS wooden; (4) 1/1 horizontal wooden casement in frieze band
Trim: Plain, Flat, Wooden surround; Wooden lintel and sills
Shutters: 3-panel wooden; 2-panel wooden; wooden louvered
- 3) **Door(s): One (1)**
Location: West bay of rear ell
Type: Single-leaf, 1/1 wooden panel with aluminum screen door
Trim: Greek Revival pediment surround with 4 light/1 panel sidelights
- 4) **Porch(es):** The east end of the rear ell contains a porch enclosed with wooden clapboard; the porch contains one bay on the south elevation.
- c. **Side: Direction: N**
- 1) **Bays: Four (4)** (Italianate front block contains no openings on the north elevation.)
- 2) **Windows:**
Fenestration: Irregular
Type: (3) 6/6 DHS wooden; (2) 6/6 DHS aluminum; porch contains (4) 1/1 DHS aluminum; (2) 6-light, fixed sash wooden
Trim: Plain, Flat, Wooden surround; Wooden sills and lintels
Shutters: Wooden louvered (2nd floor of rear block)
- 3) **Door(s): Two (2)**
Location: Center bay of northern enclosed porch; NW corner of enclosed porch
Type: Single-leaf, 15-light, wooden; Wooden bulkhead with brick ramping
Trim: Recessed panel transom and a 1/1 DHS aluminum window/1 panel sidelights
- 4) **Porch(es):** A shed-roof porch enclosed with wooden panels stretches the entire first floor of the north elevation of the rear ell.
- d. **Rear: Direction: E**
- 1) **Bays: Six (6)**
- 2) **Windows:**
Fenestration: Irregular
Type: (4) 4/4 DHS wooden; (1) 6/6 DHS wooden; (1) set of paired 6/6 DHS wooden; (2) 4/2 DHS wooden in gable of rear block; (3) 1-light, fixed wooden casement in frieze band
Trim: Plain, Flat, Wooden surround; Wooden sills and lintels
Shutters: 3-panel wooden; wooden louvered
- 3) **Door(s): One (1)**
Location: South bay of enclosed rear porch
Type: Single-leaf, modern aluminum
Trim: N/A
- 4) **Porch(es):** An enclosed porch with a concrete block foundation is situated on the east elevation of the rear ell. The chamfered posts are still visible in the interior.

9. **INTERIOR:** The interior of the dwelling is extremely intact. Many of the interior features of the rear ell are Federal period (wall paneling, mantle). Most of the interior doors retain their original hardware. The front rooms of the Italianate block still retain their original plaster ceiling medallions and plaster walls and ceilings.
10. **LANDSCAPING:** Mature magnolia, walnut, pine, cedar, and holly trees are located throughout the property. Boxwood shrubs surround most of the foundation. The tree-lined gravel driveway stretches east from Summit Bridge Road, passes south of the dwelling, and accesses the outbuildings.
11. **OTHER COMMENTS:** N/A

USE BLACK INK ONLY

CRS-2



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N00121.02

1. ADDRESS/LOCATION: 4677 Summit Bridge Road

2. FUNCTION(S): historic Ice House current Guest House

3. YEAR BUILT: 1840 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: Regular, Square

5. INTEGRITY: original site moved

<u>If moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
N/A	N/A	N/A
N/A	N/A	N/A

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. Converted to guest house with porch enclosure on north end.	c. 1960
b. Modern windows	c. 1995

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system Frame
- b. Number of stories One (1)
- c. Wall coverings Brick constructed in common bond; wooden clapboard on north end
- d. Foundation Field stone and mortar (original block); Poured concrete (N addition)
- e. Roof
 - structural system Low-pitched gable with ridge parallel to Summit Bridge Road
 - coverings Asphalt Shingles
 - openings Interior brick chimney located on northern end

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: W
 - 1) bays: Two (2)
 - 2) windows: Regular; (1) set of paired 6/6 DHS vinyl (exterior), original wooden windows can be seen on the interior; brick lintels and sills; plain, flat, wooden surround
 - 3) door(s): (1) located in north end: single-leaf, 9-light/ 2-panel wooden
 - 4) other: One-bay, one-story, entry porch with modern brick stoop. The ridge of the low-pitched gable roof, supported by two square wooden posts, sits lower than the icehouse roof.

- b. **Side: direction: N**
- 1) **bays: One (1)**
 - 2) **windows: (1) louvered wooden attic vent underneath gable**
 - 3) **door(s): 0**
 - 4) **other: Wooden clapboard covers the entire elevation; gable is accentuated by a plain boxed wooden cornice.**
- c. **Side: direction: S**
- 1) **bays: Three (3)**
 - 2) **windows: (2) 6/6 DHS vinyl modern (wooden muntins) with brick sills and lintels; plain, flat, wooden surround**
 - 3) **door(s): (1) center bay; original bulkhead (brick and mortar ramping) with hinged wooden door**
 - 4) **other: The brick on this elevation has been re-worked to accommodate modern windows; wooden horizontal siding on gable.**
- d. **Rear: direction: E**
- 1) **bays: Two (2)**
 - 2) **windows: Southern Bay: (1) 6/6 DHS modern vinyl (wooden muntins) with brick sill and lintel; Northern Bay: (1) 6/6 DHS wooden (possibly original)**
 - 3) **door(s): 0**
 - 4) **other: Most of the original brickwork on this elevation is intact; northern end is clad with wooden clapboard.**

9. **INTERIOR (if accessible):**

a) **Floor plan** **Not accessible**

b) **Partition/walls** **Not accessible**

c) **Finishes** **Not accessible**

d) **Furnishings/machinery** **Not accessible**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N00121.03

1. ADDRESS/LOCATION: 4677 Summit Bridge Road

2. FUNCTION(S): historic Smokehouse current Tool Shed

3. YEAR BUILT: 1850 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: Regular, Rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
N/A	N/A	
N/A	N/A	

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. Plywood at lower half of east elevation	1990
b. Clad in horizontal wooden siding with a poured concrete foundation	1920

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system Timber Frame
- b. Number of stories One (1)
- c. Wall coverings Vertical, circular-sawn planks under clapboards; painted red
- d. Foundation Poured Concrete
- e. Roof
 - structural system High-pitched gable with the ridge perpendicular to Summit Bridge Road
 - coverings Rolled asphalt shingles
 - openings N/A

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: W
 - 1) bays: One (1)
 - 2) windows: 0
 - 3) door(s): (1) board and batten with metal strap hinges; hinged at south side
 - 4) other: Stone pathway leads to entry.

b. Side: direction: N

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

c. Side: direction: S

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

d. Rear: direction: E

- 1) bays: One (1)
- 2) windows: (1) rectangular opening is screened over
- 3) door(s): 0
- 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan Open; currently used for storage

b) Partition/walls N/A

c) Finishes Unfinished

d) Furnishings/machinery N/A



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N00121.04

1. ADDRESS/LOCATION: 4677 Summit Bridge Road

2. FUNCTION(S): historic Tenant House current Tenant House

3. YEAR BUILT: 1840 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: Nineteenth-century Vernacular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
N/A	N/A	N/A
N/A	N/A	N/A

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. Screened-in porch on east elevation	c. 1970
b. House jacked up on concrete block foundation	c. 1950

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system Timber Frame
- b. Number of stories Two-and-a-half (2.5)
- c. Wall coverings Wooden clapboard siding (painted white)
- d. Foundation Full; concrete block
- e. Roof
 - structural system High-pitched gable with ridge parallel to Summit Bridge Road
 - coverings Asphalt shingle
 - openings Interior brick chimney; centrally located

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: E
 - 1) bays: Two (2)
 - 2) windows: Regular; 2nd floor: (2) 6/6 DHS wooden with plain flat wooden surround
 - 3) door(s): 1st Floor: (2) single-leaf, 4-light/2-horizontal panel, wooden; plain, flat, wooden surround
 - 4) other: Screened-in porch stretches the entire first floor of the east elevation; two concrete block steps lead to the concrete floor; five wooden posts support the shed roof.

- b. Side: direction: S
- 1) bays: Four (4)
 - 2) windows: (4) 6/6 DHS wooden with aluminum storm; plain, flat, wooden surround; (1) arched wooden louvered attic vent
 - 3) door(s): (1) 1/4 light (covered with screen) single-leaf, wooden, on porch; 1-screen/1-panel sidelights
 - 4) other: Plain, boxed, wooden cornice surrounds gable return
- c. Side: direction: N
- 1) bays: Five (5)
 - 2) windows: (4) 6/6 DHS wooden with aluminum storm; plain, flat, wooden surround; (1) arched wooden louvered attic vent; (1) screened-in opening to porch
 - 3) door(s): 0
 - 4) other: Plain, boxed, wooden cornice surrounds gable return
- d. Rear: direction: W
- 1) bays: Four (4)
 - 2) windows: (4) 6/6 DHS wooden with aluminum storm; aluminum with plain, flat, wooden surround
 - 3) door(s): 0
 - 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan Not accessible

b) Partition/walls Not accessible

c) Finishes Not accessible

d) Furnishings/machinery Not accessible



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N00121.05

1. ADDRESS/LOCATION: 4677 Summit Bridge Road

2. FUNCTION(S): historic Garage/Cart Shed current Garage

3. YEAR BUILT: 1925 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: Open, Rectilinear

5. INTEGRITY: original site moved

if moved, from where

N/A

original location's CRS #

N/A

year

N/A

N/A

N/A

N/A

list major alterations and additions with years (if known)

a. Corrugated metal sheets at walls

year

1965

b. N/A

N/A

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system Frame

b. Number of stories One (1)

c. Wall coverings Corrugated metal sheets with traces of red paint

d. Foundation Tapered, poured concrete piers support posts

e. Roof

structural system Assymmetrical gable with the ridge perpendicular to Summit Bridge Road

coverings Corrugated metal sheets

openings N/A

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: S

1) bays: One (1)

2) windows: 0

3) door(s): 0

4) other: Open for automobile access into interior.

b. Side: direction: W

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

c. Side: direction: E

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

d. Rear: direction: N

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0
- 4) other: Framing system of metal piping at exterior supports this wall.

9. INTERIOR (if accessible):

a) Floor plan Open

b) Partition/walls N/A

c) Finishes Unfinished

d) Furnishings/machinery N/A



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N00121.06

1. ADDRESS/LOCATION: 4677 Summit Bridge Road

2. FUNCTION(S): historic Corncrib/Granary current Dwelling/Storage

3. YEAR BUILT: 1840 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: Central aisle flanked by cribs with open space above

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
N/A	N/A	N/A
N/A	N/A	N/A

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. Shed-roof addition to house machinery located on east elevation	1880
b. Addition of modern windows at upper level when converted to living space.	1960

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system **Timber frame**
- b. Number of stories **Two (2)**
- c. Wall coverings **Corrugated metal sheets with traces of red paint**
- d. Foundation **Stone**
- e. Roof
 - structural system **Moderately pitched gable with ridge parallel to Summit Bridge Road; evidence of deterioration of framing system in swale**
 - coverings **Rolled asphalt shingle**
 - openings **N/A**

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: **N**
 - 1) bays: **Two (2)**
 - 2) windows: **(1) louvered vent at gable peak**
 - 3) door(s): **(2) E: paneled wood door covers opening, does not appear to be functional**
Center: 20th-century, paired, wooden hinged doors
 - 4) other: **N/A**

- b. Side: direction: E
- 1) bays: Three (3)
 - 2) windows: (3) 2 single (2/2 and 6/6 DHS) and 1 paired (6/6 DHS) at upper story below eaves
 - 3) door(s): 0
 - 4) other: Brick flue attached to wall at north end of elevation; shed addition of frame construction rests on concrete block piers and covers entire first story; portion of cribbing is visible at lower level near south elevation.
- c. Side: direction: W
- 1) bays: Three (3)
 - 2) windows: (2) paired 6/6 DHS and (1) paired 2/2 DHS at upper story below eaves
 - 3) door(s): 0
 - 4) other: First floor obscured by overgrown cedar shrubbery
- d. Rear: direction: S
- 1) bays: Two (2)
 - 2) windows: (2) fixed, 6-light windows flank one large picture window at second story; (1) louvered window at gable
 - 3) door(s): (1) pedestrian door; 4 light/3 panels at western bay; (1) central, 20th-century vertical paired, hinged, wooden door with inset pedestrian door of particle board construction
 - 4) other: N/A

9. INTERIOR (if accessible):

- a) Floor plan 1st Floor: Center aisle flanked by cribs, large hand-hewn timbers overhead; one grain chute remains, wide board flooring
- b) Partition/walls Aisle flanked by cribs
- c) Finishes Unfinished
- d) Furnishings/machinery None visible; no evidence of machine power now or ever per conservation with Mr. Robb



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N00121.07

1. ADDRESS/LOCATION: 4677 Summit Bridge Road

2. FUNCTION(S): historic Horse/Cow Barn current Storage

3. YEAR BUILT: 1830 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: Gable front bank barn (man-made earthen ramp on north elevation)

5. INTEGRITY: original site moved

if moved, from where

N/A

original location's CRS #

N/A

year

N/A

N/A

N/A

N/A

list major alterations and additions with years (if known)

year

a. Roof re-worked to accommodate transition to dairy barn

c.

1890

b. Stables added to east and west elevations

c.

1880

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system: Timber frame

b. Number of stories: Two (2)

c. Wall coverings: Board and batten, painted red

d. Foundation: Field stone and mortar

e. Roof: High-pitched gable with ridge parallel to Summit Bridge Road; shed-roof on wings

Structural system: Wood frame

Coverings: Corrugated metal, unpainted

Openings: Metal circulation vent on center of ridge of main barn

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: N

1) Bays: Three (3)

2) Windows: (2) wooden louvered vents located in east and west stable wings

3) Door(s): (1) set of paired vertical plank barn doors on metal tracking

4) Other: A hay hood with original track is still present on this elevation.

- b. Side: Direction: W
- 1) Bays: Three (3)
 - 2) Windows: (2) window-like openings; square with plain, flat wooden lintel and surround
 - 3) Door(s): (1) single-leaf, vertical plank, attached with metal strap hinges
 - 4) Other: One-story stable wing conceals any openings on first floor of main barn; the main barn contains no openings on the second floor.
- c. Side: Direction: E
- 1) Bays: Eight (8)
 - 2) Windows: (6) 9-light, fixed, wooden; (1) wooden square opening; plain, flat, wooden surround, lintel, and sill
 - 3) Door(s): (1) single-leaf, vertical plank attached with metal strap hinges, located in southern bay
 - 4) Other: One-story, one-bay stable wing conceals first-floor of main barn (no openings on 2nd floor), wooden feed wing leads to concrete and stave silo (situated SE of barn); concrete-enclosed ladder stall.
- d. Rear: Direction: S
- 1) Bays: Eight (8)
 - 2) Windows: (3) 4-light, fixed, wooden on milkhouse; (1) louvered vent in first floor of forebay
 - 3) Door(s): (3) vertical plank Dutch doors attached with metal strap hinges
 - 4) Other: One-story concrete block milkhouse projects off of SE corner of main barn; hand-hewn beams exposed on forebay. The horse/water trough (small stone & mortar) is located in field to southeast of barn.

9. INTERIOR (if accessible):

a) Floor plan: Stabling in center with side aisles separating stabling and milking spaces of side aisles

b) Partition/walls: Stable walls in west addition and center block. Milking stanchions in east addition

c) Finishes: White paint

d) Furnishings/machinery: N/A



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N00121.08

1. ADDRESS/LOCATION: 4677 Summit Bridge Road

2. FUNCTION(S): historic Milkhouse current Storage

3. YEAR BUILT: 1925 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: Regular, Rectangular

5. INTEGRITY: original site moved

if moved, from where

N/A

original location's CRS #

N/A

year

N/A

N/A

N/A

N/A

list major alterations and additions with years (if known)

a. N/A

year

N/A

b. N/A

N/A

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system: Frame

b. Number of stories: One-and-a-half (1.5)

c. Wall coverings: Vertical board siding with traces of red paint

d. Foundation: Poured concrete, approximately 2.5' high, painted white

e. Roof: High-pitched gable with ridge perpendicular to Summit Bridge Road

Structural system: Wood frame

Coverings: Metal sheets

Openings: N/A

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: W

1) Bays: One (1)

2) Windows: 0

3) Door(s): (1) single-leaf, vertical board, painted white, hinged at northern end

4) Other: N/A

- b. **Side: Direction: S**
 - 1) **Bays: One (1)**
 - 2) **Windows: (1) two-light wooden, hinged at bottom.**
 - 3) **Door(s): 0**
 - 4) **Other: Exposed eaves.**

- c. **Side: Direction: N**
 - 1) **Bays: Two (2)**
 - 2) **Windows: (2), two-light, wooden sash, hinged at bottom.**
 - 3) **Door(s): 0**
 - 4) **Other: N/A**

- d. **Rear: Direction: E**
 - 1) **Bays: One (1)**
 - 2) **Windows: One, two-light, wooden, hinged at bottom.**
 - 3) **Door(s): 0**
 - 4) **Other: N/A**

9. INTERIOR (if accessible):

a) Floor plan: Not accessible

b) Partition/walls: Not accessible

c) Finishes: Not accessible

d) Furnishings/machinery: Not accessible



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N00121.09

1. ADDRESS/LOCATION: 4677 Summit Bridge Road

2. FUNCTION(S): historic Calf Barn current Storage

3. YEAR BUILT: 1925 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: Rectilinear with interior partitions for stables

5. INTEGRITY: original site moved

if moved, from where

N/A

original location's CRS #

N/A

year

N/A

N/A

N/A

N/A

list major alterations and additions with years (if known)

a. N/A

year

N/A

b. N/A

N/A

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system Frame; variety of timbers—appear to be recycled from other structures

b. Number of stories One (1)

c. Wall coverings Corrugated metal sheets, now rusted; portion of vertical board siding remains at north end of west elevation

d. Foundation poured concrete

e. Roof

structural system Low-pitched gable with ridge parallel to Summit Bridge Road

coverings Metal sheets

openings N/A

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: S

1) bays: One (1)

2) windows: 0

3) door(s): 0

4) other: Opening in poured concrete wall for access; door now gone

- b. Side: direction: W
- 1) bays: Three (3)
 - 2) windows: 0
 - 3) door(s): (2) N door of vertical board and metal strap hinges is heavily deteriorated; S door of grooved vertical boards with metal hinges
 - 4) other: portion of elevation at north end clad in vertical wood boards

- c. Side: direction: E
- 1) bays: One (1)
 - 2) windows: 0
 - 3) door(s): (1) vertical wooden door at center of elevation, obscured by honeysuckle vines
 - 4) other: N/A

- d. Rear: direction: N
- 1) bays: One (1)
 - 2) windows: (1) 6-light, fixed wooden sash at upper story
 - 3) door(s): (1) grooved vertical wooden board with metal hinges at western end
 - 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan: Rectilinear; Central space is open with poured concrete floor which extends along the east wall

b) Partition/walls: Frame partitions separate four stabling spaces

c) Finishes: Unfinished

d) Furnishings/machinery: None visible from south elevation opening



CULTURAL RESOURCE SURVEY
MAP FORM

DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CRS#:

N00121.


1. ADDRESS/LOCATION: 4677 Summit Bridge Rd

2. NOT FOR PUBLICATION:


3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)



4. SITE PLAN:



CRS No. N00138

Name: Charles Beasten House

Address: North side of Bethel Church Road, approximately 0.5 mile west of U.S. 301

Tax Parcel: 1105700005


Date of Construction/Major Alterations: ca. 1840

Time Period: 1830-1880±, Industrialization and Early Urbanization

Geographic Zone: Upper Peninsula

**Historic Period Theme(s): Agriculture, Architecture, Engineering, and Decorative Arts
(Residential Architecture)**

This property was documented in 1977 and since that time the dwelling and related outbuildings associated with the property have been removed. As part of the current study, a CRS 10 Survey Update Form was prepared. The property has potential historic archeological significance and should be further investigated if it could be directly affected by the project.



U.S. 301 Project Development
1962 Aerial

Charles Beaston House - CRS No. N00138





CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

1. HISTORIC NAME/FUNCTION: Charles Beasten House

2. ADDRESS/LOCATION: North Side of Bethel Church Road, Approximately 0.5 Miles West of U.S. 3

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: Dwelling previously documented is not accessible and presumed demolished.

5. SETTING INTEGRITY: Long dirt land is cordoned off and leads to location of former buildings. Vacant fields surround the property.

6. FORMS ADDED:

#:	Form:	List Property Types:
1	CRS09	N/A

7. SURVEYOR INFORMATION:

Surveyor Name: Catherine M. Druzak / Architectural Historian

Principal Investigator Name: Barbara Copp / Sr. Architectural Historian

Principal Investigator Signature: *Barbara M. Copp*

Organization: A.D. Marble & Company Date: 8/15/2005

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II
- 1600-1750 Contact Period (Native American)
- 1630-1730 Exploration and Frontier Settlement
- 1730-1770 Intensified and Durable Occupation
- 1770-1830 Early Industrialization
- 1830-1880 Industrialization and Early Urbanization
- 1880-1940 Urbanization and Early Suburbanization
- 1940-1960 Suburbanization and Early Ex-urbanization
- 1960-2000 Deurbanization and Sprawl

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |
| <input type="checkbox"/> Other | <input type="checkbox"/> Unknown |



**CULTURAL RESOURCE SURVEY
MAP FORM**

**DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901**

CRS#:

N00138.


1. ADDRESS/LOCATION: North Side of Bethel Church Road, Approximately 0.5 Miles West of U.S. 301

2. NOT FOR PUBLICATION:


3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)



4. SITE PLAN:



CRS No. N00188

Name: Greenlawn; Brady House

Address: North Broad Street near intersection of Greenlawn Road

Tax Parcel: N/A


Date of Construction/Major Alterations: 1810

Time Period: 1770-1830±, Early Industrialization; 1830-1880±, Industrialization and Early Urbanization

Geographic Zone: Upper Peninsula

Historic Period Theme(s): Agriculture, Architecture, Engineering, and Decorative Arts (Residential Architecture)

This property was individually listed in the National Register in 1973 and as a related property in 1992 as part of the "Dwellings of the Rural Elite in Central Delaware, 1770-1830± multiple property nomination. Since the 1992 multiple property nomination, the property has been demolished. As part of the current study, a CRS 10 Survey Update Form was prepared. Although the former location of the dwelling is located amidst development, an assessment to determine the presence or absence of a historic archeological site should be conducted if the project has the potential to affect this location.



U.S. 301 Project Development
1962 Aerial
Greenlawn/Brady House - CRS No. N00188





CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS

N00188.

1. HISTORIC NAME/FUNCTION: Greenlawn; Brady House
2. ADDRESS/LOCATION: North Broad Street Near Intersection of Greenlawn Rd
3. CURRENT CONDITION: excellent good fair poor demolished
4. INTEGRITY: House and carriage barn previously documented for HABS have been demolished.
5. SETTING INTEGRITY: Greenlawn Road now goes through where farm once stood. Modern commercial development to north and modern residential development to east and south.

6. FORMS ADDED:

#:	Form:	List Property Types:
1	CRS09	N/A

7. SURVEYOR INFORMATION:

Surveyor Name: Catherine M. Dluzak / Architectural Historian

Principal Investigator Name: Barbara Copp / Sr. Architectural Historian

Principal Investigator Signature: *Barbara M. Copp*

Organization: A.D. Marble & Company Date: 8/15/2005

8. OTHER NOTES OR OBSERVATIONS:

CRS#

N00188.

Individually listed in the National Register on 04241973; related property of the "Dwellings of the Rural Elite in Central Delaware, 1770-1830+/-", in 1992.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II
- 1600-1750 Contact Period (Native American)
- 1630-1730 Exploration and Frontier Settlement
- 1730-1770 Intensified and Durable Occupation
- 1770-1830 Early Industrialization
- 1830-1880 Industrialization and Early Urbanization
- 1880-1940 Urbanization and Early Suburbanization
- 1940-1960 Suburbanization and Early Ex-urbanization
- 1960-2000 Deurbanization and Sprawl

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |
| <input type="checkbox"/> Other | <input type="checkbox"/> Unknown |



**CULTURAL RESOURCE SURVEY
MAP FORM**

**DELAWARE STATE HISTORIC PRESERVATION OFFICE
16 THE GREEN, DOVER, DE 19901**

CRS#:

N00188


1. ADDRESS/LOCATION: North Broad Street Near Intersection of Greenlawn Rd

2. NOT FOR PUBLICATION:


3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)



4. SITE PLAN:



CRS No. N00413

Address: 4353 Summit Bridge Road

Name: A. Eliason House/Twin Holly Farms

Tax Parcels: 1300700078; 1300740094

Date of Construction/Major Alterations: ca. 1856; ca. 1900; ca. 1960s; 2004

Time Period: 1830-1880±, Industrialization and Early Urbanization; 1880-1940±, Urbanization and Early Suburbanization; 1960-2000±, Deurbanization and Sprawl

Geographic Zone: Upper Peninsula

Historic Period Theme(s): Architecture, Engineering, and Decorative Arts (Residential Architecture); Agriculture

Description

The A. Eliason House/Twin Holly Farms property was listed in the National Register of Historic Places in 1985 as part of the *Rebuilding St. Georges Hundred, New Castle County, 1850-1880* multiple property nomination. The property is located along the east side of Summit Bridge Road (U.S. 301) between Boyds Corner Road and Victoria Drive. The resource consists of a *circa*-1856 dwelling, a *circa*-1856 stable, a *circa*-1900 carriage house, a *circa*-1900 privy, two modern sheds, a modern garage, a modern dog house, and a modern pool. All of the buildings and structures, with the exception of the stable, are situated on the 1.51-acre lot at 4353 Summit Bridge Road, which is planted with mature trees and surrounded by modern residential development. The stable is situated on an adjacent tax parcel (1300740094, 718 Victoria Drive), but is included in the National Register boundary for the resource because it is historically associated and dates to the period of significance. The “twin” holly trees for which the resource is named are also situated on tax parcel 1300740094, west of the stable, and are included in the National Register boundary of the resource.

The multiple-property National Register nomination form for *Rebuilding St. George’s Hundred* included documentation of the dwelling and historic outbuildings on the A. Eliason House/Twin Holly Farms property. The dwelling is currently in good condition and retains all of the features for which it is significant. The three-story, L-shaped, brick dwelling (consisting of a main block with a hipped roof and a rear ell with a side gable roof) primarily features Greek Revival stylistic elements, including a five-bay, symmetrical façade, a shallow pitched roof, a central façade porch, a central entrance with a transom and sidelights, and six-over-six, double-hung sash windows. The dwelling also exhibits Italianate stylistic influences, including the bracketed cornice. The only notable alteration made to the dwelling since 1985 is the addition of a wood deck to the east elevation in 2004.

A paved driveway is located to the south of the dwelling, providing access from Summit Bridge Road to the secondary buildings located east of the dwelling. The previously prepared National Register nomination form mentioned the stable and carriage house, as well as a smokehouse, granary, and cartshed that are no longer extant. The modern sheds, garage, doghouse, and pool appear to have been added to the property after 1985.

Historical Narrative

Andrew Eliason commissioned the dwelling on this property in the 1850s. Scharf's *History of Delaware* describes Eliason's growth from tenant farmer to successful landholder and owner of at least three farms, and mentions the physical improvements made to Eliason's dwelling during Rebuilding (Herman et al. 1985). Because the resource was previously listed in the National Register and a National Register nomination form was prepared for the farm, no additional research was conducted on the historical development of the property.

National Register Evaluation

The A. Eliason House/Twin Holly Farms was listed in the National Register as part of the multiple property nomination *Rebuilding St. Georges Hundred, New Castle County, 1850-1880* under Criterion A for its agricultural significance and under Criterion C for its architectural significance. The resource is significant as a representative example of the rebuilding process in the local area. The dwelling is also significant for its embodiment of the essential features of the Greek Revival style, modified slightly with Italianate elements.

As part of the U.S. 301 study, the property was revisited and examined to see if it retained sufficient integrity to continue to be eligible for listing in the National Register. All of the significant exterior features of the dwelling from the period of significance remain intact. A small, one-story, brick-clad addition was made at the intersection of the ell during the 1960s and a wood deck was added to the east elevation in 2004; however, these do not significantly detract from the resource's architectural integrity. The dwelling at the A. Eliason House/Twin Holly Farms property retains sufficient integrity to convey its architectural significance. A CRS form was completed for the dwelling to document the addition of the rear deck since it was listed in the National Register. CRS forms were also prepared for the stable, carriage house and privy because they were not previously documented on CRS forms. The property remains eligible for listing in the National Register under Criterion C, but lacks sufficient integrity to convey its significance under Criterion A due to the loss of several of its historic outbuildings, as well its historic farmland and small-scale agricultural features (farm lane, fencelines, etc).

National Register Boundary

The Eliason House was previously listed in the National Register as part of the *Rebuilding of St. Georges Hundred National Register* thematic nomination in 1985. While no mapping of a boundary for the property could be located, the verbal boundary description of the National Register nomination provides information that was used in delineating a boundary for the resource. The verbal boundary description for the Eliason House indicates:

The A. Eliason House is located on the east side of Rt. 896 approximately .5 miles south of Rt. 896 and Rt. 15, north of Mount Pleasant. The house and farmstead stands in cultivated farmland near the present Summit Airfield. The nomination includes the house, smokehouse, granary, cartshed, and a brick stable. Noncontributing elements are a modern addition to the brick stable and modern farm buildings to the rear of the lot. The nominated acreage encompasses 7 acres.

The nominated parcel begins at a point .5 miles north of the intersection of Rts. 896 and 15 north of Mt. Pleasant and 50 feet to the east of Rt. 15. Here it extends

east for 500 feet where it makes a 90 degree turn to the north and proceeds for another 500 feet until it forms a 90 degree turn toward the west back toward Rt. 15. The boundary is completed where it makes another 90 degree turn and runs parallel to Rt. 15 to join the first point, now the southwest corner. The nominated parcel contains sufficient acreage to provide for the preservation of the house, outbuildings, grounds, and immediate setting.

This documentation is meant to provide more detail and clarification on the National Register boundary due to recent changes in the property's integrity. To delineate the National Register boundary, A.D. Marble & Company staff plotted the tract description and found that it measured 5.7 acres. A large modern subdivision has been built around the original farm complex. The tax parcel boundary for the A. Eliason House (1300700078) has been reconfigured. The brick stable is now located on a separate parcel (1300740094) to the east of the Eliason House parcel. The second parcel includes the original brick stable as well as a large modern house (not shown in aerial), which is part of the modern subdivision. The proposed National Register boundary has been reconfigured to show these changes in the property's integrity.

The revised National Register boundary includes the house, barn, and outbuildings and excludes the recent development to the north, south, and east. The proposed boundary is drawn along the current tax parcel (1300700078) to the north, Summit Bridge Road to the west, and the current tax parcel to the south. At the eastern end the boundary includes a portion of tax parcel 1300740094. The boundary follows along the eastern end of the brick barn to exclude the modern dwelling located further east. The total acreage of the proposed National Register boundary revision is 3.09 acres. This boundary was prepared in accordance with the National Register guidelines and in consultation with the SHPO, DelDOT, and FHWA for purposes of Section 106 compliance.

CRS No. N00413



N00413. Photograph 1. Dwelling, view looking northeast.




N00413. Photograph 2. Dwelling, view looking southwest. Note the holly tree to the right of the photograph. This tree is one of a pair that flanks the façade of the dwelling.

CRS No. N00413




N00413. Photograph 3. Stable, view looking southeast. Not addition to north elevation.



N00413. Photograph 4. Stable, view looking west. Note tractor shed and storage additions to east elevation.


CRS No. N00413



N00413. Photograph 5. Carriage house/storage loft, view looking northwest.



N00413. Photograph 6. Privy, view looking south.



U.S. 301 Project Development 1962 Aerial

A. Eliason House/Twin Holly Farms - CRS No. N00413





CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS

N00413.

1. HISTORIC NAME/FUNCTION: A. Eliason House; Twin Holly Farms
2. ADDRESS/LOCATION: 4353 Summit Bridge Rd
3. CURRENT CONDITION: excellent good fair poor demolished
4. INTEGRITY: A wood deck was added to the rear elevation of the dwelling in 2004; however, this alteration does not significantly diminish the integrity of the building.
5. SETTING INTEGRITY: The property is surrounded by modern residential development, and does not include any farm land, a farm lane, or other small scale agricultural features. The historic smokehouse, cartshed, and granary were demolished after 1985.

6. FORMS ADDED:

#:	Form:	List Property Types:
1	CRS02	Dwelling
3	CRS03	Carriage house/stg loft, Privy, Stable
1	CRS09	N/A

7. SURVEYOR INFORMATION:

Surveyor Name: Elizabeth Amisson / Architectural Historian

Principal Investigator Name: Barbara Copp / Sr. Architectural Historian

Principal Investigator Signature: *Barbara M. Copp*

Organization: A.D. Marble & Company Date: 8/12/2005

8. OTHER NOTES OR OBSERVATIONS:

CRS#

N00413.

Listed in the National Register in 1985 as part of the "Rebuilding St. Georges Hundred, New Castle County, 1850-1880" Multiple Property Nomination.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II
- 1600-1750 Contact Period (Native American)
- 1630-1730 Exploration and Frontier Settlement
- 1730-1770 Intensified and Durable Occupation
- 1770-1830 Early Industrialization
- 1830-1880 Industrialization and Early Urbanization
- 1880-1940 Urbanization and Early Suburbanization
- 1940-1960 Suburbanization and Early Ex-urbanization
- 1960-2000 Deurbanization and Sprawl

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |
| <input type="checkbox"/> Other | <input type="checkbox"/> Unknown |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N00413.01

1. ADDRESS/LOCATION: 4353 Summit Bridge Road
2. FUNCTION(S): historic Single dwelling current Single dwelling
3. YEAR BUILT: 1856 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE OR FLOOR PLAN: center hall with ell

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>other location's CRS #</u>	<u>year</u>
N/A	N/A	N/A
N/A	N/A	N/A

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. 1 story brick addition to N side of rear ell	1960
b. modern wood deck attached to addition	2004

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: L - shaped Stories: Three (3)
Additions: see above

b. Structural system (if known): brick

c. Foundation: materials: stone
basement: full partial not visible no basement

d. Exterior walls (original if visible & any subsequent coverings): brick

e. Roof: shape: main block - side gable; ell - shed roof
materials: asphalt shingles
cornice: wood with brackets
dormers: N/A
chimney: location(s): interior of E end of ell; interior of N & S ends of main block

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: W
- 1) Bays Five (5)
 - 2) Windows 1st story - 4; 2nd & 3rd stories - 5
fenestration Regular
type 6/6 DHS wood
trim wood
shutters 1st story - wood paneled; 2nd & 3rd stories - wood louvered

Facade (cont'd)

- 3) **Door(s)** 1
 location central bay
 type double-leaf, wood panel
 trim wood
- 4) **Porch(es)** extends across 3 central bays - original porch with replaced floor (concrete) & steps (brick)
- b. Side: Direction: N**
- 1) **Bays** Two (2)
- 2) **Windows** 2 on each story
 fenestration Regular
 type 6/6 DHS wood
 trim wood
 shutters N/A
- 3) **Door(s)** 0
 location N/A
 type 6/6 DHS wood
 trim N/A
- 4) **Porch(es)** 1 - story enclosed addition attached to north elevation of rear ell
- c. Side: Direction: S**
- 1) **Bays** Five (5)
- 2) **Windows** 1st story - 3; upper stories - 4
 fenestration Irregular
 type 6/6 dh wood
 trim wood
 shutters N/A
- 3) **Door(s)** 2
 location 2nd & 4th bays from W end
 type wood, 6 panel, wood, 6-light over multi-panel
 trim wood
- 4) **Porch(es)** extends across central 3 bays - original porch with replaced floor (concrete) & steps (bricks)
- d. Rear: Direction: E**
- 1) **Bays** 0
- 2) **Windows** 0
 fenestration N/A
 type N/A
 trim N/A
 shutters N/A
- 3) **Door(s)** 0
 location N/A
 type N/A
 trim N/A
- 4) **Porch(es)** N/A

9. **INTERIOR:** Not accessible

10. **LANDSCAPING:** Fountain in front walkway; walkway is brick herringbone pattern; iron fence across front yard at road; modern driveway & parking lot; no remaining farm fields

11. **OTHER COMMENTS:** N cornice of rear ell is enclosed with aluminum



CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N00413.02

1. ADDRESS/LOCATION: 4353 Summit Bridge Road

2. FUNCTION(S): historic stable current storage/tractor shed

3. YEAR BUILT: 1850-1870 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
N/A	N/A	N/A
N/A	N/A	N/A

list major alterations and additions with years (if known) year

- | | |
|---|-----|
| a. cinder block, shed roof addition & frame pole shed (tractor shed) & cinder block, flat roof addition to east elevation | N/A |
| b. cinder block, gable roof addition to North elevation | N/A |

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system brick
- b. Number of stories one (1)
- c. Wall coverings asphalt shingles
- d. Foundation brick
- e. Roof
 - structural system Side gable; wood frame
 - coverings asphalt shingles
 - openings N/A

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S
 - 1) bays: one (1)
 - 2) windows: 0
 - 3) door(s): 1 garage door - modern wood
 - 4) other: hinged, vertical wood board door over hay loft opening in gable

- b. Side: direction: W
- 1) bays: three (3)
 - 2) windows: 0
 - 3) door(s): 1 small, vertical wood board dutch door at N end of 1st story; 3 hinged, vertical wood doors in 2nd story
 - 4) other: former opening in center of elevation in 1st story is now covered with plywood; addition to N elevation contains 1 double window opening with wood 2/2 dh sash and a modern metal door in the W elevation
- c. Side: direction: E
- 1) bays: Not visible
 - 2) windows: 0
 - 3) door(s): 2 garage openings: 1 at S end of elevation contains a modern door; other is covered with plywood
 - 4) other: 2 modern, cinder block additions and a modern, frame pole shed (tractor shed) are attached to the E elevation
- d. Rear: direction: N
- 1) bays: one (1)
 - 2) windows: 0
 - 3) door(s): 1 modern garage door
 - 4) other: modern addition to N elevation of stable obscures original N elevation; louvered vent in gable

9. INTERIOR (if accessible):

- a) Floor plan Not accessible
- b) Partition/walls Not accessible
- c) Finishes Not accessible
- d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N00413.03

1. ADDRESS/LOCATION: 4353 Summit Bridge Road

2. FUNCTION(S): historic carriage house current storage

3. YEAR BUILT: 1856 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: no style; rectangular

5. INTEGRITY: original site moved

if moved, from where

N/A

original location's CRS #

N/A

year

N/A

N/A

N/A

N/A

list major alterations and additions with years (if known)

a. N/A

year

N/A

b. N/A

N/A

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system brick

b. Number of stories two (2)

c. Wall coverings asphalt shingles

d. Foundation brick

e. Roof

structural system hipped; wood frame

coverings asphalt shingles

openings N/A

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: S

1) bays: two (2)

2) windows: 2 - 2nd story, 6/6 dh wood with wood sills & trim

3) door(s): 2 - carriage doors, double-leaf, metal strap hinges

4) other: timber beam across top of 1st story; exposed rafters in eaves

b. Side: direction: E

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0
- 4) other: exposed rafters in eaves

c. Side: direction: W

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0
- 4) other: exposed rafters in eaves

d. Rear: direction: N

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0
- 4) other: small trash enclosure attached to elevation at west end (modern)

9. INTERIOR (if accessible):

a) Floor plan Not accessible

b) Partition/walls Not accessible

c) Finishes Not accessible

d) Furnishings/machinery Not accessible



CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N00413.04

1. ADDRESS/LOCATION: 4353 Summit Bridge Road

2. FUNCTION(S): historic privy current vacant/not in use

3. YEAR BUILT: 1900 CIRCA?: ARCHITECT/BUILDER: unknown

4. STYLE/FLOOR PLAN: no style; rectangular

5. INTEGRITY: original site moved

if moved, from where

N/A

original location's CRS #

N/A

year

N/A

N/A

N/A

N/A

list major alterations and additions with years (if known)

a. N/A

year

N/A

b. N/A

N/A

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood frame

b. Number of stories one (1)

c. Wall coverings asphalt shingles

d. Foundation wood

e. Roof

structural system shed roof; wood frame

coverings asphalt shingles

openings N/A

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: N

1) bays: one (1)

2) windows: 0

3) door(s): 1 - batten wood with sliver moon cut out; metal strap hinges; metal handle

4) other: N/A

b. Side: direction: W

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0

4) other: wood louvered shutters appear to be decorative - no opening visible behind shutters

c. Side: direction: E

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0

4) other: wood louvered shutters appear to be decorative - no opening visible behind shutters

d. Rear: direction: S

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0

4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan Not accessible

b) Partition/walls Not accessible

c) Finishes Not accessible

d) Furnishings/machinery Not accessible



**CULTURAL RESOURCE SURVEY
MAP FORM**

**DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901**

CRS#:

N00413


1. ADDRESS/LOCATION: 4353 Summit Bridge Rd

2. NOT FOR PUBLICATION:


3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)



4. SITE PLAN:



CRS No. N00425

Address: N/A

Date of Construction/Major Alterations: N/A

Time Period: 1730-1770±, Intensified and Durable Occupation; 1770-1830±, Early Industrialization; 1830-1880±, Industrialization and Early Urbanization; 1880-1940±, Urbanization and Early Suburbanization;

Geographic Zone: Upper Peninsula

Historic Period Theme(s): Architecture, Engineering, and Decorative Arts (Residential Architecture); Agriculture; Settlement Patterns and Demographic Changes; Community Organizations; Transportation and Communication

Name: Middletown Historic District

Tax Parcels: Multiple

The Middletown Historic District was listed in the National Register in 1978 under Criterion A and C as the political, industrial, and commercial nucleus for lower New Castle County in the nineteenth century. The Middletown Historic District required no reassessment and no documentation for the district was prepared as part of the current study.

CRS No. N00427

Name: Woodside

Address: 1358 Choptank Road

Tax Parcel: 1301100022

Date of Construction/Major Alterations: ca. 1860

Time Period: 1830-1880±, Industrialization and Early Urbanization; 1880-1940±, Urbanization and Early Suburbanization;

Geographic Zone: Upper Peninsula

Historic Period Theme(s): Architecture, Engineering, and Decorative Arts (Residential Architecture); Agriculture;

Description

The property consists of a *circa-1860* brick dwelling, a stable, a granary, a cattle/dairy barn, an equipment shed, and a water tower. The brick dwelling stands two stories tall and measures five bays wide. The dwelling is lit by two-over-two double hung sash windows. The rear ell stands three stories tall and is also clad in brick. The outbuildings are located east of the dwelling.

National Register Evaluation

Woodside was previously listed in the National Register as part of the *Rebuilding of St. Georges Hundred National Register* thematic nomination in 1985. The property was revisited in 2002 as part of the Choptank Road study, and in 2006 as part of the current study. The property appears to retain sufficient integrity to convey its significance under National Register Criteria A and C.

National Register Boundary

The present-day tax parcel, measuring 3.5 acres, serves as the National Register boundary.

CRS

N00427.



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

1. HISTORIC NAME/FUNCTION Woodside; Henry Clayton House

2. ADDRESS/LOCATION: 1358 Choptank Rd

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: This property appears to be in a similar condition as noted in the Choptank Road study.

5. SETTING INTEGRITY: This property is located on the east side of Choptank Road. Modern developments flank the property to the north, west, south.

6. FORMS ADDED:

#:	Form:	List Property Types:
1	CRS09	N/A

7. SURVEYOR INFORMATION:

Surveyor Name: Barbara Copp / Architectural Historian

Principal Investigator Name: Barbara Copp / Sr. Architectural Historian

Principal Investigator Signature: *Barbara M Copp*

Organization: A.D. Marble & Company Date: 7/11/2006

8. OTHER NOTES OR OBSERVATIONS:

CRS#

N00427.

Listed in the National Register in 1985 as part of the "Rebuilding St. Georges Hundred, New Castle County, 1850-1880" Multiple Property Nomination.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II
- 1600-1750 Contact Period (Native American)
- 1630-1730 Exploration and Frontier Settlement
- 1730-1770 Intensified and Durable Occupation
- 1770-1830 Early Industrialization
- 1830-1880 Industrialization and Early Urbanization
- 1880-1940 Urbanization and Early Suburbanization
- 1940-1960 Suburbanization and Early Ex-urbanization
- 1960-2000 Deurbanization and Sprawl

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- Agriculture
- Forestry
- Trapping/Hunting
- Mining/Quarrying
- Fishing/Oystering
- Manufacturing
- Retailing/Wholesaling
- Finance
- Professional Services
- Other
- Transportation and Communication
- Settlement Patterns and Demographic Changes
- Architecture, Engineering and Decorative Arts
- Government
- Religion
- Education
- Community Organizations
- Occupational Organizations
- Major Families, Individuals and Events
- Unknown



**CULTURAL RESOURCE SURVEY
MAP FORM**

**DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901**

CRS#: N00427


1. ADDRESS/LOCATION: 1358 Choptank Rd

2. NOT FOR PUBLICATION:


3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)



4. SITE PLAN:



CRS No. N03930

Name: Achmester

**Address: North side of Marl Pit Road,
one mile east of Summit Bridge Road**

Tax Parcel: 1301700036

Date of Construction/Major Alterations: 1829; ca. 1850; ca. 1900

Time Period: 1770-1830±, Early Industrialization; 1830-1880±, Industrialization and Early Urbanization; 1880-1940±, Urbanization and Early Suburbanization

Geographic Zone: Upper Peninsula

Historic Period Theme(s): Architecture, Engineering, and Decorative Arts (Residential Architecture); Agriculture

Description

Achmester was listed in the National Register of Historic Places in the 1980s. The property is located along the north side of Marl Pit Road, approximately one mile east of Summit Bridge Road (U.S. 301). The 277.63-acre lot is planted with mature trees and includes cultivated fields. The property consists of a dwelling constructed in 1829, a *circa*-1850 barn that is in partial ruins; a *circa*-1850 smokehouse of log construction (with wood vertical board exterior cladding), a *circa*-1900 shed, a *circa*-1900 milkhouse, a modern equipment shed/garage, and a modern trailer.

A National Register nomination form was prepared for Achmester in 1979, prior to the property's listing in the 1980s. The dwelling is currently in fair condition and retains all of the features for which it is significant. The one-and-one-half-story, L-shaped, wood frame dwelling (consisting of a five-bay main block, a five-bay, gable end wing, and a five-bay rear service ell) is an early-nineteenth-century vernacular dwelling with Gothic Revival style elements applied during the mid-nineteenth century. Gothic Revival features in the dwelling include sawnwork trim, pendants, vergeboards, and brackets. No notable alterations have been made to the dwelling since 1979; however, the building is exhibiting some signs of neglect, especially in the shed roof porch attached to the rear service ell. Plywood currently covers the windows and doors in the dwelling.

The farm lane is located to the east of the dwelling, providing access from Marl Pit Road to the secondary buildings located north of the dwelling. The previously prepared National Register nomination form mentioned a dairy barn, milkhouse, two granaries, smokehouse, shed, wind-powered water pump (windmill), modern garage, and modern trailer. The dairy barn is partially collapsed, and the granaries and windmill are no longer extant. HABS documentation was completed for the dwelling, granaries, and smokehouse in 1985.

Historical Narrative

Richard Mansfield resided at Achmester from 1819, when he purchased the property, until his death in 1846. Mansfield was a successful farmer, a commissioner of the Delaware Railroad, and a Brigadier-General in the Delaware militia. Mansfield kept detailed records of his activities between 1826 and 1844, and room by room inventories were taken of the dwelling at Achmester in 1841 and 1846. Primary records indicate that at least the main block of the dwelling was constructed in 1829, and the house had reached its present form by 1846 (Warnock 1979). Because the resource was previously listed in the National Register and a National Register

nomination form was prepared for the farm, no additional research was conducted on the historical development of the property.

National Register Evaluation

Achmester was listed in the National Register in 1980 under Criterion A for its agricultural significance and under Criterion C for its architectural significance. The resource is significant as a unique example of the rebuilding process in the local area. The dwelling is also significant for its Gothic Revival style features.

As part of the U.S. 301 study, the property was revisited and examined to see if it retained sufficient integrity to continue to be eligible for listing in the National Register. All of the significant exterior features of the dwelling from the period of significance remain intact. The dwelling at Achmester retains sufficient integrity to convey its architectural significance under Criterion C. Two granaries and a windmill are no longer extant; however, the remaining outbuildings convey the agricultural significance of the property. The property remains eligible for listing in the National Register under Criterion A in the area of agriculture.

As part of the U.S. 301 intensive-level survey, a CRS form was not completed for the dwelling because it was documented in the National Register nomination form and has not undergone any notable alterations since 1979. CRS forms were prepared for the barn, milkhouse, smokehouse, and shed because they were not previously documented on CRS forms.

National Register Boundary

The National Register boundary was delineated based on the guidance in the 1985 nomination form, which included a map and verbal boundary description. The nomination indicated the nominated acreage measured approximately 210 acres and provided the following description:

Beginning at a point where the north edge of Road 429 right-of-way meets the railroad right then to the east about 4200 feet to the western edge of the right-of-way of Cedar Lane and proceed along the hedgerow west about 1900 feet, then north about 1000 feet to meet a creek. Proceed westward along the creek for approximately 4000 feet to the east edge of the railroad right-of-way. Then proceed south along the railroad right-of-way about 2400 feet to the point of origin (National Register nomination, Achmester, 1979).

The boundary was mapped as described above and includes 266.23 acres rather than 210 acres, which is most of tax parcel 1301700036. This boundary was prepared in accordance with the National Register guidelines and in consultation with the SHPO, DeIDOT, and FHWA for purposes of Section 106 compliance.

CRS No. N03930



N03930. Photograph 1. Dwelling, view looking northeast.



N03930. Photograph 2. Dwelling, view looking southwest.

CRS No. N03930



N03930. Photograph 3. Cow barn, view looking southwest.




N03930. Photograph 4. Milkhouse, view looking northwest.

CRS No. N03930



N03930. Photograph 5. Shed, view looking south. Note addition to north elevation.



N03930. Photograph 6. Smokehouse, view looking northwest.



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS

N03930.

1. HISTORIC NAME/FUNCTION: Achmester
2. ADDRESS/LOCATION: North Side of Marl Pit Rd, One Mile East of Summit Bridge Rd
3. CURRENT CONDITION: excellent good fair poor demolished
4. INTEGRITY: The dwelling has not undergone any significant alterations since the National Register nomination form was prepared in 1979.

5. SETTING INTEGRITY: The property retains cultivated farm land, a farm lane, an identifiable farm plan, and multiple historic outbuildings. The dairy barn is in partial ruins, and the corn crib/granary and windmill mentioned in the previous documentation are no longer extant

6. FORMS ADDED:

#:	Form:	List Property Types:
4	CRS03	Dairy barn, Milkhouse, Shed, Smokehouse
1	CRS09	N/A

7. SURVEYOR INFORMATION:

Surveyor Name: Elizabeth Amisson / Architectural Historian

Principal Investigator Name: Barbara Copp / Sr. Architectural Historian

Principal Investigator Signature: *Barbara M. Copp*

Organization: A.D. Marble & Company Date: 8/16/2005

8. OTHER NOTES OR OBSERVATIONS:

CRS#

N03930.

Listed in the National Register in 1980 under Criterion A for its agricultural significance and under Criterion C for its architectural significance.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II
- 1600-1750 Contact Period (Native American)
- 1630-1730 Exploration and Frontier Settlement
- 1730-1770 Intensified and Durable Occupation
- 1770-1830 Early Industrialization
- 1830-1880 Industrialization and Early Urbanization
- 1880-1940 Urbanization and Early Suburbanization
- 1940-1960 Suburbanization and Early Ex-urbanization
- 1960-2000 Deurbanization and Sprawl

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |
| <input type="checkbox"/> Other | <input type="checkbox"/> Unknown |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N03930.02

1. ADDRESS/LOCATION: North side Marl Pit Road, 1 mile east of Summit Bridge Road

2. FUNCTION(S): historic Cow Barn current Empty/not in use

3. YEAR BUILT: 1850 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: Open, regular, rectangular, single cell

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
N/A	N/A	N/A
N/A	N/A	N/A
<u>list major alterations and additions with years (if known)</u>		<u>year</u>
a. N/A		N/A
b. N/A		N/A

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system Frame
- b. Number of stories Two (2)
- c. Wall coverings Unfinished batten board with traces of red paint
- d. Foundation None visible
- e. Roof
 - structural system High-pitched gable roof with ridge perpendicular to road
 - coverings Corrugated aluminum
 - openings None

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S
 - 1) bays: Three (3)
 - 2) windows: 1 - 2nd story; details not visible, only open space remains
 - 3) door(s): 2 - single, batten board, hinged on E side; one each in west and central bays
 - 4) other: Details of far east bay not visible due to cow barn's poor condition

b. Side: direction: E

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0
- 4) other: Cow barn is in poor condition on rear elevations so that bay, window and door details/placement are not visible

c. Side: direction: W

- 1) bays: Not accessible
- 2) windows: Not accessible
- 3) door(s): Not accessible
- 4) other: Details/elevation is not visible/accessible due to severe vegetation overgrowth

d. Rear: direction: N

- 1) bays: Not visible
- 2) windows: Not visible
- 3) door(s): Not visible
- 4) other: Cow barn is in poor condition; the rear details of windows, doors, are not visible

9. INTERIOR (if accessible):

- a) Floor plan Not accessible

- b) Partition/walls Not accessible

- c) Finishes Not accessible

- d) Furnishings/machinery Not accessible



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N03930.03

1. ADDRESS/LOCATION: North side Marl Pit Road, 1 mile east of Summit Bridge Road

2. FUNCTION(S): historic Milkhouse current Vacant/not in use

3. YEAR BUILT: 1900 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: No style; open rectangular floor plan

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
N/A	N/A	N/A
N/A	N/A	N/A

list major alterations and additions with years (if known) year

a. Addition attached to NW corner unk.

b. N/A N/A

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system Wood frame

b. Number of stories One (1)

c. Wall coverings Vertical wood boards

d. Foundation Concrete slab

e. Roof

structural system Front gable with side gable addition to NW corner; wood frame

coverings Corrugated metal

openings N/A

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: S

1) bays: Three (3)

2) windows: 2 openings: 1 in main block (W bay) and 1 in addition to NW corner, neither have windows intact

3) door(s): 1 opening in E bay of main block; no door intact

4) other: N/A

- b. Side: direction: E
- 1) bays: One (1)
 - 2) windows: Paired window opening in center, but no windows intact
 - 3) door(s): 0
 - 4) other: N/A
- c. Side: direction: W
- 1) bays: 0
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A
- d. Rear: direction: N
- 1) bays: Two (2)
 - 2) windows: 1 opening in main block, no windows intact; 1 opening in addition, 6-light wood fixed
 - 3) door(s): 0
 - 4) other: N/A

9. INTERIOR (if accessible):

- a) Floor plan Open, 2-level (floor of addition to NW corner is approximately 2-3" higher than floor of original section)
- b) Partition/walls 1 wood partition wall covered with vertical wood boards splits interior of addition into 2 sections (S & N)
- c) Finishes Wood paneling/vertical wood boards
- d) Furnishings/machinery Old tank just inside entrance to W of door



CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N03930.04

1. ADDRESS/LOCATION: North side Marl Pit Road, 1 mile east of Summit Bridge Road

2. FUNCTION(S): historic Shed current Shed

3. YEAR BUILT: 1900 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: No style; open rectangular floor plan

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
N/A	N/A	N/A
N/A	N/A	N/A
<u>list major alterations and additions with years (if known)</u>		<u>year</u>
a. N/A		N/A
b. N/A		N/A

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system Wood frame
- b. Number of stories One (1)
- c. Wall coverings Vertical wood boards
- d. Foundation None
- e. Roof
 - structural system Gable, wood frame
 - coverings Corrugated metal
 - openings N/A

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: W
 - 1) bays: Two (2)
 - 2) windows: 0
 - 3) door(s): 2 double-leaf shed doors with vertical wood boards & metal strap hinges
 - 4) other: 2 concrete ramps lead to doors

b. Side: direction: S

- 1) bays: One (1)
- 2) windows: 1 opening in loft - covered with corrugated metal
- 3) door(s): 0
- 4) other: N/A

c. Side: direction: N

- 1) bays: (1)
- 2) windows: 0
- 3) door(s): 0
- 4) other: Entire historic N elevation is obstructed by a 1-story pole barn/equipment shed that is open in the N elevation & covered in other elevations by corrugated metal sheathing

d. Rear: direction: E

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan Not accessible

b) Partition/walls Not accessible

c) Finishes Not accessible

d) Furnishings/machinery Not accessible