

APPENDIX E:

HISTORIC AMERICAN BUILDING SURVEY DOCUMENTATION

THE ANDREW JACKSON WILLIAMS HOUSE

No information provided for this page.

ARCHITECTURAL DATA FORM

STATE Delaware	COUNTY New Castle County	TOWN OR VICINITY Wilmington
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Andrew Jackson Williams House (New Castle County deeds and tax records)		HABS NO.
SECONDARY OR COMMON NAMES OF STRUCTURE Paul E. Bower, Jr. House		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 2200 Newport Gap Pike (State Route 41)		
DATE OF CONSTRUCTION (INCLUDE SOURCE) ca. 1870s (New Castle County deeds and tax records)	ARCHITECT(S) (INCLUDE SOURCE)	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) This dwelling is a rural private home that was built for a middle-class family. It also documents the growth of the Greenbank area from a predominantly rural agricultural landscape into an industrial/manufacturing community.		
STYLE (IF APPROPRIATE) Greek Revival/Italianate		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) fieldstone foundation (stuccoed on the exterior) - the entire structure is completely sheathed with German siding except on part of the ell addition		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) See the enclosed floor plans.		
EXTERIOR FEATURES OF NOTE The Williams house juxtaposes frieze boards and box cornices normally found on Greek Revival structures with eave brackets and partial return gable ends imitative of Italianate buildings.		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) See the enclosed floor plans.		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES A shed addition to the rear of the kitchen replaced an earlier shed addition that was destroyed by fire during the 1920s.		
PRESENT CONDITION AND USE Recent vandalism has removed many of its' architectural features. The house is in direct line of a proposed road improvement and will be demolished.		
OTHER INFORMATION AS APPROPRIATE		
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) The Delaware Statewide Comprehensive Historic Preservation Plan, Delaware Cultural Resource Survey, New Castle County Deeds/Tax Assessments for Christiana Hundred		
COMPILER, AFFILIATION Stuart P. Dixon, Cheryl C. Powell. Center for Historic Architecture and Engineering, University of Delaware	DATE 2-14-88	

HISTORIC AMERICAN BUILDING SURVEY

INDEX TO PHOTOGRAPHS


Andrew Jackson Williams House
(Paul E. Bower, Jr., House)
2200 Newport Gap Pike (State Route 41)
South side of Newport Gap Pike approximately
.25 miles west of junction with Kirkwood Highway
(State Route 2)
Prices Corner vicinity
Wilmington
Christiana Hundred
New Castle County
Delaware

HABS. No. DE-

Photographer: David L. Ames

Fall 1987

DE- -1 NORTHEAST (FRONT) ELEVATION LOOKING WEST
DE- -2 SOUTHWEST AND SOUTHEAST ELEVATIONS LOOKING NORTHEAST
DE- -3 DETAIL OF GERMAN SIDING ON NORTHEAST ELEVATION LOOKING WEST



DE- -3

Historic American Building Survey documentation of the Andrew Jackson Williams House includes two photographs and one set of floor plans included in Chapter II. These items are located as follows:

PHOTOGRAPHS

DE- -1; Plate 3, p. 17

DE- -2; Plate 4, p. 18

DRAWINGS

Floor Plans; Figure 5, p. 21