



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N14131.090
SPO Map 08-09-33
Hundred New Castle
Quad Newark East
Other Parcel 1003340003

1. HISTORIC NAME/FUNCTION: Marie Elizabeth Moore House
2. ADDRESS/LOCATION: 56 Lark Avenue, Bear, Delaware, 19701
3. TOWN/NEAREST TOWN: Bear vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
 landscape district
5. MAIN FUNCTION OF PROPERTY: Single Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable): SR1 Lane Widening

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
0	CRS 3 Secondary Building Form	N/A
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

8. SURVEYOR INFORMATION:

Surveyor name: Patti Kuhn and Sarah Groesbeck

Principal Investigator name: Patti Kuhn

Principal Investigator signature: *Patti Kuhn*

Organization: The Louis Berger Group, Inc. Date: June 2012

9. OTHER NOTES OR OBSERVATIONS:

CRS# N14131.090

This dwelling is located in the Fair Winds Subdivision, which was evaluated as part of the "School Bell Road (SR 1 to US 40) Improvements Historic Architectural Survey and Determination of Eligibility Report" in 2004. The subdivision was evaluated as a whole, CRS numbers were assigned to each dwelling in the subdivision, but only dwellings within the project area of potential effect were recorded on Cultural Resource Survey Forms. It does not appear that the Marie Elizabeth Moore House was documented as part of the 2004 effort.

Property records and aerial photographs indicate an outbuilding located along the southeast corner of the property. The building appears to date after 1965.


The property is also being evaluated or reassessed for its National Register eligibility or listing status. This evaluation assessment is triggered by the federal undertaking initiated by DeIDOT and the Federal Highway Administration as part of the SR 1 Roth Bridge to Interstate 95, Capacity Improvement Project (T200511001; Federal Aid NH-N067(26)). Further referenced information on this property as well as other in the vicinity, can be seen in the Architectural Evaluation entitled, "Architectural Survey Report, SR 1 Widening, New Castle County, Delaware."

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N14131.090

1. ADDRESS/LOCATION: 56 Lark Avenue, Bear, Delaware 19701
2. FUNCTION(S): historic Single Dwelling current Single Dwelling
3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: Unknown
4. STYLE OR FLOOR PLAN: Cape Cod
5. INTEGRITY: original site moved
- | <u>if moved, from where</u> | <u>other location's CRS #</u> | <u>year</u> |
|-----------------------------|-------------------------------|-------------|
| N/A | N/A | N/A |
| N/A | N/A | N/A |
- | <u>list major alterations and additions with years (if known)</u> | | <u>year</u> |
|---|--|-------------|
| a. N/A | | N/A |
| b. N/A | | N/A |

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: Rectangular Stories: 1.5
Additions: N/A
- b. Structural system (if known): Balloon Frame
- c. Foundation: materials: Concrete
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Asbestos Siding
- e. Roof: shape: Side Gable
materials: Asphalt Shingle
cornice: N/A
dormers: Two gabled dormers on facade
chimney: location(s): Exterior end brick chimney on southeast elevation

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: Northeast
- 1) Bays 3
- 2) Windows 4
- fenestration symmetrical, 2 large picture windows flanked by smaller windows on 1st story,
2 regular windows in dormers
type 1-light fixed wood-sash picture windows flanked by 4/4 wood-sash windows,
6/6 wood-sash windows in dormers
trim Wood trim
shutters N/A

Facade (cont'd)

- 3) **Door(s)** 1
 location Center bay of 1st story
 type Single-leaf wood-paneled door
 trim Colonial Revival wood surround with pilasters and dentil cornice
- 4) **Porch(es)** N/A

b. Side: Direction: Northwest

- 1) **Bays** 2
- 2) **Windows** 3
 fenestration One regular window and 1 smaller window on 1st story, one regular window on attic story
 type 6/6 wood-sash windows
 trim Wood trim
 shutters N/A
- 3) **Door(s)** 1
 location South end of elevation
 type Single-leaf door
 trim N/A
- 4) **Porch(es)** N/A

c. Side: Direction: Southeast

- 1) **Bays** 2
- 2) **Windows** Not Visible
 fenestration Not Visible
 type Not Visible
 trim Not Visible
 shutters Not Visible
- 3) **Door(s)** Not Visible
 location Not Visible
 type Not Visible
 trim Not Visible
- 4) **Porch(es)** One-story, one-bay, gable-roof porch with wood posts


d. Rear: Direction: Southwest

- 1) **Bays** Not Visible
- 2) **Windows** Not Visible
 fenestration Not Visible
 type Not Visible
 trim Not Visible
 shutters Not Visible
- 3) **Door(s)** Not Visible
 location Not Visible
 type Not Visible
 trim Not Visible
- 4) **Porch(es)** Not visible

9. **INTERIOR:** Not Accessible

10. **LANDSCAPING:** The house is set back from the road on a level, grassy lot that is shaded by mature trees. A paved driveway leads to the house along its northwest side. Large foundation plants line the façade of the house.

11. **OTHER COMMENTS:** N/A



CULTURAL RESOURCE SURVEY

CRS # N14131.090

MAP FORM

1. ADDRESS/LOCATION: 56 Lark Avenue, Bear, Delaware, 19701


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # N14131.090

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # N14131.090 Date 5/22/2012 Photo Roll # N/A Surveyor S. Groesbeck
P. Kuhn

Description View of property from road looking southeast; Main (north) and west elevations looking southeast

Negative location (if other than SHPO)

Attach contact print(s):

