

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-03181

1. HISTORIC NAME/FUNCTION: Joseph Robbins House

2. ADDRESS/LOCATION: 15127 Old State Road

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: House was completely updated ca. 1950

5. SETTING INTEGRITY: Trailer park to the north, newer residential property to the south.


6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
X	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Kate Farnham

Principal Investigator name: Grace Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc Date: 4/3/2008

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03181

Resurveyed for US113 North/South Study, Delaware Department of Transportation, by John Milner Associates, Inc.

The owner states that the husband purchased house and 'redid it' in 1950. Not sure how old it is, but the husband says it is "historic"


9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-03181.001

1. ADDRESS/LOCATION: 15127 Old State Road

2. FUNCTION(S): historic Domestic, agricultural current Domestic/ agricultural

3. YEAR BUILT: 1900 CIRCA?: ARCHITECT/BUILDER:

4. STYLE OR FLOOR PLAN: 3-bay I-house

5. INTEGRITY: original site moved

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

- a. new windows and porches ca. 1950, new siding, modern rear door and chimney
- b. concrete over foundation

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)


- a. Overall shape: L-plan Stories: 2.5
Additions:
- b. Structural system (if known): wood-framed
- c. Foundation: materials: poured concrete (possibly stucco)
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): aluminum siding
- e. Roof: shape: side gable, cross gable
materials: asphalt
cornice: boxed
dormers:
chimney: location(s): ext. gable at rear, concrete block

8. DESCRIPTION OF ELEVATIONS:

a.	Facade: Direction: W	
	1)	Bays 3
	2)	Windows 2 (1 st story); 3 (2 nd story)
		fenestration regular
		type double hung, 2/2 horizontal division (ca. 1950)
		trim wood
	shutters	

Facade (cont'd)											
3)	<table border="1"> <tr> <td>Door(s)</td> <td>1</td> </tr> <tr> <td>location</td> <td>center</td> </tr> <tr> <td>type</td> <td>wood and glass; half-wheel light, 4 panels (ca. 1950)</td> </tr> <tr> <td>trim</td> <td>plain</td> </tr> </table>	Door(s)	1	location	center	type	wood and glass; half-wheel light, 4 panels (ca. 1950)	trim	plain		
Door(s)	1										
location	center										
type	wood and glass; half-wheel light, 4 panels (ca. 1950)										
trim	plain										
4)	Porch(es) full width hip-roof porch with square wood replacement columns, cinderblock and poured concrete, beadboard ceiling										
b. Side: Direction: N											
1)	Bays 2										
2)	<table border="1"> <tr> <td>Windows</td> <td>2 per story (6 total)</td> </tr> <tr> <td>fenestration</td> <td>regular</td> </tr> <tr> <td>type</td> <td>double hung 2/2 horizontal div. (ca. 1950) (attic windows are fixed, 2 light)</td> </tr> <tr> <td>trim</td> <td>wood</td> </tr> <tr> <td>shutters</td> <td></td> </tr> </table>	Windows	2 per story (6 total)	fenestration	regular	type	double hung 2/2 horizontal div. (ca. 1950) (attic windows are fixed, 2 light)	trim	wood	shutters	
Windows	2 per story (6 total)										
fenestration	regular										
type	double hung 2/2 horizontal div. (ca. 1950) (attic windows are fixed, 2 light)										
trim	wood										
shutters											
3)	<table border="1"> <tr> <td>Door(s)</td> <td>0</td> </tr> <tr> <td>location</td> <td></td> </tr> <tr> <td>type</td> <td></td> </tr> <tr> <td>trim</td> <td></td> </tr> </table>	Door(s)	0	location		type		trim			
Door(s)	0										
location											
type											
trim											
4)	Porch(es) 0										
c. Side: Direction: S											
1)	Bays 4										
2)	<table border="1"> <tr> <td>Windows</td> <td>4 (1st and 2nd stories), 2 on 3rd story</td> </tr> <tr> <td>fenestration</td> <td>irregular</td> </tr> <tr> <td>type</td> <td>double hung 2/2 horizontal division (ca. 1950)</td> </tr> <tr> <td>trim</td> <td>wood</td> </tr> <tr> <td>shutters</td> <td></td> </tr> </table>	Windows	4 (1 st and 2 nd stories), 2 on 3 rd story	fenestration	irregular	type	double hung 2/2 horizontal division (ca. 1950)	trim	wood	shutters	
Windows	4 (1 st and 2 nd stories), 2 on 3 rd story										
fenestration	irregular										
type	double hung 2/2 horizontal division (ca. 1950)										
trim	wood										
shutters											
3)	<table border="1"> <tr> <td>Door(s)</td> <td>1</td> </tr> <tr> <td>location</td> <td>Southeast side</td> </tr> <tr> <td>type</td> <td>wood and glass, half-wheel light with 4 panels (ca. 1950)</td> </tr> <tr> <td>trim</td> <td>plain</td> </tr> </table>	Door(s)	1	location	Southeast side	type	wood and glass, half-wheel light with 4 panels (ca. 1950)	trim	plain		
Door(s)	1										
location	Southeast side										
type	wood and glass, half-wheel light with 4 panels (ca. 1950)										
trim	plain										
4)	Porch(es) gabled entry porch (modern) with concrete steps, plywood gable siding, square posts										
d. Rear: Direction: E											
1)	Bays 2										
2)	<table border="1"> <tr> <td>Windows</td> <td>2 on 1st story, 2 on 2nd story</td> </tr> <tr> <td>fenestration</td> <td>irregular</td> </tr> <tr> <td>type</td> <td>double hung, 2/2 horizontal div. (ca. 1950)</td> </tr> <tr> <td>trim</td> <td>wood</td> </tr> <tr> <td>shutters</td> <td></td> </tr> </table>	Windows	2 on 1 st story, 2 on 2 nd story	fenestration	irregular	type	double hung, 2/2 horizontal div. (ca. 1950)	trim	wood	shutters	
Windows	2 on 1 st story, 2 on 2 nd story										
fenestration	irregular										
type	double hung, 2/2 horizontal div. (ca. 1950)										
trim	wood										
shutters											
3)	<table border="1"> <tr> <td>Door(s)</td> <td>1</td> </tr> <tr> <td>location</td> <td>center</td> </tr> <tr> <td>type</td> <td>aluminum clad, 6 panel, modern</td> </tr> <tr> <td>trim</td> <td>plain</td> </tr> </table>	Door(s)	1	location	center	type	aluminum clad, 6 panel, modern	trim	plain		
Door(s)	1										
location	center										
type	aluminum clad, 6 panel, modern										
trim	plain										
4)	Porch(es) concrete stoop										

9.	INTERIOR:
10.	LANDSCAPING: u-shaped gravel driveway, front lawn with 2 mature Japanese Maples and a few shrubs, all outbuildings are to the rear of the house, agricultural fields on all sides
11.	OTHER COMMENTS:



CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03181.002

1. ADDRESS/LOCATION: 15127 Old State Road

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: 2-car garage

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. asbestos cladding over original German wood siding
b. new corrugated doors

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood framed
- b. Number of stories 1
- c. Wall coverings wood siding (horizontal), asbestos
- d. Foundation concrete block
- e. Roof
 - structural system side gable, boxed cornices
 - coverings asphalt
 - openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S
 - 1) bays: 2
 - 2) windows: 0
 - 3) door(s): 2, center, corrugated metal garage doors
 - 4) other:

- b. Side: direction: W
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: E
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: N
 - 1) bays: 2
 - 2) windows: 2, double hung 8/8 wood sash
 - 3) door(s):
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03181.003

1. ADDRESS/LOCATION: 15127 Old State Road

2. FUNCTION(S): historic Well house current Well house

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: One pen

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. replacement door
b. tin cladding on sides

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system wood-framed
b. Number of stories 1/2
c. Wall coverings wood siding (vertical), metal
d. Foundation none inside
e. Roof gable front
structural system boxed cornices
coverings asphalt
openings

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: S
1) bays:
2) windows:
3) door(s): 1, centered, plywood with no lights or panels
4) other:

- b. Side: direction: W
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: E
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: N
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03181.004

1. ADDRESS/LOCATION: 15127 Old State Road

2. FUNCTION(S): historic Agricultural shed current Equipment shed

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: One pen

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. deteriorated, doors missing
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system concrete block
b. Number of stories 1
c. Wall coverings wood siding (vertical) in gable area
d. Foundation
e. Roof
structural system gable front, boxed cornices
coverings asphalt
openings

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: N
1) bays: 1
2) windows:
3) door(s): 1, center, wood and glass garage door, 8 lights and 24 panels
4) other:

- b. Side: direction: W
 - 1) bays: 2
 - 2) windows: 1, fixed 2/2
 - 3) door(s): 1, southwest side, wood and glass, 1 light and 3 panels (broken)
 - 4) other:

- c. Side: direction: E
 - 1) bays: 1
 - 2) windows:
 - 3) door(s): 1, center, corrugated metal sliding doors, 1 missing.
 - 4) other:

- d. Rear: direction: S
 - 1) bays: 2
 - 2) windows: 2, regular, fixed 2/2
 - 3) door(s): 0
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03181.005

1. ADDRESS/LOCATION: 15127 Old State Road

2. FUNCTION(S): historic Workshop/agricultural current storage

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. replacement metal sliding door

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-framed

b. Number of stories 1

c. Wall coverings

d. Foundation concrete block

e. Roof
structural system side gable, boxed cornices
coverings asphalt
openings 3 metal pipe vents along ridgepole

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: N

1) bays: 5

2) windows: 3, double hung 8/8, 4/4

3) door(s): 2, center and northeast side, 5-panel wood door (inset in old wooden sliding door) and sliding metal

4) other:

- b. Side: direction: W
- 1) bays:
 - 2) windows: 2, double hung 8/8
 - 3) door(s): 1, center, wood and glass (2 panel, 1 light – broken)
 - 4) other: porch: shed hood, no stoop

- c. Side: direction: E
- 1) bays: 2
 - 2) windows: 2, double hung 8/8
 - 3) door(s):
 - 4) other:

- d. Rear: direction: S
- 1) bays: 3
 - 2) windows: 3, double hung 8/8
 - 3) door(s):
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03181.006

1. ADDRESS/LOCATION: 15127 Old State Road

2. FUNCTION(S): historic Chicken house current Chicken house

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. plywood cladding
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-framed
- b. Number of stories 1
- c. Wall coverings wood siding (horizontal), plywood, screening
- d. Foundation concrete piers
- e. Roof structural system side gable, boxed cornices
coverings corrugated metal
openings metal hopper at each end

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S
 - 1) bays: 4
 - 2) windows: regular, continuous screened openings
 - 3) door(s): 4, center, board and batten doors – some missing
 - 4) other: _____

- b. Side: direction: W
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: E
 - 1) bays: 1
 - 2) windows:
 - 3) door(s): 1, southeast side, plain wood door
 - 4) other:

- d. Rear: direction: N
 - 1) bays:
 - 2) windows:
 - 3) door(s): 3 + 8 hatches at ground level, plywood and screen doors
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03181.007

1. ADDRESS/LOCATION: 15127 Old State Road

2. FUNCTION(S): historic Chicken house current Vacant/ not in use

3. YEAR BUILT: 1960 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. patching and deterioration
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-framed
- b. Number of stories 1
- c. Wall coverings wood siding (horizontal), plywood panels
- d. Foundation concrete block
- e. Roof
structural system side gable, boxed cornices
coverings corrugated metal
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: N
 - 1) bays:
 - 2) windows: 4, screened groups of continuous opening, 1 bay
 - 3) door(s): 3, center, missing
 - 4) other:

- b. Side: direction: E
 - 1) bays: 1
 - 2) windows:
 - 3) door(s): 1, plywood double doors
 - 4) other:

- c. Side: direction: W
 - 1) bays: 1
 - 2) windows:
 - 3) door(s): 1, center, paired plywood doors
 - 4) other:

- d. Rear: direction: S
 - 1) bays: 4 (maybe more, boarded up)
 - 2) windows: irregular, screened
 - 3) door(s): 2, center, missing
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03181.008

1. ADDRESS/LOCATION: 15127 Old State Road

2. FUNCTION(S): historic Chicken house current Vacant/ not in use

3. YEAR BUILT: 1960 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved

if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. plywood patches, deterioration (partial)

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-framed
- b. Number of stories 1
- c. Wall coverings asphalt, bricktex, and plywood
- d. Foundation concrete piers
- e. Roof structural system shed roof, boxed cornice
coverings corrugated metal
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S
 - 1) bays: 33 (partially collapsed)
 - 2) windows: 22, screened
 - 3) door(s): 11, center, wooden batten doors
 - 4) other: _____

- b. Side: direction: W
 - 1) bays:
 - 2) windows:
 - 3) door(s): 1, boarded over
 - 4) other:

- c. Side: direction: E
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: N
 - 1) bays:
 - 2) windows:
 - 3) door(s): 6, batten doors or missing
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03181.009

1. ADDRESS/LOCATION: 15127 Old State Road

2. FUNCTION(S): historic Ag. shed current Vacant/ not in use

3. YEAR BUILT: 1965 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: One pen

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. deteriorated, loss of doors
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood framed
- b. Number of stories 1
- c. Wall coverings metal
- d. Foundation concrete block
- e. Roof
structural system shed roof, exposed rafter ends
coverings corrugated metal
openings _____

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: W
 - 1) bays: _____
 - 2) windows: _____
 - 3) door(s): 1, center, missing
 - 4) other: _____

- b. Side: direction: S
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: N
 - 1) bays: 4
 - 2) windows: regular fenestration, fixed, missing windows
 - 3) door(s):
 - 4) other:

- d. Rear: direction: E
 - 1) bays: 1
 - 2) windows:
 - 3) door(s): 1, center, missing
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY
STRUCTURE (BUILDING-LIKE) FORM

CRS # S-03181.010

1. ADDRESS/LOCATION: 15127 Old State Road

2. FUNCTION: corncrib IN USE?

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/PLAN: Single pen

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with dates (if known) year
a. collapsing
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION (describe the structure as completely as possible):

a) Overall shape rectangular
height
length
width

b) Structural system: frame

c) Foundation: cinder block


d) Exterior covering: wood siding (vertical)

7. DESCRIPTION (cont'd):

CRS # S-03181.010

e) Openings 1 door, west side

f) Other features



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-03181

1. ADDRESS/LOCATION: 15127 Old State Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-03182

1. HISTORIC NAME/FUNCTION: Jonathan Macklin House

2. ADDRESS/LOCATION: U.S. Route 113

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: badly deteriorated

5. SETTING INTEGRITY:

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Scott Pickens

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:

Organization: John Milner Associates, Inc. Date: 8/1/2005

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03182

Resurveyed for the U.S. 113 North/South Study by JMA on behalf of the Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750∇ Contact Period (Native American)
- 1630-1730∇ Exploration and Frontier Settlement
- 1730-1770∇ Intensified and Durable Occupation
- 1770-1830∇ Early Industrialization
- 1830-1880∇ Industrialization and Early Urbanization
- 1880-1940∇ Urbanization and Early Suburbanization
- 1940-1960∇ Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** west end
 - Type:** wood-and-glass (6 lights, 4 panels)
 - Trim:**
- 4) **Porch(es):** full-width, screened-in shed roof with concrete block foundation and wood decking

b. Side: Direction: east

- 1) **Bays:** 6
- 2) **Windows:** 4, first story; 6, second story; 2, attic level
 - Fenestration:** regular
 - Type:** 6/6 double-hung sash; awning at attic level
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):** 2
 - Location:** north end, northeast corner
 - Type:** missing
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: west

- 1) **Bays:** 6
- 2) **Windows:** 4, first story; 4 second story; 2 attic level
 - Fenestration:** regular
 - Type:** 6/6 double-hung sash; 3-light fixed at attic level
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** north end
 - Type:** wood-and-glass (4 lights, 2 panels)
 - Trim:**
- 4) **Porch(es):** wood stoop, nearly destroyed


d. Rear: Direction: north

- 1) **Bays:** 2
- 2) **Windows:** 3, first story; 1, second story
 - Fenestration:** regular
 - Type:** 6/6 double-hung sash; 6-light fixed; 3-light fixed
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

10. **LANDSCAPING:** large agricultural field to east of house

11. **OTHER COMMENTS:** severely deteriorated



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-03182

1. ADDRESS/LOCATION: U.S. Route 113


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-03187

1. HISTORIC NAME/FUNCTION: Clarence Burton House

2. ADDRESS/LOCATION: McColley's Chapel Road

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: Asbestos shingle siding has deteriorated significantly, front entry porch removed

5. SETTING INTEGRITY: property has become very overgrown

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Kate Farnham

Principal Investigator name: Grace Ziesing

Principal Investigator signature:

Organization: John Milner Associates Inc Date: 4/3/2008

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03187

Resurveyed for US113 North/South Study, Delaware Department of Transportation, by John Milner Associates, Inc.

Vacant and deteriorating; probably a farm house, but no farm buildings remain

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II


 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-03187.001

1. ADDRESS/LOCATION: McColley's Chapel Road

2. FUNCTION(S): historic Domestic current Vacant/ not in use

3. YEAR BUILT: 1900 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: Victorian

5. INTEGRITY: original site moved

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. Asbestos shingle siding

b. side porch rebuilt, front entry porch removed

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: T-plan Stories: 2.5
Additions:

b. Structural system (if known): wood framed

c. Foundation: materials: none
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): asbestos

e. Roof: shape: cross gable, side gable, gable front
materials: asphalt
cornice: boxed
dormers:
chimney: location(s): middle of front wing at gable peak, brick

8. DESCRIPTION OF ELEVATIONS:


a.	Facade: Direction:	<u>E</u>
1)	Bays	<u>3</u>
2)	Windows	<u>2 (1st story); 2 (2nd) and 1 (3rd)</u>
	fenestration	<u>regular</u>
	type	<u>double hung 2/2</u>
	trim	<u>wood</u>
	shutters	

	Facade (cont'd)	
3)	Door(s)	1
	location	center
	type	wood and glass (1 light, 4 panels – original)
	trim	plain
4)	Porch(es)	stoop; shadow of gabled porch – now missing
b.	Side: Direction: N	
1)	Bays	4
2)	Windows	4 (1 st story), 4 (2 nd), 1 (3 rd)
	fenestration	regular
	type	double hung, 2/2 original
	trim	wood
	shutters	
3)	Door(s)	1
	location	east side of “T”
	type	wood and glass, 1 light, 4 panel - original
	trim	plain
4)	Porch(es)	missing
c.	Side: Direction: S	
1)	Bays	4
2)	Windows	4 (1 st story), 4 (2 nd), 2 (3 rd)
	fenestration	regular
	type	double hung, 2/2 original
	trim	wood
	shutters	
3)	Door(s)	1
	location	east side of “T”
	type	wood and glass, 1 light 4 panels - original
	trim	
4)	Porch(es)	portico; shed roofed porch with replacement square posts, beadboard ceiling, concrete floor; partially collapsing
d.	Rear: Direction: W	
1)	Bays	2
2)	Windows	2 (2 nd story)
	fenestration	regular
	type	double hung, 2/2 original
	trim	wood
	shutters	
3)	Door(s)	1
	location	center
	type	missing
	trim	plain
4)	Porch(es)	flat concrete stoop

9.	INTERIOR:
-----------	------------------

10.	LANDSCAPING: Property filled with scrub and small trees. Pine grove to south, a few small deciduous trees at rear, overgrown foundation shrubs in front, 2 big deciduous trees in back yard
------------	--

11.	OTHER COMMENTS: modern shed at rear, grass driveway on south side of house
------------	---



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-03187

1. ADDRESS/LOCATION: McColley's Chapel Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN

