1. SOUTH APPROACH ROADWAY LOOKING NORTH

2. EAST ELEVATION LOOKING WEST

3. GENERAL VIEW LOOKING NORTH

4. TIDAL LOOKING WEST (BOOK)

5. TIDAL LOOKING EAST

6. ASPHALT OVERLAY LOOKING SOUTH

7. EAST RAIL SOUTH DRAIN CLOGGED WITH ASPHALT LOOKING EAST

8. WEST RAIL EXPOSED REBAR NEAR SOUTH END LOOKING WEST

9. EROSION AT SOUTH END OF SOUTHEAST WINGWALL LOOKING NORTH

10. SOUTH ABUTMENT HEAVY EFFLORESCENCE AT WEST END LOOKING SOUTH

11. GIRDER 5, CRACK WITH RUST AT NORTH END LOOKING NORTH

12. GIRDER 7, EXPOSED BAR AT SOUTH END LOOKING UP

13. NORTH ABUTMENT SPALL/ WATERSCALING & UNDERWATER EXPOSED BAR LOOK N