



| EQUIPMENT/PERSONNEL TOTALS    |        |
|-------------------------------|--------|
| TRAFFIC CONES                 | 8      |
| ARROW BOARDS                  | -      |
| VMS                           | -      |
| POLICE VEHICLES               | -      |
| DELDOT TRUCKS                 | -      |
| TYPE 3 BARRICADES             | -      |
| DETOUR SIGN EXIST. POST       | -      |
| DETOUR SIGN W/SUPPORT         | -      |
| PERSONNEL (DIRECTING TRAFFIC) | 1      |
| RESP. FOR EQUIP. SETUP        | DelDOT |

| BACKGROUND COLOR |          |          |       |
|------------------|----------|----------|-------|
| ROADWAY          | BUILDING | CONCRETE | GRASS |

| CONE TAPER & TANGENT LENGTHS |                          |         |       |       |  |
|------------------------------|--------------------------|---------|-------|-------|--|
| APPROACH                     | DESCRIPTION              | TANGENT | TAPER | CONES |  |
| NB CLAPHAM                   | CLOSE RIGHT PASSING LANE | 350'    | -     | 8     |  |
|                              |                          |         |       |       |  |
|                              |                          |         |       |       |  |
|                              |                          |         |       |       |  |

**DRAWING NOT TO SCALE**

**DETOUR REFERENCE #:**  
**DE1- - - -SB05123-05140-1B**

**CONTROL POINT B:**  
**CLAPHAM ROAD AND**  
**BUFFALO ROAD**

|                            |                  |                                      |
|----------------------------|------------------|--------------------------------------|
| <b>DATE:</b><br>APRIL 2010 | <b>BY:</b><br>JZ | <b>REFERENCE NUMBER:</b><br><b>B</b> |
|----------------------------|------------------|--------------------------------------|